

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD385Z - AIG

AAD1712-240

Not Authored
85401
Runny B4 pain

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD385Z - JHOW
 VF1ABL15AUC282683
 RENAULT
 LATITUDE
 23.12.2017
AIG

PART			LIST	
1	1	BUMPER COVER FRT	\$	1,259.42
2	1	BUMPER ABSORBER FRT	\$	394.68
3	1	BUMPER BEAM FRT	\$	914.08
4	1	BUMPER SPOILER FRT	\$	181.75
5	1	BUMPER GRILLE LOWER FRT	\$	266.80
6	1	BUMPER FOG LAMP GRILLE RH	\$	207.22
7	1	BUMPER RETAINER FRT RH	\$	151.41
8	1	BUMPER BRACKET FRT RH	\$	181.75
9	1	HEADLAMP RH	\$	1,184.43
10	1	HEADLAMP PANEL FRT RH	\$	152.15
11	1	FENDER PANEL FRT RH	\$	783.83
12	1	FENDER INSULATOR RH	\$	130.84
13	1	FENDER BRACKET FRT RH	\$	34.14
14	1	WHEELARCH FRT RH	\$	278.84
15	1	RADAIOR GRILLE	\$	1,707.78
16	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	173.36
17	1	RADAIOR GRILLE FRAME	\$	1,353.75
18	1	FRAME FULL SUPPORT PANEL	\$	615.90
19	1	FRAME FULL SUPPORT BRACKET	\$	89.79
20	1	BONNET	\$	1,941.63
21	1	WIPER RESERVOIR	\$	348.25
22	1	WIPER RESERVOIR NECK	\$	136.11
23	1	WIPER RESERVOIR MOTOR	\$	270.06
24	1	DOOR PANEL FRT RH	\$	2,844.66
25	1	DOOR MIRROR RH	\$	1,483.40
26	1	DOOR MIRROR GLASS RH	\$	148.20
27	1	DOOR MIRROR BACK COVER RH	\$	218.46
28	1	DOOR WHETHERSTRIP FRT RH	\$	474.21
29	1	DOOR SEAL FRT RH	\$	68.67
30	1	ROCKER PANEL OUTER RH	\$	987.49

TOTAL	\$	18,983.07
10%	\$	1,898.31
	\$	17,084.77

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-240

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD385Z - AIG

Specical Nett

1	1SET	WHEELARCH CLIP FRT RH	\$	na	66.00 X
2	1SET	FRONT BUMPER CLIP	\$	na	66.00 X
3	1	RIM RH FRT	\$	na	385.00 X
4	1	TYRE RH FRT	\$	na	330.00 X
5	1	DOOR STICKER "Trans-cab"	\$	na	80.00 X
6	1	DOOR STICKER "Classic"	\$	na	30.00 X
7	1	DOOR STICKER "6555-3333"	\$	na	80.00 X

TOTAL	\$	1,037.00
TOTAL PARTS	\$	18,121.77

To Check Electrical Lighting Concerned.	\$	na	170.00 X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	10d
Putty and spray painting of the affected portion.	\$	3,000.00	44d
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na	170.00 X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To check steering geometry and computer wheel alignment	\$	na	220.00 X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	na	170.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	na	170.00 X
Towing fees	\$	na	120.00 X
To rust-proofing of the affected areas.	\$	na	170.00 X

- UKK Auto Consultants Inc. hereby declares that the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplier's price to be referred to final approval from Insurance Company

(PARTS BY PARTS) Repair Days

TOTAL	\$	7,160.00
Over All Total	\$	25,281.77

10 Days

1 day

Acknowledged by Repairer

Signature:

Date: