

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AXA Insurance Pte Ltd
8 Shenton Way #27-01, AXA Tower
Singapore 068811

Our File No: CS/AXA17024581/T1VBS2**Date:** 17/10/2018REFERENCE

Insured/Claimant:	BOO CHIN THYE	Policy No:	GA237298	
Date of Loss:	24/12/2017	Nature of Claim:	OD	Claim No: C0464449

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD6088U	Engine No:	4A92CJ4253
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSRCY1AGU005586
Reg. Date:	24/06/2016 (Man. Year: 2016)	Odometer:	24640 km
Colour:	Silver		
Engine Capacity:	1590 cc		
Market Value/New Car Price:	S\$76,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,715.00	13,832.00	3,883.00	21.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,200.00	8,390.00	1,810.00	17.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,915.00	22,222.00	5,693.00	20.39
Approved Total (Overridden) (\$\$)		20,000.00		
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	27,515.00	19,600.00	7,915.00	28.77
+ GST 7.00/7.00% (\$\$)	1,926.05	1,372.00	554.05	28.77
Nett Amount (\$\$)	29,441.05	20,972.00	8,469.05	28.77

INSPECTION

Date of Assignment: 28/12/2017

Date Inspected: 28/12/2017 Inspected At:

Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)
209 PANDAN GARDENS
Singapore 609339

Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2018)
Parts:	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD6088U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE, FR BUMPER (CONSISTENT)	Deformed	1,030.00 FS	*1,030.00 FS
2	1		*COVER, FR BUMPER (CONSISTENT)	Missing	37.00 FS	*37.00 FS
3	1		*REINFORCEMENT, FR BUMPER (CONSISTENT)	Bent	87.00 FS	*87.00 FS
4	1		*BRACKET, FR BUMPER SIDE, RH (CONSISTENT)	Necessary	16.00 FS	*16.00 FS
5	1		*BRACKET, FR BUMPER SIDE, LH (CONSISTENT)	Necessary	16.00 FS	*16.00 FS
6	1		*SUPPORT, FR BUMPER, RH (CONSISTENT)	Necessary	12.00 FS	*12.00 FS
7	1		*SUPPORT, FR BUMPER, LH (CONSISTENT)	Necessary	12.00 FS	*12.00 FS
8	1		*COVER, HEADLAMP SUPT PANEL (CONSISTENT)	Deformed	66.00 FS	*66.00 FS
9	1		*GARNISH, FR BUMPER, LH (CONSISTENT)	Deformed	36.00 FS	*36.00 FS
10	1		*GARNISH, FR BUMPER, RH (CONSISTENT)	Deformed	36.00 FS	*36.00 FS
11	1		*GRILLE, FR BUMPER (CONSISTENT)	Cracked	77.00 FS	*77.00 FS
12	1		*GARNISH, FR BUMPER, CTR (CONSISTENT)	Cracked	231.00 FS	*231.00 FS
13	1		*COVER, FR BUMPER GRILLE (CONSISTENT)	Deformed	5.00 FS	*5.00 FS
14	1		*COVER, FR BUMPER GRILLE (CONSISTENT)	Deformed	5.00 FS	*5.00 FS
15	1		*COVER, FR FOG LAMP (CONSISTENT)	Deformed	19.00 FS	*19.00 FS
16	1		*GRILLE, RADIATOR (CONSISTENT)	Cracked	266.00 FS	*266.00 FS
17	1		*BRKT,F/BMPR AIR INLET GARN (CONSISTENT)	Not Necessary	2.00 FS	*- FS
18	1		*BRKT,F/BMPR AIR INLET GARN (CONSISTENT)	Not Necessary	2.00 FS	*- FS
19	1		*BRKT,F/BMPR AIR INLET GARN (CONSISTENT)	Not Necessary	2.00 FS	*- FS
20	1		*BRKT,F/BMPR AIR INLET GARN (CONSISTENT)	Not Necessary	2.00 FS	*- FS
21	1		*BRKT,F/BMPR AIR INLET GARN (CONSISTENT)	Not Necessary	2.00 FS	*- FS
22	1		*BRKT,F/BMPR AIR INLET GARN (CONSISTENT)	Not Necessary	2.00 FS	*- FS
23	1		*BRKT,F/BMPR AIR INLET GARN (CONSISTENT)	Not Necessary	2.00 FS	*- FS
24	1		*REINFORCEMENT, FR BUMPER (CONSISTENT)	Bent	408.00 FS	*408.00 FS
25	1		*COVER, ENG ROOM UNDER, FR (CONSISTENT)	Deformed	163.00 FS	*163.00 FS
26	1		*COVER, ENG ROOM SIDE, RH (CONSISTENT)	Deformed	83.00 FS	*83.00 FS
27	1		*COVER, ENG ROOM SIDE, LH (CONSISTENT)	Deformed	82.00 FS	*82.00 FS
28	1		*COVER, ENG ROOM UNDER, FR (CONSISTENT)	Deformed	324.00 FS	*324.00 FS
29	1		*HOOD (CONSISTENT)	Bent	845.00 FS	*845.00 FS
30	1		*HINGE, HOOD, LH (CONSISTENT)	Bent	60.00 FS	*60.00 FS
31	1		*HINGE, HOOD, RH (CONSISTENT)	Bent	60.00 FS	*60.00 FS
32	1		*INSULATOR, HOOD (CONSISTENT)	Deformed	89.00 FS	*89.00 FS
33	1		*WEATHERSTRIP, HOOD (CONSISTENT)	Cut	17.00 FS	*17.00 FS
34	1		*WEATHERSTRIP, HOOD, FR (CONSISTENT)	Deformed	29.00 FS	*29.00 FS
35	1		*LATCH, HOOD (CONSISTENT)	Bent	54.00 FS	*54.00 FS
36	2		*DAMPER, HOOD (CONSISTENT)	Not Necessary	14.00 FS	*- FS
37	1		*FENDER, FR RH (CONSISTENT)	Bent	614.00 FS	*614.00 FS
38	1		*FENDER, FR LH (CONSISTENT)	Bent	614.00 FS	*614.00 FS
39	1		*BRACKET, FR FENDER, LH (CONSISTENT)	Bent	15.00 FS	*15.00 FS
40	1		*BRACKET, FR FENDER, RH (CONSISTENT)	Bent	15.00 FS	*15.00 FS
41	1		*SHIELD, FR FENDER, FR RH (CONSISTENT)	Deformed	112.00 FS	*112.00 FS
42	1		*SHIELD, FR FENDER, FR LH (CONSISTENT)	Deformed	112.00 FS	*112.00 FS
43	1		*PROTECTOR, FR FENDER, RR RH (CONSISTENT)	Not Necessary	17.00 FS	*- FS
44	1		*PROTECTOR, FR FENDER, RR LH (CONSISTENT)	Not Necessary	15.00 FS	*- FS
45	1		*PANEL HEADLAMP SUPPORT, LWR (CONSISTENT)	Not Necessary	480.00 FS	*- FS
46	1		*EXTENSION, FR SIDEMEMBER, RH (CONSISTENT)	Not Necessary	39.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*EXTENSION, FR SIDEMEMBER, LH (CONSISTENT)	Not Necessary	39.00 FS	*- FS
48	1		*PNL, HEADLAMP SUPT, UPR LH (CONSISTENT)	Bent	81.00 FS	*81.00 FS
49	1		*PNL, HEADLAMP SUPT, UPR RH (CONSISTENT)	Bent	81.00 FS	*81.00 FS
50	1		*PANEL, HEADLAMP SUPPORT, UPR (CONSISTENT)	Bent	279.00 FS	*279.00 FS
51	1		*PLATE, FR SIDEMEMBER, LH (CONSISTENT)	Not Necessary	35.00 FS	*- FS
52	1		*PLATE, FR SIDEMEMBER, RH (CONSISTENT)	Not Necessary	35.00 FS	*- FS
53	1		*GARNISH, FR DECK (CONSISTENT)	Not Necessary	129.00 FS	*- FS
54	1		*HEADLAMP ASSY, LH (CONSISTENT)	Cracked	838.00 FS	*838.00 FS
55	1		*HEADLAMP ASSY, RH (CONSISTENT)	Cracked	838.00 FS	*838.00 FS
56	1		*LAMP ASSY, FOG, FR LH (CONSISTENT)	Cut	286.00 FS	*286.00 FS
57	1		*LAMP ASSY, FOG, FR RH (CONSISTENT)	Missing	286.00 FS	*286.00 FS
58	1		*LAMP ASSY, SIDE MARKER, LH (CONSISTENT)	Not Necessary	613.00 FS	*- FS
59	1		*LAMP ASSY, SIDE MARKER, RH (CONSISTENT)	Missing	613.00 FS	*613.00 FS
60	1		*TANK, WINDSHIELD WASHER (CONSISTENT)	Deformed	85.00 FS	*85.00 FS
61	1		*MOTOR, WINDSHIELD WASHER (CONSISTENT)	Not Necessary	146.00 FS	*- FS
62	1		*HORN (CONSISTENT)	Not Necessary	84.00 FS	*- FS
63	1		*BRACKET, BATTERY (CONSISTENT)	Not Necessary	60.00 FS	*- FS
64	1		*L-BOLT KIT, BATTERY (CONSISTENT)	Not Necessary	11.00 FS	*- FS
65	1		*CONDENSER ASSY, A/C REFRIGE (CONSISTENT)	Bent	1,070.00 FS	*1,070.00 FS
66	1		*HOSE, A/C COMPR DISCHARGE (CONSISTENT)	Bent	195.00 FS	*195.00 FS
67	1		*PIPE, A/C CONDENSER OUTLET (CONSISTENT)	Bent	114.00 FS	*114.00 FS
68	1		*HOSE, A/C COMPR SUCTION (CONSISTENT)	Bent	260.00 FS	*260.00 FS
69	1		*PIPE, RR A/C DISCHARGE (CONSISTENT)	Not Necessary	130.00 FS	*- FS
70	1		*MEMBER, FR SUSP, CTR (CONSISTENT)	Bent	248.00 FS	*248.00 FS
71	1		*CAP ASSY, RADIATOR (CONSISTENT)	Not Necessary	88.00 FS	*- FS
72	1		*TANK ASSY, RADIATOR COND (CONSISTENT)	Not Necessary	57.00 FS	*- FS
73	1		*BKRT, RADIATOR COND TANK (CONSISTENT)	Not Necessary	35.00 FS	*- FS
74	1		*HOSE, RADIATOR, LWR (CONSISTENT)	Not Necessary	73.00 FS	*- FS
75	1		*HOSE, RADIATOR, UPR LH (CONSISTENT)	Not Necessary	50.00 FS	*- FS
76	1		*RADIATOR ASSY (CONSISTENT)	Bent	1,113.00 FS	*1,113.00 FS
77	1		*INSULATOR, RDTR SUPPORT, UPR (CONSISTENT)	Not Necessary	9.00 FS	*- FS
78	1		*INSULATOR, RDTR SUPPORT, LWR (CONSISTENT)	Not Necessary	9.00 FS	*- FS
79	1		*SHROUD, COOLING FAN (CONSISTENT)	Distorted	254.00 FS	*254.00 FS
80	1		*FAN, COOLING (CONSISTENT)	Cut	71.00 FS	*71.00 FS
81	1		*MOTOR, COOLING FAN (CONSISTENT)	Distorted	441.00 FS	*441.00 FS
82	1		*DUCT, A/CLNR INTAKE (CONSISTENT)	Not Necessary	153.00 FS	*- FS
83	1		*BODY ASSY, AIR CLEANER (CONSISTENT)	Deformed	138.00 FS	*138.00 FS
84	1		*COVER, AIR CLEANER (CONSISTENT)	Not Necessary	148.00 FS	*- FS
85	1		*BRACKET, AIR CLEANER (CONSISTENT)	Not Necessary	64.00 FS	*- FS
86	1		*DUCT, AIR/CLNR TO THROT BODY (CONSISTENT)	Not Necessary	91.00 FS	*- FS
87	1		*BRACKET, ROLL STOPPER (CONSISTENT)	Deformed	114.00 FS	*114.00 FS
88	1		*BRACKET, ENG FR MOUNTING (CONSISTENT)	Not Necessary	192.00 FS	*- FS
89	1		*BRACKET, T/M MOUNTING (CONSISTENT)	Not Necessary	159.00 FS	*- FS
90	1		*COVER, ASSY, ENG, UPR (CONSISTENT)	Cut	129.00 FS	*129.00 FS
91	1		*MANIFOLD. INLET, UPR (CONSISTENT)	Not Necessary	762.00 FS	*- FS
92	1		*HOSE, T/M OIL COOLER LINE (CONSISTENT)	Deformed	47.00 FS	*47.00 FS
93	1		*TUBE, T/M OIL COOLER LINE (CONSISTENT)	Deformed	24.00 FS	*24.00 FS
94	1		*GARNISH, FR PILLAR, LH (CONSISTENT)	Not Necessary	27.00 FS	*- FS
95	1		*GARNISH, FR PILLAR, RH (CONSISTENT)	Not Necessary	24.00 FS	*- FS
96	1		*GARNISH, FR FENDER (CONSISTENT)	Not Necessary	61.00 FS	*- FS
97	1		*FRT NUMBER PLATE WITH FRAME (CONSISTENT)	Bent	50.00 FS	*50.00 FS
98	1		*SUNDRY (CONSISTENT)	Necessary	20.00 FS	*20.00 FS
99	1		*BATTERY (CONSISTENT)	Necessary	160.00 FS	*140.00 FS
100	1		*TUBE, A/T OIL COOLER FEED (CONSISTENT)	Deformed	87.00 FS	*87.00 FS
101	4		*GASKET, CYLINDER BLOCK (CONSISTENT)	Necessary	8.00 FS	*8.00 FS
102	2		*GROMMET, HEADLAMP (CONSISTENT)	Necessary	6.00 FS	*6.00 FS
103	1		*LLC 4L (CONSISTENT)	Necessary	26.00 FS	*26.00 FS
104	10		*CLIP (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
105	20		*CLIP (CONSISTENT)	Necessary	80.00 FS	*80.00 FS
106	1		*CAP, WASHER TANK FILTER (CONSISTENT)	Deformed	8.00 FS	*8.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
107	1		*HOSE, W/SHLD WSHR TANK FLR (CONSISTENT)	Deformed	9.00 FS	*9.00 FS
108	1		*HOSE, W/SHLD WSHR TANK FLR (CONSISTENT)	Deformed	23.00 FS	*23.00 FS
109	6		*AT FLUID 1L (CONSISTENT)	Necessary	93.00 FS	*93.00 FS
F=Franchise part. S=SpcNett.						
				Total Parts (\$\$)	17,715.00	13,832.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW FRT BUMPER, FRT SUPPORT PANEL, FRT FENDER RH & LH REPAIR BOTH FRT CHASSIS, FRT DOOR RH & LH.	New	3,850.00	3,300.00
2	TO REMOVE & INSTALL AIRCON CONDENSER & RADIATOR.	New	100.00	100.00
3	TO TOP UP AIRCON GAS.	New	80.00	80.00
4	TO STRAIGHTEN FRT BOTH CHASSIS.	New	500.00	500.00
5	TO APPLY SEALANT FOR ACCIDENT PORTION.	New	120.00	120.00
6	TO SPRAY PAINT FOR FRT BUMPER, BONNET, FRT SUPPORT PANEL FRT FENDER RH & LH, FRT DOOR RH & LH, FRT CHASSIS RH & LH.	New	4,200.00	2,940.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM.	New	20.00	20.00
8	TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM.	New	200.00	200.00
9	TO RENEW FRT CROSS MEMBER, REMOVE & INSTALL FRT UNDER CARRIAGE.	New	500.00	500.00
10	TOWING FEE.	New	130.00	130.00
11	REMOVE & INSTALL ENGINE TO FACILITATE REPAIR.	New	500.00	500.00
Gross Labour Cost (\$\$)			10,200.00	8,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >