



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Boo Chin Thye Blk 359 Yung An Road #10-81 Singapore 610359 Contact No Mobile: 92257930	Cust No/Name /Mr Boo Chin Thye Reg No/Reg Date SLD6088U / 24/06/201 Date In/Mileage / 0 Chassis No JMYSRCY1AGU005586 Engine No 4A92CJ4253 Make/Model MIT/16MY LANCER EX 1.6 4AT Colour/Trim A01 WARM SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	28/12/2017/ 11:16	BLC	442 / CocoLu	18948			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3300 3850.00
TO RENEW FRT BUMPER, FRT SUPPOR PANEL, BONNET, FRT FENDER RH&LH								
REPAIR BOTH FRT CHASSIS, FRT DOOR RH & LH,								✓ 100.00
E PNT88000								✓ 80.00
TO REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								bt 50.00
A 54900099								
TO TOP UP AIRCON GAS								
M SUNDRY								
TO SUPPLY FRT NUMBER PLATE WITH FRAME								photo ? 500.00
E PNT88000								✓ 120.00
TO STRAIGHTEN FRT BOTH CHASSIS								2940 4200.00
M SUNDRY								
TO APPLY SEALANT FOR ACCIDENT PORTION								
E PNT98000								
TO SPRAY PAINT FOR FRT BUMPER, BONNET, FRT SUPPORT PANEL								✓ 20.00
FRT FENDER RH & LH, FRT DOOR RH & LH, FRT CHASSIS RH & LH								✓ 200.00
A 54900099								✓ 20.00
TO CHECK WIRING & ELECTRICAL SYSTEM								
A 54900099								
TO CONDUCT DIAGNSOTIC CHECK FOR THE CAR SYSTEM								✓ 500.00
M SUNDRY								?
Sundry								?
A 54900099								
TO RENEW FRT CROSS MEMBER, REMOVE & INSTALL FRT UNDER CARRIAGE								?
M SUNDRY								
TO SUPPLY BATTERY					1.00	1030.00	00.00	de 1030.00
M FACE,FR BUMPER					1.00	37.00	00.00	mis 37.00
M COVER,FR BUMPER					1.00	87.00	00.00	bt 87.00
M REINFORCEMENT,FR BUMPER					1.00	16.00	00.00	na 16.00
M BRACKET,FR BUMPER SIDE,RH					1.00	16.00	00.00	na 16.00
M BRACKET,FR BUMPER SIDE,LH					1.00	12.00	00.00	na 12.00
M SUPPORT,FR BUMPER,RH					1.00	12.00	00.00	na 12.00
M SUPPORT,FR BUMPER,LH					1.00	12.00	00.00	na 12.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the windscreen or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
Mr Boo Chin Thye	Cust No/Name /Mr Boo Chin Thye
Blk 359 Yung An Road	Reg No/Reg Date SLD6088U / 24/06/201
#10-81	Date In/Mileage / 0
Singapore 610359	Chassis No JMYSRCY1AGU005586
Contact No Mobile: 92257930	Engine No 4A92CJ4253
	Make/Model MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim A01 WARM SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	28/12/2017/ 11:16	BLC	442 / CocoLu	18948
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M COVER, HEADLAMP SUPT PANEL		1.00	66.00	00.00	de 66.00
M GARNISH, FR BUMPER, LH		1.00	36.00	00.00	de 36.00
M GARNISH, FR BUMPER, RH		1.00	36.00	00.00	de 36.00
M GRILLE, FR BUMPER		1.00	77.00	00.00	de 77.00
M GARNISH, FR BUMPER, CTR		1.00	231.00	00.00	de 231.00
M COVER, FR BUMPER GRILLE		1.00	5.00	00.00	de 5.00
M COVER, FR BUMPER GRILLE		1.00	5.00	00.00	de 5.00
M COVER, FR FOG LAMP		1.00	19.00	00.00	de 19.00
M GRILLE, RADIATOR		1.00	266.00	00.00	de 266.00
M BRKT, F/BMPR AIR INLET GARN		1.00	2.00	00.00	de 2.00
M BRKT, F/BMPR AIR INLET GARN		1.00	2.00	00.00	de 2.00
M BRKT, F/BMPR AIR INLET GARN		1.00	2.00	00.00	de 2.00
M BRKT, F/BMPR AIR INLET GARN		1.00	2.00	00.00	de 2.00
M BRKT, F/BMPR AIR INLET GARN		1.00	2.00	00.00	de 2.00
M BRKT, F/BMPR AIR INLET GARN		1.00	2.00	00.00	de 2.00
M BRKT, F/BMPR AIR INLET GARN		1.00	2.00	00.00	de 2.00
M REINFORCEMENT, FR BUMPER		1.00	408.00	00.00	de 408.00
M COVER, ENG ROOM UNDER, FR		1.00	163.00	00.00	de 163.00
M COVER, ENG ROOM SIDE, RH		1.00	83.00	00.00	de 83.00
M COVER, ENG ROOM SIDE, LH		1.00	82.00	00.00	de 82.00
M COVER, ENG ROOM UNDER, FR		1.00	324.00	00.00	de 324.00
M HOOD		1.00	845.00	00.00	de 845.00
M HINGE, HOOD, LH		1.00	60.00	00.00	de 60.00
M HINGE, HOOD, RH		1.00	60.00	00.00	de 60.00
M INSULATOR, HOOD		1.00	89.00	00.00	de 89.00
M WEATHERSTRIP, HOOD		1.00	17.00	00.00	de 17.00
M WEATHERSTRIP, HOOD, FR		1.00	29.00	00.00	de 29.00
M LATCH, HOOD		1.00	54.00	00.00	de 54.00
M DAMPER, HOOD		2.00	7.00	00.00	de 14.00
M FENDER, FR RH		1.00	614.00	00.00	de 614.00
M FENDER, FR LH		1.00	614.00	00.00	de 614.00
M BRACKET, FR FENDER, LH		1.00	15.00	00.00	de 15.00
M BRACKET, FR FENDER, RH		1.00	15.00	00.00	de 15.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
Mr Boo Chin Thye	Cust No/Name /Mr Boo Chin Thye
Blk 359 Yung An Road	Reg No/Reg Date SLD6088U / 24/06/201
#10-81	Date In/Mileage / 0
Singapore 610359	Chassis No JMYSRCY1AGU005586
Contact No Mobile: 92257930	Engine No 4A92CJ4253
	Make/Model MIT/16MY LANCER EX 1.6 4AT
	Colour/Trim A01 WARM SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	28/12/2017/ 11:16	BLC	442 / CocoLu	18948			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	SHIELD,FR FENDER,FR RH				1.00	112.00	00.00	112.00
M	SHIELD,FR FENDER,FR LH				1.00	112.00	00.00	112.00
M	PROTECTOR,FR FENDER,RR RH				1.00	17.00	00.00	17.00
M	PROTECTOR,FR FENDER,RR LH				1.00	15.00	00.00	15.00
M	PANEL,HEADLAMP SUPPORT,LWR				1.00	480.00	00.00	480.00
M	EXTENSION,FR SIDEMEMBER,RH				1.00	39.00	00.00	39.00
M	EXTENSION,FR SIDEMEMBER,LH				1.00	39.00	00.00	39.00
M	PNL,HEADLAMP SUPT,UPR LH				1.00	81.00	00.00	81.00
M	PNL,HEADLAMP SUPT,UPR RH				1.00	81.00	00.00	81.00
M	PANEL,HEADLAMP SUPPORT,UPR				1.00	279.00	00.00	279.00
M	PLATE,FR SIDEMEMBER,LH				1.00	35.00	00.00	35.00
M	PLATE,FR SIDEMEMBER,RH				1.00	35.00	00.00	35.00
M	GARNISH,FR DECK				1.00	129.00	00.00	129.00
M	HEADLAMP ASSY,LH				1.00	838.00	00.00	838.00
M	HEADLAMP ASSY,RH				1.00	838.00	00.00	838.00
M	LAMP ASSY,FOG,FR LH				1.00	286.00	00.00	286.00
M	LAMP ASSY,FOG,FR RH				1.00	286.00	00.00	286.00
M	LAMP ASSY,SIDE MARKER,LH				1.00	613.00	00.00	613.00
M	LAMP ASSY,SIDE MARKER,RH				1.00	613.00	00.00	613.00
M	TANK,WINDSHIELD WASHER				1.00	85.00	00.00	85.00
M	MOTOR,WINDSHIELD WASHER(*)				1.00	146.00	00.00	146.00
M	HORN				1.00	84.00	00.00	84.00
M	BRACKET,BATTERY				1.00	60.00	00.00	60.00
M	L-BOLT KIT,BATTERY				1.00	11.00	00.00	11.00
M	CONDENSER ASSY,A/C REFRIGE				1.00	1070.00	00.00	1070.00
M	HOSE,A/C COMPR DISCHARGE				1.00	195.00	00.00	195.00
M	PIPE,A/C CONDENSER OUTLET				1.00	114.00	00.00	114.00
M	HOSE,A/C COMPR SUCTION				1.00	260.00	00.00	260.00
M	PIPE,RR A/C DISCHARGE				1.00	130.00	00.00	130.00
M	MEMBER,FR SUSP,CTR				1.00	248.00	00.00	248.00
M	CAP ASSY,RADIATOR				1.00	88.00	00.00	88.00
M	TANK ASSY,RADIATOR COND				1.00	57.00	00.00	57.00
M	BRKT,RADIATOR COND TANK				1.00	35.00	00.00	35.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Boo Chin Thye Blk 359 Yung An Road #10-81 Singapore 610359 Contact No Mobile: 92257930	Cust No/Name /Mr Boo Chin Thye Reg No/Reg Date SLD6088U / 24/06/201 Date In/Mileage / 0 Chassis No JMYSRCY1AGU005586 Engine No 4A92CJ4253 Make/Model MIT/16MY LANCER EX 1.6 4AT Colour/Trim A01 WARM SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	28/12/2017/ 11:16	BLC	442 / CocoLu	18948
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M HOSE,RADIATOR,LWR		1.00	73.00	00.00	73.00
M HOSE,RADIATOR,UPR LH		1.00	50.00	00.00	50.00
M RADIATOR ASSY		1.00	1113.00	00.00	1113.00
M INSULATOR,RDTR SUPPORT,UPR		1.00	9.00	00.00	9.00
M INSULATOR,RDTR SUPPORT,LWR		1.00	9.00	00.00	9.00
M SHROUD,COOLING FAN		1.00	254.00	00.00	254.00
M FAN,COOLING		1.00	71.00	00.00	71.00
M MOTOR,COOLING FAN(*)		1.00	441.00	00.00	441.00
M DUCT,A/CLNR INTAKE		1.00	153.00	00.00	153.00
M BODY ASSY,AIR CLEANER		1.00	138.00	00.00	138.00
M COVER,AIR CLEANER		1.00	148.00	00.00	148.00
M BRACKET,AIR CLEANER		1.00	64.00	00.00	64.00
M DUCT,A/CLNR TO THROT BODY		1.00	91.00	00.00	91.00
M BRACKET,ROLL STOPPER		1.00	114.00	00.00	114.00
M BRACKET,ENG FR MOUNTING		1.00	192.00	00.00	192.00
M BRACKET,T/M MOUNTING		1.00	159.00	00.00	159.00
M COVER ASSY,ENG,UPR		1.00	129.00	00.00	129.00
M MANIFOLD,INLET,UPR		1.00	762.00	00.00	762.00
M HOSE,T/M OIL COOLER LINE		1.00	47.00	00.00	47.00
M TUBE,T/M OIL COOLER LINE		1.00	24.00	00.00	24.00
M GARNISH,FR PILLAR,LH		1.00	27.00	00.00	27.00
M GARNISH,FR PILLAR,RH		1.00	24.00	00.00	24.00
M GARNISH,FR FENDER		1.00	61.00	00.00	61.00

Estimate

SURVEYOR NAME: Tan Jiah 97495749SURVEYOR SIGNATURE: Tan JiahDATE: 28/12/17 @ 4:30 pmREMARKS: Ex \$400 To check repair limit.Authorized Repairer *Repair limit \$20K

Confirms Auto-Consentments hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

Rep 11-12 days. Repairs agreed repair limit \$20K.Resurvey before paint

Nett	26,915.00
7% GST on	1884.05
Total Payable	28,799.05

Validity of this estimate is from the date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional work which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.