

ASS. REC. BY:

REF:

AIG/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 5660B

Yr Regn:

12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Peravit

c.c

1995

Colour

n. white IR

A/C:

Insured / Std / NI / NA

Sp. Reading

359677

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABL 15AUC 281153

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NIT / S/Rim / STD A/Rim or

Tyre Size:

F: Giti

215/60R16

R: Palkon

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

J

mm

Rear

R/Bal.

6

mm

L/Bal.

J

mm

L/Bal.

6

mm

D.O.A.

24/12/17

D.O.I.

27/12/17

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Acc body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/12

File pass to Coroner
8/12/18 3:00

R (\$33,581.66/92%)

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/LCR17024582/Kjs3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 28-12-2017	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLK 9345X	Veh. Inspected	SHC 5660B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	24/12/2017	Inspection Date	27/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5660B
Vehicle to be Exported:	Yes
Intended De-registration Date:	27 Dec 2017
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002402
Chassis No.:	VF1ABL15AUC281153
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	24 Dec 2014
First Registration Date:	24 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Dec 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	23 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$32,207.00
Total Rebate Amount:	\$41,580.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Dec 2017

OK

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5660B - AIG**AAD1712-251***Not Authored
11 Sep 8 3100*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5660B - JHOW

VF1ABL15AUC281153

RENAULT

LATITUDE

24.12.2017

AIG**PART****LIST**

1	1	BUMPER COVER REAR	\$	R	1,108.46	}	X
2	1	BUMPER LOWER REAR	\$	S _{in}	768.84		
3	1	BUMPER BRACKET CTR REAR	\$	S _{in}	113.47		
4	1	BUMEPR BRACKET SIDE RH REAR	\$	S _{in}	135.97		
5	1	BUMEPR RETAINER RH REAR	\$	S _{in}	44.99		
6	1	BUMPER REFLECTOR RH	\$	S _{in}	43.61		
7	1	BUMEPR BRACKET SIDE LH REAR	\$	S _{in}	135.97		
8	1	BUMEPR RETAINER LH REAR	\$	S _{in}	44.99		
9	1	ROCKER PANEL OUTER RH	\$	R	987.49	}	X
10	1	FENDER PANEL REAR RH	\$	R	3,299.13		
11	1	WHEELARCH REAR RH	\$	S _{in}	543.47		
12	1	TAILLAMP RH	\$	S _{in}	552.55		
13	1	TAILLAMP PANEL RH	\$	R	986.70		
14	1	EXHAUST REAR	\$	R	7,489.05		
15	1	EXHAUST CAP REAR	\$	R	230.49		
16	1	DOOR PANEL REAR RH	\$	Not used	2,844.66	}	X
17	1	DOOR GUIDE REAR RH	\$	S _{in}	176.82		
18	1	DOOR HINGE UPPER RH	\$	R	274.50		
19	1	DOOR HINGE LOWER RH	\$	R	300.55		
20	1	DOOR CHECK REAR RH	\$	S _{in}	203.06		
21	1	DOOR LOCK REAR RH	\$	R	908.75		
22	1	DOOR GRAB HANDLE REAR RH	\$	S _{in}	210.96		
23	1	DOOR HANDLE OUTER REAR RH	\$	S _{in}	126.49		
24	1	DOOR HANDLE CAP REAR RH	\$	S _{in}	35.52		
25	1	DOOR HANDLE SEAL REAR RH	\$	S _{in}	7.89		
26	1	DOOR HANDLE COVER REAR RH	\$	S _{in}	13.22		
27	1	DOOR HANDLE MODULE REAR RH	\$	S _{in}	133.60		
28	1	DOOR FINISHER REAR RH	\$	S _{in}	423.10		
29	1	DOOR WHEATHESTRIIP REAR RH	\$	S _{in}	410.66		
30	1	DOOR SEAL REAR RH	\$	S _{in}	162.02		
31	1	DOOR WAIST SEAL OUTER REAR RH	\$	S _{in}	334.69		
32	1	DOOR MOULDING REAR RH	\$	S _{in}	176.82		
33	1	DOOR PANEL FRT RH	\$	R	2,844.66		

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-251**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5660B - AIG

TOTAL	\$	26,073.16
10%	\$	2,607.32
	\$	23,465.84

Specical Nett

1	1SET	PARKING AID	\$	Sn	700.00	} X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	nn	10.00	
5	1SET	BUMEP R RETAINER RH CLIP RR	\$	nn	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	
8	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	
9	1	TAILLAMP CLIP RH	\$	nn	5.00	
10	1SET	WHEELARCH CLIP RR RH	\$	nn	66.00	
11	2	REAR WINDSCREEN SELANT	\$	nn	80.00	
12	1	WINDSCREEN MOULDING	\$	nn	100.00	
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
14	1	CAP HUB RH RR	\$	Sn	35.00	
15	1	RIM RH RR	\$	Sn	385.00	
16	1	TYRE RH RR	\$	Sn	330.00	
17	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	
18	1	DOOR STICKER "Classic"	\$	nn	30.00	
19	1	DOOR STICKER "6555-3333"	\$	nn	80.00	

TOTAL	\$	2,225.82
TOTAL PARTS	\$	25,691.66

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	6601
To reinstall rear bumper parking sensor.	\$	nn	170.00 X
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	5001
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-251**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5660B - AIG

To repair and realign rear exhaust pipe.	\$	~ 170.00 X
Towing Fees	\$	~ 120.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	~ 170.00 601
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	~ 380.00 X

TOTAL	\$	10,990.00
Over All Total	\$	36,681.66

(PARTS BY PARTS)**Repair Days****15 Days****3 days**

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To detail damage report after resurvey
- Parts price will be based on quotation
- This process will be on "Without Prejudice" basis
- No assumption will be made
- Sup: will be surveyed and insured by the Insurance Company

Action: _____

Sign: _____

Date: _____

Joy Irene (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Friday, 5 January 2018 11:32 AM
To: Joy Irene (LKKAUTO)
Cc: Admin A
Subject: RE: TRANSCAB SHC 5660B AND SLK 9345X ON 24.12.2017; TCS REF: AAD1712-251
Attachments: image004.emz

WITHOUT PREJUDICE

Dear Joy

Our driver's didn't submit any evidence/ witness statement to us.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]
Sent: Friday, January 05, 2018 10:15 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: TRANSCAB SHC 5660B AND SLK 9345X ON 24.12.2017

WITHOUT PREJUDICE

Dear Wai Yin,

We refer to the above subject.

Is there any available substantial evidence available from your side? Such as CCTV, scene photos or independent witness statement?

If yes, please send us a copy for our review and for our principal's consideration.

Thank you.

Best Regards,
Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6749-5792 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1712-251

Your Ref : SLK9345X

Date : 12.May 2018

AIG ASIA PACIFIC INSURANCE

Dear Sir/Madam,

ACCIDENT INVOLVING SHC5660B AND SLK9345X ON 24/12/17 08:45 AM ALONG GEYLANG RD TOWARDS GEYLANG LORONG 33

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	3,317.00
2.	Loss of Rental for ____ days @ \$_____ per day	\$	202.92
3.	Loss of Income for ____ days @ \$_____ per day	\$	100.00
4.	LTA Search Fee	\$	5.35
5.	Survey Fee	\$	0.00
	Total	\$	3,625.27

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act


Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666

Fax: 6287 7764

Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO: AIG ASIA PACIFIC INSURANCE PTE LTD 78 Shenton Way #07-16 CHARTIS Building 079120 Singapore ATTENTION:	INVOICE NO. : INV1801-131 DATE : 30. January 2018 REFERENCE NO : AAD1712-251 TERMS : Net 30 Days DUE DATE : 1. March 2018 PAGE : 1
--	---

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHC5660B;DOA 24.12.17(LUMP SUM-18)	1	3,317.00	3,317.00

Total SGD Excl. GST : 3,100.00**7% GST : 217.00****Total SGD Incl. GST : 3,317.00******** THREE THOUSAND THREE HUNDRED SEVENTEEN SGD ONLY ******

- 1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.**THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE**

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

05 April, 2018

To Whom It May Concern

Dear Sir / Madam,

Accident on 24/12/17 08:45 AM at GEYLANG RD TOWARDS GEYLANG LORONG 33

1. We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the registered owner of the taxi bearing vehicle registration no. SHC5660B. The taxi was hired to TOH BENG HUAT a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$101.46 per day (inclusive of GST).
2. Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
3. Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan

General Manager

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

24-12-2017

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.
Accident No.	AAD1712-251	Accident Date 24-12-2017
27/12/2017 10:00	28/12/2017 14:20	SHC5660B

Yours Faithfully,

Trans-Cab Services Pte Ltd**Jasmine Tan****General Manager**

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Authorization To Act

We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHC5660B and SLK9345X along GEYLANG RD TOWARDS GEYLANG LORONG 33 on 24/12/17 08:45 AM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 5 (day) of April 2018

Yours Faithfully

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SLK4609T	23 Dec 2017 / 11:35:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.
FBK7466L	25 Dec 2017 / 03:45:00	NTUC INCOME INS CO-OP LTD
SFP3088Y	23 Dec 2017 / 14:10:00	TOKIO MARINE INSURANCE SINGAPORE LTD
SLK9345X	24 Dec 2017 / 08:45:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Print](#)[OK](#)[Save as PDF](#)

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 19 June 2018 11:47 AM
To: 'Ng Wai Yin'
Cc: Admin A
Subject: TRANSCAB SHC 5660B AND SLK 9345X ON 24.12.2017; TCS REF: AAD1712-251
Attachments: SLK 9345X.pdf

WITHOUT PREJUDICE

Dear Wai Yin,

We refer to the subject.

Our insured driver reiterated that the incident was due to the entire negligence of your driver by making a turn, hitting his parked vehicle.

We have reviewed the matter and our opinion is that damage profile (brush in nature) supports the scenario of our insured, parked and brushed by your turning taxi.

In view of the above, we regret to inform you that we are unable to look into your claim.

Should you have further evidence to provide, please send us a copy for our review.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Ng Wai Yin [<mailto:waivin.ng@transcab.com.sg>]
Sent: Friday, 5 January 2018 11:32 AM
To: Joy Irene (LKKAuto) <joyirene@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: TRANSCAB SHC 5660B AND SLK 9345X ON 24.12.2017; TCS REF: AAD1712-251

WITHOUT PREJUDICE

Dear Joy

Our driver's didn't submit any evidence/ witness statement to us.

Thank You
Best Regards,

Joy Irene (LKKAUTO)

From: Mavis, Chew <Chew.Mavis@aig.com>
Sent: Monday, 4 June 2018 2:24 PM
To: Joy Irene (LKKAUTO)
Cc: Admin A; Vivian Lau (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: AIG ref: #5784310115SG003#023# / LCR SLK 9345X ON 24.12.2017 / SHC 5660B

Dear Joy

We refer to your email dated 28.05.18.

Please note that we did not receive any PIR and it is likely that there will not be any involvement from Traffic Police as there is no injury reported.

We share the same view that OI's version of the accident is more consistent based on the damages sustained to both vehicles. Kindly request for AVF or more evidence from Trans-cab otherwise you may proceed to reject based on the damage pattern which you have highlighted in your earlier email.

Do keep us posted if there is new development, thank you.

Best Regards,
Ms. Mavis Chew
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120
Tel +(65) 6419 1970 | Fax +(65) 6835 7416
chew.mavis@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Joy Irene (LKKAUTO) [mailto:JoyIrene@lkkauto.com]
Sent: Monday, 28 May, 2018 11:28 AM
To: Mavis, Chew
Cc: Admin A; Vivian Lau (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: 5784310115SG / LCR SLK 9345X ON 24.12.2017 / SHC 5660B

Dear Mavis,

LCR driver reported that his vehicle was parked when TPV collided with it.

TP reported that OIV moved out.

TP had no evidence available.

We have reviewed the matter and our opinion is that TPV did not sustain dent on its body but brush damage. We believe OI's version is more credible that taxi brushed against parked OIV.

We would like to check if LCR has provided PIR result on this case. We also would like to ask for your opinion/view and instruction.

Kindly advise.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Dec 2017 Edit Reg		27 Dec 2017 00:00 Edit Adj Rpt	S\$3,100.00 Edit Estimates	S\$3,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303678K								
Vehicle Reg. No.:	SHC5660B	Date of Loss:	24/12/2017 08:00 - :59 [36 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5784310115SG	Policy/Cover Note No.:	0999995166						
Vehicle Reg. No. (Insured):	SLK9345X	Policy No. (Claimant):	VPX/P1680520						
		Excess:							
Reparer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 09/01/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC5660B (5784310115SG)**
[SLK9345X]
TP
TRANS-CAB SERVICES PTE LTD
Dec 24 2017 8:00AM
[LCRF PTE LTD]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	02/01/18 10:58	Accident Statement <small>From: SC - Reg. No: SLK9345X, Claimant: LCRF PTE LTD</small>	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
2	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
3	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
11	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
12	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/05/18 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/17 14:24	TP GIA REPORT	Load PDF	<input type="checkbox"/>
2	28/12/17 14:24	TP ESTIMATE- MARKED	Load PDF	<input type="checkbox"/>
3	19/06/18 11:49	APPROVAL TO REJECT	Load PDF	<input type="checkbox"/>
4	19/06/18 11:49	REJECTION EMAIL TO TP	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR17024582/KJB3Q2

Date: 25/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995166
Claimant Vehicle No : SHC5660B **Insured Vehicle No :** SLK9345X
 Date of Loss: 24/12/2017 Nature of Claim: TP Claim No: 5784310115SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5660B**
 Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Engine No: M9R8839C002402
 Reg. Date: 24/12/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC281153
 Colour: Metallic White/Red Odometer: 359677 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Giti 8 mm Rear Left Side: Falken 6 mm
 Front Right Side: Giti 8 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,691.65	2,620.19	23,071.46	89.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,990.00	1,250.00	9,740.00	88.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,681.65	3,870.19	32,811.46	89.45
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	36,681.65	3,100.00	33,581.65	91.55
+ GST 7.00/7.00% (S\$)	2,567.72	217.00	2,350.72	91.55
Nett Amount (S\$)	39,249.37	3,317.00	35,932.37	91.55
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 27/12/2017
 Date Inspected: 27/12/2017 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
 2, Ang Mo Kio Street 63
 Singapore 569111
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Repair	1,108.46 FL	*- FL
2	1		*BUMPER LOWER REAR	Serviceable	768.84 FL	*- FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*ROCKER PANEL OUTER RH	Repair	987.49 FL	*- FL
10	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
11	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
12	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
13	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
14	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
15	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
16	1		*DOOR PANEL REAR RH	Dented / Warped	2,844.66 FL	*2,844.66 FL
17	1		*DOOR GUIDE REAR RH	Serviceable	176.82 FL	*- FL
18	1		*DOOR HINGE UPPER RH	Repair	274.50 FL	*- FL
19	1		*DOOR HINGE LOWER RH	Repair	300.55 FL	*- FL
20	1		*DOOR CHECK REAR RH	Serviceable	203.06 FL	*- FL
21	1		*DOOR LOCK REAR RH	Repair	908.75 FL	*- FL
22	1		*DOOR GRAB HANDLE REAR RH	Serviceable	210.96 FL	*- FL
23	1		*DOOR HANDLE OUTER REAR RH	Serviceable	126.49 FL	*- FL
24	1		*DOOR HANDLE CAP REAR RH	Serviceable	35.52 FL	*- FL
25	1		*DOOR HANDLE SEAL REAR RH	Serviceable	7.89 FL	*- FL
26	1		*DOOR HANDLE COVER REAR RH	Serviceable	13.22 FL	*- FL
27	1		*DOOR HANDLE MODULE REAR RH	Serviceable	133.60 FL	*- FL
28	1		*DOOR FINISHER REAR RH	Serviceable	423.10 FL	*- FL
29	1		*DOOR WEATHERSTRIP REAR RH	Serviceable	410.66 FL	*- FL
30	1		*DOOR SEAL REAR RH	Serviceable	162.02 FL	*- FL
31	1		*DOOR WAIST SEAL UTER REAR RH	Serviceable	334.69 FL	*- FL
32	1		*DOOR MOULDING REAR RH	Serviceable	176.82 FL	*- FL
33	1		*DOOR PANEL FRT RH	Repair	2,844.66 FL	*- FL
34	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
35	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
36	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
37	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
38	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
39	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
40	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
41	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
42	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
43	1		*SET WHEELARCH CLIP RR RH	Not Necessary	66.00 FS	*- FS
44	2		*REAR WINDSCREEN SELANT	Not Necessary	80.00 FS	*- FS
45	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
46	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
47	1		*CAP HUB RH RR	Serviceable	35.00 FS	*- FS
48	1		*RIM RH RR	Serviceable	385.00 FS	*- FS
49	1		*TYRE RH RR	Serviceable	330.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*. FS
51	1		*DOOR STICKER CLASSIC	Not Necessary	30.00 FS	*. FS
52	1		*DOOR STICKER 6555-3333	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,298.97	2,904.66
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,607.32	284.47
Total Parts (\$\$)	25,691.65	2,620.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	660.00
2	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	4,200.00	500.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO REPAIR REAR REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TOWING FEES	New	120.00	0.00
8	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
12	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
13	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
Gross Labour Cost (\$\$)			10,990.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >