

Surveyor

ASSIGNMENT (Office)

CWS

From (Person): Joanne Yong

of

FCI

Date/Time: 12:14pm @ 28/12/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 8554 Y

Insured:

SH 6097P

at Workshop n/s

K. Kim Hin Auto

Tel:

64527018

of

160 Sing Ming Drive #02-20

Policy No:

Claim No:

DI7611815 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

'up'

D.O.A. 22/12/17
02/01/2017 @ 6 am owner waiting

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:55pm @ 28/12/17

Person Contacted:

Shuman

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLE 8554 Y - NS/INC17024566/K1+b	D.O.A: 22/12/17
	SH 6097P - NS/INC17024566/K1+b	D.O.A: 22/12/17
2/12	To sum 1.B.1 8/1359.50 (Owner revert to OD claim)	
	(Red 973.75, 41%)	

ASSIGNMENT

From: _____ Date: 02/01/2017

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To inspect Vehicle No: SLE 8554Y

at Workshop/mis K. Kim Hin Auto

of 160 Sin Ming Drive # 02-20

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

10 am @ owner waiting

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NIS	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

3/1 File pass to Corrine

RECEIVED 21 DEC 2018

Veh No: SLE 8554Y Yr Regn: 10 09

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Tug

A/T/S

C.C.

1588

Colour: M. Green

A/C

Insured / Std / NI / NA

Sp. Reading: 133579

T. Radio

Insured / Std / NI / NA

Eng/No: _____

C/No: MR0538EE106158079

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F: 195/65R15

R: _____

BS ☒ SUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

22/1 2/17

D.O.I.

2/1/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 15m

The U/C / Chassis frame / Body Structure affected due to collision:

Date/Time File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee

Transportation

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Photos

Diagrams

Report Format: TP

Lump Sum / I.E: \$ 1359.50

110
50
50
13
223



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17024588/Krd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6097P	Veh. Inspected	SLE 8554Y
Policy No.		Coverage (\$)	0.00
Claim No.	D17011815MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	28/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/12/2017	Inspection Date
Survey held at	160 SIN MING DRIVE # 02-20,575722	
Repairer	K KIM HIN AUTOMOTIVE PTE LTD	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	26-12-2017	Our Ref No. D17011815MFSH
Accident Date	22-12-2017	Claim Type. Third Party
Insured Vehicle	SH6097P	Third Party Vehicle. SLE8554Y
Survey Location	160 Sin Ming Drive #02-20SIN MING AUTOCITY	
Contact Person.	SHUMAN	
Contact No.	64527018/ 0	Fax No. 64583895
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	K. KIM HIN AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232321)



PRI Documents



Close X

PRI Header Details

Claim No	D17011815MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & K. KIM HI
Workshop Name	K. KIM HIN AUTO PTE LTD (Contact Person : SHUMAN)	Survey Location & Contact Details	160 Sin Ming Drive #02-20SIN MING AUTOCITY Mobile: 0 , Phone: 64527018 , Fax: 64583895 EmailId: ADMIN1@KKIMHIN.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH6097P	TP Vehicle No	SLE8554Y
PRI Recieved Date	27-12-2017 04:57:17 PM	Surveyor Appointed Date	28-12-2017 12:13:27 PM	Surveyor Accept Date	28-12-2017 0.

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-12-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 7834Z

Vehicle Details

Vehicle No.: SLE8554Y

Vehicle to be Exported: No

Intended
Deregistration Date: 05 Nov 2018

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6
AUTO

Primary Colour: Silver

Manufacturing Year: 2009

Engine No.: 3ZZ4940036

Chassis No.: MR053ZEE106158079

Maximum Power
Output: 80.0 kW (107 bhp)

Open Market Value: \$17,853.00

Original Registration
Date: 23 Oct 2009

First Registration Date: 23 Oct 2009

Transfer Count: 1

Actual ARF Paid: \$17,853.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 22 Oct 2019

PARF Rebate Amount: \$8,926.00

Intended COE Rebate Details

COE Expiry Date: 22 Oct 2019

COE Category: A - Car (1600cc &
below)

COE Period(Years): 10

QP Paid: \$16,201.00

COE Rebate Amount: \$1,559.00

Total Rebate Amount: \$10,485.00

The information contained herein is correct as at 05 Nov 2018

OK

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 29396

Vehicle Insured : SH 6097 P
Accident Date : 22-Dec-2017

Date : 27-Dec-2017

Our Ref : 170923 (NTUC) / SHUMAN

PAGE : 1

TANG GEK LENG (MS)
Singapore

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6 A (2009) SLE8554Y
=====

- 1 pc front bumper
2 pcs front bumper side retainer (LH/RH)
10 pcs front bumper clips
1 pc o/s headlamp assy
1 pc o/s front fender "VVT-i" emblem

Br 569.00 —
@ S\$ 45.00 410/1 90.00 —
@ S\$ 5.00 m 50.00 —
m 535.00 —
m 27.00 —
1,271.00
Less 25% : -317.75

953.25

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

600.00 200

To focus headlamps. To check front
wiring and lighting operation.

30.00 20

To putty and respray on affected
portions.

750.00 220

Total : S\$ 2,333.25
=====

Singapore Dollars Two Thousand Three Hundred
and Thirty Three and Cents Twenty Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification is allowed
• Supplementary items must be resurveyed and
is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17024588/Kcd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6097P	Veh. Inspected	SLE 8554Y	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011815MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	28/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053ZEE106158079	Colour	METALLIC GREEN	
Odometer	133574	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DUNLOP	9 mm	
L/H Front Tyre	195/65 R15	DUNLOP	9 mm	
R/H Rear Tyre	195/65 R15	DUNLOP	9 mm	
L/H Rear Tyre	195/65 R15	DUNLOP	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/12/2017	Inspection Date	02/01/2018	
Survey held at	160 SIN MING DRIVE # 02-20,575722			
Repairer	K KIM HIN AUTOMOTIVE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 8554Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	569.00	569.00
2	FRONT BUMPER SIDE RETAINER (LH/RH) @\$45.00	O/S DISTORTED	90.00	45.00
10	FRONT BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	O/S HEADLAMP ASSY	CUT	535.00	535.00
1	O/S FRONT FENDER "VVT-I" EMBLEM	NECESSARY	27.00	27.00
	LESS 25% DISCOUNT		-317.75	-306.50
			953.25	919.50
	<u>LABOUR</u>			
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.		600.00	200.00
	TO FOCUS HEADLAMPS.TO CHECK FRONT WIRING AND LIGHTING OPERATION.		30.00	20.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		750.00	220.00
			1,380.00	440.00
	GRAND TOTAL		2,333.25	1,359.50
	RECOMMENDED COST OF REPAIRS			1,359.50

Report Ref No. CS/FCI17024588/Kcd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.