22/03/2002 ASS. PEC. BY:	REF. CS/MS1617024590/G1	
Menmen -	GU ASSIGNMENT (Office)	
From (Person):	Monica chung of MSIG	Detertine
Estimated Cost:	Bill to:	
	/ IP RES / OD RES / EVA / INV / MV / CS	-
To Inspect Vehi		Insured: FBH 9338B
at Workshop m/		Tel: 68443360
of 1/0. 18	Defy Ave 2,539522	
Policy No. M	18D VMT 17-986907-WTT Claim No:	MSC/V/17-001957
Sum Insured:	Excess:	
Make of Veh:(Client's Record)		D.O.A. 18/12/17
•	REP. / REV 24 HRS Wp) 03.01.2017 @	llam
	ACET. / REV 24 HRS	H.O.D. Endorsement
Deterance.	2.20pm@ 22 2 3 Person Contacted: Karen	Vehicle NOUT
Date/Time	Action/Instruction () Estimate	
	1266246-x	
	FBH43388-X	
	Confirm \$676.13, 2 days	
,	Rd: \$ 1112.62, 62%.	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internation	onale Des Experts En Auton	nobile Comments
	SINGAPORE) PTE LTD	Ref : CS/MSG17024	
16 RAFFLES QUAY #24-01 HONG LEON	G BLDG SINGAPORE 048581	Date : 28-12-2017 Code : MSG	
1.	Policy Particulars	:- THIRD PARTY CLA	M
Insured Veh.	FBH 9338B	Veh. Inspected	PC 6624E
Policy No.	MSD/VMT/17-986907-WTT	Coverage (\$)	0.00
Claim No.	MSC/V/17-001957	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	28/12/2017
2.	Vehicle Parti	culars & Condition	
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3.	Conditi	ons of Tyres	
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4:4:	venDescripti	on of Damages	
5. Emple No.	Genera Genera	Information	
Accident Date	18/12/2017	Inspection Date	Constitution of State Conference (State Conference on State Confer
Survey held at	THINK ONE AUTOCARE PTE L	ŤD	
	NO.18 DEFU AVENUE 2 SINGAPORE 539522		
5a. 12	R	emarks	
A)THE INSPECTI	ON WAS CONDUCTED ON A"WIT	HOUT PREJUDICE" BAS	SIS.
DJIN ACCORDAN	ICE TO YOUR INSTRUCTIONS, W	E MAVE NOT AUTHORIS	DEU KEPAIKS.

...CLAIM SUBFOLDER...(New Assignment)

CLATM SUR	FOLDER TRACE	(ING					
Case	.,	Est Submitted	Adj Assigneo	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Dec 2017		22 Dec 2017 11:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETA	(LS		[Created by ir	surer]
Insured:	PEK KIAP HOW, ID: S8817	'656A		
Main Claimant:	THINK ONE LEASING PTE L	TD, Co. Reg. No.: 20111560)9M	
Vehicle Reg. No.:	PC6624E	Date of Loss:	18/12/2017 18:	
Claim Type:	TP / MSC/V/17-001957	Policy/Cover Note No	Party Only)	36907-WTT (Third 1/2017 - 17/11/2018
Vehicle Reg. No. (Insured):	FBH9338B	Policy No. (Claimant):	//////////////////////////////////////
Venicle Reg. Ho. (1.156, 55)		Excess:		
Repairer:	Think One Autocare Pte Lt	d (HQ) No. 18 Defu Avenue 2,	539522 Ubi - Tel: 6844330	0
Handling Insurer:	MSIG Insurance (Singapor	e) Pte. Ltd. (HQ) - Tel: +65	6827 7888 [Handled by I	nonica Chung Pei
Adiuster:	LKK Auto Consultants Pte	Ltd (HQ) - Tel: 6256-3561	[Imm.Advice due 23/	12/201/5
Driver/Custodian (Insured):		8624993F, Tel: +65810056	54	
Adj Asg. Remarks:	Pls assign Marcus. No. 18 Del	fu Avenue 2, 539522		
ASSOCIATED MAIL RECE	IVED	4777	View All	Compose Case Mail
There are no mail for this cas				- Adams - Adam
ALL ASSOCIATED TASKS		View A	Search Tasks Create	New Task Complete
	ype fask Group Subject	Handler Assigned By	Completed On C	reated On Done

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Monica Chung Pei Zhen Date: 15 Mar 2018

Preliminary Advice

Insured Vehicle No: FBH9338B

TP Vehicle No : PC6624E Accident Date : 18/12/2017

Make : TOYOTA HIACE Assignment Date : 22/12/2017

Date of Inspection : 03/01/2018 Est. Duration of Repair : 2.00

Inspection At : THINK ONE AUTOCARE PTE LTD (HQ)

NO. 18 DEFU AVENUE 2 SINGAPORE 539522

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,788.75
Revised Amount	:S\$	676.13
Check Items (Estimated)	:S\$	0.00
Total	:S\$	676.13

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

1) The vehicle is	economical/not	economical	for	repair.
---	------------------	----------------	------------	-----	---------

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

AR201912-0345 MT/0974364

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	aioresaid.	
		ACCIDENT STATEMENT
	Date Of Report	19/12/2017 14:03
	Date Of Accident	18/12/2017 18:00
	Exact Location Of Accident	ALONG BUKIT TIMAH ROAD JUNCTION
	Country/State of Loss	SINGAPORE
	D	ETAILS OF OWN VEHICLE
	Vehicle Registration Number	PC6624E
1	Insured/Policyholder	
· .	Name Of Registered Owner	THINK ONE LEASING PTE LTD
	Co Reg No	201115609M
	Email Address	NOEMAIL
	Mobile Phone No	(LOCAL) +65-96788288
	Alternative Phone No	OFFICE-68443300
	Vehicle Particulars	
	Manufacturer	TOYOTA
	Model	HIACE-3.0 D GL (A)
	Exact Purpose for which vehicle was being used at time of accident	WORKING
	Are you claiming under your own insurance policy for repair to your vehicle?	NO
	If No, Please state action to be taken	THIRD PARTY
	Vehicle Category	PRIVATE CAR
,	Insurance Company	
	Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
	Type Of Coverage	COMPREHENSIVE
	Fleet Policy	NO
	Policy Number	5070785764-02
	Cover Note Number	

Driver

Name of Driver VEERAPPAN SUBBAIAH

NRIC No S8182246H
Date Of Birth 17/05/1981
Occupation OUTDOOR
Date Of Driving Pass 20/10/2005

Driving Experience 12 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-84404139

Fax Number

Contact Number

EMail Address NOEMAIL

Address

APT BLK 48 BENDEMEER ROAD #03-1491

Postcode

330048

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

NO

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO YES

Was any other material or property damaged?

i have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 18.12.2017 AT ABOUT 1800HRS I WAS DRIVING A VEHICLE (PC6624E) ALONHG MACKENZIE ROAD HEADING TOWARD BUKIT TIMAH ROAD. A MOTOR VEHICLE (FBH9338E) KNOCK ONTO MY REAR RIGHT SIDE FROM BEHIND. NO INJURIES INVOLVED.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBH9338B

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE B

Name of Driver

PEK KIAP YONG

NRIC/Passport Number

S8624993F

Contact Number

81005654

Address

APT BLK 672D EDGEFIELD PLAINS

#15-579 824672

Postcode Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

00 18.10 17 1 11/09 drilling Hobids, (DC/6)/15) along the war 21
ON 18-12-17 I was driving vehicle (PC6604E) along Mackenzie Rd heading toward Bucit Timah Road. A motorvehicle (FBH9338B) Knock onto my lear Right side from behind. No Injuries.
heading toward Burit Timati Road. A motoruetricle (+BH9338B)
Knock note my Rear Right side from behind No Milmies
and only my and round are more actived. The man
1

DECLARATION

I/We declare the following particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time: 19/12/2017

Think One Jutocare Pte Ltd 18 Defa Lane Avenue 2 ax: 6842 4988

Reporting Centre Personnel's Signature Name: Karun lan NRIC/FIN No.: 8783 156 C

Enquire Transfer Fee

Vehicle Details

Vehicle No.:

PC6624E

Vehicle Type:

Z20 - Private Hire (Chauffeur) Bus/Coach/Minibus

Vehicle Attachment 1:

No Attachment

Vehicle Scheme:

Public Service Vehicle (Others)

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE COMMUTER GL 3.0 AUTO

Chassis No.:

KDH2230032966

Propellant:

Diesel

Engine No.:

1KD2726598

Engine Capacity:

2982 cc

Maximum Power

Output:

Maximum Laden

2990 kg

Weight:

Unladen Weight:

2140 kg

Year Of Manufacture:

2017

Original Registration

Date:

29 Sep 2017

Lifespan Expiry Date:

28 Sep 2037

COE Category:

C - Goods Vehicle & Bus

PQP Paid:

\$19,289.00

COE Expiry Date:

28 Sep 2027

Road Tax Expiry Date:

28 Sep 2018

Inspection Due Date:

28 Sep 2018

Intended Transfer

04 Jan 2018

Date:

CO2 Emission:



Think One Autocare Pte Ltd

18 Defu Ave 2 Singapore 539522 Tel: 6844 3300 Fax: 6842 4988

ROC: 201322501G

ESTIMATE

PC6624E TOYOTA HIACE COMMUTER GL 3.0 AUTO

Page No.: 1 of 1

per :	No. 2 to Applicate Control of the Co	Coul		timate By orkshops.	Adjusted (\$)
PARTS & LABOUR REAR RIGHT TAILLAMP	•		\$	588. 75	301.5 :226.13
				23/0	1:226.9
<mark>LABOUR</mark> LABOUR FOR PANEL E RIGHT AFFECTED ARE	BEATING, CUT, WELD, STRAIGHTEN REAL	₹,	! ! \$	600. 00	200
TO PUTTY & SPRAY F	PAINTING REAR RIGHT PORTION	· ·	\$	600.00	
			• Farts once • Third party	ou of this follow betche after sident gamaged part(as are subject to	oray painting s) during resurvey confirmation Without Prejudice
	2 Pays.		 Suppleme is subject to 	ntary item(s) m	st be resurveyed a from Insurance Co
	tempor topan		Signature: Date:		
	After report photo pat by put.	۶۶.	67	6.13	
	pat by pat.		:		
	6ma liay - 8- 03/1/18				
	03/1/18				
LESS \$100 DISCOUNT	<u> </u>			<u>. </u>	
			9	1,788.75	

Page 1 of 1

No results.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	A	dj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	20 Dec 2017		22 Dec 2017 11:38 Edit Adj Rpt	s:	\$676.12 Edit Estimates	\$\$676.12 View Rpt		Pending for Survey Report Cancel Case	
	Main	Refere	ence		Claim Details	ا	Documents	Show All	
CLAIM SU	JBFOLDER DET	AILS					(Created by in	surer]	
Insured:		PEK KIAP HO	W, ID: S8817	56A					
Main Claim	nant:	THINK ONE	LEASING PTE L	rD,	Co, Reg. No.: 20	1115609M			
Vehicle Re	g. No.:	PC6624E			Date of Loss:	:	18/12/2017 18:0	0 - :59	
Claim Type	2;	TP / MSC/V	//17-001957	_	Policy/Cover	Note No.:	MSD/VMT/17-986907-WTT (Third Party Only) Coverage: 18/11/2017 - 17/11/201		
Vehicle Re	g. No. (Insured):	o. (Insured): FBH9338B Policy No. (Claimant):							
					Excess:				
Repairer:		Think One A	utocare Pte Ltd	(HQ)	No. 18 Defu Ave	enue 2, 539522 U	bi - Tel: 68443300		
Handling I	nsurer:	MSIG Insura Zhen - 6594) Pte.	. Ltd. (HQ) - Tei	1: +65 6827 7888	[Handled by Mo	onica Chung Pei	
Adjuster:		LKK Auto Co due 21/01/2		d (HC	Q) - Tel: 6256-3	561 [Handled b	y MARCUS CHUA] [Final Rpt	
Driver/Cus	todian (Insured):	PEK KIAP YON	IG (), NRIC: SE	62499	93F, Tel: +658	1005654			
Adj Asg. R	emarks:	Pls assign Mar	cus. No. 18 Defu	Aven	ue 2, 539522				
ASSOCIA	TED MAIL REC	EIVED					View All	Compose Case Mail	
There are	no mail for this ca	ise.						· · · · · · · · · · · · · · · · · · ·	
ALL ASS	OCIATED TASK	sE) (i.e.	ew All Search 1	asks Create Ne	w Task Complete	

Page 1 of 2 Merimen e-Claims

Claim Documents

*PC6624E (MSC/V/17-001957) [FBH9338B] TP THINK ONE LEASING PTE LTD Dec 18 2017 6:00PM [PEK KIAP HOW] Think One Autocare Pte Ltd

		pload Photos Compose New Letter		lew View in Bro	
Ass	essment Reports		1 pe	rpage 🗸	<u> </u>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/12/17 10:59	Accident Statement From:SC - Reg. No: F8H9338B, Claimant: PEK KIAP HOW	0	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/03/18 15:22	Adjuster Immediate Advice	1	Load HTM	
Pho	itos/Images		3 pe	r page	\square
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/03/18 15:04	General View	0	Load JPG	Ø
2	15/03/18 15:04	General View	Ð	Load JPG	Ø
3	15/03/18 15:04	General View	0	Load JPG	Z
4	15/03/18 15:04	General View	0	Load JPG	\square
5	15/03/18 15:04	General View	0	Load JPG	\square
6	15/03/18 15:04	General View	0	Load JPG	\square
7	15/03/18 15:04	General View	0	Load JPG	∡
8	15/03/18 15:04	General View	0	Load JPG	Ø
9	15/03/18 15:04	General View	0	Load JPG	✓
10	15/03/18 15:04	General View	0	Load JPG	7
11	15/03/18 15:04	General View	0	Load JPG	4
12	15/03/18 15:04	General View	0	Load JPG	3
13	15/03/18 15:18	Reinspection Photo	0	Load JPG	V
			1		
Doc	umentation		1 pe	r page 💙	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/12/17 10:59	TP SURVEY REPORT	0	Load PDF	
2	22/12/17 10:59	ESTIMATE	•	Load TIF	
3	22/12/17 10:59	TP GIA Rep -PC6624E From:SC - Reg. No: FBH9338B, Claimant: PEK KJAP HOW	0	Load PDF	
4	22/12/17 11:37	TP WORKSHOP NOMINATE MARCUS FROM LKK TO BE THE SJE	0	Load PDF	
5	02/01/18 11:19	PHOTO (1)	0	Load JPG	>
6	02/01/18 11:19	PHOTO (2)	0	Load JPG	(
7	02/01/18 11:19	РНОТО (3)	0	Load JPG	K
8	02/01/18 11:19	РНОТО (4)	0	Load JPG	K
9	02/01/18 11:19	PHOTO (5)	Ø	Load JPG	[5]
10	02/01/18 11:19	РНОТО (6)	0	Load JPG	S
11	02/01/18 11:19	PHOTO (7)	0	Load JPG	\mathbf{Z}
12	02/01/18 11:19	PHOTO (8)	0	Load JPG	\

Merimen e-Claims Page 2 of 2

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.		-		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
	^			
	~			
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG17024590/GRD3E2

Date:

15/03/2018

REFERENCE

MSIG Insurance (Singapore) Pte. Policy No: Handling Insurer:

MSD/VMT/17-986907-

WTT

Claimant Vehicle

PC6624E

Insured Vehicle

FBH9338B

No: Date of Loss:

18/12/2017

Nature of Claim:

ΤP

Claim No:

MSC/V/17-001957

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

PC6624E

Make & Model:

TOYOTA HIACE, 3.0 D GL (A)

No:

Engine No:

1KD2726598

Reg. Date: Colour:

29/09/2017 (Man. Year: 2017) White

Chassis No: Odometer:

KDH2230032966 17340 km

Engine Capacity:

2982 cc N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): **CONDITION OF TYRES**

Yes Engine Modification:

Front Tyre Size:

195/80 R15

Rear Tyre Size:

195/80 R15

Front Left Side:

Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	588.75	226.12	362.63	61.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	450.00	750.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,788.75	676.12	1,112.63	62.20
+ GST 7.00/7.00% (S\$)	125.21	47.33	77.88	62.20
Nett Amount (S\$)	1,913.96	723.45	1,190.51	62.20

INSPECTION

Date of Assignment:

22/12/2017

Date Inspected:

03/01/2018 Inspected At: Think One Autocare Pte Ltd (HQ)

No. 18 Defu Avenue 2 Singapore 539522

Estimated Period of Repair:

2.0 days

Adjuster: MARCUS CHUA Manager:

Janice Lee Si Hua

Page 2 of 4 Adjuster Report NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 15 Mar 2018)

Parts:

213

TOYOTA HIACE 3.0 D GL (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC6624E)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*REAR RIGHT TAILLAMP	Cracked	588.75 F	*301.50 FL
nchise	part. L=ListItem	Disc.			
			Sub Total (S\$)	588.75	301.50
		- List Item Discount on L	. Items 0.00/25.00% (S\$)	0.00	75.38
			Total Parts (S\$)	588.75	226.12
	1	1	1 *REAR RIGHT TAILLAMP inchise part. L=ListItemDisc.	1 *REAR RIGHT TAILLAMP Cracked unchise part. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 0.00/25.00% (S\$)	1 *REAR RIGHT TAILLAMP Cracked 588.75 F unchise part. L=ListItemDisc. Sub Total (\$\$) 588.75 - List Item Discount on L Items 0.00/25.00% (\$\$) 0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR, RIGHT AFFECTED AREA	New	600.00	200.00
2	TO PUTTY & SPRAY PAINTING REAR RIGHT PORTION	New	600.00	250.00
	Gross Labour Cost (S\$)		1,200.00	450.00
	Report was unsubmitted durir	g this print-out.		

< END OF ESTIMATES >