

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 29 Dec 2017

Preliminary Advice

Vehicle No	: SGL4447Y	Accident Date	: 23/12/2017
Make	: TOYOTA VIOS	Policy No.	: DMPCSN3079351600
Assignment Date	: 27/12/2017	Excess	: S\$0.00
Date of Inspection	: 28/12/2017	Est. Duration of Repair	: 6.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,249.19
Revised Amount	:S\$	1,928.88
Check Items (Estimated)	:S\$	1,107.75
Total	:S\$	3,036.63
Lump Sum Repair (ESTIMATED)	:S\$	2,400.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	9,489.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,511.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :