

22/03/2002

ASS. REC. BY:

REF: CS/AXA17024593/Std302

Special Instructions:

Specialist: Sebastian MenmenASSIGNMENT (Office)

From (Person):

Winnie Ho

of

AXA

Date/Time:

28/12/17 @ 9:36am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 5151L

Insured:

at Workshop m/s

Elite Am

Tel:

63397378

of

280 woodlands Ind. Park ES # 01-17

Policy No:

VPA/P1895664

Claim No:

Sum Insured:

Excess:

\$400.00

Make of Veh:

(Client's Record)

D.O.A.

16/12/17CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:47am @ 28/12/17

Person Contacted:

YenVehicle IN / OUT

Date/Time

Action/Instruction


(✓) Estimate

SLB 5151L - x28/12/17Revert via menmen.Part by Part \$23401 (Red: 6062 : 72%)

REF: AXA

ASSIGNMENT

From: _____ Date: 28/12/17
 Estimated Cost: _____
☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SLB 5151L
 at Workshop no: Elite Am
 of 280 Woodlands Ind. Park ES # 01-17
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: \$400.00
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$80k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lump Sum: _____ % 3 Val: Yes or No

☒ CA REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLB 5151L Vr Page: 22/3/2016
 Type: ☒ Car / ☐ M Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or _____
 Make: Honda Vezel cc 1500
 Colour: Blue A/C ☐ Insured / Std / NI / NA
 Sp. Reading: 33404 T Radio: Insured / Std / NI / NA
 Eng/No: _____
 C.No: RH11113761
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: In ☒ Order / Jammed / Leaked / Burnt or
 Brake: In ☒ Order / Jammed / Leaked / Burnt or
 Mod: ☒ N / S / Rim / STD A / Rim or
 Tyre Size: F: 225 / 50 ZR17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 16/12/2017 D.O.I. 28/12/2017
 Survey held at Elite
 Des. of Damages ☒ Fr / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

RECEIVED 07 MAY 2018

Date/Time File Passed: ☐ Preli. Report
23/14 Typist ☒ Final Report
 Date/Time File Return to: _____

Days Of Repair: 4
 Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Tech. Ins \$
☐ Clean up \$

Report Format: OD
 Lump Sum: 2340

Survey Fee
 Transportation

 Phone

200

TOTAL

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CS/AXA17024593/Std3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 28-12-2017	
		Code : AXA2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLB 5151L
Policy No.	VPAP1895664	Coverage (\$)	0.00
Claim No.		Excess (\$)	400.00
Assign From	MERIMEN (WINNIE HO)	Assign Date	28/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/12/2017	Inspection Date	28/12/2017
Survey held at	ELITE AM PTE. LTD. 280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST @ WOODLANDS, 757322 WOODLANDS		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Denise Tay (LKKAUTO)

From: Elite AM <eliteamclaim@gmail.com>
Sent: Monday, 23 April 2018 4:48 PM
To: Denise Tay (LKKAUTO)
Subject: Re: Supplier Invoice For Vehicle No: SLB 5151L

Hi Denise,

Good day! We accept the offer, but please take note our co is GST registered. Thanks!

Regards,

Christy

On Fri, Apr 20, 2018 at 5:14 PM, Denise Tay (LKKAUTO) <denisetay@lkkauto.com> wrote:

Dear Christy,

Parts - \$1510

Labour - \$830

Total - \$2340

Repair days: 4

Kindly check and confirm

Best Regards,

Denise Tay | Case Handler

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Winnie Ho

Date: 28 Dec 2017

Preliminary Advice

Vehicle No	: SLB5151L	Accident Date	: 16/12/2017
Make	: HONDA VEZEL	Policy No.	: VPA/P1895664
Assignment Date	: 28/12/2017	Excess	: S\$400.00
Date of Inspection	: 28/12/2017	Est. Duration of Repair	: 4.00
Inspection At	: ELITE AM PTE LTD (HQ) 280 WOODLANDS INDUSTRIAL PARK E5, #01-17 HARVEST @ WOODLANDS SINGAPORE 757322		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,237.00
Revised Amount	:S\$	2,055.00
Check Items (Estimated)	:S\$	2,520.00
Total	:S\$	4,575.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	46,080.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,920.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : We have authorise repair @ 28/12 14:00HRS

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	8458A

Vehicle Details

Vehicle No.:	SLB5151L
Vehicle to be Exported:	No
Intended De-registration Date:	28 Dec 2017
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	L15B4033763
Chassis No.:	RU11113761
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,208.00
Original Registration Date:	22 Mar 2016
First Registration Date:	22 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$10,292.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2026
PARF Rebate Amount:	\$7,719.00

Intended COE Rebate Details

COE Expiry Date:	21 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,651.00
COE Rebate Amount:	\$38,361.00
Total Rebate Amount:	\$46,080.00

The information contained herein is correct as at 28 Dec 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/12/2017 15:21
Date Of Accident	16/12/2017 12:30
Exact Location Of Accident	ALONG BUKIT PANJANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB5151L
Insured/Policyholder	
Name Of Registered Owner	TOH KWOK HOONG JERRY (DU GUOHONG JERRY)
NRIC No	S8018458A
Email Address	JERRY.TOH@ZOH0.COM
Mobile Phone No	(LOCAL) +65-96690783
Alternative Phone No	OFFICE-96690783

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1895664
Cover Note Number	

Driver

Name of Driver	TOH KWOK HOONG JERRY (DU GUOHONG JERRY)
NRIC No	S8018458A
Date Of Birth	03/07/1980
Occupation	INDOOR
Date Of Driving Pass	10/04/2004
Driving Experience	13 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96690783
Fax Number	
Contact Number	OFFICE-96690783
EMail Address	JERRY.TOH@ZOH0.COM

Address 511 SEMBAWANG ROAD
#01-71

Postcode 757711

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJW8059P

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver GOH GEOK CHOO

NRIC/Passport Number

Contact Number 97975109

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


Details of Witness

Name

Phone Number

Email Address

Accident Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[The following text is extremely faint and illegible due to heavy noise and low contrast in the original document. It appears to be a series of lines of text, possibly a list or a description, but cannot be transcribed accurately.]

Elite AM Pte Ltd (Co.Reg.No:201606209K)

280 Woodlands Industrial Park E5, #01-17 Harvest @ Woodlands

Singapore 757322

Tel: 63346276 Fax: 63346617 Email: eliteamclaim@gmail.com

INSURER: AXA Insurance Pte Ltd (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	VPA/P1895664	Date of Loss:	16/12/2017
Vehicle Reg. No.:	SLB5151L	Driveable?	
Driver Age/Info:	37 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TOH KWOK HOONG JERRY (DU GUOHONG JERRY)	Contact No:	+6596690783
Driver:	TOH KWOK HOONG JERRY (DU GUOHONG JERRY)		
Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	22/03/2016
Vehicle Colour:	BLUE		
Engine No:	L15B4033763	Chassis No:	RU11113761
Odometer:	32999 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	PLEASE REFER TO ATTACHMENT		
Present Location:	ELITE AM PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	4,907.00
Miscellaneous Items	60.00
Labour	3,270.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	8,237.00
- Excess (S\$)	400.00
(S\$)	7,837.00
+ GST 7.00% (S\$)	548.59
Nett Amount (S\$)	8,385.59

This claim is handled by: CHRISTY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 Dec 2017)**Parts:** M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLB5151L)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET ✓ DT ✓	0.00	0.00	360 *395.00 F ✓
2	1		*BONNET INSULATION X Reuse	0.00	0.00	*80.00 F ✓
3	10		*BONNET INSULATION CLIPS ✓ NEC ✓	0.00	0.00	20 *50.00 F 30 ✓
4	2		*BONNET HINGES ✓ DT ✓	0.00	0.00	*60.00 F ✓
5	2		*BONNET RUBBER STRIP ✓ NEC ✓	0.00	0.00	*30.00 F ✓
6	1		*BONNET INNER STICKER (WHITE COLOUR)	0.00	0.00	*30.00 F
7	1		*BONNET AIR CONDITIONER SYSTEM STICKER	0.00	0.00	*30.00 F
8	1		*BONNET MODULE YELLOW/ WHITE STICKER } NEC \$30	0.00	0.00	*30.00 F
9	2		*FRONT WIPER SIDE GARNISH Y NN	0.00	0.00	*32.00 F X
10	1		*BONNET LOCK ✓ BT ✓	0.00	0.00	*65.00 F ✓
11	1		*BONNET LOCK TOP SQUARE BRACKET ? ✓ ORA	0.00	0.00	*20.00 F
12	1		*FRONT GRILLE ✓ CRK ✓	0.00	0.00	*180.00 F
13	1		*FRONT GRILLE H EMBLEM ✓ NEC ✓	0.00	0.00	*15.00 F
14	1		*FRONT GRILLE LOWER MOULDING ? ✓ Chrome moulding - nec	0.00	0.00	40 *140.00 F
15	10		*FRONT GRILLE CLIPS X NEC NN	0.00	0.00	*50.00 F
16	1		*FRONT GRILLE TOP COVER ✓ SCR ✓	0.00	0.00	*40.00 F
17	10		*FRONT TOP COVER CLIPS X NEC NN	0.00	0.00	*50.00 F 30
18	1		*FRONT SUPPORT PANEL R	0.00	0.00	*310.00 F R
19	2		*HEADLAMP ? NN	0.00	0.00	*1,640.00 F
20	2		*HEADLAMP LOWER BRACKET ? ✓ CRK	0.00	0.00	40 *46.00 F
21	1		*FRONT BUMPER R	0.00	0.00	*200.00 F R
22	10		*FRONT BUMPER CLIPS ✓ NEC ✓	0.00	0.00	40 *50.00 F 30
23	1		*FRONT BUMPER LOWER GRILLE ? ✓ SLR	0.00	0.00	*48.00 F
24	10		*FRONT BUMPER LOWER GRILLE CLIPS ? ✓ NEC	0.00	0.00	20 *50.00 F
25	1		*FRONT BUMPER LOWER SPOILER ? ✓ SCR ✓	0.00	0.00	20 *130.00 F ✓
26	2		*FRONT BUMPER SIDE GARNISH X NN	0.00	0.00	*160.00 F
27	2		*FRONT FOG LAMP ? NN	0.00	0.00	*330.00 F
28	2		*FRONT FOG LAMP GARNISH ? Deform	0.00	0.00	30 *46.00 F
29	1		*FRONT BUMPER CENTRE MOULDING ✓ SCR X NBP	0.00	0.00	*120.00 F ✓
30	2		*FRONT BUMPER SIDE MOULDING X NN	0.00	0.00	*240.00 F
31	2		*FRONT BUMPER SIDE RETAINER ✓ NEC ✓	0.00	0.00	*20.00 F ✓
32	1		*FRONT BUMPER REINFORCEMENT ? ✓ DT	0.00	0.00	*180.00 F
33	2		*FRONT BUMPER BRACKET ? Nu	0.00	0.00	*20.00 F ✓
34	1		*RADIATOR COOLANT X NN	0.00	0.00	*20.00 F X

F=Franchise part.

Total Parts (\$\$)**4,907.00**

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT NUMBER PLATE C/W HOLDER X <i>b</i> <i>hw</i>	60.00
Sub Total (S\$)			60.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Labour charges to remove & install front end attachments and fittings to enable repairs; to cut & weld front panellings where necessary; to straighten & repairs both front fenders and inner support panels and front fenders brackets; to replace damaged parts as listed above	New	1,500.00 400.
2	To spray painting on: bonnet (inner & outer), bonnet hinges, front support panellings, both front fenders & inner support panels, front bumper reinforcement and front bumper (two colours)	New	1,300.00 400.
3	To remove & install A/C condenser C/W receiver dryer and A/C pipings/hoses to enable repairs; to reconnet hoses/ pipings and charge up gas	New	150.00 X
4	To remove & install radiator & hoses to enable repairs; to reconnet hoses and pressurize cooling system	New	90.00 X
5	To check electrical lights and focus headlights	New	30 . 50.00
6	To remove & install front wirings E.C.U sensor unit to enable repairs and reset system after necessary repairs	New	180.00 X
Gross Labour Cost (S\$)			3,270.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Sebastian

28/12/2017.

- Part by part repair.
- Question mark Item Photo.
- Photo Before Paint
- Excess : \$ 400
- Authorised.

90036121

sebastianyeang@lkkauto.com.

4 days.

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 02 Jan 2018)**Parts:** M1-SUV **HONDA VEZEL 1.5 X CVT (A)** (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Elite AM Pte Ltd/SLB5151L/02/01/2018 13:52**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT GRILLE OUTER <i>CRK</i>	0.00	0.00	*140.00 F
2	1		*AIR GUIDE LHS <i>11= form</i>	0.00	0.00	*25.00 F
Total Parts (\$\$)						165.00

F=Franchise part.

Elite AM Pte Ltd/SLB5151L/02/01/2018 13:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Dec 2017)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB5151L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET ✓ BT	0.00	0.00	300 *395.00 F ✓
2	1		*BONNET INSULATION X Reuse	0.00	0.00	*80.00 F
3	10		*BONNET INSULATION CLIPS ✓ NEC	0.00	0.00	*50.00 F 30
4	2		*BONNET HINGES ✓ BT	0.00	0.00	*60.00 F
5	2		X *BONNET RUBBER STRIP ✓ NEC	0.00	0.00	*30.00 F
6	1		*BONNET INNER STICKER (WHITE COLOUR)	0.00	0.00	*30.00 F
7	1		*BONNET AIR CONDITIONER SYSTEM STICKER } NEC \$30	0.00	0.00	*30.00 F
8	1		*BONNET MODULE YELLOW/ WHITE STICKER	0.00	0.00	*30.00 F
9	2		*FRONT WIPER SIDE GARNISH Y	0.00	0.00	*32.00 F
10	1		*BONNET LOCK ✓ BT	0.00	0.00	*65.00 F
11	1		*BONNET LOCK TOP SQUARE BRACKET ? ✓ CRK	0.00	0.00	*20.00 F
12	1		X *FRONT GRILLE ✓ CRK out for Bush \$140	0.00	0.00	*180.00 F ✓
13	1		X *FRONT GRILLE H EMBLEM ✓ NEC Bush \$180	0.00	0.00	*15.00 F
14	1		X *FRONT GRILLE LOWER MOULDING ? ✓ CRK	0.00	0.00	*140.00 F ✓
15	10		⑤ *FRONT GRILLE CLIPS ✓ NEC	0.00	0.00	*50.00 F
16	1		⑤ *FRONT GRILLE TOP COVER ✓ SCR	0.00	0.00	*40.00 F
17	10		⑥ *FRONT TOP COVER CLIPS ✓ NEC Chrome moulding ✓ NEC	0.00	0.00	*50.00 F 30
18	1		*FRONT SUPPORT PANEL R	0.00	0.00	*310.00 F
19	2		*HEADLAMP ? X	0.00	0.00	*1 640.00 F
20	2		*HEADLAMP LOWER BRACKET ? ✓ CRK	0.00	0.00	*46.00 F
21	1		*FRONT BUMPER R	0.00	0.00	*200.00 F
22	10		*FRONT BUMPER CLIPS X NEC center ✓ SCR	0.00	0.00	*50.00 F 30
23	1		*FRONT BUMPER LOWER GRILLE ? ✓ SCR	0.00	0.00	*48.00 F
24	10		*FRONT BUMPER LOWER GRILLE CLIPS ? ✓ NEC	0.00	0.00	*50.00 F 30
25	1		*FRONT BUMPER LOWER SPOILER ? ✓ SCR	0.00	0.00	*130.00 F
26	2		*FRONT BUMPER SIDE GARNISH X	0.00	0.00	*160.00 F
27	2		*FRONT FOG LAMP ? X	0.00	0.00	*330.00 F
28	2		X *FRONT FOG LAMP GARNISH ? ✓ Idom.	0.00	0.00	30 *46.00 F
29	1		*FRONT BUMPER CENTRE MOULDING X SCR X NSP	0.00	0.00	*120.00 F
30	2		*FRONT BUMPER SIDE MOULDING X	0.00	0.00	*240.00 F
31	2		*FRONT BUMPER SIDE RETAINER ✓ NEC	0.00	0.00	*20.00 F
32	1		*FRONT BUMPER REINFORCEMENT ? ✓ BT	0.00	0.00	*180.00 F
33	2		*FRONT BUMPER BRACKET ? ✓ NEC	0.00	0.00	*20.00 F
34	1		*RADIATOR COOLANT X	0.00	0.00	*20.00 F

F=Franchise part.

Total Parts (S\$)

4,907.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 FRONT NUMBER PLATE C/W HOLDER X

60.00

Sub Total (S\$)

60.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 Labour charges to remove & install front end attachments and fittings to enable repairs; to cut & weld front panellings where necessary; to straighten & repairs both front fenders and inner support panels and front fenders brackets; to replace damaged parts as listed above

New

~~1,500.00~~
400

2 To spray painting on: bonnet (inner & outer), bonnet hinges, front support panellings, both front fenders & inner support panels, front bumper reinforcement and front bumper (two colours)

New

~~1,300.00~~
400

3 To remove & install A/C condenser C/W receiver dryer and A/C pipings/hoses to enable repairs; to reconnet hoses/ pipings and charge up gas

New

150.00 X

4 To remove & install radiator & hoses to enable repairs; to reconnet hoses and pressurize cooling system

New

90.00 X

5 To check electrical lights and focus headlights

New

30 50.00

6 To remove & install front wirings E.C.U sensor unit to enable repairs and reset system after necessary repairs

New

180.00 X

Gross Labour Cost (S\$)

3,270.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Sebastian

28/12/2017.

- Part by part repair.
- Question mark Item Photo.
- Photo Before Paint
- Excess : \$ 400
- Authorized.

90036121

sebastianyeang@lkkauto.com

4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Elite AM Pte Ltd (Co.Reg.No:201606209K)

280 Woodlands Industrial Park E5, #01-17 Harvest @ Woodlands

Singapore 757322

Tel: 63346276 Fax: 63346617 Email: eliteamclaim@gmail.com

INSURER:

AXA Insurance Pte Ltd (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	VPA/P1895664	Date of Loss:	16/12/2017
Vehicle Reg. No.:	SLB5151L	Driveable?	
Driver Age/Info:	37 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TOH KWOK HOONG JERRY (DU GUOHONG JERRY)	Contact No:	+6596690783
Driver:	TOH KWOK HOONG JERRY (DU GUOHONG JERRY)		
Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Vehicle Reg. Date:	22/03/2016
Vehicle Colour:	BLUE	Chassis No:	RU11113761
Engine No:	L15B4033763		
Odometer:	32999 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	PLEASE REFER TO ATTACHMENT		
Present Location:	ELITE AM PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	4,907.00
Miscellaneous Items	60.00
Labour	3,270.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	8,237.00
- Excess (S\$)	400.00
(S\$)	7,837.00
+ GST 7.00% (S\$)	548.59
Nett Amount (S\$)	8,385.59

This claim is handled by: CHRISTY

Generated using Merimen e-Claims Internet Estimation & Adjusting System



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 198307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9039



Dept Direct: 6306 9810

Dept Direct: 6306 9411

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

ELITE AUTOMOTIVE PTE LTD
280 WOODLANDS INDUSTRIAL PARK E5 #01-17
HARVEST@WOODLANDS

SINGAPORE 757322
TEL: 63397378 FAX: 63397475
ATTN: IVAN 93882885

TAX INVOICE : AR201801-00601
DATE : 02/01/2018
CUSTOMER ID : ELI010
VEH REG. NO. : SLB5151L
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 3
CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	H71103-T7J-H00	73 BUMPER LOWER GRILLE	PA PL1-A1-08A	1	45.00	45.00
9	H91505-TM8-003	29 CLIPS BUMPER (H91505-TM8-000)	PA PL1-M1-09N	10	2.00	20.00
10	H71106-T7J-H00	28 FOG GARNISH LH	PA PL1-C1-08C	1	15.00	15.00
11	H71105-T7J-H00	28 FOG GARNISH RH	PA PL1-C1-08D	1	15.00	15.00
12	H71130-T7A-000ZZ RUI	37 REINFORCEMENT FR	PA PL1-A1-05B	1	180.00	180.00
13	H71151-T7A-000 RUI	20 UP BEAM RH FRT GRIL	PA PL1-L1-11H	1	10.00	10.00
14	H71152-T7A-000 RUI	20 UP BEAM LH FRT GRIL	PA PL1-L1-11Q	1	10.00	10.00

CONTINUE NEXT PAGE

[P] 02/01/2018 2:24:57PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 02/01/2018 2:10:24PM

(Handwritten signature)



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9609



Dept Direct: 6305 9910

Dept Direct: 6305 9911

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

ELITE AUTOMOTIVE PTE LTD
280 WOODLANDS INDUSTRIAL PARK E5 #01-17
HARVEST@WOODLANDS

SINGAPORE 757322
TEL : 63397378 FAX : 63397475
ATTN : IVAN 93882885

TAX INVOICE : AR201801-00601
DATE : 02/01/2018
CUSTOMER ID : ELI010
VEH REG. NO. : SLB5151L
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 3
CURR : S\$

SO STOCKID	DESCRIPTION	StkLoo	QTY	U/PRICE	AMOUNT
1. H71121-T7A-000 RUI	12 FR GRILLE	PA PL1-R1-010	1	180.00	180.00
2. H71122-T7A-000 RUI	51 GRILLE OUTER GARNISH	PA PL1-R1-010	1	140.00	140.00
3. H75700-S9A-G00T BE1 CL7 FD1	13 "H" EMBLEM	PA PL1-L1-04K	1	15.00	15.00
4. H71123-T7A-000 RUI	14 FR GRILLE CHROME RH	PA PL1-P1-12A	1	20.00	20.00
5. H71128-T7A-000 RUI	14 GRILLE CHROME LH	PA PL1-L1-08F	1	20.00	20.00
6. H71116-T7A-000 RUI	52 AIR GUIDE LH FRT BU	PA PL1-L1-06G	1	25.00	25.00
7. H71150-T7J-H00	UP BEAM FRT GRILLE	PA PL1-N1-11J	1	20.00	20.00

CONTINUE NEXT PAGE

[P] 02/01/2018 2:24:57PM

[B] 02/01/2018 2:10:24PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

(Handwritten signature)



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN-GLASS
Dept Direct: 6417 9791 / 6745 9839



TOYOTA
GENUINE PARTS



Dept Direct: 6305 9840

Dept Direct: 6305 9811

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9796

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Wiper blade: NWB (Nippon Wiper blade), Silper (Made In Korea),

Forch (Made In Germany)

Spark plug: Nippon Denso, NGK (Made In Japan)

ELITE AUTOMOTIVE PTE LTD
280 WOODLANDS INDUSTRIAL PARK E5 #01-17
HARVEST@WOODLANDS

SINGAPORE 757322
TEL: 63397378 FAX: 63397475
ATTN: IVAN 93882885

TAX INVOICE : AR201801-00601
DATE : 02/01/2018
CUSTOMER ID : ELI010
VEH REG. NO. : SLB5151L
TERMS : 30 days
PO NO. :
PAGE NO. : Page 3 of 3
CURR : S\$

SO	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
75	H74128-T7A-003 RUI	SEAL BONNET LH (CENTRE) Repeated?	PA PL1-C1-08T	1	15.00	15.00

SUB-TOTAL : 730.00
ADD GST 7.00 % 51.10

E. & O.E

TOTAL AMOUNT S\$: 781.10

[P] 02/01/2018 2:24:57PM

[E] 02/01/2018 2:10:24PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: CHEN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729872

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

=====~~GST REG NO: M2-0110201-3~~ ~~GO. REG. NO: 199307741M~~=====

ELITE AUTOMOTIVE PTE LTD
280 WOODLANDS INDUSTRIAL PARK E5 #01-17
HARVEST@WOODLANDS

SINGAPORE 757322

TEL : 63397378 FAX : 63397475

ATTN : IVAN 93882885

WIPSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9930



Dept Direct: 6305 9810

Dept Direct: 6305 9811

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWS (Nippon Wiper blade), Stilper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201801-00619
DATE : 02/01/2018
CUSTOMER ID : ELI010
VEH REG. NO. : SLB5151L
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : S\$

EAM (bb)

SQ STOCKID

DESCRIPTION

StkLoc

QTY

U/PRICE

AMOUNT

1 H74121-T7A-003
RU1

SEAL BONNET RH (CENTRE)

U1
L2-F11-D

1

15.00

15.00

SUB-TOTAL : 15.00

ADD GST 7.00 % 1.05

E. & O.E

TOTAL AMOUNT S\$: 16.05

[P] 02/01/2018 2:24:51PM

[E] 02/01/2018 2:24:36PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHEN



* A R 2 0 1 8 0 1 - 0 0 6 1 9 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9938

Arrange By

Driver



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9798

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

ELITE AUTOMOTIVE PTE LTD
280 WOODLANDS INDUSTRIAL PARK E5 #01-17
HARVEST@WOODLANDS

SINGAPORE 757322
TEL : 63397378 FAX : 63397475
ATTN : IVAN 93882885

TAX INVOICE : AR201801-00273
DATE : 02/01/2018
CUSTOMER ID : ELI010
VEH REG. NO. : SLB5151L
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
✓	H71140-T7A-000 /	BEAM,R FR BUMPER	PA PL1-L1-08F	1	20.00	20.00
✓	H71190-T7A-000 / RU1	33 BRACKET,L.FR BUMPER	PA PL1-L1-08L	1	20.00	20.00 ✓
10	H71102-T7W-A00 / RU1	25 FR BUMPER LOWER	PA PL4-B1-23	1	120.00	120.00
✓	H71193-T7A-000 / RU1	31 SPACER FR RH	PA PL1-L1-03F	1	10.00	10.00
✓	H71198-T7A-000 / RU1	31 SPACER FR LH	PA PL1-L1-03D	1	10.00	10.00

SUB-TOTAL : 765.00
ADD GST 7.00 % 53.55

E. & O.E

TOTAL AMOUNT S\$: 818.55

[P] 02/01/2018 10:47:00AM

[E] 02/01/2018 10:43:21AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDues Account(s).

JAE Auto Pte. Ltd.

Sales Executive: CHEN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9639

Arrange By

Driver

A. H. H. H.



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

ELITE AUTOMOTIVE PTE LTD
280 WOODLANDS INDUSTRIAL PARK E5 #01-17
HARVEST@WOODLANDS

SINGAPORE 757322
TEL : 63397378 FAX : 63397475
ATTN : IVAN 93882885

TAX INVOICE : AR201801-00273
DATE : 02/01/2018
CUSTOMER ID : ELI010
VEH REG. NO. : SLB5151L
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	H60100-T8N-T00ZZ / HRV	BONNET	PA PL1-E1-FRT	1	360.00	360.00
3	H91501-SWA-003	CLIPS, INSULATOR	PA PL1-L1-10I	10	2.00	20.00
4	H60120-T7A-000ZZ / RU1	BONNET HINGE RH	PA PL1-C1-08V	1	30.00	30.00
4	H60170-T7A-000ZZ / RU1	BONNET HINGE LH	PA PL1-C1-08Y	1	30.00	30.00
10	H74120-T7A-003 / RU1	LOCK ASSY HOOD	PA PL1-L1-11S	1	65.00	65.00
22	H91505-TM8-003 / GM2	CLIPS BUMPER (H91505-TM8-000)	PA PL1-M1-09N	20	2.00	40.00
16	H71129-T7A-000 / RU1	COVER FRT GRILLE	PA PL1-M1-09A	1	40.00	40.00

CONTINUE NEXT PAGE

[P] 02/01/2018 10:47:00AM

[E] 02/01/2018 10:43:21AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2017 Sendback Est	27 Dec 2017 12:47 S\$8,237.00	28 Dec 2017 09:36 Edit Adj Rpt	S\$2,340.00 Edit Estimates	S\$2,340.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	02 Jan 2018 13:48	02 Jan 2018 13:52 S\$165.00	02 Jan 2018 13:52			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: TOH KWOK HOONG JERRY (DU GUOHONG JERRY) , ID: S8018458A, Tel: +6596690783, Email: jerry.toh@zoho.com									
Vehicle Reg. No.: SLB5151L		Date of Loss:	16/12/2017 12:00 - :59 [20 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type: OD / C0465016		Policy/Cover Note No.:	VPA/P1895664 (Comprehensive)						
		Excess:	S\$400.00						
Repairer: Elite AM Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17 Harvest @ Woodlands, 757322 Woodlands - Tel: 63346276									
Handling Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Winnie Ho - 6880 4833]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 09/01/2018]									
Driver/Custodian: TOH KWOK HOONG JERRY (DU GUOHONG JERRY) (37 / Male), NRIC: S8018458A, Tel: +6596690783									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLB5151L (C0465016)
 OD
 Dec 16 2017 12:00PM
 [TOH KWOK HOONG JERRY (DU GUOHONG JERRY)]
 Elite AM Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	Elite AM Pte Ltd (HQ)		Thumbnail	Print
1	27/12/17 12:47	Repairer Estimates	1	Load HTM	
2	02/01/18 13:52	Repairer Estimates Suppl. #1	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/12/17 17:55	Adjuster Immediate Advice	1	Load HTM	
Photos/ Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/04/18 17:03	General View	1	Load JPG	☒
2	23/04/18 17:03	General View	1	Load JPG	☒
3	23/04/18 17:03	General View	1	Load JPG	☒
4	23/04/18 17:03	General View	1	Load JPG	☒
5	23/04/18 17:03	General View	1	Load JPG	☒
6	23/04/18 17:03	General View	1	Load JPG	☒
7	23/04/18 17:03	General View	1	Load JPG	☒
8	23/04/18 17:03	General View	1	Load JPG	☒
9	23/04/18 17:03	General View	1	Load JPG	☒
10	23/04/18 17:03	General View	1	Load JPG	☒
11	23/04/18 17:03	General View	1	Load JPG	☒
12	23/04/18 17:03	General View	1	Load JPG	☒
13	23/04/18 17:03	General View	1	Load JPG	☒
14	23/04/18 17:03	General View	1	Load JPG	☒
15	23/04/18 17:03	General View	1	Load JPG	☒
16	23/04/18 17:03	General View	1	Load JPG	☒
17	23/04/18 17:03	General View	1	Load JPG	☒
18	23/04/18 17:03	General View	1	Load JPG	☒
19	23/04/18 17:03	General View	1	Load JPG	☒
20	23/04/18 17:03	General View	1	Load JPG	☒
21	23/04/18 17:03	General View	1	Load JPG	☒
22	23/04/18 17:03	General View	1	Load JPG	☒
23	23/04/18 17:03	General View	1	Load JPG	☒
24	23/04/18 17:03	General View	1	Load JPG	☒
25	23/04/18 17:03	General View	1	Load JPG	☒
26	23/04/18 17:03	General View	1	Load JPG	☒
27	23/04/18 17:03	General View	1	Load JPG	☒
28	23/04/18 17:03	General View	1	Load JPG	☒
29	23/04/18 17:03	General View	1	Load JPG	☒
30	23/04/18 17:03	General View	1	Load JPG	☒
31	23/04/18 17:03	General View	1	Load JPG	☒
32	23/04/18 17:03	General View	1	Load JPG	☒
33	23/04/18 17:03	General View	1	Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
				☒
34	23/04/18 17:03	General View	 Load JPG	☒
35	23/04/18 17:03	General View	 Load JPG	☒
36	23/04/18 17:03	General View	 Load JPG	☒
37	23/04/18 17:03	General View	 Load JPG	☒
38	23/04/18 17:03	General View	 Load JPG	☒
39	23/04/18 17:03	General View	 Load JPG	☒
40	23/04/18 17:03	General View	 Load JPG	☒
41	23/04/18 17:03	General View	 Load JPG	☒
42	23/04/18 17:03	General View	 Load JPG	☒
43	23/04/18 17:03	General View	 Load JPG	☒
44	23/04/18 17:03	General View	 Load JPG	☒
45	23/04/18 17:03	General View	 Load JPG	☒
46	23/04/18 17:03	General View	 Load JPG	☒
47	23/04/18 17:03	General View	 Load JPG	☒
48	23/04/18 17:03	General View	 Load JPG	☒
49	24/04/18 09:49	General View	 Load PDF	
50	24/04/18 09:49	Reinspection Photo	 Load PDF	
51	24/04/18 09:49	PHOTO BEFORE REPAIR	 Load PDF	
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/17 18:01	estimate	 Load PDF	
2	11/05/18 09:19	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 17:39	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 16:03	ACCIDENT PHOTO 1	 Load JPG	☒
2	18/12/17 16:03	ACCIDENT PHOTO 2	 Load JPG	☒
3	18/12/17 16:03	ACCIDENT PHOTO 3	 Load JPG	☒
4	18/12/17 16:03	ACCIDENT PHOTO 4	 Load JPG	☒
5	18/12/17 16:03	ACCIDENT PHOTO 5	 Load JPG	☒
6	18/12/17 16:03	ACCIDENT PHOTO 6	 Load JPG	☒
7	18/12/17 16:03	ACCIDENT PHOTO 7	 Load JPG	☒
8	18/12/17 16:03	ACCIDENT PHOTO 8	 Load JPG	☒
9	18/12/17 16:03	ACCIDENT PHOTO 9	 Load JPG	☒
10	18/12/17 16:03	ACCIDENT PHOTO 10	 Load JPG	☒
11	18/12/17 16:03	ACCIDENT PHOTO 11	 Load JPG	☒
12	18/12/17 16:03	ODOMETER READING	 Load JPG	☒
13	18/12/17 16:03	CHASSIS NUMBER	 Load JPG	☒
14	18/12/17 16:12	ACCIDENT SCENE PHOTO 1	 Load JPG	☒
15	18/12/17 16:12	ACCIDENT SCENE PHOTO 2	 Load JPG	☒
16	18/12/17 16:12	ACCIDENT SCENE PHOTO 3	 Load JPG	☒
17	18/12/17 16:12	ACCIDENT SCENE PHOTO 4	 Load JPG	☒
18	18/12/17 16:12	ACCIDENT SCENE PHOTO 5	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
19	18/12/17 16:12	ACCIDENT SCENE PHOTO 6	 Load JPG	☒
20	18/12/17 16:12	ACCIDENT SCENE PHOTO 7	 Load JPG	☒
21	18/12/17 16:12	ACCIDENT SCENE PHOTO 8	 Load JPG	☒
22	18/12/17 16:12	ACCIDENT SCENE PHOTO 9	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Elite AM Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 16:00	Accident Sketch Plan	 Load JPG	☒
2	18/12/17 16:00	DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	 Load JPG	☒
3	18/12/17 16:00	CERTIFICATE OF INSURANCE	 Load JPG	☒
4	18/12/17 16:00	OWNER IC & DRIVING LICENCE (FRONT)	 Load JPG	☒
5	18/12/17 16:00	OWNER IC & DRIVING LICENCE (BACK)	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)  			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AXA Insurance Pte Ltd
8 Shenton Way #24-01, AXA Tower
Singapore 068811

Our File No: CS/AXA17024593/STD3E2

Date: 11/05/2018

REFERENCE

Insured/Claimant: TOH KWOK HOONG JERRY (DU GUOHONG JERRY)

Policy No: VPA/P1895664

Date of Loss: 16/12/2017

Nature of Claim: OD Claim No: C0465016

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB5151L**
Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4033763
Reg. Date: 22/03/2016 (Man. Year: 2015) Chassis No: RU11113761
Colour: Blue Odometer: 33404 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$80,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50Z R17 Rear Tyre Size: 225/50Z R17
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,072.00	1,510.00	3,562.00	70.23
Miscellaneous Items	60.00	0.00	60.00	100.00
Labour	3,270.00	830.00	2,440.00	74.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,402.00	2,340.00	6,062.00	72.15
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	8,002.00	1,940.00	6,062.00	75.76
+ GST 7.00/7.00% (S\$)	560.14	135.80	424.34	75.76
Nett Amount (S\$)	8,562.14	2,075.80	6,486.34	75.76

INSPECTION

Date of Assignment: 28/12/2017 Present Location:

Date Inspected: 28/12/2017 Inspected At:

Elite AM Pte Ltd (HQ)

280 Woodlands Industrial Park E5, #01-17

Harvest @ Woodlands

Singapore 757322

Estimated Period of Repair: 4.0 days

Adjuster: Sebastian Yeang Wai Keen**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 May 2018)
Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLB5151L)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	395.00 F	*360.00 F
2	1		*BONNET INSULATION	Reuse	80.00 F	*- F
3	10		*BONNET INSULATION CLIPS	Necessary	50.00 F	*20.00 F
4	2		*BONNET HINGES	Bent	60.00 F	*60.00 F
5	2		*BONNET RUBBER STRIP	Necessary	30.00 F	*30.00 F
6	1		*BONNET INNER STICKER (WHITE COLOUR)		30.00 F	*- F
7	1		*BONNET AIR CONDITIONER SYSTEM STICKER		30.00 F	*- F
8	1		*BONNET MODULE YELLOW/ WHITE STICKER		30.00 F	*- F
9	2		*FRONT WIPER SIDE GARNISH	Not Necessary	32.00 F	*- F
10	1		*BONNET LOCK	Bent	65.00 F	*65.00 F
11	1		*BONNET LOCK TOP SQUARE BRACKET	Cracked	20.00 F	*20.00 F
12	1		*FRONT GRILLE	Cracked	180.00 F	*180.00 F
13	1		*FRONT GRILLE H EMBLEM	Necessary	15.00 F	*15.00 F
14	1		*FRONT GRILLE LOWER MOULDING	Necessary	140.00 F	*40.00 F
15	10		*FRONT GRILLE CLIPS	Not Necessary	50.00 F	*- F
16	1		*FRONT GRILLE TOP COVER	Scratched	40.00 F	*40.00 F
17	10		*FRONT TOP COVER CLIPS	Not Necessary	50.00 F	*- F
18	1		*FRONT SUPPORT PANEL	Repair	310.00 F	*- F
19	2		*HEADLAMP	Not Necessary	1,640.00 F	*- F
20	2		*HEADLAMP LOWER BRACKET	Cracked	46.00 F	*40.00 F
21	1		*FRONT BUMPER	Repair	200.00 F	*- F
22	10		*FRONT BUMPER CLIPS	Necessary	50.00 F	*40.00 F
23	1		*FRONT BUMPER LOWER GRILLE	Scratched	48.00 F	*45.00 F
24	10		*FRONT BUMPER LOWER GRILLE CLIPS	Necessary	50.00 F	*20.00 F
25	1		*FRONT BUMPER LOWER SPOILER	Scratched	130.00 F	*120.00 F
26	2		*FRONT BUMPER SIDE GARNISH	Not Necessary	160.00 F	*- F
27	2		*FRONT FOG LAMP	Not Necessary	330.00 F	*- F
28	2		*FRONT FOG LAMP GARNISH	Deformed	46.00 F	*30.00 F
29	1		*FRONT BUMPER CENTRE MOULDING	No such part	120.00 F	*- F
30	2		*FRONT BUMPER SIDE MOULDING	Not Necessary	240.00 F	*- F
31	2		*FRONT BUMPER SIDE RETAINER	Necessary	20.00 F	*20.00 F
32	1		*FRONT BUMPER REINFORCEMENT	Dented	180.00 F	*180.00 F
33	2		*FRONT BUMPER BRACKET	Necessary	20.00 F	*20.00 F
34	1		*RADIATOR COOLANT	Not Necessary	20.00 F	*- F
Supplementary #1						
35	1		*FRONT GRILLE OUTER	Cracked	140.00 F	*140.00 F
36	1		*AIR GUIDE LHS	Deformed	25.00 F	*25.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part.				Total Parts (S\$)	5,072.00	1,510.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NUMBER PLATE C/W HOLDER (NOT NECESSARY)	60.00	0.00
Sub Total (S\$)			60.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Labour charges to remove & install front end attachments and fittings to enable repairs; to cut & weld front panellings where necessary; to straighten & repairs both front fenders and inner support panels and front fenders brackets; to replace damaged parts as listed above	New	1,500.00	400.00
2	To spray painting on: bonnet (inner & outer), bonnet hinges, front support panellings, both front fenders & inner support panels, front bumper reinforcement and front bumper (two colours)	New	1,300.00	400.00
3	To remove & install A/C condenser C/W receiver dryer and A/C pipings/hoses to enable repairs; to reconnet hoses/ pipings and charge up gas	New	150.00	0.00
4	To remove & install radiator & hoses to enable repairs; to reconnet hoses and pressurize cooling system	New	90.00	0.00
5	To check electrical lights and focus headlights	New	50.00	30.00
6	To remove & install front wirings E.C.U sensor unit to enable repairs and reset system after necessary repairs	New	180.00	0.00
Gross Labour Cost (S\$)			3,270.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >