

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 488K***Not Authored  
1.B.1  
Remy B4pam***AAD1712-261***85765-76*

Vehicle No.:	<b>SHD 488K</b>
Chassis No.:	VF1ABL15AUC282329
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	25.12.2017
Third Party Insurer :	<b>AIG</b>

<b>PART</b>		<b>LIST</b>	
1	1	ROCKER PANEL OUTER RH	\$ <i>R</i> 1,024.79 X
2	1	DOOR REAR RH	\$ <i>Rollway</i> 2,844.66 ✓
3	1	DOOR HANDLE OUTER REAR RH	\$ <i>Sn</i> 126.49 X
4	1	FENDER PANEL REAR RH	\$ <i>R</i> 3,299.13 X
5	1	FENDER WHEELARCH REAR RH	\$ <i>Sn</i> 543.47 X
6	1	BUMPER COVER REAR	\$ <i>CPA</i> 1,108.46 ✓
7	1	BUMPER BRACKET CTR REAR	\$ <i>Sn</i> 113.47 X
8	1	BUMPER BRACKET KIT REAR	\$ <i>R</i> 260.69 X
9	1	BUMEPR BRACKET SIDE RH REAR	\$ <i>Sn</i> 135.97 X
10	1	BUMEPR BRACKET CTR RH REAR	\$ <i>Sn</i> 44.99 X
11	1	BUMEPR BLOCK RH REAR	\$ <i>Sn</i> 150.18 X
12	1	BUMPER LOWER REAR	\$ <i>CPA</i> 768.84 ✓
13	1	BUMPER REFLECTOR RH	\$ <i>Sn</i> 43.61 X
<b>TOTAL</b>		<b>\$</b>	<b>10,464.74</b>
<b>10%</b>		<b>\$</b>	<b>1,046.47</b>
		<b>\$</b>	<b>9,418.27</b>

**Special Nett**

14	1	DOOR STICKER "Trans-cab"	\$ <i>Nu</i> 80.00 X
15	1	DOOR STICKER "Classic"	\$ <i>an</i> 30.00 X
16	1	DOOR STICKER "6555-3333"	\$ <i>Nu</i> 80.00 <i>born</i>
17	1SET	WHEELARCH CLIP RH	\$ <i>nu</i> 66.00 X
18	1SET	REAR BUMPER CLIP	\$ <i>nu</i> 66.00 ✓
19	1SET	BUMEPR RETAINER RH CLIP RH	\$ <i>nu</i> 20.00 ✓
<b>TOTAL</b>		<b>\$</b>	<b>342.00</b>

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 488K**

**AAD1712-261**

**TOTAL PARTS \$ 9,760.27**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,450.00	<i>500</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
Putty and spray painting of the affected portion.	\$	1,750.00	<i>660</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	340.00	<i>601</i>
To rust-proofing of the affected areas.	\$	170.00	<i>301</i>
To transfer of fender fittings, attachment and perform water seepage test.	\$	340.00	<i>1001</i>

**TOTAL \$ 5,610.00**

**Over All Total \$ 15,370.27**

**(PARTS BY PARTS) Repair Days**

LKK Auto Consultants hence notify the Repairer **7 Days** the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_