

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1268/2017/JT
Date	:	28-Dec-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Low Siew Choo
Address	:	60 Elite Terrace
		Singapore 458810
Telephone	:	HP +65 9735 9988
Type of Claim	:	Third Party Claims
Policy No.	:	5096002993
Vehicle No	:	SLU 1638 B
Model Code	:	Audi Q2 1.0 TFSI S-tronic
Model / Year	:	Nov-17
Engine No	:	CHZ 580326
Chassis No	:	WAUZZZGA2JA033381
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	26-Dec-17
Place of Accident	:	Changi Road T-junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLU 1638 B.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper. Re-organize rear crash management components. Reinstall all parts removed.	\$ 900.00 500 ✓	
3	To respray rear bumper.	\$ 800.00 550 ✓	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 2,172.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 1638 B.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR BUMPER <i>Repl</i>	\$ 982.00	+
2	REAR BUMPER SPOILER <i>Retained</i>	\$ 232.00	✓
3	REAR REINFORCEMENT BEAM <i>not on</i>	\$ 461.00	+
4	REAR BUMPER HOLDING STRAP - LHS/RHS <i>not on</i>	\$ 20.00	+
5	REAR BUMPER GUIDE - LHS/RHS <i>not on</i>	\$ 88.00	+
6	REAR WHEEL ARCH TRIM - LHS/RHS <i>not on</i>	\$ 292.00	✓
7	REAR PARKING AID SENSOR <i>not on</i>	2 \$ 415.00	+
8	SUNDRIES <i>?</i>	\$ 300.00	?
GRAND TOTAL SPARE PARTS		: \$ 2,790.00	
TOTAL LABOUR CHARGES		: \$ 2,172.00	
GRAND TOTAL		: \$ 4,962.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian L
Surveyed Date : 09/01/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant