

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SGE5875A

TP/AXA

DOA: 23/12/17

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 23/12/2017

TP Veh Reg No: XB7761X

Estimate No: ES1791441/WS

Date: 27 Dec 2017

Policy No: 5071512621-02

Veh Reg No: SGE5875A

Make/Model: HONDA CITY M

Chassis No: MRHGD8506P010078

Engine No: L15A24801848

Reg. Date: 21/03/2006

Estimate Repair Cost to Vehicle No :SGE5875A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	446.30	1 PC	446.30	✓
2 FRONT BUMPER LH SIDE RETAINER	13.20	1 PC	13.20	✓
3 FRONT BUMPER CLIPS	3.70	6 PCS	22.20	✓
4 LH HEAD LAMP	448.50	1 PCS	448.50	✓
5 FRONT LH FENDER	332.40	1 PC	332.40	✓
6 FRONT LH FENDER LAMP	30.10	1 PC	30.10	?
7 FRONT LH FENDER INNER SHIELD	75.10	1 PC	75.10	✓
8 FRONT LH FENDER INNER SHIELD CLIPS	3.70	6 PCS	22.20	✓
9 FRONT LH FENDER TRIANGLE GLASS MOULDING	34.10	1 PCS	34.10	✓
10 FRONT LH MUDFLAP	26.50	1 PC	26.50	✓
11 FRONT LH DOOR	669.10	1 PC	669.10	✓
12 FRONT LH DOOR PROTECTOR	62.20	1 PC	62.20	✓
13 FRONT LH DOOR STICKER	50.10	1 PC	50.10	✓
14 FRONT LH DOOR OUTER HANDLE	87.80	1 PC	87.80	✓
15 FRONT LH SIDE MIRROR	285.80	1 PCS	285.80	✓
16 REAR LH DOOR PROTECTOR	57.50	1 PC	57.50	✓
17 FRONT SHOCK ABSORBER	262.30	1 PC	262.30	?
18 FRONT LH KNUCKLE ARM	222.30	1 PCS	222.30	?
19 FRONT LH WHEEL BEARING	119.20	1 PC	119.20	?
			3,266.90	
		Less 20%	653.38	2,613.52
Special Net				
20 FRONT LH SPORT RIM	380.00	1 PC	380.00	320.00
			380.00	380.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 23/12/2017

TP Veh Reg No: XB7761X

Estimate No: ES1791441/WS

Date: 27 Dec 2017

Policy No: 5071512621-02

Veh Reg No: **SGE5875A**

Make/Model: HONDA CITY M

Chassis No: MRHGD8506P010078

Engine No: L15A24801848

Reg. Date: 21/03/2006

Estimate Repair Cost to Vehicle No :SGE5875A

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
21 PANEL BEATING = REMOVE AND REFIX FRONT BUMPER ASSY, FRONT LH FENDER, HEAD LAMP, FRONT LH DOOR AND ATTACHMENT. TO KNOCK AND REPAIR FRONT LH WINDSCREEN PILLAR, REAR LH DOOR AND REALIGN THE SAME	680.00	1 LA	680.00	550
22 REMOVE AND REFIX FRONT LH DOOR GLASS	60.00	1 LA	60.00	✓
23 REMOVE AND REFIX FRONT LH FENDER GLASS	40.00	1 LA	40.00	✓
24 PUTTY AND RESPRAY ON FRONT BUMPER, FRONT LH FENDER, WINDSCREEN PILLAR, FRONT AND REAR LH DOOR, PROTECTORS, SIDE MIRROR AND ALL AFFECTED AREA	950.00	1 LA	950.00	850
25 REMOVE AND REFIX FRONT LH UNDER CARRIAGE	180.00	1 LA	180.00	?
26 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
27 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,030.00	2,030.00
			Total	S\$ 5,023.52
			Add GST @ 7%	351.65
			Total Amount Payable	S\$ 5,375.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE