

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024605/AVD3N2
Date: 14/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	P27193449DMA
Claimant Vehicle No :	SJP8168U	Insured Vehicle No :	SJT5628H
Date of Loss:	23/12/2017	Nature of Claim:	TP
		Claim No:	542512

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP8168U		
Make & Model:	HONDA CITY, 1.5 CVT (A)	Engine No:	L15Z11400953
Reg. Date:	03/06/2014 (Man. Year: 2014)	Chassis No:	MRHGM6660EP000019
Colour:	Brown	Odometer:	60031 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R16	Rear Tyre Size:	195/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,729.52	1,508.40	2,221.12	59.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,390.00	1,790.00	1,600.00	47.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,298.40	3,821.12	53.67
	Approved Total (Overridden) (S\$)	2,600.00		
	Nett Amount (S\$)	2,600.00	4,519.52	63.48

INSPECTION

Date of Assignment:	28/12/2017		
Date Inspected:	28/12/2017	Inspected At:	HIAP HONG MOTOR REPAIR 2 KAKI BUKIT AVE 2 #02-13 SINGAPORE 417921
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2018)
Parts: 143	HONDA CITY 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: LKK Auto Consultants Pte Ltd/SJP8168U/14/03/2018 17:09	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR DOOR	Dented	906.80 FL	*633.20 FL
2	2		*LH REAR DOOR HINGE	Lower Bent	88.00 FL	*44.00 FL
3	1		*SET LH REAR DOOR SASH PILLAR BLACK STICKER	Necessary	51.80 FL	*51.80 FL
4	1		*LH REAR DOOR INNER LOCK	Not Necessary	252.20 FL	*- FL
5	1		*LH REAR DOOR GLASS REGULATOR C/W MOTOR	Damaged	390.20 FL	*153.20 FL
6	1		*LH REAR DOOR WEATHERSTRIP	Necessary	112.10 FL	*51.00 FL
7	1		*LH REAR DOOR CHECKER	Not Necessary	46.70 FL	*- FL
8	1		*LH ROCKER PANEL GARNISH	Repair	420.60 FL	*- FL
9	12		*LH ROCKER PANEL GARNISH CLIP	Not Necessary	45.60 FL	*- FL
10	1		*LH FRONT DOOR	Dented	906.80 FL	*656.30 FL
11	1		*LH FRONT DOOR INNER LOCK	Damaged	268.70 FL	*199.20 FL
12	1		*SET LH FRONT DOOR SASH PILLAR BLACK STICKER	Necessary	48.10 FL	*48.10 FL
13	1		*LH FRONT DOOR GLASS REGULATOR C/W MOTOR	Not Necessary	397.20 FL	*- FL
14	1		*LH FRONT DOOR WEATHERSTRIP	Necessary	112.10 FL	*48.70 FL
15	1		*LH DOOR CENTRE PILLAR	Repair	615.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,661.90	1,885.50
- List Item Discount on L Items 20.00/20.00% (\$)	932.38	377.10
Total Parts (\$)	3,729.52	1,508.40

LKK Auto Consultants Pte Ltd/SJP8168U/14/03/2018 17:09. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK DOOR WIRING AND CENTRAL LOCKING SYSTEM FUNCTIONS	New	60.00	30.00
2	TO REMOVE,TRANSFER AND INSTALL FRONT DOOR GLASS	New	90.00	80.00
3	TO REMOVE,TRANSFER AND INSTALL REAR DOOR GLASS	New	90.00	80.00
4	TO APPLY ANTI-RUST UNDERCOATING	New	150.00	50.00
5	LABOUR CHARGES TO REMOVE AND REPLACE,TO CUT AND WELD,TO KNOCK AND RESHAPE AFFECTED PARTS/AREAS	New	1,500.00	700.00
6	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY ALL AFFECTED PARTS/AREAS FRONT DOOR,REAR DOOR,ROCKER PANEL,REAR FENDER,DOOR CENTRE PILLAR,ETC	New	1,500.00	850.00
			Gross Labour Cost (\$)	3,390.00
				1,790.00

LKK Auto Consultants Pte Ltd/SJP8168U/14/03/2018 17:09. Not valid without Reference section.

< END OF ESTIMATES >