

ASS. REC. BY:

REF: CS/MSG17024605/Avd3 | ⁿ²

Special Instruction:

Suit/vevot: Adrian
Merimen

ASSIGNMENT (Office)

From (Person): Monica chung of MSG

Date/Time: 28/12/17 @ 9:05am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJP 81684 Insured: SJT 5628H

at Workshop m/s Hiap Hong Motor Tel: 6745 9633

of 2 kaki Bkt Ave 2 # 02-13 AutoHub

Policy No: P2719 344DMA Claim No: 542512

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement: _____

Date/Time: 9:59am @ 28/12/17 Person Contacted: Mr. Chua

Vehicle IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/> Estimate
	SJP81684-X
	SJT5628H-X
29/12/17	Informed Monica pending est from repairer by merimen
9/1/18	Adrian confirmed LS \$3250 (Red 3869.52, 5470)
10/1/18	Sand; preli revised by merimen

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJP8168U Yr Regn: 2014 JuneType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Harder City C.C. 1497Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 60031 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRH6m6660EP000019Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/55R16R: 195/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 28/12/17Survey held at Hiap HongDes. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPMSlg.

RECEIVED 10 JAN 2018

Date/Time, File Pass to?

 : Preli. Report : Final Report

1)

Date/Time, File Return to?

2) 10/1 - typist

Report Format: MerimenLump Sum / I.B.I: (\$) 3250/2Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$ _____) : Interview (\$ _____) : Tech Invs (\$ _____) : Weekend (\$ _____)

) \$ - RS (\$ _____)

) Photos

) Other

TOTAL

200

10

210

Survey Department Check List (Case Handler)

Reference No.: CS | MSG 170 24605 | Avd3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

		Case Handler		Typist	
		Y-Date	N-Date	Y-Date	N-Date
1) Office Assign Form					
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

		Case Handler		Typist	
		Y-Date	N-Date	Y-Date	N-Date
(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)					
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form					
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)					
C	Resurvey photo Uploaded	✓			

Check By: VERON 10/11/18
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17024605/A/03	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 28-12-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJT 5628H	Veh. Inspected	SJP 8186U
Policy No.	P2719344DMA	Coverage (\$)	0.00
Claim No.	542512	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	28/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			m
L/H Front Tyre			m
R/H Rear Tyre			m
L/H Rear Tyre			m
4. Description of Damages			
5. General Information			
Accident Date	23/12/2017	Inspection Date	28/12/2017
Survey held at	HIAP HONG MOTOR REPAIR 2 KAKI BUKIT AVE 2 #02-13 SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2017		28 Dec 2017 09:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHOONG EK WEI, ID: S1343923J, Tel: +6596550023, Email: jack.choong@yahoo.com.sg								
Main Claimant:	CHOO KWEE LUANG, ID: S1301641J								
Vehicle Reg. No.:	SJP8168U	Date of Loss:	23/12/2017 10:00 - :59						
Claim Type:	TP / 542512	Policy/Cover Note No.:	P27193449DMA (Comprehensive) Coverage: 19/10/2017 - 18/10/2018						
Vehicle Reg. No. (Insured):	SJT5628H	Policy No. (Claimant):							
		Excess:							
Repairer:	- Not Applicable - (-)								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/12/2017]								
Driver/Custodian (Insured):	CHOONG EK WEI (58 / Male), NRIC: S1343923J, Tel: +6596550023								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Monica Chung Pei Zhen	Date: 10 Jan 2018

Preliminary Advice

Insured Vehicle No	: SJT5628H	Accident Date	: 23/12/2017
TP Vehicle No	: SJP8168U	Assignment Date	: 28/12/2017
Make	: HONDA CITY	Est. Duration of Repair	: 6.00
Date of Inspection	: 28/12/2017		
Inspection At	: HIAP HONG MOTOR REPAIR		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,119.52
Revised Amount	:S\$	3,250.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	3,250.00
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

View Sent Message

This mail is associated with :

***SJP8168U (542512)**
[SJT5628H]
TP
CHOO KWEE LUANG
Dec 23 2017 10:00AM
[CHOONG EK WEI]

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 29/12/2017 17:13 PM.
To MSIG_CPZ
Subject TP SURVEY SJP 8168U

Dear Monica,

Please be informed that we have inspected the vehicle SJP 8168U on 28/12/2017.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Nivitha (LKK Auto)

From: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>
Sent: Thursday, 28 December, 2017 9:04 AM
To: 'Tng Soon Chye'; 'Nivitha (LKK Auto)'
Cc: Monica Chung; Rashitha Binte Shahuthuman
Subject: RE: PRI- accident on 23.12.17@1020hours involving sjp8168u & sjt5628h along toa payoh lorong 4

Dear LKK,

Please arrange to survey SJP8168U at Hiap Hong Motor. We will grant rights to you in merimen soon. Thank you .

Rashitha

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msig-asia.com



MSIG



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

From: Tng Soon Chye [mailto:tsclx@singnet.com.sg]
Sent: Thursday, 28 December, 2017 8:46 AM
To: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>
Cc: Monica Chung <Monica_Chung@sg.msig-asia.com>
Subject: RE: PRI- accident on 23.12.17@1020hours involving sjp8168u & sjt5628h along toa payoh lorong 4

Dear Sirs

We refer to your email dated 27 December 2017 to us.

Our client instructs that he agrees to the appointment of M/s LKK Auto Consultants Pte Ltd as the single joint expert for the pre-repair inspection of the vehicle SJP8168U at the workshop, Hiap Hong Motor Repair, situated at 2 Kaki Bukit Avenue 2 #02-13 Auto Hub Singapore 417921 (tel: 67459633).

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you. Our client's rights are hereby expressly reserved.

Thank You & Best Regards

Tng Soon Chye
M/s Tng Soon Chye & Co
150 South Bridge Road

#02-19
Fook Hai Building
Singapore 058727
(Our Ref: TSC.SJP8168U.Accid.2017 (HH)-c)

Confidentiality: This e-mail and its attachments are intended for the above named only and may be confidential. If they have come to you in error you must take no action based on them, nor must you copy or show them to anyone; please reply to this e-mail and highlight the error. The firm reserves the right to monitor all incoming and outgoing e-mail.

Security Warning: Please note that this e-mail has been created in the knowledge that Internet e-mail is not a 100% secure communications medium. We advise that you understand and observe this lack of security when e-mailing us.

Viruses: Although we have taken steps to ensure that this e-mail and attachments are free from any virus, we advise that in keeping with good computing practice the recipient should ensure they are actually virus free.

From: Rashitha Binte Shahuthuman [mailto:rashitha_shahuthuman@sg.msig-asia.com]
Sent: 27 December 2017 13:13
To: 'tscllex@singnet.com.sg' <tscllex@singnet.com.sg>
Cc: Monica Chung <Monica_Chung@sg.msig-asia.com>; Muhd Ashik B Madi <ashik_madi@sg.msig-asia.com>; Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>
Subject: FW: PRI- accident on 23.12.17@1020hours involving sjp8168u & sjt5628h along toa payoh lorong 4

OUR REF - SJT5628H

WITHOUT PREJUDICE

Dear Sirs,

We refer to your fax dated 26/12/2017.

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for any of the above surveyor to be the SJE (Single Joint Expert) .

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

Thank you.

Rashitha

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msig-asia.com



MSIG



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

From: Tng Soon Chye [<mailto:tsclex@singnet.com.sg>]

Sent: 27 December 2017 09:48

To: Claims <claims@sg.msig-asia.com>

Subject: PRI- accident on 23.12.17@1020hours involving sjp8168u & sjt5628h along toa payoh lorong 4

IMMEDIATE ATTENTION

Dear Sirs,

We refer to the above.

We enclose herewith copy of our firm's letter dated 26th December 2017 to MSIG Insurance (Singapore) Pte Ltd for your reference.

Thank You & Best Regards,

Tng Soon Chye
M/s Tng Soon Chye & Co
150 South Bridge Road
#02-19
Fook Hai Building
Singapore 058727
(Our Ref: TSC.SJP8168U.Accid.2017 (HH))

Confidentiality: This e-mail and its attachments are intended for the above named only and may be confidential. If they have come to you in error you must take no action based on them, nor must you copy or show them to anyone; please reply to this e-mail and highlight the error. The firm reserves the right to monitor all incoming and outgoing e-mail.

Security Warning: Please note that this e-mail has been created in the knowledge that Internet e-mail is not a 100% secure communications medium. We advise that you understand and observe this lack of security when e-mailing us.

Viruses: Although we have taken steps to ensure that this e-mail and attachments are free from any virus, we advise that in keeping with good computing practice the recipient should ensure they are actually virus free

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any

湯順才律師樓
TNG SOON CHYE & CO.

ADVOCATES & SOLICITORS
NOTARY PUBLIC
COMMISSIONER FOR OATHS
UEN NO: 53131141D

POSTED

F A X E D
DATE: _____

150 South Bridge Road #02-19 Fook Hai Building Singapore 058727
Tel: 6438 3133 • Fax: 6438 6066

(Service of Court documents via fax is not acceptable)

26 DEC 2017

Our Ref: TSC.SJP8168U.Accid.2017 (HH)-c
Your Ref: SJT5628H

26th December 2017

M/S MSIG INSURANCE (SINGAPORE) PTE LTD
Motor Claim Department
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
(Insurer of vehicle no. SJT5628H)

URGENT ATTENTION
By Fax/Email/Hand
(Fax: 6225 6371)
(email: claims@sg.msig-asia.com)

cc. to:

CHOONG EK WEI
102 Cowdray Avenue
Singapore 558103
(Owner of vehicle no. SJT5628H)

By Certificate of Posting

Dear Sirs,

**ACCIDENT ON 23rd DECEMBER 2017 @ 1020HRS INVOLVING MOTOR-VEHICLES
NOS. SJP8168U & SJT5628H ALONG TOA PAYOH LORONG 4**

We are instructed by Choo Kwee Luang to notify you of a road traffic accident on 23rd December 2017 at about 1020hrs along Toa Payoh Lorong 4 involving our client's vehicle registration number SJP8168U and vehicle registration number SJT5628H driven by your insured driver at the material time. A copy of the Singapore accident statement/ traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days** of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle at 2 Kaki Bukit Avenue 2 #02-13 Auto Hub Singapore 417921.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you. Our client's rights are hereby expressly reserved.

Yours faithfully

Tng Soon Chye
enc

cc. client – via fax: 6747 8602 only
(ref: SJP8168U)

Hiap Hong Motor Repair

Blk 2 Kaki Bukit Ave 2#02-13 Singapore 417921

Tel: 6745 9633 Fax: 6747 8602 Email: hiap.hong.motor@gmail.com

Company Reg. No. 42051700-J

Date: 26 December 2017

The Motor Claims Department
MSIG Insurance (Singapore) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 06887
Fax: +65 6225 6371)

Yecan

REPAIR QUOTATION FOR SJP8168U HONDA CITY 1.5 SV CVT

	Qty	(\$)	Discount	(\$)
LH rear door <i>dent</i>	1	906.80	20%	725.44
LH rear door hinge <i>Lower Bolt</i>	2	88.00	20%	70.40 <i>35.20</i>
LH rear door sash pillar black sticker set <i>me</i>	1	51.80	20%	41.44
LH rear door inner lock <i>me</i>	1	252.20	20%	201.76 <i>+</i>
LH rear door glass regulator c/w motor <i>3rd</i>	1	390.20	20%	312.16 <i>2</i>
LH rear door weatherstrip <i>me</i>	1	112.10	20%	89.68
LH rear door checker <i>me</i>	1	46.70	20%	37.36 <i>+</i>
LH rocker panel garnish <i>2yr</i>	1	420.60	20%	336.48 <i>+</i>
LH rocker panel garnish clip <i>me</i>	12	45.60	20%	36.48 <i>+</i>
LH front door <i>Dented</i>	1	906.80	20%	725.44
LH front door inner lock <i>Damaged</i>	1	268.70	20%	214.96
LH front door sash pillar black sticker set <i>me</i>	1	48.10	20%	38.48
LH front door glass regulator c/w motor <i>me</i>	1	397.20	20%	317.76 <i>+</i>
LH front door weatherstrip <i>me</i>	1	112.10	20%	89.68
LH door centre pillar <i>2yr</i>	1	615.00	20%	492.00 <i>x</i>
Total Cost of parts				3,729.52

2272.48

LABOUR

To check door wiring and central locking system functions.	60.00 <i>30</i>
To remove, transfer and install front door glass.	90.00 <i>80</i>
To remove, transfer and install rear door glass.	90.00 <i>80</i>
To apply anti-rust undercoating.	150.00 <i>50</i>
Labour charges to remove and replace, to cut and weld, to knock and reshape affected parts/areas.	1,500.00 <i>700</i>
Spray painting charges to putty and spray all affected parts/areas front door, rear door, rocker panel, rear fender, door centre pillar, etc.	1,500.00 <i>850</i>

Total Cost of labour 3,390.00

Total Repair Cost 7,119.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To ~~inspect~~ (damaged parts) during resurvey.
- Parts prices are subject to confirmation.
- Third party survey is on a 'Without Prejudice' basis.

Chua Meng Liang (Signature) is allowed

- Supplementary items must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer:
Signature:
Date:

Yours faithfully

Adrian Lj
28/12/17
H/S obdnp

total: 4062.48
H/S 3250

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024605/AVD3N2
Date: 11/01/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	P27193449DMA
Claimant Vehicle No :	SJP8168U	Insured Vehicle No :	SJT5628H
Date of Loss:	23/12/2017	Nature of Claim:	TP
			Claim No: 542512

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP8168U	Engine No:	L15Z11400953
Make & Model:	HONDA CITY, 1.5 CVT (A)	Chassis No:	MRHGM6660EP000019
Reg. Date:	03/06/2014 (Man. Year: 2014)	Odometer:	60031 km
Colour:	Brown		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55R16	Rear Tyre Size:	195/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,729.52	2,272.48	1,457.04	39.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,390.00	1,790.00	1,600.00	47.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,119.52	4,062.48	3,057.04	42.94
Approved Total (Overridden) (S\$)		3,250.00		
Nett Amount (S\$)	7,119.52	3,250.00	3,869.52	54.35

INSPECTION

Date of Assignment:	28/12/2017		
Date Inspected:	28/12/2017	Inspected At:	HIAP HONG MOTOR REPAIR 2 KAKI BUKIT AVE 2 #02-13 SINGAPORE 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2018)
Parts: 143	HONDA CITY 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJP8168U)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR DOOR	Dented	906.80 FL	*906.80 FL
2	2		*LH REAR DOOR HINGE	Lower Bent	88.00 FL	*44.00 FL
3	1		*SET LH REAR DOOR SASH PILLAR BLACK STICKER	Necessary	51.80 FL	*51.80 FL
4	1		*LH REAR DOOR INNER LOCK	Not Necessary	252.20 FL	*- FL
5	1		*LH REAR DOOR GLASS REGULATOR C/W MOTOR	Damaged	390.20 FL	*390.20 FL
6	1		*LH REAR DOOR WEATHERSTRIP	Necessary	112.10 FL	*112.10 FL
7	1		*LH REAR DOOR CHECKER	Not Necessary	46.70 FL	*- FL
8	1		*LH ROCKER PANEL GARNISH	Repair	420.60 FL	*- FL
9	12		*LH ROCKER PANEL GARNISH CLIP	Not Necessary	45.60 FL	*- FL
10	1		*LH FRONT DOOR	Dented	906.80 FL	*906.80 FL
11	1		*LH FRONT DOOR INNER LOCK	Damaged	268.70 FL	*268.70 FL
12	1		*SET LH FRONT DOOR SASH PILLAR BLACK STICKER	Necessary	48.10 FL	*48.10 FL
13	1		*LH FRONT DOOR GLASS REGULATOR C/W MOTOR	Not Necessary	397.20 FL	*- FL
14	1		*LH FRONT DOOR WEATHERSTRIP	Necessary	112.10 FL	*112.10 FL
15	1		*LH DOOR CENTRE PILLAR	Repair	615.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,661.90	2,840.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	932.38	568.12
Total Parts (\$\$)	3,729.52	2,272.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK DOOR WIRING AND CENTRAL LOCKING SYSTEM FUNCTIONS	New	60.00	30.00
2	TO REMOVE,TRANSFER AND INSTALL FRONT DOOR GLASS	New	90.00	80.00
3	TO REMOVE,TRANSFER AND INSTALL REAR DOOR GLASS	New	90.00	80.00
4	TO APPLY ANTI-RUST UNDERCOATING	New	150.00	50.00
5	LABOUR CHARGES TO REMOVE AND REPLACE,TO CUT AND WELD,TO KNOCK AND RESHAPE AFFECTED PARTS/AREAS	New	1,500.00	700.00
6	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY ALL AFFECTED PARTS/AREAS FRONT DOOR,REAR DOOR,ROCKER PANEL,REAR FENDER,DOOR CENTRE PILLAR,ETC	New	1,500.00	850.00
Gross Labour Cost (\$\$)			3,390.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >