

ASS. REC. BY:

REF: CS3/AIG17024607/Sd3e2

Special Instruction:

DAR & days

Surveyor: Sebastian

ASSIGNMENT (Office)

From (Person): Chin Lee Yingof AIGDate/Time: 9:18am @ 28/12/17

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFT 31JInsured: GBG 595Pat Workshop m/s: Oscarma Global AutomotiveTel: 9117 0086of 71 Woodland Ave 10 # 02-09

Policy No:

Claim No: 9382783736SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/12/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 9:49am @ 28/12/17

Person Contacted:

Mr. LimVehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SFT 31J - X</u>
	<u>GBG 595P - X</u>
	<u>Dismantle: 2/1/2018</u>

REF: AIG

ASSIGNMENT

From: Date: 28/12/17

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFT 317

at Workshop m/s: Oscarma Global Automobile
of 71 woodland Ave 10 #02-09 737743

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

1w

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SFT 317

Vr Regn: 28/5/2012

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 640i

o.c. 2979

Colour: White

A/C Insured / Std / NI / NA

Sp. Reading: 100529

T/Pack: Insured / Std / NI / NA

Eng/No:

C/No: WBSHLW32070C799068

Gen. Cond: Good / ~~Bad~~ / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: ~~STD~~ / S/Rim / STD A/Rim or

Tyre Size: F: 245/35ZR20

R: 285/30 ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / ~~MO~~ / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 22/12/2017

D.O.A. 28/12/2017.

Survey held at: Oscarma

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/10 Submit DAR report.

RECEIVED 16 APR 2018

Date/Time: File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1.

☐ : Final Report

Resurvey No. of Trip: 1

Survey Fee:

Date/Time: File Return to?

Transportation:

2.

Add Fee: ☐ : Site Insp. \$

\$ - \$ - \$

☐ : Interview \$

Photos

☐ : Tech. Insp. \$

Other

☐ : Weekend \$

Report Format: DAR

Lump Sum / L.B. / S:

TOTAL

180

20

200

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE GBG595P AND SFT31J ON 22/12/2017**

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: Thursday, 28 December, 2017 9:18:15 AM
Attachments:  GBG595P.TIF  3878_001.pdf  3931_001.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI DIO MUNIANDY
SEGA PARAM
TIWARY ANURADHA
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
SELWYN TAN YINGXIAN

Unique Entity Number: 200721148H

✓HEAD OFFICE

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
✓: (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawllc.com

BRANCH

TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: SFT 31 J (SI)
Your Ref: 9382783736SG003

27 December 2017

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120
[Attention : Motor Claim Department]

BY EMAIL ONLY
<yokeshi.chan@aig.com>

Dear Sirs,

ACCIDENT INVOLVING MOTOR VEHICLE SFT 31 J & GBG 595 P ON 22 DECEMBER 2017 AT JURONG WEST ST 91 (BLK 949) CARPARK ABOUT 0900 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email of even date informing that you wish to conduct a pre-repair survey and to your List of Surveyors.

TAKE NOTICE that we are instructed to object to all your surveyors stated in your said List for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we propose Constant Appraiser Services as the Single Joint Expert.

Please reply within 2 working days.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

cc: SFT 31 J – By email only

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI DIO MUMANDY
SEGA PARAM
TIWARY ANURADHA
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAY
JANICE HAN JIA LIN
SELWYN TAN YINGXIAN

Unique Entity Number: 200721148H

✓HEAD OFFICE
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
✓: (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawllc.com

BRANCH

TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER.

Our Ref: SFT 31 J (SI)
Your Ref: SGBG 595 P

27 December 2017

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120
[Attention : Motor Claim Department]

BY FAX (6415 3727) & EMAIL
<shenyang.lim@aig.com>

Dear Sirs,

ACCIDENT INVOLVING MOTOR VEHICLE SFT 31 J & GBG 595 P ON 22 DECEMBER 2017 AT JURONG WEST ST 91 (BLK 949) CARPARK ABOUT 0900 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We are instructed by LIM SIEW HENG to notify you of a road traffic accident on 22 DECEMBER 2017 AT JURONG WEST ST 91 (BLK 949) CARPARK ABOUT 0900 HOURS involving our client's vehicle registration number SFT 31 J and vehicle registration number GBG 595 P driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

cc: SFT 31 J - By email only

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
TIWARY ANURADHA
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
SELWYN TAN YINGXIAN

Unique Entity Number: 200721148H

✓HEAD OFFICE

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
✓: (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawllc.com

BRANCH

TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: SFT 31 J (SI)
Your Ref: 9382783736SG003

27 December 2017

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120
[Attention : Motor Claim Department]

BY EMAIL ONLY
<yokeshi.chan@aig.com>

Dear Sirs,

ACCIDENT INVOLVING MOTOR VEHICLE SFT 31 J & GBG 595 P ON 22 DECEMBER 2017 AT JURONG WEST ST 91 (BLK 949) CARPARK ABOUT 0900 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email of even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle can be inspected on Monday 11 December 2017 at:

Venue : OSCARMA GLOBAL AUTOMOBILE
71 Woodland Avenue 10
#02-09 Woodland Industrial XChange
Singapore 737743
Contact Person : Ah Xiang @ 9117 0086 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

cc: SFT 31 J - By email only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

CONFIDENTIALITY
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

From Fiction

Battery Bracket

Vehicle No. SFT 31J

- * 5 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Apr 2018 Edit Reg		28 Dec 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by adjuster]			
Insured:	MECTRON ENGINEERING PTE LTD , Co. Reg. No.: -					
Main Claimant:	LIM SIEW HENG					
Vehicle Reg. No.:	SFT31J	Date of Loss:	22/12/2017 00:00 - :59 [66 Months and 24 Days From LTA Reg Date (Man Yr)]			
Claim Type:	TP / 9382783736SG	Policy/Cover Note No.:	(Comprehensive)			
Vehicle Reg. No. (Insured):	GBG595P	Policy No. (Claimant):				
		Excess:				
Repairer:	Oscarma Global Automotive (HQ) 71 Woodlands Avenue 10, #02-07 Woodlands Industrial Xchange, 737743 Woodlands - Tel:					
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 12/04/2018]					
Claimant's Solicitor:	VISION LAW LLC - Tel: 65342811					

ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
AIG_SG (04/04/2018): TP GIA REPORT				

ALL ASSOCIATED TASKS			View All	Search Tasks	Create New Task	Complete			
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFT31J (9382783736SG)**
[GBG595P]
TP
LIM SIEW HENG
Dec 22 2017 12:00AM
[MECTRON ENGINEERING PTE LTD]
Oscarma Global Automotive

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/18 16:35	General View	 Load JPG	☒
2	03/04/18 16:35	General View	 Load JPG	☒
3	03/04/18 16:35	General View	 Load JPG	☒
4	03/04/18 16:35	General View	 Load JPG	☒
5	03/04/18 16:35	General View	 Load JPG	☒
6	03/04/18 16:35	General View	 Load JPG	☒
7	03/04/18 16:35	General View	 Load JPG	☒
8	03/04/18 16:35	General View	 Load JPG	☒
9	03/04/18 16:35	General View	 Load JPG	☒
10	03/04/18 16:35	General View	 Load JPG	☒
11	03/04/18 16:35	General View	 Load JPG	☒
12	03/04/18 16:35	General View	 Load JPG	☒
13	03/04/18 16:35	General View	 Load JPG	☒
14	03/04/18 16:35	General View	 Load JPG	☒
15	03/04/18 16:35	General View	 Load JPG	☒
16	03/04/18 16:35	General View	 Load JPG	☒
17	03/04/18 16:35	General View	 Load JPG	☒
18	03/04/18 16:35	General View	 Load JPG	☒
19	03/04/18 16:35	General View	 Load JPG	☒
20	03/04/18 16:35	General View	 Load JPG	☒
21	03/04/18 16:35	General View	 Load JPG	☒
22	03/04/18 16:35	General View	 Load JPG	☒
23	03/04/18 16:35	Chassis Number	 Load JPG	☒
24	03/04/18 16:35	Odometer Reading	 Load JPG	☒
25	03/04/18 16:35	General View	 Load JPG	☒
26	03/04/18 16:35	General View	 Load JPG	☒
27	03/04/18 16:35	General View	 Load JPG	☒
28	03/04/18 16:35	General View	 Load JPG	☒
29	03/04/18 16:35	General View	 Load JPG	☒
30	12/04/18 18:27	Photographs of Damaged Parts	 Load JPG	☒
31	12/04/18 18:27	Photographs of Damaged Parts	 Load JPG	☒
32	12/04/18 18:27	Photographs of Damaged Parts	 Load JPG	☒
33	12/04/18 18:27	Photographs of Damaged Parts	 Load JPG	☒
34	12/04/18 18:27	Photographs of Damaged Parts	 Load JPG	☒
35	12/04/18 18:27	Photographs of Damaged Parts	 Load JPG	☒
36	12/04/18 18:27	Photographs of Damaged Parts	 Load JPG	☒
37	12/04/18 18:27	Photographs of Damaged Parts	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
39	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
40	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
41	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
42	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
43	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
44	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
45	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
46	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
47	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
48	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
49	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
50	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
51	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
52	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
53	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
54	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
55	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
56	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
57	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
58	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
59	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
60	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
61	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
62	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
63	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
64	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
65	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
66	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
67	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
68	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
69	12/04/18 18:27	Photographs of Damaged Parts	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/04/18 14:58	OI GIA REPORT	Load PDF	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17024607/SD3E2

Date: 17/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SFT31J

Insured Vehicle No : GBG595P

Date of Loss: 22/12/2017

Nature of Claim: TP Claim No: 9382783736SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFT31J

Make & Model: BMW 640i, 3.0 (A)

Engine No: HIDDEN

Reg. Date: 28/05/2012 (Man. Year: 2012)

Chassis No: WBALW32070C799068

Colour: White

Odometer: 100329 km

Engine Capacity: 2979 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35Z R20

Rear Tyre Size: 285/30Z R20

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/12/2017

Date Inspected: 28/12/2017 Inspected At:

71 Woodland Ave 10 #02-09

Repairer : Oscarma Global Automotive (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Damaged	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER REINFORCEMENT	* Check	0.00 F	*- F
4	1		*FRT BUMPER SPONGE	Torn	0.00 F	*- F
5	1		*FRT BUMPER LOWER SPOILER	Broken	0.00 F	*- F
6	1		*FRT BUMPER SENSOR	Shorted	0.00 F	*- F
7	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
8	1		*BONNET	Repair	0.00 F	*- F
9	1		*RADIATOR	Damaged	0.00 F	*- F
10	1		*RADIATOR HOSE BOTTOM	* Check	0.00 F	*- F
11	1		*AIR DUCT	Broken	0.00 F	*- F
12	1		*FRT RH FENDER	Repair	0.00 F	*- F
13	1		*FRT RH FENDER INNER PANEL	* Check	0.00 F	*- F
14	1		*FRT RH FENDER INNER SHIELD	Broken	0.00 F	*- F
15	1		*FRT RH MUDFLAP	Broken	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >