

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA INSURANCE	DATE	: 26/12/2017
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJG1728Y		
MODEL	: HYUNDAI AVANTE 1.6A	Vic	
CHASSIS NO		KMHDAU41BR8u525136.	
<u>ACCIDENT DETAILS</u>		DATE	: 22-Dec-17
		TIME	: 22:10HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 482.20	\$ 482.20
2	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 167.50	\$ 167.50
3	FRONT BUMPER FOGLAMP GARNISH <i>new</i>	1	\$ 89.20	\$ 89.20
4	FRONT BUMPER SIDE RETAINER <i>new</i>	1	\$ 43.60	\$ 43.60
5	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 322.20	\$ 322.20
6	FRONT BUMPER SPONGE <i>new</i>	1	\$ 123.00	\$ 123.00
7	FRONT BUMPER UNDER COVER <i>Not new</i>	1	\$ 190.00	\$ 190.00
8	HEAD LAMP LH <i>new</i>	1	\$ 480.00	\$ 480.00
9	HEAD LAMP LOWER BRACKET LH <i>new</i>	1	\$ 89.00	\$ 89.00
10	FRONT FENDER RH <i>Distorted</i>	1	\$ 450.00	\$ 450.00
11	FRONT FENDER EMBLEM 'VVT' RH <i>new</i>	1	\$ 29.60	\$ 29.60
12	FRONT FENDER INNER COWLING <i>Distorted</i>	2	\$ 95.40	\$ 190.80
13	FRONT DOOR LH <i>new</i>	1	\$ 1,055.20	\$ 1,055.20
14	SUPPORT PANEL <i>new</i>	1	\$ 890.00	\$ 890.00
15	FRONT KNUCLE ARM <i>Best</i>	1	\$ 376.40	\$ 376.40
16	FRONT KNUCLE BEARING <i>new</i>	1	\$ 183.90	\$ 183.90
17	FRONT WHEEL HUP <i>new</i>	1	\$ 192.80	\$ 192.80
18	FRONT SHOCK ABSORBER <i>Best</i>	1	\$ 349.60	\$ 349.60

297.30

19	FRONT LOWER ARM <i>Best</i>	1	\$ 422.30	\$ 422.30
20	FRONT DRIVESHAFT <i>3me</i>	1	\$ 1,679.80	\$ 1,679.80
21	FRONT STEERING RACK AND PINION <i>3me</i>	1	\$ 1,974.60	\$ 1,974.60

4274.40

3419.52

TOTAL PRICE \$ 9,781.70

LESS 20% \$ 1,956.34

SUB TOTAL PRICE \$ 7,825.36

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP(SET) <i>me</i>	1	\$ 20.00	\$ 20.00
2	FRONT BUMPER LOWER LID <i>couled</i>	1	\$ 890.00	\$ 890.00 600.
3	FRONT FENDER SEALANT LH <i>me</i>	1	\$ 80.00	\$ 80.00
4	FRONT FENDER COWLING <i>clips LH</i>	1	\$ 20.00	\$ 20.00
5	FRONT WHEEL TYRE <i>me</i>	1	\$ 450.00	\$ 450.00
6	FRONT WHEEL RIM <i>cl</i>	1	\$ 850.00	\$ 850.00 400.

1040

TOTAL \$ 2,310.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	700.	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	600.	
3	WIRING CHECK	\$ 60.00	30.	
4	REFOCUS HEADLAMP BEAM	\$ 60.00	x	
5	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 320.00	220.	
6	TO PRESS FRONT WHEEL BEARING	\$ 80.00	x	
7	FOUR WHEEL ALIGNMENT	\$ 100.00	30	
8	TO TRANSFER FRONT DOOR FITTING	\$ 150.00	x	

1580

\$3,170.00

1. K Auto Consultants hereby notify the Repairer of the following:

- To disassemble and reassemble parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier's price is subject to final approval from insurance Company

Acknowledged by Repairer

Signature: TOTAL LABOUR COST : \$

Date: TOTAL PARTS COST : \$

TOTAL REPAIR COST : \$

10,135.36

3,170.00

13,305.36

Adrian G
4/5 28/12/17
06 days

total: 6039.52

4/5: 4K

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :