

ASS. REC. BY:

REF: CS/FCI17024619/Kvd307

Special Instruction:

SA/VEH:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person): Serene Ter

of

FCI

Date/Time: 5:19pm @ 27/12/17

Estimated Cost:

Bill to:

OD ☒ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 7168X

Insured:

SHC 3049E

at Workshop m/s

Ahlim Motor

Tel:

64831244

of

10, Amk Ind Park 2A # 01-09

Policy No:

Claim No:

D17011818 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/12/17

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

5:23pm @ 27/12/17

Person Contacted:

Zila

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction () Estimate

SLC 7168X - X

SHC 3049E - CS/FCI14001783/Rvm 3k3

D.O.A. 21/11/2012

29/12/17

Email preli revised to FCI

14/3/18

Kenneth confirmed \$13,498.68 (Red 6572.34, 3270)

Abstract

1163

Survey Department Check List (Case Handler)

Reference No.: CS/FCI No 24619 Kvd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp. Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des. of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 14/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17024619/Kvd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-12-2017		
		Code : FCI2		
1. Policy Particulars - THIRD PARTY CLAIM				
Insured Veh.	SHC 3049E	Veh. Inspected	SLC 7168X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17011818MFSH	Excess (\$)	0.00	
Assign From	CWS (SERENE LER)	Assign Date	28/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Engine No.	HIDDEN	Accident Date	22/12/2017	Inspection Date
		Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047	
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	26-12-2017	Our Ref No. D17011818MFSH
Accident Date	22-12-2017	Claim Type. Third Party
Insured Vehicle	SHC3049E	Third Party Vehicle. SLC7168X
Survey Location	10, ANG MO KIO IND PARK 2A #01-09 AMK AUTOPOINT	
Contact Person.	ZILA	
Contact No.	64831244/ 0	Fax No. 64836170
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AH LIM MOTOR COMPANY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232309)



PRI Documents



Close



PRI Header Details

Claim No	D17011818MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & AH LIM M
Workshop Name	AH LIM MOTOR COMPANY (Contact Person : ZILA)	Survey Location & Contact Details	10, ANG MO KIO IND PARK 2A #01-09 AMK AUTOPOINT Mobile: 0 , Phone: 64831244 , Fax: 64836170 EmailId: ZILA@AHLIMMOTOR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3049E	TP Vehicle No	SLC7168X
PRI Recieved Date	27-12-2017 05:37:31 PM	Surveyor Appointed Date	27-12-2017 05:18:24 PM	Surveyor Accept Date	28-12-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-12-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name	Action
-----------	--------

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 29 December, 2017 2:11 PM
To: 'Claim Workflow System'
Cc: SERENELER@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011818MFSH/1, SLC 7168X
Attachments: SLC 7168X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLC 7168X
Date of survey: 28/12/2017
Number of days:9 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 28 December, 2017 9:19 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011818MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

"Wishes you a Happy New Year 2018"

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 27 December, 2017 5:18 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SERENELER@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011818MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17011818MFSH
Our ref: CS/FCI17024619/Kvd3

Date : 29/12/2017

The Motor Claims Department
M/s First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLC 7168X


We thank for your instruction on 27/12/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28/12/2017 at the premises of M/s AH LIM MOTOR CO and have the following to report:-

Workshop Estimate Amount	: S\$19,621.17
Revised Estimate Amount	: S\$12,431.41
"Check" Items Amount	: S\$3,380.56
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s and front n/s portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3673B

Vehicle Details

Vehicle No.: SLC7168X

Vehicle to be Exported: No

Intended De-registration
Date: 23 Dec 2017

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 CVT

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 1ZRY279545

Chassis No.: MR053REH104549216

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$19,990.00

Original Registration Date: 24 May 2016

First Registration Date: 24 May 2016

Transfer Count: 0

Actual ARF Paid: \$19,990.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 23 May 2026

PARF Rebate Amount: \$14,992.00

Intended COE Rebate Details

COE Expiry Date: 23 May 2026

COE Category: A - Car up to 1600cc &
97kW (130bhp)

COE Period(Years): 10

QP Paid: \$47,020.00

COE Rebate Amount: \$39,575.00

Total Rebate Amount: \$54,567.00


The information contained herein is correct as at 23 Dec 2017

OK

Sketch Plan Pg. 4



82824056





D/C

NO reg. no.

9092350

414x



NP 428A



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/12/2017 11:49
Date Of Accident	22/12/2017 14:40
Exact Location Of Accident	AMK AVE 5 & YIO CHU KANG JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC7168X
Insured/Policyholder	
Name Of Registered Owner	WU XIAODONG
NRIC No	S8083673B
Email Address	DADONGWU@ICLOUD.COM
Mobile Phone No	(LOCAL) +65-90923520
Alternative Phone No	OTHERS-82824056

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00401894
Cover Note Number	07/09/2017 - 06/09/2018

Driver

Name of Driver	HE YUEMEI
NRIC No	S8280089A
Date Of Birth	03/12/1982
Occupation	INDOOR
Date Of Driving Pass	21/02/2014
Driving Experience	3 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-82824056
Fax Number	
Contact Number	OTHERS-90923520
Email Address	YUEMEIHE@GMAIL.COM

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHA7777X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name


Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 2

Date of accident: 22-Dec-2017 Time: 2:43 pm Location: Ang MOKIO Ave 5 & Yio Chu Kang Jundu
 My Vehicle A: SLC 7168X Vehicle B: SHA 7777X Vehicle C: SHC 3049E

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The accident happened at Ang MOKIO AVE 5, Date 1 & 2

I was changing lane from lane 1 to lane 2. Car B suddenly stopped. So I hit the back (right side) of Car B and Car C, who was behind me hit onto my car.

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop :

Email address :

& myself :

Email address : yue mei he @ g mail. com

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

AH LIM MOTOR COMPANY



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : WU XIAODONG
47A EDGEFIELD PLAINS
#15-19 WATERBAY
SINGAPORE 828714
TEL: 82824056
ATTN:

Estimate No: MC0912700
Date: 26 Dec 2017
Policy No: MT/00401894
Veh Reg No: SLC7168X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT

Your Ref No: SLC7168X
Claim Type: Third Party (from cap)
Accident Date: 22/12/2017
TP Veh Reg No: SHC3049E

Not Authorized
1-B1
Recovery B4 point 9 days

Estimate Repair Cost to Vehicle No :SLC7168X

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR BOOT EMBLEM	1 PC	nn 52.80	X
2 REAR BOOT LOGO (ALTIS) RH	1 PC	nn 47.20	X
3 REAR BOOT LOGO (COROLLA) RH	1 PC	nn 44.13	X
4 REAR BUMPER	1 PC	Bu 496.50	✓
5 REAR BUMPER SIDE RETAINERS RH	1 PC	D1 114.70	✓
6 REAR BUMPER RETAINERS CTR RH	1 PC	89.20	?
7 REAR BUMPER CLIPS	12 PC	nn 46.68	✓
8 REAR BUMPER LOWER REFLECTOR RH	1 PC	CM 81.64	✓
9 REAR BUMPER REINFORCEMENT	1 PC	R 396.60	✓
10 REAR BUMPER REINFORCEMENT BRACKET RH	1 PC	R 89.45	✓
11 TAILAMP RH	1 PC	nn 365.33	X
12 TAILAMP CLIPS RH	3 PC	nn 12.60	X
13 REAR FENDER COWLING RH	1 PC	72.90	?
14 REAR FENDER COWLING CLIPS	10 PC	32.10	?
15 REAR REVERSE SENSOR	2 PC	423.22	?
16 FRONT BONNET	1 PC	R 1,140.40	✓
17 FRONT BONNET HINGE LH & RH	2 PC	R 142.60	X
18 FRONT BONNET INSULATOR CLIPS	8 PC	nn 25.68	✓
19 FRONT BONNET INNER LOCK	1 PC	R 129.70	X
20 FRONT GRILLE ASSY	1 PC	nn 564.00	✓
21 FRONT GRILLE CLIPS	8 PC	nn 25.68	✓
22 HEADLAMP WITH HID LH & RH	2 PC	5,632.02	✓
23 HEADLAMP TOP CHROME LH & RH	2 PC	nn 356.04	✓
24 HEADLAMP CLIPS	4 PC	nn 12.84	✓
25 FRONT BUMPER	1 PC	R 521.20	✓
26 FRONT BUMPER SIDE RETAINER	2 PC	151.60	4
27 FRONT BUMPER CLIPS	12 PC	nn 46.68	✓
28 FRONT BUMPER LOWER AIR GRILLE CTR	1 PC	nn 178.02	4 ?
29 FRONT BUMPER REINFORCEMENT	1 PC	411.60	?
30 FRONT BUMPER REINFORCEMENT BRACKET LH	1 PC	R 115.70	X
31 FRONT BUMPER SPONGE	1 PC	CM 97.40	✓
32 FRONT BUMPER LOWER COVER CTR	1 PC	nn 178.90	X
33 FOGLAMP LH	1 PC	226.73	?
34 FOGLAMP COVER BLACK OUTER LH	1 PC	nn 96.33	✓
35 FRONT FENDER LH	1 PC	Bu 858.00	✓
36 FRONT FENDER COWLING LH	1 PC	D1 195.60	✓
37 FRONT FENDER COWLING CLIPS	10 PC	nn 32.10	✓



cls 11/12/17

NIS Bu

NIS CM



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : WU XIAODONG
47A EDGEFIELD PLAINS
#15-19 WATERBAY
SINGAPORE 828714
TEL: 82824056
ATTN:

Estimate No: MC0912700
Date: 26 Dec 2017
Policy No: MT/00401894
Veh Reg No: SLC7168X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT

Your Ref No: SLC7168X
Claim Type: Third Party
Accident Date: 22/12/2017
TP Veh Reg No: SHC3049E

Estimate Repair Cost to Vehicle No :SLC7168X

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
38 FRONT FENDER LOGO (VVT-I)	2 PC	Me 103.20	4
39 RADIATOR SUPPORT PANEL	1 PC	Bu 1,075.98	✓
40 BRACE PANEL	1 PC	n 115.90	X
41 AIR CON CONDENSER	1 PC	1,389.70	?
42 RADIATOR ASSY	1 PC	1,510.90	?
43 RESONATOR TANK LH	1 PC	cm 165.30	✓
44 RESONATOR TANK HOSE	1 PC	du 211.61	✓
45 GEARBOX LOWER COVER LH	1 PC	156.30	?
46 GEARBOX LOWER COVER CLIPS	6 PC	16.74	?
47 FRONT WHEELHOUSE INNER SIDE BRACKET LH	1 PC	Bu 98.72	✓
		18,348.22	
	Less 25%	4,587.06	13,761.17

Special Nett

48 RADIATOR COOLANT	1 PC	Me 35.00	20.00
49 NUMBER PLATE	1 PC	Sn 35.00	X
		70.00	70.00

LABOUR

50 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20
51 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	na 80.00	X
52 TO REMOVE AND REFIT ENGINE ASSEMBLY WITH TRANSMISSION TO FACILITATE REPAIR.	1 PC	nn 380.00	X
53 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS - FRONT FENDER LH & FRONT CHASSIS FRAME LH.	1 PC	90 150.00	
54 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL,FRONT BUMPER REINFORCEMENT & BRACKET LH.TO KNOCK & REPAIR FRONT DOOR LH,FRT FENDER RH,FRT WHEELHOUSE, FRONT CHASSIS FRAME & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,600.00	700
55 TO SPRAY FRT BONNET,FRT BUMPER,FRONT BUMPER REINFORCEMENT & BRACKET LH,FRONT FENDER LH & RH,FRONT DOOR LH,RADIATOR SUPPORT PANEL, FRONT CHASSIS FRAME LH & RH, FRONT WHEELHOUSE LH & RH.	1 PC	1,400.00	1000
56 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20
57 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	50





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : WU XIAODONG
47A EDGEFIELD PLAINS
#15-19 WATERBAY
SINGAPORE 828714
TEL: 82824056
ATTN:

Estimate No: MC0912700
Date: 26 Dec 2017
Policy No: MT/00401894
Veh Reg No: SLC7168X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT

Your Ref No: SLC7168X
Claim Type: Third Party
Accident Date: 22/12/2017
TP Veh Reg No: SHC3049E

Estimate Repair Cost to Vehicle No :SLC7168X

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
58 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS - END PANEL,SPARE TYRE PANEL,REAR CHASSIS FRAME RH.	1 PC	200.00	X
59 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR BUMPER REINFORCEMENT & BRACKET RH.TO KNOCK & REPAIR END PANEL,SPARE TYRE PANEL, REAR CHASSIS FRAME RH,REAR BOOT,REAR FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	450
60 TO SPRAY REAR BOOT,REAR BUMPER,REAR BUMPER REINFORCEMENT & BRACKET RH,END PANEL,SPARE TYRE PANEL,REAR CHASSIS FRAME RH,REAR FENDER RH.	1 PC	900.00	600
61 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	120.00	100
		5,790.00	5,790.00
		Total	S\$ 19,621.17
		Add GST @ 7%	1,373.48
		Total Amount Payable	S\$ 20,994.65

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND NINE HUNDRED NINETY FOUR AND CENTS SIXTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORIZED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: WU XIAODONG
47A EDGEFIELD PLAINS
#15-19 WATERBAY
SINGAPORE 828714
TEL: 82824056
ATTN:

Estimate No: MC0912700
Date: 26 Dec 2017
Policy No: MT/00401894
Veh Reg No: SLC7168X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT

Your Ref No: SLC7168X
Claim Type: Third Party
Accident Date: 22/12/2017
TP Veh Reg No: SHC3049E

LKK Auto

Kenner

p.B.P

Not Notified

17.30pm 1.B.1

Recovery Bt Pering

9 days

Estimate Repair Cost to Vehicle No :SLC7168X

Description	Quantity	List Price SS	Amount SS
SPARE PARTS			
1 REAR BOOT EMBLEM	1 PC	52.80	X
2 REAR BOOT LOGO (ALTIS) RH	1 PC	47.20	X
3 REAR BOOT LOGO (COROLLA) RH	1 PC	44.13	X
4 REAR BUMPER	1 PC	496.50	✓
5 REAR BUMPER SIDE RETAINERS RH	1 PC	114.70	✓
6 REAR BUMPER RETAINERS CTR RH	1 PC	89.20	X
7 REAR BUMPER CLIPS	12 PC	46.68	✓
8 REAR BUMPER LOWER REFLECTOR RH	1 PC	81.64	✓
9 REAR BUMPER REINFORCEMENT	1 PC	396.60	✓
10 REAR BUMPER REINFORCEMENT BRACKET RH	1 PC	89.45	✓
11 TAILAMP RH	1 PC	365.33	X
12 TAILAMP CLIPS RH	3 PC	12.60	X
13 REAR FENDER COWLING RH	1 PC	72.90	X
14 REAR FENDER COWLING CLIPS	10 PC	32.10	X
15 REAR REVERSE SENSOR	2 PC	423.22	✓
16 FRONT BONNET	1 PC	1,140.40	✓
17 FRONT BONNET HINGE LH & RH	2 PC	142.60	X
18 FRONT BONNET INSULATOR CLIPS	8 PC	25.68	✓
19 FRONT BONNET INNER LOCK	1 PC	129.70	X
20 FRONT GRILLE ASSY	1 PC	564.00	✓
21 FRONT GRILLE CLIPS	8 PC	25.68	✓
22 HEADLAMP WITH HID LH & RH	2 PC	5,632.02	✓
23 HEADLAMP TOP CHROME LH & RH	2 PC	356.04	✓
24 HEADLAMP CLIPS	4 PC	12.84	✓
25 FRONT BUMPER	1 PC	521.20	✓
26 FRONT BUMPER SIDE RETAINER	2 PC	151.60	✓
27 FRONT BUMPER CLIPS	12 PC	46.68	✓
28 FRONT BUMPER LOWER AIR GRILLE CTR	1 PC	178.02	X
29 FRONT BUMPER REINFORCEMENT	1 PC	411.60	X
30 FRONT BUMPER REINFORCEMENT BRACKET LH	1 PC	115.70	X
31 FRONT BUMPER SPONGE	1 PC	97.40	✓
32 FRONT BUMPER LOWER COVER CTR	1 PC	178.90	X
33 FOGLAMP LH	1 PC	226.73	X
34 FOGLAMP COVER BLACK OUTER LH	1 PC	96.33	✓
35 FRONT FENDER LH	1 PC	858.00	✓
36 FRONT FENDER COWLING LH	1 PC	195.60	✓
37 FRONT FENDER COWLING CLIPS	10 PC	32.10	✓



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY


M/S : WU XIAODONG
47A EDGEFIELD PLAINS
#15-19 WATERBAY
SINGAPORE 828714
TEL: 82824056
ATTN:

Estimate No: MC0912700
Date: 26 Dec 2017
Policy No: MT/00401894
Veh Reg No: SLC7168X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT

Your Ref No: SLC7168X
Claim Type: Third Party
Accident Date: 22/12/2017
TP Veh Reg No: SHC3049E

Estimate Repair Cost to Vehicle No :SLC7168X

Description	Quantity	List Price	Amount
38 FRONT FENDER LOGO (VVT-1)	1/2 PC	103.20	SS
39 RADIATOR SUPPORT PANEL	1 PC	1,075.98	SS
40 BRACE PANEL	1 PC	115.90	X
41 AIR CON CONDENSER	1 PC	1,389.70	X
42 RADIATOR ASSY	1 PC	1,510.90	X
43 RESONATOR TANK LH	1 PC	165.30	—
44 RESONATOR TANK HOSE	1 PC	211.61	—
45 GEARBOX LOWER COVER LH	1 PC	156.30	X
46 GEARBOX LOWER COVER CLIPS	6 PC	16.74	X
47 FRONT WHEELHOUSE INNER SIDE BRACKET LH	1 PC	98.72	X
		18,348.22	
	Less 25%	4,587.06	13,761.17
Special Nett			
48 RADIATOR COOLANT	1 PC	35.00	20.00
49 NUMBER PLATE	1 PC	35.00	X
		70.00	70.00
LABOUR			
50 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20.00
51 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	X
52 TO REMOVE AND REFIT ENGINE ASSEMBLY WITH TRANSMISSION TO FACILITATE REPAIR.	1 PC	380.00	X
53 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS - FRONT FENDER LH & FRONT CHASSIS FRAME LH.	1 PC	150.00	90.00
54 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD RADIATOR SUPPORT PANEL, FRONT BUMPER REINFORCEMENT & BRACKET LH TO KNOCK & REPAIR FRONT DOOR LH, FRT FENDER RH, FRT WHEELHOUSE, FRONT CHASSIS FRAME & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,600.00	700.00
55 TO SPRAY FRT BONNET, FRT BUMPER, FRONT BUMPER REINFORCEMENT & BRACKET LH, FRONT FENDER LH & RH, FRONT DOOR LH, RADIATOR SUPPORT PANEL, FRONT CHASSIS FRAME LH & RH, FRONT WHEELHOUSE LH & RH.	1 PC	1,400.00	1,000.00
56 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20.00
57 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	50.00





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : WU XIAODONG
47A EDGEFIELD PLAINS
#15-19 WATERBAY
SINGAPORE 828714
TEL: 82824056
ATTN:

SURVEYOR COPY

Estimate No: MC0912700
Date: 26 Dec 2017
Policy No: MT/00401894
Veh Reg No: SLC7168X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT

Your Ref No: SLC7168X
Claim Type: Third Party
Accident Date: 22/12/2017
TP Veh Reg No: SHC3049E

Estimate Repair Cost to Vehicle No :SLC7168X

Description	Quantity	List Price	Amount
58 TO SPRY-ANTI-RUST-COATING ON-AFFECTED AREAS- END PANEL,SPARE TYRE PANEL,REAR CHASSIS FRAME RH.	1 PC	200.00	200.00
59 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR BUMPER REINFORCEMENT & BRACKET RH.TO KNOCK & REPAIR END PANEL,SPARE TYRE PANEL, REAR CHASSIS FRAME RH,REAR BOOT,REAR FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	800.00
60 TO SPRAY REAR BOOT,REAR BUMPER,REAR BUMPER REINFORCEMENT & BRACKET RH,END PANEL,SPARE TYRE PANEL,REAR CHASSIS FRAME RH,REAR FENDER RH.	1 PC	900.00	900.00
61 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	120.00	120.00
		5,790.00	5,790.00
	Total		S\$ 19,621.17
	Add GST @ 7%		1,373.48
	Total Amount Payable		S\$ 20,994.65

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND NINE HUNDRED NINETY FOUR AND CENTS SIXTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORIZED SIGNATURE

2007102



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S: WU XIAODONG
47A EDGEFIELD PLAINS
#15-19 WATERBAY
SINGAPORE 828714
TEL: 82824056
ATTN:

Claim No: MC0912700
No: MF0910898
Date: 09 Mar 2018
Policy No: MT/00401894
Veh Reg No: SLC7168X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT

Your Ref No: SLC7168X
Claim Type: Third Party
Accident Date: 22/12/2017
TP Veh Reg No: SHC3049E

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLC7168X

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	496.50	
2 REAR BUMPER SIDE RETAINERS RH	1 PC	114.70	
3 REAR BUMPER CLIPS	12 PC	46.68	
4 REAR BUMPER LOWER REFLECTOR RH	1 PC	81.64	
5 REAR BUMPER REINFORCEMENT	1 PC	396.60	
6 REAR BUMPER REINFORCEMENT BRACKET RH	1 PC	89.45	
7 REAR REVERSE SENSOR	2 PC	423.22	
8 FRONT BONNET	1 PC	1,140.40	
9 FRONT BONNET INSULATOR CLIPS	8 PC	25.68	
10 FRONT GRILLE ASSY	1 PC	564.00	
11 FRONT GRILLE CLIPS	8 PC	25.68	
12 HEADLAMP WITH HID LH & RH	2 PC	5,632.02	
13 HEADLAMP TOP CHROME LH & RH	2 PC	356.04	
14 HEADLAMP CLIPS	4 PC	12.84	
15 FRONT BUMPER	1 PC	521.20	
16 FRONT BUMPER SIDE RETAINER LH	1 PC	75.80	
17 FRONT BUMPER CLIPS	12 PC	46.68	
18 FRONT BUMPER SPONGE	1 PC	97.40	
19 FOGLAMP COVER BLACK OUTER LH	1 PC	96.33	
20 FRONT FENDER LH	1 PC	858.00	
21 FRONT FENDER COWLING LH	1 PC	195.60	
22 FRONT FENDER COWLING CLIPS	10 PC	32.10	
23 FRONT FENDER LOGO (VVT-I)	1 PC	51.60	
24 RADIATOR SUPPORT PANEL	1 PC	1,075.98	
25 RESONATOR TANK LH	1 PC	165.30	
26 RESONATOR TANK HOSE	1 PC	211.61	
27 FRONT WHEELHOUSE INNER SIDE BRACKET LH	1 PC	98.72	
28 FENDER WHEEL HOUSE LH	1 PC	581.30	
29 BUMPER SIDE CLIPS	1 PC	18.50	
		13,531.57	
Special Nett		3,382.89	10,148.68
30 RADIATOR COOLANT	1 PC	20.00	
LABOUR		20.00	20.00

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A #01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : WU XIAODONG
47A EDGEFIELD PLAINS
#15-19 WATERBAY
SINGAPORE 828714
TEL: 82824056
ATTN:

Claim No: MC0912700
No: MF0910898
Date: 09 Mar 2018
Policy No: MT/00401894
Veh Reg No: SLC7168X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT

Your Ref No: SLC7168X
Claim Type: Third Party
Accident Date: 22/12/2017
TP Veh Reg No: SHC3049E

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLC7168X

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
31 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
32 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS - FRONT FENDER LH & FRONT CHASSIS FRAME LH.	1 PC	90.00	
33 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL,FRONT BUMPER REINFORCEMENT & BRACKET LH.TO KNOCK & REPAIR FRONT DOOR LH,FRT FENDER RH,FRT WHEELHOUSE, FRONT CHASSIS FRAME & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,000.00	
34 TO SPRAY FRT BONNET,FRT BUMPER,FRONT BUMPER REINFORCEMENT & BRACKET LH,FRONT FENDER LH & RH,FRONT DOOR LH,RADIATOR SUPPORT PANEL, FRONT CHASSIS FRAME LH & RH, FRONT WHEELHOUSE LH & RH.	1 PC	1,000.00	
35 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
36 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
37 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR BUMPER REINFORCEMENT & BRACKET RH.TO KNOCK & REPAIR END PANEL,SPARE TYRE PANEL, REAR CHASSIS FRAME RH,REAR BOOT,REAR FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	450.00	
38 TO SPRAY REAR BOOT,REAR BUMPER,REAR BUMPER REINFORCEMENT & BRACKET RH,END PANEL,SPARE TYRE PANEL,REAR CHASSIS FRAME RH,REAR FENDER RH.	1 PC	600.00	
39 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	
		3,330.00	3,330.00

AH LIM MOTOR COMPANY
No.10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : WU XIAODONG
47A EDGEFIELD PLAINS
#15-19 WATERBAY
SINGAPORE 828714
TEL: 82824056
ATTN:

Claim No: MC0912700
No: MF0910898
Date: 09 Mar 2018
Policy No: MT/00401894
Veh Reg No: SLC7168X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT

Your Ref No: SLC7168X
Claim Type: Third Party
Accident Date: 22/12/2017
TP Veh Reg No: SHC3049E

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLC7168X

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 13,498.68
		Less Excess	S\$ 0.00
		Amount Before GST	S\$ 13,498.68
		Add GST @ 7%	944.91
		Total Amount Payable	S\$ 14,443.59

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND FOUR HUNDRED FORTY THREE AND CENTS FIFTY NINE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 28/12/2017

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
AUTORISED SIGNATURE
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : WU XIAODONG
47A EDGEFIELD PLAINS
#15-19 WATERBAY
SINGAPORE 828714
TEL: 82824056
ATTN:

Estimate No: MC0912700
Date: 02 Jan 2018
Policy No: MT/00401894
Veh Reg No: SLC7168X
Make/Model: TOYOTA COROLLA
ALTIS 1.6 CVT

Your Ref No: SLC7168X
Claim Type: Third Party
Accident Date: 22/12/2017
TP Veh Reg No: SHC3049E

Estimate Repair Cost to Vehicle No :SLC7168X

Description	Quantity	List Price S\$	Amount S\$
Supplementary Parts to Repair			
SPARE PARTS			
1 FENDER WHEEL HOUSE LH	1 PC	581.30	
2 BUMPER SIDE CLIPS	1 PC	18.50	
		599.80	
	Less 25%	149.95	449.85
	Total		S\$ 449.85
	GST Amount		S\$ 31.49
	Total Amount Payable		S\$ 481.34

The above vehicle was surveyed by KENNETH KONG-LKK on 28/12/2017

2018.11.30 AM.
A/C

For AH LIM MOTOR COMPANY

AUTHORIZED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17024619/Kvd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 16-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3049E	Veh. Inspected	SLC 7168X	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011818MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	27/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104549216	Colour	METALLIC PEARL WHITE	
Odometer	18195	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	MICHELIN	8 mm	
L/H Front Tyre	215/45 R17	MICHELIN	8 mm	
R/H Rear Tyre	215/45 R17	MICHELIN	8 mm	
L/H Rear Tyre	215/45 R17	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/12/2017	Inspection Date	28/12/2017	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 7168X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT EMBLEM	NOT NECESSARY	52.80	-
1	REAR BOOT LOGO (ALTIS) RH	NOT NECESSARY	47.20	-
1	REAR BOOT LOGO (COROLLA) RH	NOT NECESSARY	44.13	-
1	REAR BUMPER	BUCKLED	496.50	496.50
1	REAR BUMPER SIDE RETAINERS RH	DISTORTED	114.70	114.70
1	REAR BUMPER RETAINERS CTR RH	SERVICEABLE	89.20	-
12	REAR BUMPER CLIPS	NECESSARY	46.68	46.68
1	REAR BUMPER LOWER REFLECTOR RH	CRACKED	81.64	81.64
1	REAR BUMPER REINFORCEMENT	BENT	396.60	396.60
1	REAR BUMPER REINFORCEMENT BRACKET RH	BENT	89.45	89.45
1	TAILLAMP RH	SERVICEABLE	365.33	-
3	TAILLAMP CLIPS RH	NOT NECESSARY	12.60	-
1	REAR FENDER COWLING RH	SERVICEABLE	72.90	-
10	REAR FENDER COWLING CLIPS	NOT NECESSARY	32.10	-
2	REAR REVERSE SENSOR	SHORTED	423.22	423.22
1	FRONT BONNET	BENT	1,140.40	1,140.40
2	FRONT BONNET HINGE LH & RH	TO REPAIR SEE LABOUR	142.60	-
8	FRONT BONNET INSULATOR CLIPS	NECESSARY	25.68	25.68
1	FRONT BONNET INNER LOCK	TO REPAIR SEE LABOUR	129.70	-
1	FRONT GRILLE ASSY	MTG CRACKED	564.00	564.00
8	FRONT GRILLE CLIPS	NECESSARY	25.68	25.68
2	HEADLAMP WITH HID LH & RH	O/S CRACKED / N/S BROKEN	5,632.02	5,632.02
2	HEADLAMP TOP CHROME LH & RH	NECESSARY	356.04	356.04
4	HEADLAMP CLIPS	NECESSARY	12.84	12.84
1	FRONT BUMPER	BENT	521.20	521.20
1	FRONT BUMPER SIDE RETAINER	N/S CRACKED	151.60	75.80
12	FRONT BUMPER CLIPS	NECESSARY	46.68	46.68
1	FRONT BUMPER LOWER AIR GRILLE CTR	SERVICEABLE	178.02	-

Report Ref No. CS/FCI17024619/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	411.60	-
1	FRONT BUMPER REINFORCEMENT BRACKET LH	TO REPAIR SEE LABOUR	115.70	-
1	FRONT BUMPER SPONGE	CRACKED	97.40	97.40
1	FRONT BUMPER LOWER COVER CTR	SERVICEABLE	178.90	-
1	FOG LAMP LH	SERVICEABLE	226.73	-
1	FOGLAMP COVER BLACK OUTER LH	SCRATCHED	96.33	96.33
1	FRONT FENDER LH	BUCKLED	858.00	858.00
1	FRONT FENDER COWLING LH	DISTORTED	195.60	195.60
10	FRONT FENDER COWLING CLIPS	NECESSARY	32.10	32.10
1	FRONT FENDER LOGO (VVT-I)	NECESSARY-1 PC ONLY	103.20	51.60
1	RADIATOR SUPPORT PANEL	BUCKLED	1,075.98	1,075.98
1	BRACE PANEL	TO REPAIR SEE LABOUR	115.90	-
1	AIR CON CONDENSER	SERVICEABLE	1,389.70	-
1	RADIATOR ASSY	SERVICEABLE	1,510.90	-
1	RESONATOR TANK LH	CRACKED	165.30	165.30
1	RESONATOR TANK HOSE	DENTED	211.61	211.61
1	GEARBOX LOWER COVER LH	SERVICEABLE	156.30	-
6	GEARBOX LOWER COVER CLIPS	NOT NECESSARY	16.74	-
1	FRONT WHEELHOUSE INNER SIDE BRACKET LH	BENT	98.72	98.72
1	FENDER WHEEL HOUSE LH (ADDITIONAL)	BENT	581.30	581.30
1	BUMPER SIDE CLIPS (ADDITIONAL)	NECESSARY	18.50	18.50
	LESS 25% DISCOUNT		-4,737.00	-3,382.89
			14,211.02	10,148.68
	SPECIAL NETT ITEMS			
1	RADIATOR COOLANT (SN)	NECESSARY	35.00	20.00
1	NUMBER PLATE (SN)	SERVICEABLE	35.00	-
			70.00	20.00

Report Ref No. CS/FCI17024619/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT ENGINE ASSEMBLY WITH TRANSMISSION TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS - FRONT FENDER LH & FRONT CHASSIS FRAME LH.		150.00	90.00
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, FRONT BUMPER REINFORCEMENT & BRACKET LH. TO KNOCK & REPAIR FRONT DOOR LH, FRT FENDER RH, FRT WHEELHOUSE, FRONT CHASSIS FRAME & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF FRONT BONNET HINGE LH & RH, FRONT BONNET INNER LOCK, FRONT BUMPER REINFORCEMENT, FRONT BUMPER REINFORCEMENT BRACKET LH AND BRACE PANEL.		1,600.00	1,000.00
	TO SPRAY FRT BONNET, FRT BUMPER, FRONT BUMPER REINFORCEMENT & BRACKET LH, FRONT FENDER LH & RH, FRONT DOOR LH, RADIATOR SUPPORT PANEL, FRONT CHASSIS FRAME LH & RH, FRONT WHEELHOUSE LH & RH.		1,400.00	1,000.00
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR BUMPER SENSORS.		80.00	50.00
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS, END PANEL, SPARE TYRE PANEL, REAR CHASSIS FRAME RH.	NOT NECESSARY	200.00	-
	TO DISMANTLE ALL DAMAGED PARTS, TO CUT & WELD REAR BUMPER REINFORCEMENT & BRACKET RH. TO KNOCK & REPAIR END PANEL, SPARE TYRE PANEL, REAR CHASSIS FRAME RH, REAR BOOT, REAR FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		800.00	450.00

Report Ref No. CS/FCI17024619/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY REAR BOOT, REAR BUMPER, REAR BUMPER REINFORCEMENT & BRACKET RH, END PANEL, SPARE TYRE PANEL, REAR CHASSIS FRAME RH, REAR FENDER RH.		900.00	600.00
	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		120.00	100.00
			5,790.00	3,330.00
GRAND TOTAL			20,071.02	13,498.68

RECOMMENDED COST OF REPAIRS			13,498.68
-----------------------------	--	--	-----------

Report Ref No. CS/FCI17024619/Kvd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.