

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05693

Vehicle Insured : SKG816X  
Accident Date : 24-Dec-2017

*Not Authored*  
*1-B1*  
*Resurvey B6 part*  
*5 days*

Date : 27-Dec-2017

Our Ref : 217198 (AXA) / CHAN

PAGE : 1

WONG YEW WENG  
BLK 45 LOR 5  
TOA PAYOH #02-151  
Singapore 310045

ESTIMATED COST OF REPAIR FOR HYUNDAI ELANTRA 1.6 SDN4141D  
=====

1 pc	Front o/s shock absorber		432.90	?
1 pc	Front o/s knuckle arm		423.80	✓
1 pc	Front o/s knuckle bearing hub		493.80	✓
1 pc	Front o/s lower arm		346.90	?
1 pc	Front o/s stabiliza bar link		128.00	?
1 pc	Front o/s drive shaft		956.70	?
1 pc	Steering rack n pinon		1,157.90	?
1 pc	Front o/s ABS sensor wire		232.00	X
1 pc	Front o/s sport rim		1,197.10	✓
1 pc	Front o/s fender		571.20	X
1 pc	Front o/s fender inner shield		124.10	✓
8 pcs	O/s fender inner shield clip @ S\$ 5.90		47.20	✓
1 pc	O/s headlamp		1,198.80	✓
1 pc	Front support panel		949.30	?
1 pc	O/s headlamp lower bracket		39.70	?
1 pc	Front bumper fascia		484.30	✓
1 pc	Front o/s bumper side retainer		28.00	✓
1 pc	Front o/s foglamp		295.10	?
1 pc	Front o/s foglamp cover		39.40	✓
1 pc	Front o/s day lamp		412.15	?
1 pc	Front o/s day lamp bracket		29.70	?
1 pc	Front w/s glass washer tank		98.20	?
1 pc	Front bumper reinforcement		695.80	?
1 pc	Front bumper inner sponge		59.30	?
			-----	
			10,441.35	
Less 20% :			2,088.27	
			-----	

8,353.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKG816X

Page : 2

To towing	60.00	<i>501</i>
To rewire damaged parts and refocus headlamp beam.	40.00	<i>201</i>
To remove air con condenser, pipes and drier, vacuum and to recharge gas	120.00	<i>?</i>
To dismantle and lower front undercarriage	250.00	<i>2001</i>
To check and adjust wheel alignment	80.00	<i>601</i>
To putty and spray replaced parts	750.00	<i>4401</i>
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	900.00	<i>?</i>
To transfer front o/s tyre	60.00	<i>?</i>
To rewire foglamp & day lamp wire	40.00	<i>?</i>
Total :	----- S\$10,653.08 =====	

Singapore Dollars Ten Thousand Six Hundred and Fifty Three and Cents Eight Only