

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R				
Affiliated to Federation Internationale Des Experts En Automobile				
-			Ref : CS/TP17024626/R1vbe2	
EE HWEE CHENG JOSEPHINE 86 JALAN KURASSINGAPORE 577758			Date: 19-01-2018  Code: TP2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.		Veh. Inspected	SDM 4245T
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	27/12/2017
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN SHARAN	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WVWZZZ7NZEV012541	Colour	GREY
	Odometer	72709	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50Z R17	PIRELLI	6 mm
	L/H Front Tyre	225/50Z R17	PIRELLI	6 mm
	R/H Rear Tyre	225/50Z R17	PIRELLI	6 mm
	L/H Rear Tyre	225/50Z R17	PIRELLI	6 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	23/12/2017	Inspection Date	27/12/2017
	Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD		
		247 ALEXANDRA ROAD SINGAPORE 159934		
5a.	a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: