

YN8903Y
TP/EQ

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433
ATTN: Motor Claim Department
WS Ref: TP-EQ
Claim Type: Third Party
Accident Date: 21/12/2017
TP Veh Reg No: PA9570S

FAX: 62243903

*Not Authored
11/12/17
Running After Rain*

Estimate No: ES1791439/WS
Date: 22-Dec 2017
Policy No: 5072900554-02
Veh Reg No: YN8903Y
Make/Model: ISUZU NPR85UH5A
Chassis No: JAANPR85HF7100461
Engine No: 4JJ11Z6491
Reg. Date: 18/08/2015

Estimate Repair Cost to Vehicle No :YN8903Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 CABIN REAR PANEL	1,188.000	1 PCS	<i>B</i> 1,188.00	✓
2 CABIN REAR PANEL INNER GARNISH	110.4000	1 PCS	110.40	✓
3 CABIN REAR WINDSCREEN RUBBER	81.6000	1 PCS	<i>na</i> 81.60	✓
4 CABIN RH DOOR REAR PILLAR OUTER	268.8000	1 PCS	<i>B</i> 268.80	✓
5 AIR FILTER HOUSING	228.0000	1 PC	228.00	✓
6 AIR-FILTER DUCTING TOP	298.8000	1 PC	298.80	✓
7 AIR-FILTER DUCTING CENTRE	96.0000	1 PC	96.00	✓
8 REAR MUD FLAPS	24.0000	2 PCS	<i>DJ/607</i> 48.00	✓
9 REAR MUD GUARDS	78.0000	2 PCS	156.00	✓
			2,475.60	2,475.60
Special Net				
10 TAILGATE	1,600.000	1 PC	<i>B</i> 1,600.00	✓
11 TAILGATE SPEED LIMIT STICKER	10.0000	2 PCS	<i>na</i> 20.00	✓
12 REAR STEP MEMBER	180.0000	1 PCS	<i>CR</i> 180.00	✓
13 'U' BOLTS	60.0000	6 PCS	<i>B</i> 360.00	✓
14 REAR TRUCK WOODEN CHASSISS MEMBER	1,200.000	2 PCS	<i>CR</i> 2,400.00	✓
15 REAR TRUCK WOODEN FLOOR BOARD	200.0000	8 PCS	<i>CR</i> 1,600.00	✓
16 REAR TRUCK WOODEN CROSS MEMBER	150.0000	8 PCS	<i>CR</i> 1,200.00	✓
17 REAR WOODEN RAILING	450.0000	1 PCS	<i>CR</i> 450.00	✓
18 REAR TRUCK FRONT GATE	1,500.000	1 PCS	1,500.00	✓
19 REAR MUDGUARDS	150.0000	2 PCS	<i>Butcher</i> 300.00	✓
20 CANVAS	1,200.000	1 PCS	1,200.00	✓
21 RH SAFETY BAR	450.0000	1 PCS	<i>R</i> 450.00	✓
			11,260.00	11,260.00
Labour				
22 TOWING (BILL ATTACHMENT)	80.0000	1 LA	80.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department
WS Ref: TP-EQ
Claim Type: Third Party
Accident Date: 21/12/2017
TP Veh Reg No: PA9570S

Estimate No: ES1791439/WS
Date: 22 Dec 2017
Policy No: 5072900554-02
Veh Reg No: YN8903Y
Make/Model: ISUZU NPR85UH5A
Chassis No: JAANPR85HF7100461
Engine No: 4JJ11Z6491
Reg. Date: 18/08/2015

Estimate Repair Cost to Vehicle No :YN8903Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
23 REMOVE AND REFIX REAR CANOPY ASSY, CANVAS, TOOL BOX ASSY, SAFETY BAR, REAR WOODEN TRUCK, MAIN CHASSISS, CROSS MEMBER, FLOOR BOARD, REAR METAL FLOOR BOARD, TAILGATE AND FRONT GATE, 'U' BOLT AND REALIGN REAR TRUCK POSITION.	2,500.000	1 LA	2,500.00	1800
24 REMOVE AND REFIX REAR WINDSCREEN GLASS	60.0000	1 LA	60.00	✓
25 REMOVE AND REFIX SEAT, CARPET, TOP ROOF LINING, SAFETY BELT, ETC (TO REMOVE CABIN REAR PANEL)	120.0000	1 LA	120.00	✓
26 REMOVE AND REFIX AIR-FILTER ASSY, TO CUTTING, WELDING AND RENEW CABIN REAR PANEL, KNOCK AND REPAIR CABIN REAR PANEL REINFORCEMENT, STRAIGHTEN REPAIR CABIN MOUNTING BRACKET AND DOOR REAR PILLAR OUER, MAIN CHASSISS AND REALIGN CABIN POSITION, INCLUDING REMO	2,300.000	1 LA	2,300.00	2000
27 PUTTY AND RESPRAY ON CABIN REAR PANEL (INNER OUTER)TOP ROOF LINING, DOOR REAR PILLAR, TAILGATE, FRONT GATE, REAR WOODEN RAILING AND ALL AFFECTED AREA.	1,800.000	1 LA	1,800.00	1400
28 REMOVE AND REFIX REAR WARNING LIGHTS, CHECK WIRING AND RESET SYSTEM	100.0000	1 LA	100.00	60
			6,960.00	6,960.00
			Total	S\$ 20,695.60
			Add GST @ 7%	1,448.69
			Total Amount Payable	S\$ 22,144.29

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

張建福 (機件) 拖車服務
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 17334

Date: 26.12.17

寶號

Messrs:

CHENG HOE

車號

Vehicle No:

車型

Model No:

由

From:

到

To:

時間 (日/夜)

Time (day/night):

其他

Others:

CASH \$:

CHEQUE:

經手人

Authorised by:

收貨人

Received by:

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.