

1500/2010

INS. CASE OWNER:

CC 4/AXA17024631

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Pre-assign / CCU / FTE

Registered in Merimen:



Insured Vehicle No.:

SHC 50530

Claim No.:

C0464711

Name of Insured:

TRANS-CAB SERVICES PTE LTD

Policy No.:

VPX/P1680520

Insured Tel No.:

HP:

Make / Model:

RENAULT LATITUDE - 2.0L (A)

Excess Sec II :S\$

5,000.00

D.O.A.:

26/12/17

Place of Accident:

WOODLANDS AVENUE 3 SLIP ROAD
TOWARDS BKE

Is driver the owner?

(YES ☐ NO ☒)

Nature of Accident:

If NO, Driver Name / Age: KOH TECK CHYE VINCENT

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.: 9858 6338

(V/L: YES / NO)

Insured Liability:

% Final ? Yes / No

SKN 9866E



INSRS:

WSP: Insurance Auto (Pvt. Ltd.)

Tel:

Liability: NON-ARC

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

29/12/17 (THUR THRU)

SKN 9866E - X

SHC 50530 - CC2/ASC100/4577/Kbn DOA: 22/12/17

J-NA/INC04017557/p1 DOA: 28/12/17

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow / Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

WIP
\$250.

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

RECEIVED 18 JUL 2018

ONLY SENT
18/7/18

REF: AXA

Ref: 1704631/Kus3

ASSIGNMENT

From: Date: 28/12/17

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKN 9866E

at Workshop m/s Insurance Auto
of BLK 134 Pasir Ris st 11 # 04-253

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

TP-Non ARC Pls Ensure Consistence & Be
(Policy Condition) Stringent on car.Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4-6 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

lwp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKN 9866E Vr Regn: 07 12

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X5

c.c. 2928

Colour:

Black

A/O: Insured / Std / NI / NA

Sp. Reading:

255814

T. Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA8V42-0006493011

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

255/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

9 mm

R/Bal:

5 mm

L/Bal:

9 mm

L/Bal:

5 mm

D.O.A:

26/12/17

D.O.I:

28/12/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/12 1545 pass to Carter

LIS - \$ 4600.00 Red: \$ 12758.92 / 74%)

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Report Format:

Lump Sum / I.B.I. \$

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech. Insp. \$

☐

Weekend \$

\$ HRG \$

Phone

Other

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/AXA17024631/Kus3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 28-12-2017		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 5053D	Veh. Inspected	SKN 9866E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/12/2017	Inspection Date	28/12/2017	
Survey held at	INSURANCE'S AUTO BLK 5038 ANG MO KIO INDUSTRIAL PARK 2 #01-405 SINGAPORE 569541			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017		27 Dec 2017 11:37 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K	[Created by insurer]
Main Claimant:	QUEK SEE MENG, ID: S15578591	
Vehicle Reg. No.:	SKN9866E	
Claim Type:	TP / C0464711	Date of Loss: 26/12/2017 00:00 - :59
Vehicle Reg. No. (Insured):	SHC5053D	Policy/Cover Note No.: P1680520 (Third Party Only)
		Policy No. (Claimant):
		Excess: S\$5,000.00
Repairer:	Insurance's Auto - Pasir Ris (HQ) BLK 134 PASIR RIS ST 11 #04-253, 10134 Pasir Ris - Tel: 9008 9959	
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Tan Kwee May]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/01/2018]	
Driver/Custodian (Insured):	KOH TECK CHYE VINCENT (57 / Male), NRIC: S1455034H, Tel: +6598386338	
Adj Asg. Remarks:	TP-NON ARC PLS ENSURE CONSISTENCE & BE STRINGENT ON COR.	

ASSOCIATED MAIL RECEIVED

- AXA_SG (27/12/2017): New TP Assignment - C0464711/P1680520

View All

Compose Case Mail



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

27.12.2017 @ 4:22pm
 Dick veh in
 Kenneth

Insurance's Auto

Blk 5038 Ang Mo Kio Ind. Park 2 #01-405

Singapore 569541.

Fax: 64455393. Email: insurancesauto@hotmail.com

Tel: 90089959.

*Not Authored
11 Days & ?
Running After Paint*

Quek See Meng

Blk 513 Bedok North Ave 2 #09-257

Singapore 460513

Vehicle No : SKN9866 **E**
Chassis No : WBAZV42000L493011
Make : BMW X5
Year :

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1	Rear Bumper		<i>Pr</i> \$1,618.70 ✓
2	Rear Side Retainer RH/LH	\$120.00	<i>Sm</i> \$240.00 X
2	Rear Bumper Corner Mount	\$62.00	\$124.00 ?
1	Bumper Centre Guide		\$170.50 ?
2	Rear Bumper Support RH/LH	\$20.00	<i>Sm</i> \$40.00 X
2	Rear Bumper Lower Trim	\$88.00	<i>Pr</i> \$166.00 ✓
2	Rear Bumper Reflector RH/LH	\$32.00	<i>Sm</i> \$64.00 X
2	Rear Tow Cover	\$55.00	<i>Pr</i> \$110.00 ✓
1	Rear Bumper Lower Trim Centre		<i>Pr</i> \$275.00 ✓
1	Rear Bumper Under Protection		\$115.50 ?
1	Rear Reinforcement		\$758.80 ?
1	Tail Gate Assy		<i>Pr</i> \$3,102.90 X
1	Tail Gate Weatherstrip		\$263.85 ?
1	Tail Gate Lock Cable		<i>Sm</i> \$35.60 X
1	Tail Gate Lock Cover		<i>Sm</i> \$10.00 X
1	Tail Gate Lock		<i>Pr</i> \$220.25 X
1	Tail Gate Push Button		<i>Sm</i> \$46.05 X
1	Tail Gate Micro switch Lock		\$211.85 ?
1	Tail Gate Soft Close		<i>Pr</i> \$572.30 ✓
1	Lower Tail		<i>Pr</i> \$1,814.15 ✓
2	Lower Tail Damper RH/LH	\$112.00	<i>Sm</i> \$224.00 X ?
2	Tail Lamp Assy RH/LH	\$453.50	<i>Sm</i> \$913.00 X
1	Rear End Panel		\$1,140.05 ?
1	Rear End Panel Top Garnish		\$212.45 ?

1	Rear Exhaust Silencer		\$2,326.40	7
4	Rear Exhaust Silencer Mounting	\$25.00	\$100.00	X
			\$14,875.35	
		Less 10%	\$1,487.54	
			\$13,387.82	

Special Nett Item

Reverse Sensors 2pcs @ \$363.05 \$726.10 7

Reaverse Sensor Seal 2pcs @20.00 \$40.00 7

Labour Charges

To remove and replaced damaged parts including straightening repositioning replacement parts. \$1,200.00 7

Supply Paint Material and necessary items. To respray replaced and other affected panels \$1,000.00 801

Reconnect wiring at the damage section and check for proper functions. \$75.00 301

To transfer tailgate mechanisms with motor assembly and all attachments. 120.00 X

To install reverse sensor, control unit. Re-connect wires harness. Check function. \$120.00 601

To carry out antirust treatment on affected panels. \$120.00 7

To remove/refit exhaust assembly with all attachments, bracket and holders. Straighten and align centre exhaust pipe. 801 \$250.00

To check and reset fault reading setting with the aid or dignostic kit. 120.00 X

Grand Total : \$17,358.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kwee May

Date: 02 Jan 2018

Preliminary Advice

Insured Vehicle No	: SHC5053D	Accident Date	: 26/12/2017
TF Vehicle No	: SKN9866E	Assignment Date	: 27/12/2017
Make	: BMW X5	Est. Duration of Repair	: 6 days
Date of Inspection	: 28/12/2017		
Inspection At	: Insurance's Auto		
	Blk 5038 Ang Mo Kio Ind. Park 2		
	#01-405		
	Singapore 569541		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesrear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,358.92
Revised Amount	:S\$	4,505.97
Check Items (Estimated)	:S\$	8,415.53
Total	:S\$	12,921.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

Ku

Not Authorized
 21 Sep 8 4600h
 Running After Paint
 4 days

Insurance's Auto

Blk 5038 Ang Mo Kio Ind. Park 2 #01-405
 Singapore 569541.
 Fax: 64455393. Email: insurancesauto@hotmail.com
 Tel: 90089959.

Quek See Meng

Blk 513 Bedok North Ave 2 #09-257
 Singapore 460513

Vehicle No : SKN9866 E
 Chassis No : WBAZV42000L493011
 Make : BMW X5
 Year :

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1	Rear Bumper		Am \$1,618.70 ✓
2	Rear Side Retainer RH/LH	\$120.00	Sm \$240.00 X
2	Rear Bumper Corner Mount	\$62.00	Sm \$124.00 X
1	Bumper Centre Guide		CM \$170.50 ✓
2	Rear Bumper Support RH/LH	\$20.00	Sm \$40.00 X
2	Rear Bumper Lower Trim	\$88.00	DI \$166.00 ✓
2	Rear Bumper Reflector RH/LH	\$32.00	Sm \$64.00 X
2	Rear Tow Cover	\$55.00	DI PC \$110.00 ✓
1	Rear Bumper Lower Trim Centre		As \$275.00 ✓
1	Rear Bumper Under Protection		DI \$115.50 ✓
1	Rear Reinforcement		Sm \$758.80 X
1	Tail Gate Assy		R \$3,102.90 X
1	Tail Gate Weatherstrip		Sm \$263.85 X
1	Tail Gate Lock Cable		Sm \$35.60 X
1	Tail Gate Lock Cover		Sm \$10.00 X
1	Tail Gate Lock		R \$220.25 X
1	Tail Gate Push Button		Am \$46.05 X
1	Tail Gate Micro switch Lock		Sm \$211.85 X
1	Tail Gate Soft Close		BA \$572.30 ✓
1	Lower Tail		R \$1,814.15 ✓
2	Lower Tail Damper RH/LH	\$112.00	Sm \$224.00 X
2	Tail Lamp Assy RH/LH	\$453.50	Sm \$913.00 X
1	Rear End Panel		Sm \$1,140.05 X
1	Rear End Panel Top Garnish		Sm \$212.45 X

1	Rear Exhaust Silencer		22	\$2,326.40	X
4	Rear Exhaust Silencer Mounting	\$25.00	22	\$100.00	X
				\$14,875.35	
			Less 10%	\$1,487.54	
				\$13,387.82	

Special Nett Item

Reverse Sensors 2pcs @ \$363.05

3265.00

Shan \$726.10 X

Reverse Sensor Seal 2pcs @20.00

22 \$40.00 X

Labour Charges

To remove and replaced damaged parts including straightening repositioning replacement parts.

\$1,200.00 5 out

Supply Paint Material and necessary items. To respray replaced and other affected panels

\$1,000.00 2 out

Reconnect wiring at the damage section and check for proper functions.

\$75.00 2 out

To transfer tailgate mechanisms with motor assembly and all attachments.

22 \$120.00 X

To install reverse sensor, control unit. Re-connect wires harness. Check function.

\$120.00 2 out

To carry out antirust treatment on affected panels.

\$120.00 X

To remove/refit exhaust assembly with all attachments, bracket and holders. Straighten and align centre exhaust pipe.

2 out \$250.00

To check and reset fault reading setting with the aid or dignostic kit.

22 \$320.00 X

Grand Total :

\$17,358.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary test(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Print Received Message

This mail is associated with :

*SKN9866E (C0464711)
[SHC5053D]
TP
QUEK SEE MENG
Dec 26 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]
Insurance's Auto - Pasir Ris

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 01/06/2018 15:56 PM,
To LKK_HQ
CC AXA_SG
Subject Pls submit Final Bill

Hi LKK

3rd party have escalated the matter via their lawyers.

Please let us have your final bill.

Thank you.

Regards
Xinyou

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017		27 Dec 2017 11:37 Edit Adj Rpt	S\$4,600.00 Edit Estimates	S\$4,600.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Main Claimant:	QUEK SEE MENG, ID: S15578591		
Vehicle Reg. No.:	SKN9866E	Date of Loss:	26/12/2017 00:00 - :59 [64 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0464711	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHC5053D	Policy No. (Claimant):	GA052005/1
		Excess:	S\$5,000.00
Repairer:	Insurance's Auto - Amk (HQ) BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405, 569541 Ang Mo Kio - Tel:		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Chen Xinyou - 6880 4269]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/01/2018]		
Driver/Custodian (Insured):	KOH TECK CHYE VINCENT (57 / Male), NRIC: S1455034H, Tel: +6598386338		
Adj Asg. Remarks:	TP-NON ARC PLS ENSURE CONSISTENCE & BE STRINGENT ON COR.		
Insurer's Solicitor:	TAN KOK QUAN PARTNERSHIP (HQ) - Tel: 64969560 ... Incoming Assignment		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (01/06/2018): **Pls submit Final Bill**
- AXA_SG (27/12/2017): **New TP Assignment - C0464711/P1680520**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKN9866E (C0464711)**
[SHC5053D]
TP
QUEK SEE MENG
Dec 26 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]
Insurance's Auto - Amk

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
1	02/01/18 17:08	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice	Load HTM	
Documentation			1 per page	☒
No	Finalized On		Thumbnail	Print
1	27/12/17 10:51	AXA Insurance Pte Ltd (HQ) EMAIL_ABS	Load PDF	
2	27/12/17 10:51	GIA SHC5053D INSD_ABS	Load PDF	
3	27/12/17 10:51	GIA SKN9866E TP_ABS	Load PDF	
4	27/12/17 10:51	THIRD PARTY_ABS	Load PDF	
No	Relabel/Reorder		Thumbnail	Print
1	02/01/18 17:12	LKK Auto Consultants Pte Ltd (HQ) TP ESTIMATE- MARKED	Load PDF	
2	18/07/18 11:12	LKK INSPECTION PHOTOS	Load PDF	
3	18/07/18 11:12	LKK RE-INSPECTION PHOTOS	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer ☐ Insurer's Solicitor Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17024631/KUB3S2
Date: 23/07/2018

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	SKN9866E	Insured Vehicle No :	SHC5053D
Date of Loss:	26/12/2017	Nature of Claim:	TP
		Claim No:	C0464711

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN9866E	Engine No:	06148015N55B30A
Make & Model:	BMW X5, 3.0 (A)	Chassis No:	WBAZV42000L493011
Reg. Date:	31/07/2012 (Man. Year: 2012)	Odometer:	255814 km
Colour:	Metallic Black		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/55R18	Rear Tyre Size:	255/55R18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,153.91	4,878.43	9,275.48	65.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,205.00	1,470.00	1,735.00	54.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,358.91	6,348.43	11,010.48	63.43
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	17,358.91	4,600.00	12,758.91	73.50

INSPECTION

Date of Assignment:	27/12/2017		
Date Inspected:	28/12/2017	Inspected At:	Blk 134 Pasir Ris St 11 #04-253
Estimated Period of Repair:	4.0 days		Repairer: Insurance's Auto

Adjuster: KENNETH KONG

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2018)
Parts:	M1-SUV	BMW X5 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN9866E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (CONSISTENT)	Buckled	1,618.70 FL	*1,618.70 FL
2	2		*REAR SIDE RETAINER RH/LH (CONSISTENT)	Serviceable	240.00 FL	*- FL
3	2		*REAR BUMPER CORNER MONT (CONSISTENT)	Serviceable	124.00 FL	*- FL
4	1		*BUMPER CENTRE GUIDE (CONSISTENT)	Cracked	170.50 FL	*170.50 FL
5	2		*REAR BUMPER SUPPORT RH/LH (CONSISTENT)	Serviceable	40.00 FL	*- FL
6	2		*REAR BUMPER LOWER TRIM (CONSISTENT)	Distorted	166.00 FL	*166.00 FL
7	2		*REAR BUMPER REFLECTOR RH/LH (CONSISTENT)	Serviceable	64.00 FL	*- FL
8	1		*REAR TOW COVER (CONSISTENT)	O/s Dented	110.00 FL	*55.00 FL
9	1		*REAR BUMPER LOWER TRIM CENTRE (CONSISTENT)	Bent	275.00 FL	*275.00 FL
10	1		*REAR BUMPER UNDER PROTECTION (CONSISTENT)	Distorted	115.50 FL	*115.50 FL
11	1		*REAR REINFORCEMENT (CONSISTENT)	Serviceable	758.80 FL	*- FL
12	1		*TAIL GATE ASSY (CONSISTENT)	Repair	3,102.90 FL	*- FL
13	1		*TAIL GATE WEATHERSTRIP (CONSISTENT)	Serviceable	263.85 FL	*- FL
14	1		*TAIL GATE LOCK CABLE (CONSISTENT)	Serviceable	35.60 FL	*- FL
15	1		*TAIL GATE LOCK COVER (CONSISTENT)	Serviceable	10.00 FL	*- FL
16	1		*TAIL GATE LOCK (CONSISTENT)	Repair	220.25 FL	*- FL
17	1		*TAIL GATE PUSH BUTTON (CONSISTENT)	Serviceable	46.05 FL	*- FL
18	1		*TAIL GATE MICRO SWITCH LOCK (CONSISTENT)	Serviceable	211.85 FL	*- FL
19	1		*TAIL GATE SOFT CLOSE (CONSISTENT)	Bent	572.30 FL	*572.30 FL
20	1		*LOWER TAIL (CONSISTENT)	Bent	1,814.15 FL	*1,814.15 FL
21	2		*LOWER TAIL DAMPER RH/LH (CONSISTENT)	Serviceable	224.00 FL	*- FL
22	2		*TAIL LAMP ASSY RH/LH (CONSISTENT)	Serviceable	913.00 FL	*- FL
23	1		*REAR END PANEL (CONSISTENT)	Serviceable	1,140.05 FL	*- FL
24	1		*REAR END PANEL TOP GARNISH (CONSISTENT)	Serviceable	212.45 FL	*- FL
25	1		*REAR EXHAUST SILENCER (CONSISTENT)	Serviceable	2,326.40 FL	*- FL
26	1		*REAR EXHAUST SILENCER MOUNTING (CONSISTENT)	Serviceable	100.00 FL	*- FL
27	2		*REVERSE SENSORS (CONSISTENT)	Shorted	726.10 FS	*530.00 FS
28	2		*REVERSE SENSOR SEAL (CONSISTENT)	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,641.45	5,357.15
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,487.54	478.72
Total Parts (\$\$)	14,153.91	4,878.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING REPOSITIONING REPLACEMENT PARTS.	New	1,200.00	500.00
2	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS. TO RESPRAY REPLACED AND OTHER AFFECTED PANELS.	New	1,000.00	800.00
3	RECONNECT WIRING AT THE DAMAGE SECTION AND CHECK FOR PROPER FUNCTIONS.	New	75.00	30.00
4	TO TRANSFER TAILGATE MECHANISM WITH MOTOR ASSEMBLY AND ALL ATTACHMENTS.	New	120.00	0.00
5	TO INSTALL REVERSE SENSOR, CONTROL UNIT. RE-CONNECT WIRES HARNESS. CHECK FUNCTION.	New	120.00	60.00
6	TO CARRY OUT ANTI RUST TREATMENT ON AFFECTED PANELS.	New	120.00	0.00
7	TO REMOVE / REFIT EXHAUST ASSEMBLY WITH ALL ATTACHMENTS, BRACKET AND HOLDERS. STRAIGHTEN AND ALIGN CENTRE EXHAUST PIPE.	New	250.00	80.00
8	TO CHECK AND RESET FAULT READING SETTING WITH THE AID OR DIAGNOSTIC KIT.	New	320.00	0.00
Gross Labour Cost (S\$)			3,205.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >