

Insurance's Auto

Blk 5038 Ang Mo Kio Ind. Park 2 #01-405

Singapore 569541.

Fax: 64455393. Email: insurancesauto@hotmail.com

Tel: 90089959.

*Not Authored
L1 Rep & ?
Running After Paint*

Quek See Meng

Blk 513 Bedok North Ave 2 #09-257

Singapore 460513

Vehicle No : SKN9866 **E**
Chassis No : WBAZV42000L493011
Make : BMW X5
Year :

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1	Rear Bumper		<i>Pr</i> \$1,618.70 ✓
2	Rear Side Retainer RH/LH	\$120.00	<i>Sm</i> \$240.00 X
2	Rear Bumper Corner Mount	\$62.00	\$124.00 7
1	Bumper Centre Guide		\$170.50 7
2	Rear Bumper Support RH/LH	\$20.00	<i>Sm</i> \$40.00 X
2	Rear Bumper Lower Trim	\$88.00	<i>D11</i> \$166.00 ✓
2	Rear Bumper Reflector RH/LH	\$32.00	<i>Sm</i> \$64.00 X
2	Rear Tow Cover	\$55.00	<i>cls</i> <i>Pr</i> \$110.00 4
1	Rear Bumper Lower Trim Centre		<i>Pr</i> \$275.00 ✓
1	Rear Bumper Under Protection		\$115.50 7
1	Rear Reinforcement		\$758.80 7
1	Tail Gate Assy		<i>Pr</i> \$3,102.90 X
1	Tail Gate Weatherstrip		\$263.85 7
1	Tail Gate Lock Cable		<i>Sm</i> \$35.60 X
1	Tail Gate Lock Cover		<i>Sm</i> \$10.00 X
1	Tail Gate Lock		<i>Pr</i> \$220.25 X
1	Tail Gate Push Button		<i>Sm</i> \$46.05 X
1	Tail Gate Micro switch Lock		\$211.85 7
1	Tail Gate Soft Close		<i>Pr</i> \$572.30 ✓?
1	Lower Tail		<i>Pr</i> \$1,814.15 ✓
2	Lower Tail Damper RH/LH	\$112.00	<i>Sm</i> \$224.00 X 7
2	Tail Lamp Assy RH/LH	\$453.50	<i>Sm</i> \$913.00 X
1	Rear End Panel		\$1,140.05 7
1	Rear End Panel Top Garnish		\$212.45 7

1	Rear Exhaust Silencer		\$2,326.40	7
4	Rear Exhaust Silencer Mounting	\$25.00	\$100.00	X
			\$14,875.35	
		Less 10%	\$1,487.54	
			\$13,387.82	

Special Nett Item

Reverse Sensors 2pcs @ \$363.05 \$726.10 7

Reaverse Sensor Seal 2pcs @20.00 \$40.00 7

Labour Charges

To remove and replaced damaged parts including straightening repositioning replacement parts. \$1,200.00 7

Supply Paint Material and necessary items. To respray replaced and other affected panels \$1,000.00 Pay

Reconnect wiring at the damage section and check for proper functions. \$75.00 For

To transfer tailgate mechanisms with motor assembly and all attachments. \$120.00 X

To install reverse sensor, control unit. Re-connect wires harness. Check function. \$120.00 For

To carry out antirust treatment on affected panels. \$120.00 7

To remove/refit exhaust assembly with all attachments, bracket and holders. Straighten and align centre exhaust pipe. \$250.00 For

To check and reset fault reading setting with the aid or dignostic kit. \$320.00 X

Grand Total : \$17,358.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: