

REF:

C13/ A1417024655 / A1402

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$1000-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 110K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03/08 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLE 5071T. Yr Regn: 2016 July.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 Sedan. cc 1395Colour: Bronze. A/C: Insured / Std / NI / NASp. Reading: 37597. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8V261094224.Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModif: Nil / S/Rim STD A/Rim orTyre Size: F: 205/55R16.R: 205/55R16.BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU KPIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 28/12/17.Survey held at Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD A14.SLE 5071T. xPart by Part \$3,056.72 (Red: 1869.28; 37%)

RECEIVED 31 MAY 2018

Date/Time, File Pass to?

1) 31/5 Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report
☒ : Final Report
Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee: 200Transportation: 10

S + RS: \$

Photos

Others

Add Fee: ☐ : Site Insp. (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: ODLump Sum / I.E. (\$) 3056.72

TOTAL

210




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC3/AIG17024655/Atb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 29-12-2017	
			Code : AIG	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SLE 5071T
Policy No. 2100476376		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		28/12/2017
2. Vehicle Particulars & Condition				
Make & Model		c.c 0		
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 20/12/2017		Inspection Date 28/12/2017		
Survey held at		PREMIUM AUTOMOBILES PTE LTD		
		55 UBI ROAD 1 : SINGAPORE 408699		
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S6971974J**

Name: **WONG CHUN KHYAM JASON**

Birth Date: **12 Nov 1969**

Issue Date: **14 Feb 2004**

001121184F




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S6971974J**

Name: **WONG CHUN KHYAM JASON**

黄俊谦



Race: **CHINESE**

Date of birth: **12-11-1969**

Sex: **M**

Country of birth: **MALAYSIA**

S6971974J

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	Valid Date
Class 2B	MOTORCYCLES NOT EXCEEDING 200 CC	28 Jan 1995
Class 2A	MOTORCYCLES BETWEEN 201 CC AND 400 CC	04 Apr 1997
Class 2	MOTORCYCLES EXCEEDING 400 CC	05 Jan 2015
Class 3	MOTOR CARS AND MOTOR TRACTORS THE WEIGHT OF WHICH UNLADEN DOES NOT EXCEED 2500 KILOGRAMS	05 May 2015

S/No. 9000219908

S6971974J

NP 428A

Licence No: S6971974J



3440091

NRIC No. **S6971974J**

Date of Issue: **08-12-2003**

Address: **APT BLK 296 PUNGGOL CENTRAL
#06-497
SINGAPORE 820296**






CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100476376-01000

OWN DAMAGE EXCESS S\$600.00 (1)
WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes
SLE5071T

WONG CHUN KHYAM JASON

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

25 Jul 2017

4) DATE OF EXPIRY OF INSURANCE

24 Jul 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres(Tel:66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY United Overseas Bank Limited
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 12 Jun 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCGUK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S6971974J**

Name **WONG CHUN KHYAM JASON**

Birth Date: **12 Nov 1969**

Issue Date: **14 Feb 2004**

001121184F




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S6971974J**

Name **WONG CHUN KHYAM JASON**



黄俊谦

Race **CHINESE**

Date of birth **12-11-1969** Sex **M**

Country of birth **MALAYSIA**

S6971974J

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)


Class	Description	PASS DATE
Class 2B	MOTORCYCLES NOT EXCEEDING 200 CC	28 Jun 1995
Class 2A	MOTORCYCLES BETWEEN 201 CC AND 400 CC	04 Apr 1997
Class 2	MOTORCYCLES EXCEEDING 400 CC	05 Jun 2015
Class 3	MOTOR CARS AND MOTOR TRACTORS THE WEIGHT OF WHICH UNLADEN DOES NOT EXCEED 2500 KILOGRAMS	05 May 2015

S / No. 9000219908

S6971974J

Licence No: **S6971974J**

NP 428A



3440091



NRIC No. **S6971974J**



Date of issue **08-12-2003**

Address **APT BLK 296 PUNGGOL CENTRAL
#06-497
SINGAPORE 820296**



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100476376-01000

OWN DAMAGE EXCESS S\$600.00 (1)
WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes
SLE5071T

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

WONG CHUN KHYAM JASON

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

25 Jul 2017

4) DATE OF EXPIRY OF INSURANCE

24 Jul 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engng - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres(Tel:66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY United Overseas Bank Limited
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 12 Jun 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCGUK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1246/2017/JT
Date	:	21-Dec-17

Vehicle not workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Wong Chun Khyam Jason
Address	:	Blk 296 Punggol Central #06-497 Singapore 820296
Telephone	:	HP +65 9030 5780
Type of Claim	:	Own Damage Claims
Policy No.	:	2100476376-010000
Vehicle No	:	SLE 5071 T
Model Code	:	Audi A3 Sedan 1.4 TFSI (A)
Model / Year	:	Jul-16
Engine No	:	CZC 550456
Chassis No	:	WAUZZZ8V2G1094224
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	20-Dec-17
Place of Accident	:	Katong Plaza Carpark exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLE 5071 T.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓ /
2	To dismantle and renew front bumper. Re-organize front crash management components. Reinstall all parts removed.	\$ 900.00	SSD /
3	To respray front bumper.	\$ 800.00	SSD /
4	To carry out diagnostic checks.	S/N \$ 192.00	✓ /
TOTAL LABOUR CHARGES		: \$ 2,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5071 T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	\$ 1,667.00	✓ 1333 60
2	FRONT BUMPER LOWER COVER - LHS/RHS <i>new</i>	\$ 270.00	+
3	FRONT BUMPER PULL STRAP <i>new</i>	4 \$ 170.00	+
4	FRONT BUMPER GUIDE - RHS <i>new</i>	\$ 31.00	+
5	AIR GRILLE - RHS <i>new</i>	\$ 90.00	+
6	FRONT WHEEL HOUSE LINER - RHS <i>new</i>	\$ 146.00	✓ 11680
7	SUNDRIES <i>new</i>	\$ 300.00	? 4.32
TOTAL SPARE PARTS		:	\$ 2,674.00
TOTAL LABOUR CHARGES		:	\$ 2,252.00
GRAND TOTAL		:	\$ 4,926.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lim

Surveyed Date

: 28/12/17.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Authorised repairs, 03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1246/2017/JT
Date : 21-Dec-17

Vehicle not workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

3 days ok jb - 23Feb 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Wong Chun Khyam Jason
Address : Blk 296 Punggol Central
#06-497
Singapore 820296
Telephone : HP +65 9030 5780
Type of Claim : Own Damage Claims
Policy No. : 2100476376-010000
Vehicle No : **SLE 5071 T**
Model Code : Audi A3 Sedan 1.4 TFSI (A)
Model / Year : Jul-16
Engine No : CZC 550456
Chassis No : WAUZZZ8V2G1094224
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Dec-17
Place of Accident : Katong Plaza Carpark exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLE 5071 T.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper. Re-organize front crash management components. Reinstall all parts removed.	\$	900.00	\$ 500.00
3	To respray front bumper.	\$	800.00	\$ 550.00
4	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 2,252.00</u>	<u>\$ 1,602.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 5071 T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,667.00	\$ 1,333.60
2	FRONT BUMPER LOWER COVER - LHS/RHS	\$ 270.00	
3	FRONT BUMPER PULL STRAP	4 \$ 170.00	
4	FRONT BUMPER GUIDE - RHS	\$ 31.00	
5	AIR GRILLE - RHS	\$ 90.00	
6	FRONT WHEEL HOUSE LINER - RHS	\$ 146.00	\$ 116.80
7	SUNDRIES	\$ 300.00	\$ 4.32
	TOTAL SPARE PARTS	\$ 2,674.00	\$ 1,454.72
	TOTAL LABOUR CHARGES	\$ 2,252.00	\$ 1,602.00
	GRAND TOTAL	\$ 4,926.00	\$ 3,056.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLE 5071 T

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1246/2017/MAS

23 May 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLE 5071 T, Audi A3 SEDAN 1.4 TFSI

With reference to the above mentioned vehicle, no. **SLE 5071 T**, claimant, **Mr. Wong Chun Khyam Jason**, please find the related document as per attached.

1. A copy of the Original invoice no. 85012526 - \$2,628.69
2. A copy of letter of Discharge duly signed by client

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer generated document. No signature is required.

Norah Khai

Claims Dept

Encls

AIG Insurance – SLE 5071 T

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2017		29 Dec 2017 10:38 Edit Adj Rpt	\$43,056.72 Edit Estimates	\$43,056.72 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WONG CHUN KHYAM JASON , ID: S6971974J, Tel: +6590305780,		Email: JWONG296@GMAIL.COM						
Vehicle Reg. No.:	SLE5071T	Date of Loss:	20/12/2017 19:00 - :59 [16 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 2963899343SG	Policy/Cover Note No.:	2100476376-01000 (Comprehensive)						
		Excess:	S\$600.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/01/2018]								
Driver/Custodian:	WONG CHUN KHYAM JASON (48 / Male), NRIC: S6971974J, Tel: +6590305780								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (29/12/2017): SLE5071T / OD / 20/12/2017 / Coverage & Excess update 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE5071T (2963899343SG)
OD
Dec 20 2017 7:00PM
[WONG CHUN KHYAM JASON]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer
Photos/Images							3 per page
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print			
1	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
2	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
3	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
4	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
5	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
6	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
7	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
8	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
9	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
10	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
11	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
12	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
13	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
14	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
15	31/05/18 09:19	General View	Load JPG	<input checked="" type="checkbox"/>			
Documentation							1 per page
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print			
1	29/12/17 14:02	ESTIMATE	Load PDF				
2	29/12/17 14:02	Certificate of Insurance	Load PDF				
3	29/12/17 14:02	Driver's Driving License	Load PDF				
4	29/12/17 14:02	Singapore Accident Statement	Load PDF				
5	01/06/18 10:18	WORKSHOP INVOICE	Load PDF				
6	01/06/18 10:18	DISCHARGE VOUCHER	Load PDF				

Linked Accident Report Documents

			View	Use Viewer
Assessment Reports				1 per page
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/12/17 11:09	Accident Statement	Load HTM	
Photos/Images				3 per page
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/12/17 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	21/12/17 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	21/12/17 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	21/12/17 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	21/12/17 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	21/12/17 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	21/12/17 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	21/12/17 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	21/12/17 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	21/12/17 11:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	21/12/17 11:01	Sketch Plan	1	Load JPG	<input checked="" type="checkbox"/>
2	21/12/17 11:01	Sketch Plan #2	1	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17024655/ATBN2

Date: 01/06/2018

REFERENCE

Insured/Claimant: WONG CHUN KHYAM JASON Policy No: 2100476376-01000
Date of Loss: 20/12/2017 Nature of Claim: OD Claim No: 2963899343SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE5071T Engine No: CZC550456
Make & Model: AUDI A3, 1.4 TFSI (A) Chassis No: WAUZZZ8V2G1094224
Reg. Date: 25/07/2016 (Man. Year: 2016) Odometer: 37597 km
Colour: Bronze
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$110,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,674.00	1,454.72	1,219.28	45.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,252.00	1,602.00	650.00	28.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,926.00	3,056.72	1,869.28	37.95
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	4,326.00	2,456.72	1,869.28	43.21
+ GST 7.00/7.00% (S\$)	302.82	171.97	130.85	43.21
Nett Amount (S\$)	4,628.82	2,628.69	2,000.13	43.21

INSPECTION

Date of Assignment: 29/12/2017

Date Inspected: 28/12/2017 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,667.00 FS	*1,333.60 FS
2	2		*FRONT BUMPER LOWER COVER-LHS/RHS	Not Necessary	270.00 FS	*- FS
3	4		*FRONT BUMPER PULL STRAP	Not Necessary	170.00 FS	*- FS
4	1		*FRONT BUMPER GUIDE-RHS	Not Necessary	31.00 FS	*- FS
5	1		*AIR GRILLE-RHS	Not Necessary	90.00 FS	*- FS
6	1		*FRONT WHEEL HOUSE LINER-RHS	Torn	146.00 FS	*116.80 FS
7	1		*SUNDRIES	Necessary	300.00 FS	*4.32 FS
Total Parts (\$\$)					2,674.00	1,454.72

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER.RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	900.00	500.00
3	TO RESPRAY FRONT BUMPER	New	800.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			2,252.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >