

ASS. REC. BY:

REF: CS/MSG17024668/Uqd3e7

Special Instructions:

Solicitor: Marcell Menmen ASSIGNMENT (Office)From (Person): Winnie Chua of MSIG Date/Time: 29/12/17 @ 10:52am

Estimated Cost: _____ Bill to: _____

☒ OD / ☐ WP / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJR 953L Insured: _____at Workshop m/s Tan Lim Motor Tel: 68585151of 51 Defu Lane 10Policy No: A27322713 QMX Claim No: 539732Sum Insured: _____ Excess: \$500.00Make of Veh: _____ D.O.A. 5/12/17
(Client's Record)CA / ☒ REV / REP. / REV 24 HRS H.O.D. Endorsement: _____Date/Time: 11:16am @ 29/12/17 Person Contacted: Sharon Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJR 953L - x</u>
<u>29/12/17 @ 2:33pm</u>	<u>vernet to Winnie Chua via Meimen.</u>
<u>29/12/17 @ 2:55pm</u>	<u>Sian Wei informed c/o via Meimen.</u>
<u>29/12/17 @ 3:08pm</u>	<u>Informed Sharon c/o 8 ex: \$500 by email.</u>

REF:

CS1M3917024058 / 4905

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No: SJR 953L

at Workshop mis: Tan huan

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 28

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 1.5 % 3 Val.: Yes or No

☒ CA / ☐ REV / ☐ REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJR 953L Reg: 6 89

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or CA /

Make: Hyundai 1998

Colour: Black Insured / Std / NI / NA

Sp. Reading: 83933 T. Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR 05313K 410704614 /

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 215 / 60 R 16

R: _____

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 27/12/17 D.O.I. 29/12/17

Survey held at _____

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

hit n/s & hit w/screen

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

hit pedestrian

check insurance towing car charge. Reparer was replace dashboard

11/1/18 confirmed total of \$ 3714.20 with will cover
(ded \$ 3676.90, 50% -)
no lump sum

RECEIVED 12 JAN 2018

Date/Time: File Pass to? ☐ : Preli. Report

11/1/18 to MIA ☐ : Final Report

Date/Time: File Return to? _____

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee
Transportation

Add Fee: ☐ Site Insp. \$

☐ Interview \$

☐ Tech. Insp. \$

☐ Weekend \$

Report Format: Merob

Lump Sum / I.B.I. \$ 3714.20

200
10
210




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17024658/Uqd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 29-12-2017	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.	Veh. Inspected		SJR 953L
Policy No. A27322713QMX	Coverage (\$)		0.00
Claim No. 539732	Excess (\$)		500.00
Assign From MERIMEN (WINNIE CHUA)	Assign Date		29/12/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No. HIDDEN	Year of Reg.		
Chassis No.	Colour		
Odometer -	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date 05/12/2017	Inspection Date 29/12/2017		
Survey held at TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/17074658/Ug/13
Policy Type: OD / TP / TP RES / TL / EVA

SJR 953L

Admin (Muthu): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Naran): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By: [Signature] 21/1/18
Case Handler Date

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rat.	Adj. Submitted	Ins. Auth'd	Status
Main	27 Dec 2017 18:24 Sendback Est	27 Dec 2017 18:50 \$7,391.10	29 Dec 2017 10:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CHENG LENG CHUAN NICHOLAS, ID: S0016376G, Tel: +6596367714, Email: nickclc777@gmail.com		
Vehicle Reg. No.:	SJR953L	Date of Loss:	05/12/2017 23:00 - :59
Claim Type:	OD / 539732	Policy/Cover Note No.:	A27322713QMX (Comprehensive) Coverage: 09/06/2017 - 08/06/2018
		Excess:	S\$500.00
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Winnie Chua Ping Ping - 6594 2556]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/12/2017]		
Driver/Custodian:	CHENG LENG CHUAN NICHOLAS (64 / Male), NRIC: S0016376G, Tel: +6596367714		
Adj. Asg. Remarks:	please revert		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 29 December, 2017 3:08 PM
To: 'sharon.ow@tlmotor.com.sg'
Cc: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Subject: VEHICLE SJR 953L (DOA: 05/12/2017)

Dear Sharon,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle SJR 953L (excess \$500/-).

Please take noted that the towing fee is subject to receipt and sign & cop the undertaking letter and send it back to us.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	06 Dec 2017 12:24	Clim Veh Model Changed	(201714) TOYOTA CAMRY 2.0 (A).	[I] Winnie Chua Ping Ping
2	06 Dec 2017 12:24	Clim Created	Reg No: SJR953L. Policy No: A27322713QMX. Acct Date: 2017/12/05. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MTLM17160682	[I] Winnie Chua Ping Ping
3	06 Dec 2017 17:46	Clim Veh Model Changed	(201714) -> (204872) TOYOTA CAMRY 2.0 ABS AIRBAG (A).	[I] Jocelyn Ng Shin Bun
4	27 Dec 2017 18:23	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[I] Lam Wei Shong
5	27 Dec 2017 18:23	Clim Veh Model Changed	(204872) -> (201714) TOYOTA CAMRY 2.0 (A).	[R] Lam Wei Shong
6	27 Dec 2017 18:50	Clim Submitted	7391.10.	[R] Lam Wei Shong
7	28 Dec 2017 11:22	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):please revert	[I] Lui Siew Wei
8	28 Dec 2017 11:22	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/12/29	[I] Lui Siew Wei
9	28 Dec 2017 11:22	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Lui Siew Wei
10	28 Dec 2017 15:50	Assignment 1st Accessed		[A] Pauline Soh Li Ping
11	29 Dec 2017 10:52	Adj Assignment Cancelled		[I] Clara Milah Yeo
12	29 Dec 2017 10:52	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Clara Milah Yeo
13	29 Dec 2017 10:52	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):please revert	[I] Clara Milah Yeo
14	29 Dec 2017 10:52	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/12/30	[I] Clara Milah Yeo
15	29 Dec 2017 10:52	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Clara Milah Yeo
16	29 Dec 2017 11:19	Assignment 1st Accessed		[A] Nivitha Govindasamy
17	29 Dec 2017 11:59	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Nivitha Govindasamy
18	29 Dec 2017 14:23	Adj Rpt Initiated		[A] SHIAU CHAN
19	29 Dec 2017 14:31	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/01/28	[A] SHIAU CHAN
20	29 Dec 2017 14:31	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/28	[A] SHIAU CHAN
21	29 Dec 2017 14:33	Adj Mandate Request	Cur.Reg:3977.30:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY ADVISE THE TOWING FEE ABLE TO CHARGES? WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
22	29 Dec 2017 14:55	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/28. Mandate Remarks: a if c windscreen repair @ \$100.00 towing fee by workshop if repair carried out at the workshop	[I] Lui Siew Wei
23	29 Dec 2017 14:55	Adj Mandate Set	Approved:2769.30:a if c windscreen repair @ \$100.00 towing fee by workshop if repair carried out at the workshop	[I] Lui Siew Wei

ACTIVITY

[29/12/2017 10:43] Ho Pei Fang:

William informed car in.

[28/12/2017 15:51] Pauline Soh Li Ping:

Car not in, pending for Alvin to arrange and revert with survey appt.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1679635	27/12/2017 18:23	Motor	Tan Lim Motor Pte Ltd (HQ)	Tan Lim Motor Pte Ltd (Defu)	SJR953L		xx.xx
1681307	29/12/2017 14:23	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJR953L		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 29 Dec 2017

Preliminary Advice

Vehicle No	: SJR953L	Accident Date	: 05/12/2017
Make	: TOYOTA CAMRY	Policy No.	: A27322713QMX
Assignment Date	: 29/12/2017	Excess	: S\$500.00
Date of Inspection	: 29/12/2017	Est. Duration of Repair	: 4.00
Inspection At	: TAN LIM MOTOR PTE LTD (DEFU) 51 DEFU LANE 10 SINGAPORE 539216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s & front windscreen broken portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,391.10
Revised Amount	:S\$	2,789.30
Check Items (Estimated)	:S\$	1,188.00
Total	:S\$	3,977.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	28,000.00
COE / PARF Rebate	:S\$	14,798.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,202.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
Kindly advise the towing fee able to charges?
We have not authorise repair.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 6376G

Vehicle Details

Vehicle No.: SJR953L

Vehicle to be Exported: No

Intended De-registration
Date: 29 Dec 2017

Vehicle Make: TOYOTA

Vehicle Model: CAMRY 2.0 AUTO ABS
AIRBAG

Primary Colour: Black

Manufacturing Year: 2009

Engine No.: 1AZE138384

Chassis No.: MR053BK4107046141

Maximum Power Output: 108.0 kW (144 bhp)

Open Market Value: \$26,727.00

Original Registration Date: 09 Jun 2009

First Registration Date: 09 Jun 2009

Transfer Count: 0

Actual ARF Paid: \$26,727.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 08 Jun 2019

PARF Rebate Amount: \$14,699.00

Intended COE Rebate Details

COE Expiry Date: 08 Jun 2019

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$689.00

COE Rebate Amount: \$99.00

Total Rebate Amount: \$14,798.00

The information contained herein is correct as at 29 Dec 2017

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	6376G

Vehicle Details

Vehicle No.	SJR953L
Vehicle to be Exported	Yes
Intended De-registration Date	06 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour	Black
Manufacturing Year	2009
Engine No.	1AZE138384
Chassis No.	MR053BK4107046141
Maximum Power Output	108.0 kW (144 bhp)
Open Market Value	\$26,727.00
Original Registration Date	09 Jun 2009
First Registration Date	09 Jun 2009
Transfer Count	0
Actual ARF Paid	\$26,727.00 13363

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	08 Jun 2019
PARF Rebate Amount	\$14,699.00

Intended COE Rebate Details

COE Expiry Date	08 Jun 2019
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$689.00
COE Rebate Amount	\$103.00
Total Rebate Amount	\$14,802.00

The information contained herein is correct as at 06 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/12/2017 11:42
Date Of Accident	05/12/2017 23:30
Exact Location Of Accident	SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR953L
Insured/Policyholder	
Name Of Registered Owner	CHENG LENG CHUAN NICHOLAS
NRIC No	S0016376G
Email Address	NICKCLC777@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96367714
Alternative Phone No	OTHERS-96367714

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A27322713QMX
Cover Note Number	09/06/2017 TO 08/06/2018

Driver

Name of Driver	CHENG LENG CHUAN NICHOLAS
NRIC No	S0016376G
Date Of Birth	06/12/1952
Occupation	INDOOR
Date Of Driving Pass	25/06/1976
Driving Experience	41 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96367714
Fax Number	
Contact Number	OTHERS-96367714
Email Address	NICKCLC777@GMAIL.COM

Address	51A KOVAN ROAD #01-05 KOVAN LODGE
Postcode	548135
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLIDED INTO PEDESTRIAN
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to Police Report:- T/20171206/2037

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	PEDESTRIAN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
------	--

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

UNKNOWN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

NO

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

06/12/2020

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

TAN AI LAN

NRIC/FIN No.:

S7236742A

SKETCH PLAN

Sarangoon
Road

A: 5JR953L

Xin Yi
KTV

Green Garden
Bar & Rest

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

refer to Police report: - T/26/2006/2037

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

06/12/17 01:00

Driver's Signature


(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: TAN A LIA

NRIC/FIN No.:



5122679A



**SINGAPORE
POLICE FORCE**



T/20171206/2037

1 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20171206/2037

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/12/2017 11:03	Vide Report No.:	Station Diary No.: 32
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: CHENG LENG CHUAN NICHOLAS		Address: 51A KOVAN ROAD #01-05 SINGAPORE 548135	
ID Type / ID No.: NRIC NO / S0016376G		Contact No.: Home/Office: Mobile: 96367714	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 65	Date of Birth: 06/12/1952	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: RETIRED		Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Pedestrian / Cyclist	Drink Drive: No	Date/Time of Accident: 05/12/2017 23:30	Type of Location: Straight Road
Location: Along Road 1 SERANGOON ROAD				
SERANGOON ROAD TOWARDS UPPER SERANGOON ROAD AFTER BEATTY ROAD. Along the road next to 'Green Garden Bar and Flux Bar'				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Pedestrian				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJR953L	Car	TOYOTA	CAMRY 2.0 AUTO ABS AIRBAG	Black	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20171206/2037

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 3

Report No. T/20171206/2037

CONTINUATION OF REPORT

Driver			
Name	CHENG LENG CHUAN NICHOLAS	ID No.	S0016376G
Related Vehicle	NIL	Contact No.	96367714
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date, time and place, reference to incident A/20171205/0182, as I was travelling along Serangoon Road on the fourth lane of the five lane road. During this time, I passed by a traffic light which was green and continued straight. Suddenly, a pedestrian dashed out of the pedestrian walk way next to a pub and ran across the road. I did not see him run across. I immediately did an e-brake and my car swerved to the right but my vehicle still hit the pedestrian as it was too late to avoid. My car ended up on the third lane after coming to a complete stop. I wish to state that I was travelling at a speed of 50km/h during that time.

After my car came to a stop, I immediately got out of my car and went to assist the man that was at that time lying on the ground. His t-shirt was covering his face and as such, I brought his t-shirt down. During this time, the man was still breathing and there was a strong smell of alcohol. I then called for ambulance however during this time, there was a passing ambulance and I had flagged that ambulance down. The ambulance PA112 had then attended to the man and he was conveyed to Tan Tock Seng Hospital. Shortly after, traffic police had arrived and they attended to me.

As the pedestrian had hit the left side of my vehicle, there are damages to the front left head lamp and my wind screen at the left side. My car was later towed away by the traffic police. The IO in charge of my accident is IO Jeya (65476232). Reference to incident A/20171205/0182.



**SINGAPORE
POLICE FORCE**



T/20171206/2037

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 3

Report No. T/20171206/2037

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 ASHLEY ANDREW

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

06/12/2017 11:03

Officer In Charge Of Case:

TP / AEIT /

SSI 2 SITIMARSITA BINTE BOHARI

Contact No.: 65476219

Classification Of Case:

Authentication Stamp

NP168



Signature:

Singapore Police Force



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

POLICY INFORMATION

Claim Type:	OD (Own Damage)	Ref. No:	OD004122017
Policy No:	A27322713QMX	Date of Loss:	05/12/2017
Vehicle Reg. No.:	SJR953L	Driveable?	YES
Driver Age/Info:	64 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	CHENG LENG CHUAN NICHOLAS	Contact No:	+6596367714
Driver:	CHENG LENG CHUAN NICHOLAS		

Make/Model:	TOYOTA CAMRY, 2.0 (A)	Vehicle Reg. Date:	01/10/2009
Vehicle Colour:	Black	Gen Condition:	Good
Engine No:	1AZE138384	Chassis No:	MR053BK4107046141
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair 5 (day)

Description of Accident/Loss: OI HIT PEDESTRIAN
Present Location: TAN LIM MOTOR PTE LTD (DEFU)

24 - Marcus
29/12/17 C 1100h

Not Authorized
make
EXCESS \$500
4 days
taking the responsibility

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	5,141.10
Labour	0.00
Paintwork Labour	1,350.00
Towing	900.00
	0.00

Calculated Gross Total (\$\$)	7,391.10
- Excess (\$\$)	500.00
(\$\$)	6,891.10
+ GST 7.00% (\$\$)	482.38
Nett Amount (\$\$)	7,373.48

As the Consultants hence notify
the insurer of the following:
• Resurvey before spray painting
• Display (damaged parts) during resurvey
• This price are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No other modification is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

This claim is handled by: LAM WEI SHONG

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Dec 2017)
 Parts: 143 TOYOTA CAMRY 2.0 (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Tan Lim Motor Pte Ltd/SJR953L/27/12/2017 18:50
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*bonnet <i>22/34C</i>	0.00	0.00	*360.00 F	✓
2	2		*bonnet hinges <i>n</i>	0.00	0.00	*50.00 F	✓
3	1		*bonnet insulator <i>11</i>	0.00	0.00	*160.00 F	✓
4	9		*bonnet insulator <i>11</i>	0.00	0.00	*13.50 F	✓
5	12		*bonnet underseal weatherstrip clips <i>11C</i>	0.00	0.00	*18.00 F	✓
6	1		*n/s headlamp <i>320</i>	0.00	0.00	*250.00 F	✓
7	1		*front bumper <i>22/1004</i>	0.00	0.00	*180.00 F	✓
8	2		*front bumper retainers <i>11/304</i>	0.00	0.00	*50.00 F	✓
9	2		*front bumper chrome moulding side <i>11</i>	0.00	0.00	*70.00 F	✓
10	1		*n/s front bumper spot lights <i>11</i>	0.00	0.00	*90.00 F	✓
11	1		*n/s front bumper spot lights garnish <i>11</i>	0.00	0.00	*25.00 F	✓
12	10		*front bumper clips <i>11</i>	0.00	0.00	*15.00 F	✓
13	1		*n/s front fender <i>11</i>	0.00	0.00	*165.00 F	✓
14	1		*n/s front fender VVTI badge <i>11</i>	0.00	0.00	*20.00 F	✓
15	5		*n/s front fender inner cowlings clips <i>11</i>	0.00	0.00	*7.50 F	✓
16	1		*wiper grille <i>11</i>	0.00	0.00	*185.00 F	✓
17	1		*n/s wiper blade <i>11</i>	0.00	0.00	*35.00 F	✓
18	1		*n/s wiper arm <i>11</i>	0.00	0.00	*60.00 F	✓
19	1		*wiper linkage 1 set <i>11</i>	0.00	0.00	*185.00 F	✓
20	1		*front windscreen glass <i>320</i>	0.00	0.00	*400.00 F	✓
21	1		*front windscreen glass weatherstrip <i>11</i>	0.00	0.00	*40.00 F	✓
22	1		*front windscreen glass solar film <i>11</i>	0	0.00	*250.00 FS	✓
23	1		*front windscreen glass sealant <i>11</i>	0	0.00	*50.00 FS	✓
24	1		*front windscreen glass inner sponge seal <i>11</i>	0	0.00	*120.00 FS	✓
25	1		*front windscreen glass ERP bracket <i>11</i>	0	0.00	*12.00 FS	✓
26	1		*n/s front windscreen A pillar - repair <i>11</i>	0.00	0.00	*250.00 F	✓
27	1		*instrument dashboard assy <i>11</i>	0.00	0.00	*680.00 F	✓
28	1		*front support panel <i>11</i>	0.00	0.00	*972.00 F	✓

F=Franchise part. S=SpcNett.

Sub Total (S\$)	4,713.00
+ Margin on L,N Items 10.00% (S\$)	428.10
Total Parts (S\$)	5,141.10

Tan Lim Motor Pte Ltd/SJR953L/27/12/2017 18:50. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

1-2002
 102
 220220
 1123714.20

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Putty and spray painting of the affected portion.	New 700	900.00
Labour Items			
2	To remove and refit front windscreen glass.	New 120	200.00
3	To check electrical lighting concerned.	New 20	60.00
4	To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	New 200	380.00
5	Towing charges.	New POC	60.00 X
6	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New 400	650.00
Gross Labour Cost (\$\$)			2,250.00

Tan Lim Motor Pte Ltd/SJR953L/27/12/2017 18:50. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

1440



HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
 TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
 DAIHATSU / KIA / SUZUKI / HONDA
 TEL: 6291 2827 FAX: 6296 4390
 A/C: 6291 1886 FAX: 6291 7717
 Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

ALSO TIAN LIN MOTOR PTE LTD

NO 0719197759

DATE

TIME

AMOUNT

11.11.11

11.11.11

11.11.11

11.11.11

9.11.11

11.11.11

11.11.11

11.11.11

11.11.11

QTY	DESCRIPTION	UNIT	PRICE	TOTAL
1	FRONT BUMPER	DB118	880.00	880.00
1	FRONT BUMPER	DB118	880.00	880.00
1	FRONT BUMPER	DB361	880.00	880.00
1	FRONT BUMPER	DB361	880.00	880.00
1	FRONT BUMPER	DB361	880.00	880.00
1	FRONT BUMPER	DB361	880.00	880.00
1	FRONT BUMPER	DB361	880.00	880.00
1	FRONT BUMPER	DB361	880.00	880.00
1	FRONT BUMPER	DB361	880.00	880.00
1	FRONT BUMPER	DB361	880.00	880.00

Our D/O No: DDO9021004

1	FRONT BUMPER	DB361	880.00	880.00
---	--------------	-------	--------	--------

QUANTITY

TOTAL

SIN 2,002.00

ADD GST 12%

240.24

GRAND TOTAL

SIN 2,142.14

Print NAME: 3012 2012 21 21 21 21

SALTSMA: NAME

This document is computer generated. No signature required.

GOODS SHALL BE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Putty and spray painting of the affected portion.	New 700	900.00
Labour Items			
2	To remove and refit front windscreen glass.	New 120	200.00
3	To check electrical lighting concerned.	New	60.00
4	To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	New 300	380.00
5	Towing charges.	New ?	60.00
6	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New 400	650.00
Gross Labour Cost (S\$)			2,250.00

Tan Lim Motor Pte Ltd/SJR953L/27/12/2017 18:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

Parts \$2,002.00


Labour \$200.20

\$2,202.20

Goods \$72.00

Labour \$40.00

\$3,714.20



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017 18:24 Sendback Est	27 Dec 2017 18:50 S\$7,391.10	29 Dec 2017 10:52 Edit Adj Rpt	S\$3,714.20 Edit Estimates	S\$3,714.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:	CHENG LENG CHUAN NICHOLAS , ID: S0016376G, Tel: +6596367714, Email: nickclc777@gmail.com		
Vehicle Reg. No.:	SJR953L	Date of Loss:	05/12/2017 23:00 - :59
Claim Type:	OD / 539732	Policy/Cover Note No.:	A27322713QMX (Comprehensive) Coverage: 09/06/2017 - 08/06/2018
		Excess:	S\$500.00
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Winnie Chua Ping Ping - 6594 2556]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 28/01/2018]		
Driver/Custodian:	CHENG LENG CHUAN NICHOLAS (64 / Male), NRIC: S0016376G, Tel: +6596367714		
Adj Asg. Remarks:	please revert		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- MSIG_SG (29/12/2017): Alert - Adj Mandate Approved (S\$2769.30) - SJR953L - Claim Handler: Winnie Chua ...



































ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJR953L (539732)
OD
Dec 5 2017 11:00PM
[CHENG LENG CHUAN NICHOLAS]
Tan Lim Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>	
Assessment Reports				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)		Thumbnail	Print
1	06/12/17 12:11	Accident Statement		Load HTM	
2	27/12/17 18:50	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/12/17 14:31	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/12/17 15:40	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
2	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
3	29/12/17 15:40	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
4	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
5	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
6	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
7	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
8	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
9	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
10	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
11	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
12	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
13	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
14	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
15	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
16	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
17	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
18	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
19	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
20	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
21	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
22	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
23	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
24	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
25	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
26	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
27	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
28	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
29	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
30	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>
31	29/12/17 15:40	General View		Load JPG	<input checked="" type="checkbox"/>

32	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	29/12/17 15:40	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
59	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
60	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
61	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
62	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
63	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
64	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
65	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
66	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
67	11/01/18 09:32	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	06/12/17 17:35	PARF COE	1	Load PDF	
2	08/12/17 15:07	aspectus investigation report - 50/50 pend for pedestrian police report and pir	1	Load PDF	
3	14/12/17 13:53	email from nat - will keep us update on police report and pir	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/12/17 14:32	WORKSHOP ESTIMATE	1	Load PDF	
2	16/01/18 16:55	Parts Invoice	1	Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print

1	06/12/17 12:11	Accident Statement	1	Load HTM	
Photos/ Images			3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)		Thumbnail	Print
1	06/12/17 12:10	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	06/12/17 12:10	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	06/12/17 12:10	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	06/12/17 12:10	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	06/12/17 12:11	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)		Thumbnail	Print
1	06/12/17 11:52	Sketch Plan	1	Load TIF	
2	06/12/17 11:52	Police Report	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p>Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17024658/UQD3E2

Date: 16/01/2018

REFERENCE

Insured/Claimant: CHENG LENG CHUAN NICHOLAS

Policy No: A27322713QMX

Date of Loss: 05/12/2017

Nature of Claim: OD

Claim No: 539732

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR953L

Make & Model: TOYOTA CAMRY, 2.0 (A)

Engine No: 1AZE138384

Reg. Date: 09/06/2009 (Man. Year: 2009)

Chassis No: MR053BK4107046141

Colour: Black

Odometer: 83933 km

Engine Capacity: 1998 cc

Market Value/New Car Price: S\$28,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,141.10	2,274.20	2,866.90	55.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	740.00	610.00	45.19
Paintwork Labour	900.00	700.00	200.00	22.22
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,391.10	3,714.20	3,676.90	49.75
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	6,891.10	3,214.20	3,676.90	53.36
+ GST 7.00/7.00% (S\$)	482.38	224.99	257.39	53.36
Nett Amount (S\$)	7,373.48	3,439.19	3,934.29	53.36

INSPECTION

Date of Assignment: 29/12/2017

Present Location:

Tan Lim Motor Pte Ltd (Defu)

Date Inspected: 29/12/2017

Inspected At:

51 Defu Lane 10
Singapore 539216

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 16 Jan 2018)

Parts: 143 **TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: (Unsubmitted, no print-code for SJR953L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*bonnet (WCP)	Dented / Buckled	360.00 F	*360.00 F
2	2		*bonnet hinges (WCP)	Repair	50.00 F	*- F
3	1		*bonnet insulator (WCP)	Not Necessary	160.00 F	*- F
4	9		*bonnet insulator (WCP)	Not Necessary	13.50 F	*- F
5	12		*bonnet underseal weatherstrip clips (WCP)	Serviceable	18.00 F	*- F
6	1		*n/s headlamp (WCP)	Broken	250.00 F	*250.00 F
7	1		*front bumper (WCP)	Deformed / Warped	180.00 F	*180.00 F
8	1		*front bumper retainers (WCP)	N/S Bent	50.00 F	*25.00 F
9	2		*front bumper chrome moulding side (WCP)	Not Necessary	70.00 F	*- F
10	1		*n/s front bumper spot lights (WCP)	Not Necessary	90.00 F	*- F
11	1		*n/s front bumper spot lights garnish (WCP)	Not Necessary	25.00 F	*- F
12	10		*front bumper clips (WCP)	Necessary	15.00 F	*12.00 F
13	1		*n/s front fender (WCP)	Repair	165.00 F	*- F
14	1		*n/s front fender VVTI badge (WCP)	Necessary	20.00 F	*20.00 F
15	5		*n/s front fender inner cowling clips (WCP)	Not Necessary	7.50 F	*- F
16	1		*wiper grille (WCP)	Not Necessary	185.00 F	*- F
17	1		*n/s wiper blade (WCP)	Cracked	35.00 F	*35.00 F
18	1		*n/s wiper arm (WCP)	Not Necessary	60.00 F	*- F
19	1		*wiper linkage 1 set (WCP)	Not Necessary	185.00 F	*- F
20	1		*front windscreen glass (WCP)	Broken	400.00 F	*400.00 F
21	1		*front windscreen glass weatherstrip (WCP)	Necessary	40.00 F	*40.00 F
22	1		*front windscreen glass solar film	Not Insured	250.00 FS	*- FS
23	1		*front windscreen glass sealant	Necessary	50.00 FS	*40.00 FS
24	1		*front windscreen glass inner sponge seal	Necessary	120.00 FS	*20.00 FS
25	1		*front windscreen glass ERP bracket	Necessary	12.00 FS	*12.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*n/s front windscreen A pillar - repair (WCP)	Repair	250.00 F	*- F
27	1		*instrument dashboard assy (WCP)	Cut	680.00 F	*680.00 F
28	1		*front support panel (WCP)	Repair	972.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	4,713.00	2,074.00
+ Margin on L,N Items 10.00/10.00% (S\$)	428.10	200.20
Total Parts (S\$)	5,141.10	2,274.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Putty and spray painting of the affected portion.	New	900.00	700.00
<u>Labour Items</u>				
2	To remove and refit front windscreen glass.	New	200.00	120.00
3	To check electrical lighting concerned.	New	60.00	20.00
4	To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	New	380.00	200.00
5	Towing charges.	New	60.00	0.00
6	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	650.00	400.00
Gross Labour Cost (\$)			2,250.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >