

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7797H - AIG**AAD1712-277***Not Authored
1/1/8*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB7797H - JHOW

KL1LA69RJB107763

CHEVROLET

CHEVROLET EPICA 2.0

26.12.2017

AIG**PART****LIST**

1	1	Front Bumper	\$	<i>Bu</i> 1,202.00 ✓
2	1	Front Bumper Lower Absorber	\$	<i>Sn</i> 180.00 X
3	1	Front Bumper Reinforcement	\$	<i>R</i> 356.00 X
4	1	Front Bumper Retainer RH	\$	<i>Div</i> 102.00 ✓
5	1	Front Bumper Retainer LH	\$	<i>Sn</i> 102.00 X
6	1	Front Bumper Lower Grille	\$	<i>Sn</i> 78.00 X
7	1	Front Bumper Lower Stiffener	\$	<i>Sn</i> 134.37 X
8	1	Bumper Fog Lamp Cover RH	\$	<i>Sn</i> 32.40 X
9	1	Front Headlamp RH	\$	<i>Gr</i> 816.00 ✓
10	1	Front Fender RH	\$	<i>R</i> 837.60 ✓
11	1	Front Fender Liner RH	\$	<i>Div</i> 47.00 ✓
12	1	Windscreen Washer Tank - Filler Neck	\$	<i>Sn</i> 4.80 X
13	1	Windscreen Washer Tank	\$	<i>Sn</i> 62.00 X
14	1	Windscreen Washer Tank Motor	\$	<i>Sn</i> 51.00 X
15	1	Front Shock Absorber Assy RH	\$	<i>Sn</i> 216.17
16	1	Front Lower Arm RH	\$	<i>Sn</i> 283.00
17	1	Front Knuckle Arm RH	\$	<i>Sn</i> 230.00
18	1	Bonnet	\$	<i>R</i> 1,250.00
19	1	Bonnet Moulding	\$	<i>Sn</i> 161.97
20	1	Bonnet hinge RH	\$	<i>R</i> 36.00
21	1	Bonnet hinge LH	\$	<i>R</i> 36.00
22	1	Front Support Panel Assy	\$	<i>R</i> 1,222.32
23	1	Radiator Grille (Grille A-Rad)	\$	<i>Sn</i> 367.00
24	1	Radiator Grille Top Cover	\$	<i>Sn</i> 45.02
25	1	Front Door RH	\$	<i>R</i> 1,133.00
26	1	Front Side View Mirror RH	\$	<i>Sn</i> 939.00

TOTAL	\$	9,924.65
10%	\$	992.47
	\$	8,932.19

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-277**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7797H - AIG**Specical Nett**

1	1 Set Front Bumper Fastener Clip	\$	<i>nr</i> 30.00 ✓
2	1 Set Front Fender Liner Clip RH	\$	<i>nr</i> 30.00 ✓
3	1 Front Wheel Rim Hub Cap RH	\$	<i>sn</i> 166.30 X
4	1 Front Tyre RH	\$	<i>sn</i> 180.00 X
5	1 Front Tyre Rim RH	\$	<i>sn</i> 126.00 X
6	1 Door Sticker "Trans-cab" RH	\$	<i>nr</i> 80.00 X

TOTAL	\$	612.30
TOTAL PARTS	\$	9,544.49

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	5,400.00 <i>400</i>
To Rust-Proofing Of The Affected Areas.	\$	220.00 <i>30</i>
Putty and Spray Painting Of The Affected Portion.	\$	5,350.00 <i>400</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>20</i>
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00 X
Towing Fees.	\$	<i>nr</i> 120.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nr</i> 380.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nr</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-277**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7797H - AIG

TOTAL	\$	12,370.00
Over All Total	\$	21,914.49

REPAIR DAYS~~20~~**DAYS***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: