

REPAIR ESTIMATE*

VEHICLE NO : SH 7441Y

DATE 28/12/2017 14:13

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 538.80
	Front Bumper Bracket (RH) ?			\$ 20.10
	Headlamp (RH) ✓		\$ 797.90	\$ 1,595.80
	SUB TOTAL			\$ 2,154.70
	LESS 20%			\$ 430.94
	DISCOUNTED TOTAL			\$ 1,723.76
	Labour Charge			
	Panel Beating			\$ 500.00 ²⁰⁰
	Spray Painting Charge			\$ 400.00 ³⁶⁰
	Wiring Charge			\$ 50.00 ²⁰
	TOTAL LABOUR			\$ 950.00
	ESTIMATE TOTAL			\$ 2,673.76
<p>Calvin CLKK</p> <p>28/12/17 1510hrs</p> <p>2 Days</p> <p>4/5</p> <p>After Repair photo</p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				