CITY CAB PTE LTD REPAIR ESTIMATE*

VEHICLE NO: SHC 7927U

MAKE

ALG

DATE 27/12/2017 15:02

DOA: 26.12.17

Qty	Parts Description/ Labour	Type	Unit Price	1	Amount
	Rear Bumper	* 4		\$	603.60
	Rear Bumper Reinforcement ?			\$	504.35
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$	360.00
	Rear Bumper Side Bracket ?		3 100.00	555	
	Rear Bumper Clips			8	49.00
				S	22.00
	Rear Bumper Sponge ?			\$	143.40
	Rear Bumper Under Cover			\$	225.00
	Rear Bumper Reflector Lamp (RH)			\$	32.00
	SUB TOTAL			\$	1,939.35
	LESS 20%			S	387.87
	DISCOUNTED TOTAL			\$	1,551.48
					1,001110
	Rear Bumper Reverse Sensor			\$	135.70
	Rear Bumper Rubber Mat			\$	50.00
				\$	185.70
	Labour Charge				200
	Panel Beating			\$	560.00
	Spray Painting Charge			\$	400.00
	Wiring Charge			\$	50.00
	R/Refix Reverse Sensor			\$	120.00
	TOTAL LABOUR			\$	1,130.00
	ESTIMATE TOTAL			\$	2,867.18
	1 1 . 1161				
	Kalun 1(11/4) 1/2 1/2/12 1100 hm 2 8/2/12 1100 hm				
arry Ng	11 0/0/2 1106				
	// 28/2/c+ 1100 cm				
	7 2 Pm;				
	T. 6 /2/2				
	PIP				
	Ola Part plob				
	2 Pags Poto Petore Part plob				
			111 == 1		
	This is an initial estimate based on a visual inspection of the	e above vo	ehicle. The final repair of	quant	um will