

26 Dec 2017

AIG Insurance Pte Ltd

Singapore

Attn: Motor Claim Department

Re : 1 Quotation

Vehicle SLF 2441Z (Citreon C4)

Not Authetic
1 B.1
Recovery B & pain
6 days

S/N	Description	Amount (\$S)
	Parts Replacement	
	Front Bumper <i>B₁</i>	\$ 1,354.00
	Front mudguard left <i>B₁</i>	\$ 789.00
	Headlamp Left <i>S₁</i>	\$ 892.00
	Side lamp Left <i>C₁</i>	\$ 853.00
	Front bumper retainer left <i>P₁</i>	\$ 98.00
	Spot lamp Left	\$ 245.00
	Spot lamp cover <i>C₁</i>	\$ 187.00
	Shock absorber Left	\$ 654.00
	Knuckle with bearing <i>A₁</i>	\$ 1,189.00
	Wheel rim <i>P₁</i>	\$ 870.00
	Front mudguard cowling <i>N₁</i>	\$ 290.00
	Mudguard inner garnish <i>S₁</i>	\$ 187.00
	Autogear computer board ECU <i>C₁</i>	\$ 2,950.00
	Front bumper grille <i>C₁</i>	\$ 478.00
	Horn	\$ 178.00
	Front bumper spone	\$ 324.00
	Front bumper reinforcement	\$ 590.00
	Mudguard inner panel <i>P₁</i>	\$ 249.00
	front lower panel garnish	\$ 184.00
	Left lower control arm	\$ 487.00
	Left drive shaft	\$ 1,890.00
	Wiper grille spone <i>S₁</i>	\$ 98.00
	Head lamp inner garnish	\$ 198.00
		\$ 15,234.00
	less 5%	\$ 14,472.30
	Nett items:	
	Tyre <i>P₁</i>	\$ 300.00
	Tow to workshop	\$ 70.00
	Labour Charges	

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

LOH HENG

Automotive Repair Services
Accident Insurance Claims

	Labour to remove and replace new parts.	\$ 780.00
	To do reprogramming ECU auto gearbox.	\$ 450.00
	To readjust front wheel alignment	\$ 80.00
	To remove and fix front shock absorber	\$ 120.00
	To putty and spray paint on rear panel and new parts. Pearl White	\$ 980.00
	Total:	\$ 17,252.30

600
?
60
✓
800

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384