

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF687S - AXA**AAD1712-291***Not Authorized*
L1 Sing & 5550h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF687S - JHOW

VF1ABL15AUC278758

RENAULT

LATITUDE

27.12.2017

AXA**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Mr</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Mr</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sm</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>Sm</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sm</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>Sm</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>Mr</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1	BOOT REAR	\$	<i>Mr</i> 2,872.68 ✓
14	1	BOOT FINISHER	\$	<i>Sm</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>Sm</i> 323.05 X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 493.35 X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 493.35 X
18	1	BOOT BADGE 'RENAULT'	\$	<i>Mr</i> 225.36 ✓
19	1	BOOT BADGE	\$	<i>Mr</i> 225.36 ✓
20	1	BOOT SWITCH	\$	<i>Sm</i> 168.13
21	1	BOOT LOCK	\$	<i>R</i> 202.67
22	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40
23	2	LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52
24	2	BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81
25	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
26	1	WHEELARCH REAR LH	\$	<i>Sm</i> 543.47
27	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13
28	1	WHEELARCH REAR RH	\$	<i>Sm</i> 543.47
29	1	TAILLAMP RH	\$	<i>Sm</i> 552.55
30	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70
31	1	TAILLAMP LH	\$	<i>Sm</i> 552.55
32	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70
33	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77 X
34	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Mr</i> 404.56 ✓

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-291

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF687S - AXA

35	1	EXHAUST REAR	\$	7,489.05 X
36	1	EXHAUST CAP REAR	\$	230.49 X

TOTAL	\$	29,849.67
10%	\$	2,984.97
	\$	26,864.70

Specical Nett

1	1SET	PARKING AID	\$	700.00 X
2	1SET	REAR BUMPER CLIP	\$	66.00
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00 X
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	20.00 X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	10.00 X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00
10	1	EXHAUST MOUNTING REAR	\$	17.82 X
11	1SET	BOOT FINISHER CLIP	\$	24.20 X
12	1	BOOT STICKER "Trans-cab"	\$	30.00
13	1	BOOT STICKER "6555-3333"	\$	30.00
14	1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00 X
15	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00 X
16	1	TAILLAMP CLIP RH	\$	5.00 X
17	1	TAILLAMP CLIP LH	\$	5.00 X
18	2	REAR WINDSCREEN SELANT	\$	80.00 X
19	1	WINDSCREEN MOULDING	\$	100.00 X
20	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00 X
21	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00 X
22	1	SPARE TYRE	\$	330.00 X

TOTAL	\$	2,124.02
TOTAL PARTS	\$	28,988.72

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00 400
To Rust-Proofing Of The Affected Areas.	\$	170.00 301

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-291**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF687S - AXA

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
Towing Fees	\$	~ 120.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X

TOTAL	\$	7,710.00
Over All Total	\$	36,698.72

(PARTS BY PARTS)
Repair Days

10-Days*2 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date