

ASS. REC. BY:

REF: CS/MSG17024669/Aqd3n2

Special Instruction:

SUPERVISOR:

Adrian

ASSIGNMENT (Office)

From (Person):

Monica chung

of

MSG

Date/Time: 28/12/17 @ 5:02pm

Estimated Cost:

Bill to:

OD ☒ WS ☐ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM 716G

Insured:

SLU 38684

at Workshop m/s

TK Motor Workshop

Tel:

9627 3323

of Blk 1, kaki Bkt Ave 6 #02-56 Autobay

Policy No:

29032696TMC

Claim No:

543192

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/12/17

CA / REV / REP. / REV 24 HRS

(wp)

29/12/17

H.O.D. Endorsement:

Date/Time:

5:23pm @ 28/12/17

Person Contacted:

Keong

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (☒) Estimate

SJM 716G - CCA / ICS17007111 / Kub3

D.O.A. : 03/04/2017

SLU 38684 - X

03/11/18 @ 9.40a Informed Monica, we are pending estimate from repairer.

19/11/18 @ 5.56pm revised to Monica Chung via Messenger.

15 @ 7000, 8 days CRED @ 11075, 61%

REF: MSIG

19/12/2008

(Repairs ask to call)

ASSIGNMENT

12 2008

From: Date: 29/12/17

Estimated Cost:

OD TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJM 716G
at Workshop m/s: TK Motor Workshop
of Blk 1, Kelki Bkt Ave 6 #02-56

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record) Keong @ 9627 3323

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 1wp

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJM 716G.

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ford Mondeo 2261

Colour: Brown A/O Insured / Std / NI / NA

Sp. Reading: 209219 T. Radio: Insured / Std / NI / NA

Eng/No:

C/No: WFOEXX 488E 7P89085

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. D.O.I. 29/12/17

Survey held at: T.K.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MSIG.

RECEIVED 21 SEP 2018

Date/Time File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time File Return to?

2:

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee

Transportation

300

10

310

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Insp (\$)☐ Weekend (\$)

Report Format: MEK-7P

Lump Sum / I.B. (\$)

7000



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17024669/Aqd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 29-12-2017

Code : MSG



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 3858U	Veh. Inspected	SJM 716G
Policy No.	29032696TMC	Coverage (\$)	0.00
Claim No.	543192	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	29/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/12/2017	Inspection Date	29/12/2017
Survey held at	T K MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-56 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 19 Sep 2018

Preliminary Advice

Insured Vehicle No	: SLU3858U	Accident Date	: 26/12/2017
TP Vehicle No	: SJM716G	Assignment Date	: 28/12/2017
Make	: FORD MONDEO	Est. Duration of Repair	: 8
Date of Inspection	: 29/12/2017		
Inspection At	: TK MOTOR WORKSHOP		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,075.00
Revised Amount	:S\$	9,167.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,167.40

Lump Sum Repair	:S\$	7,000.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Dec 2017		28 Dec 2017 17:02 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RIDE NOW PRIVATE LIMITED, Co. Reg. No.: 201628643D		
Main Claimant:	POH BOON SIONG DERRICK, ID: S8124432D		
Vehicle Reg. No.:	SJM716G	Date of Loss:	26/12/2017 00:00 - :59
Claim Type:	TP / 543192	Policy/Cover Note No.:	29032696TMC (Third Party Only) Coverage: 27/10/2017 - 26/10/2018
Vehicle Reg. No. (Insured):	SLU3858U	Policy No. (Claimant):	
		Excess:	
Repairer:	Tk Motor Workshop (HQ) Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt, 417883 Kaki Bukit - Tel: 67466896		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/12/2017]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Nivitha (LKK Auto)

From: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>
Sent: Thursday, 28 December, 2017 4:45 PM
To: 'Kuru & Co'; 'Nivitha (LKK Auto)'
Cc: Monica Chung; Rashitha Binte Shahuthuman
Subject: RE: PRI SURVEY - SLU3858U(OI) / SJM716G ON 26/12/2017 --Our ref: L.17.1900.It(jt)

Dear LKK,

Please arrange to survey SJM716G at TK Motor workshop.





We will grant rights to you in merimen soon. Thank you .

Rashitha

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Thursday, 28 December, 2017 3:19 PM
To: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>
Cc: Monica Chung <Monica_Chung@sg.msig-asia.com>
Subject: Re: PRI SURVEY - SLU3858U(OI) / SJM716G ON 26/12/2017 --Our ref: L.17.1900.It(jt)

Dear Sirs,

Our client is agreeable to the following surveyor(s) as the Single Joint Expert: **LKK Auto Consultants Pte Ltd**

Please arrange for your surveyor to survey our client's vehicle at the following address:

TK Motor Workshop
AutoBay@Kaki Bukit
Blk 1 Kaki Bukit Ave 6
#02-56
Singapore 417883
Tel: 96273323

Please instruct your surveyor to conduct the pre-repair survey immediately and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey(s).

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Thanks / Rgds,

Lena
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

From: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msiga-asia.com>
To: 'Kuru & Co' <kurulegal@yahoo.com.sg>
Cc: Monica Chung <Monica_Chung@sg.msiga-asia.com>; Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msiga-asia.com>
Sent: Thursday, 28 December 2017, 14:50
Subject: PRI SURVEY - SLU3858U(OI) / SJM716G ON 26/12/2017

OUR REF – TAB

WITHOUT PREJUDICE

Dear Sirs,

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for any of the above surveyor to be the SJE (Single Joint Expert) .

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.





Thank you.

Rashitha

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 3 January, 2018 9:40 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SJM 716G (YOUR REF: 543192)

This mail is associated with :
***SJM716G (543192)**
[SLU3858U]
TP
POH BOON SIONG DERRICK
Dec 26 2017 12:00AM
[RIDE NOW PRIVATE LIMITED]
Tk Motor Workshop

Dear Monica,

Please be informed that we have inspected the vehicle SJM 716G on 29/12/2017.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561
Fax: 6256 4315

[This mail is sent from a mailer account - do not reply to this email address]

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

MSUU17170166 / Success United Pte Ltd - HD
ENTRY DATE & TIME: 27/12/2017 19:11
SUBMITTED BY: Sirina Soon

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 27/12/2017 19:11
Date Of Accident 26/12/2017 07:35
Exact Location Of Accident SLE TOWARDS WOODLAND
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJM716G
Insured/Policyholder
Name Of Registered Owner POH BOON SIONG, DERRICK
NRIC No S8124432D
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-97275236
Alternative Phone No OFFICE-97275236
Vehicle Particulars
Manufacturer FORD
Model MONDEO-2.3 GHIA (A)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company ECICS LIMITED
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number MPC17A00322401
Cover Note Number
Driver
Name of Driver POH BOON SIONG, DERRICK
NRIC No S8124432D
Date Of Birth 10/08/1981
Occupation INDOOR
Date Of Driving Pass 03/10/2003
Driving Experience 14 YEARS AND 2 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97275236
Fax Number
Contact Number OFFICE-97275236
Email Address NOEMAIL

Address 36 WOODLANDS DRIVE 16, #08-35
 Postcode 737772
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : CRYSTAL LEE CHUN NEE
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name EUNOS NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620, POSTCODE: 470629, COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4439999 - FAX NO: 62444376
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO. T/20171227/2090

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLU3858U
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver LIM KAI BOON
 NRIC/Passport Number S9613486Z
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

DETAILS OF INJURED PERSON 1

Name POH BOON SIONG, DERRICK
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJM716G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name CRYSTAL LEE CHUN NEE
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJM716G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel


Sketch Plan

SLE 5426M

CTE Toward Woodlands

(A) SJM 716 G

(B) SL4 38584






Sketch Plan #2

Describe Circumstances of the Accident

Refer To Police Report NO: T/20171227/2090

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time
Driver's Signature (if driver is not the policyholder) / Date
& Time
Witnessed by Reporting Office
Personnel



**SINGAPORE
POLICE FORCE**



T/20171227/2090

1 of 4

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

Report No: T/20171227/2090

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/12/2017 15:31		Vide Report No.:		Station Diary No.: 28	
Informant's Particulars					
Name of Informant: POH BOON SIONG, DERRICK			Address: 36 WOODLANDS DRIVE 16 #06-35 SINGAPORE 737772		
ID Type / ID No.: NRIC NO / S8124432D			Contact No.: Home/Office: Mobile: 97275236		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 36	Date of Birth: 10/08/1981	Type of Informant: Vehicle Owner		
Race: Chinese			Language: English		Institution / School Name:
Occupation: BANKER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 26/12/2017 07:35	Type of Location: Straight Road
Location: Along Road 1 SELETAR EXPRESSWAY between upper Thomson and Mandai Exit				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJM716G	Car	FORD		Red	Slightly Damaged	2
SLU3858U	Car	MAZDA		Red		2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20171227/2090

4 of 4

Police Station Of Origin:

Eunos NPP

629 Bedok Reservoir Road #01-1620

SINGAPORE 470629

Tel No: 1800-4439999

Report No. T/20171227/2090

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

G /

Staff Sgt HEAP ZHI YONG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt LEE SOON LYE

Contact No.: 65476239

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

27/12/2017 15:31

Classification Of Case:

SIGNATURE

T K MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 96273323 FAX: 68442641
CO. REG NO : 53049097L

Adrian
T/P MSLG Ins.
45 10 day.

DATE: 28/01/2018

POH BOON SIONG, DERRICK
36 WOODLANDS DRIVE 16 #08-35
SINGAPORE 737772

TPMSIG.

Xiao Chen.

Hand 5/4/2018

WFOEXX6BBE7P89085

DEAR SIR

ACCIDENT DATE: 26/12/2017

ESTIMATE COST OF REPAIRS BILL TO FORD MONDEO- 2.3 GHIA (A) CAR NO: SJM716G

1 PC REAR SPARE WHEEL HOLDER	Not	S\$ 78.00	78.00 x
1 PC REAR SPARE WHEEL GARNISH	Deland	512.00	512.00 ✓
2 PC REAR SPARE WHEEL GARNISH SPONGE	crushed.	474.00	474.00 ✓
1 PC REAR TOOLBOX SPONGE		202.00	202.00 x m
2 PC REAR TAILLAMP	lt	1,248.00	1,248.00 840
2 PC REAR TAILLAMP LOWER BRACKET	Not	110.00	110.00 x
1 PC REAR END PANEL	Deland	756.00	756.00 ✓
1 PC REAR END PANEL GARNISH	Deland	178.00	178.00 ✓
1 PC REAR END PANEL LOCK	Not	176.00	176.00 x
1 SET REAR REVERSE SENSOR HARLESS WIRING	Not	298.00	298.00 x
1 SET REAR WINDSCREEN MOULDING		110.00	110.00 ✓
1 PC REAR WINDSCREEN INNER SEAL		26.00	26.00 S/NETT ✓
1 PC REAR WINDSCREEN INNER SEALANT		45.00	45.00 S/NETT ✓
1 PC REAR FORD EMBLEM	Not	70.00	70.00 ✓
1 PC REAR MONDEO LOGO		68.00	68.00 ✓
1 PC REAR BOOTLID	Crushed	1,780.00	1,780.00 1384
2 PC REAR BOOTLID ASBORBER	Not	410.00	410.00 x
1 PC REAR BOOTLID RUBBER	Not	211.00	211.00 ✓
1 PC REAR BOOTLID LOCK	Deland	312.00	312.00 ✓
1 PC REAR BOOTLID TRIMBOARD	Not	548.00	548.00 x
1 PC REAR BOOTLID THIRD BRAKE LIGHT ASSY	Not	308.00	308.00 x
2 PC REAR BOOTLID REFLECTOR LAMP		770.00	770.00 x
1 PC REAR NO. PLATE	Not	30.00	30.00 S/NETT x
1 PC REAR NO. PLATE GARNISH	crushed	476.00	476.00 ✓
2 PC REAR NO. PLATE GARNISH INNER BRACKET	Not	296.00	296.00 x
1 PC REAR BOOTLID HANDLE	Not	348.00	348.00 x
1 PC REAR BOOTLID HANDLE INNER BRACKET	Not	138.00	138.00 x
1 PC REAR BUMPER	Deland	1,180.00	1,180.00 948
8 PC REAR BUMPER CLIP	Not	40.00	40.00 30
1 PC REAR BUMPER REINFORCEMENT BEAM	Bent	550.00	550.00 ✓
2 PC REAR BUMPER SIDE RETAINER	Not	230.00	230.00 x
2 PC REAR BUMPER LOWER BRACKET	Not	56.00	56.00 x
1 PC REAR BUMPER LOWER GARNISH	Deland	302.00	302.00 ✓
1 PC REAR BUMPER TOWING COVER	Not	25.00	25.00 x
2 PC REAR BUMPER REFLECTOR	Not	96.00	96.00 x
1 PC REAR BUMPER CENTRE RETAINER	Deland	158.00	158.00 ✓
4 PC REAR BUMPER REVERSE SENSOR	Deland	480.00	480.00 240 (100)
1 PC REAR L/H EXHAUST PIPE	Bent	1,650.00	1,650.00 1350

8246
6596.80

S.N. 71

T K MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL:96273323 FAX: 68442641
CO. REG NO :53049097L

TO CHECK WRING & REINSTALL REAR REVERSE SENSOR HARLESS WIRING.	180.00	180.00 60
TO SPRAY PAINTING.	1,000.00	1,000.00 900
TO REMOVE & REFIX REAR EXHAUST PIPE.	80.00	80.00 ✓
TO REMOVE & REFIX REAR INTERIOR UPHOSLY.	150.00	150.00 60
TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION.	150.00	150.00 40
TO MEASURE,DRILL THE REPLACED BUMPER,POSITION & RESTALL REAR REVERSE SENSOR,CONTROL UNIT,CHECK & TEST FOR FUNCTIONING.	80.00	80.00 30
TO LABOUR CHARGE FOR PANEL BEATING,WELDING,REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC.	900.00	900.00 800
TO REMOVE & REFIX REAR WINDSCREEN.	150.00	150.00 120
TO COMPUTER WHEEL ALIGHTMENT	90.00	90.00 X
TO REMOVE & REFIX REAR UNDERCARRIGE & CHASSIC CROSS MEMBER.	2090 550.00	550.00 X

TOTAL S\$

18,075.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

71C.

08 Days.

total: 8757-8

u/s: 71C
08 Days

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024669/AQD3N2

Date: 21/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29032696TMC
Claimant Vehicle No :	SJM716G	Insured Vehicle No :	SLU3858U
Date of Loss:	26/12/2017	Nature of Claim:	TP
		Claim No:	543192

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM716G	Engine No:	HIDDEN
Make & Model:	FORD MONDEO, 2.3 Ghia (A)	Chassis No:	WF0EXXGBBE7P89085
Reg. Date:	19/12/2008 (Man. Year: 2008)	Odometer:	209219 km
Colour:	Brown		
Engine Capacity:	2261 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,745.00	7,077.40	7,667.60	52.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	2,090.00	1,240.00	37.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,075.00	9,167.40	8,907.60	49.28
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	18,075.00	7,000.00	11,075.00	61.27

INSPECTION

Date of Assignment:	28/12/2017	
Date Inspected:	29/12/2017 Inspected At:	Tk Motor Workshop (HQ) Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt Singapore 417883
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2018)
Parts: 143	FORD MONDEO 2.3 Ghia (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJM716G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR SPARE WHEEL HOLDER	Not Necessary	78.00 F	*- FL
2	1	*REAR SPARE WHEEL GARNISH	Deformed	512.00 F	*512.00 FL
3	2	*REAR SPARE WHEEL GARNISH SPONGE	Cracked	474.00 F	*474.00 FL
4	1	*REAR TOOLBOX SPONGE	Not Necessary	202.00 F	*- FL
5	2	*REAR TAILLAMP	Cut	1,248.00 F	*840.00 FL
6	2	*REAR TAILLAMP LOWER BRACKET	Not Necessary	110.00 F	*- FL
7	1	*REAR END PANEL	Dented	756.00 F	*756.00 FL
8	1	*REAR END PANEL GARNISH	Deformed	178.00 F	*178.00 FL
9	1	*REAR END PANEL LOCK	Not Necessary	176.00 F	*- FL
10	1	*SET REAR REVERSE SENSOR HARLESS WIRING	Not Necessary	298.00 F	*- FL
11	1	*SET REAR WINDSCREEN MOULDING	Necessary	110.00 F	*110.00 FL
12	1	*REAR FORD EMBLEM	Necessary	70.00 F	*70.00 FL
13	1	*REAR MONDEO LOGO	Necessary	68.00 F	*68.00 FL
14	1	*REAR BOOTLID	Buckled	1,780.00 F	*1,384.00 FL
15	2	*REAR BOOTLID ABSORBER	Not Necessary	410.00 F	*- FL
16	1	*REAR BOOTLID RUBBER	Not Necessary	211.00 F	*- FL
17	1	*REAR BOOTLID LOCK	Damaged	312.00 F	*312.00 FL
18	1	*REAR BOOTLID TRIMBOARD	Not Necessary	548.00 F	*- FL
19	1	*REAR BOOTLID THIRD BRAKE LIGHT ASSY	Not Necessary	308.00 F	*- FL
20	2	*REAR BOOTLID REFLECTOR LAMP	Not Necessary	770.00 F	*- FL
21	1	*REAR NO PLATE GARNISH	Cracked	476.00 F	*476.00 FL
22	2	*REAR NO PLATE GARNISH INNER BRACKET	Not Necessary	296.00 F	*- FL
23	1	*REAR BOOTLID HANDLE	Not Necessary	348.00 F	*- FL
24	1	*REAR BOOTLID HANDLE INNER BRACKET	Not Necessary	138.00 F	*- FL
25	1	*REAR BUMPER	Deformed	1,180.00 F	*948.00 FL
26	8	*REAR BUMPER CLIP	Necessary	40.00 F	*30.00 FL
27	1	*REAR BUMPER REINFORCEMENT BEAM	Bent	550.00 F	*550.00 FL
28	2	*REAR BUMPER SIDE RETAINER	Not Necessary	230.00 F	*- FL
29	2	*REAR BUMPER LOWER BRACKET	Not Necessary	56.00 F	*- FL
30	1	*REAR BUMPER LOWER GARNISH	Deformed	302.00 F	*302.00 FL
31	1	*REAR BUMPER TOWING COVER	Not Necessary	25.00 F	*- FL
32	2	*REAR BUMPER REFLECTOR	Not Necessary	96.00 F	*- FL
33	1	*REAR BUMPER CENTRE RETAINER	Deformed	158.00 F	*158.00 FL
34	4	*REAR BUMPER REVERSES ENSOR	Damaged	480.00 F	*240.00 FL
35	1	*REAR L/H EXHAUST PIPE	Bent	1,650.00 F	*1,350.00 FL
36	1	*REAR WINDSCREEN INNER SEAL	Necessary	26.00 FS	*26.00 FS
37	1	*REAR WINDSCREEN INNER SEALANT	Necessary	45.00 FS	*45.00 FS
38	1	*REAR NO PLATE	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,745.00	8,829.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,751.60
Total Parts (\$\$)	14,745.00	7,077.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING & REINSTALL REAR REVERSE SENSOR HARLESS WIRING	New	180.00	60.00
2	TO SPRAY PAINTING	New	1,000.00	900.00
3	TO REMOVE & REFIX REAR EXHAUST PIPE	New	80.00	80.00
4	TO REMOVE & REFIX REAR INTERIOR UPHOSLY	New	150.00	60.00
5	TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION	New	150.00	40.00
6	TO MEASURE,DRILL THE REPLACED BUMPER,POSITION & RESTALL REAR REVERSES ENSOR,CONTROL UNIT,CHECK & TEST FOR FUNCTIONING	New	80.00	30.00
7	TO LABOUR CHARGE FOR PANEL BEATING,WELDING,REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC	New	900.00	800.00
8	TO REMOVE & REFIX REAR WINDSCREEN	New	150.00	120.00
9	TO COMPUTER WHEEL ALIGHMENT	New	90.00	-
10	TO REMOVE & REFIX REAR UNDERCARRIAGE & CHASSIC CROSS MEMBER	New	550.00	-
Gross Labour Cost (S\$)			3,330.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >