

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHF699H - AXA

Not Authored
1.B.1
Referring B4 page

AAD1712-263

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHF699H - JASMINE
VF1ABL15AUC281180
RENAULT
LATITUDE
26.12.2017
AXA

PART			LIST	
1	1	BUMPER COVER FRT	\$	CM 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	Sm 181.75 X
3	1	BUMPER ABSORBER FRT	\$	CM 394.68 ✓
4	1	BUMPER RETAINER FRT LH	\$	Sm 151.41 X
5	1	BUMPER SUPPORT FRT LH	\$	Sm 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	Sm 150.77 X
7	1	BUMPER SUPPORT FRT RH	\$	Sm 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	Sm 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	Sm 266.80 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	Sm 207.21 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	Sm 207.21 X
12	1	BUMPER BEAM FRT	\$	914.08 ?
13	1	TOW COVER FRT	\$	Sm 28.61
14	1	RADAIOR GRILLE	\$	Sm 1,707.78
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	Sm 225.36
16	1	RADAIOR GRILLE FRAME	\$	Sm 1,353.75
17	1	FRAME FULL SUPPORT PANEL	\$	R 615.90 } X
18	1	FRAME FULL SUPPORT BRACKET	\$	R 89.79
19	1	FRONT BRACE PANEL	\$	R 177.22
20	1	HORN	\$	Sm 314.17
21	1	HORN BRACKET	\$	R 40.45
22	1	HEADLAMP LH	\$	mg-CM 1,184.43 ✓
23	1	HEADLAMP PANEL FRT RH	\$	R 152.15
24	1	BONNET	\$	R 1,941.63
25	1	BONNET INSULATOR	\$	Sm 405.73
26	1	BONNET STRUT LH	\$	Sm 88.61
27	1	BONNET STRUT RH	\$	Sm 88.61
28	1	BONNET HINGE LH	\$	R 348.31 } X
29	1	BONNET HINGE RH	\$	R 348.31
30	1	BONNET LOCK	\$	R 305.48
31	1	BONNET CABLE	\$	Sm 119.19
32	1	BONNET CABLE COVER	\$	Sm 161.03
33	1	BONNET SEAL OUTER	\$	Sm 92.36
34	1	FENDER PANEL FRT LH	\$	R 783.83

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-263**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO GST REG NO. 201019626G

WHEEL ARCH FRT LH

SHF699H - AXA

35	1	FENDER BRACKET LOWER LH	\$	Sin	278.84
36	1	FENDER BRACKET LOWER LH	\$	Sin	15.79
37	1	FENDER INSULATOR LH	\$	Sin	130.84
38	1	AIR CLEANER LOWER	\$	Sin	271.26
39	1	AIR CLEANER HOSE	\$	Sin	76.14
40	1	A/C CONDENSER	\$	Sin	2,020.37
41	1	A/C CONDENSER GARNISH LH UPPER	\$	Sin	39.67
42	1	A/C CONDENSER GARNISH RH UPPER	\$	Sin	39.67
43	1	A/C CONDENSER GARNISH LH	\$	Sin	58.81
44	1	A/C CONDENSER GARNISH RH	\$	Sin	59.60
45	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sin	208.39
46	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sin	658.72
47	1	A/C PIPE COMPRESSOR	\$	Sin	334.29
48	1	A/C PIPE	\$	Sin	658.72
49	1	A/C COMRPRESSOR	\$	Sin	2,684.61
50	1	AIR COOLER	\$	Sin	792.60
51	1	AIR INTERCOOLER HOSE (LONG)	\$	Sin	1,014.13
52	1	AIR INTERCOOLER HOSE (Short)	\$	Sin	375.14
53	1	TRANSMISSION COOLER	\$	Sin	1,219.30
54	1	TRANSMISSION COOLER PAD	\$	Sin	17.96
55	1	RADIATOR	\$	Sin	1,202.20
56	2	RADIATOR STUD UPPER	\$	Sin	14.41
57	2	RADIATOR BUSH UPPER	\$	Sin	50.12
58	2	RADIATOR MTG LOWER	\$	Sin	55.85
59	1	RADAITOR FAN COWLING	\$	Sin	820.54
60	1	RADIATOR FAN MOTOR LH	\$	Sin	967.36
61	1	RADIATOR FAN MOTOR RH	\$	Sin	1,479.46
62	1	RADIATOR TANK	\$	Sin	324.62
63	1	RADIATOR HOSE UPPER	\$	Sin	240.56
64	1	RADIATOR HOSE LOWER	\$	Sin	491.18
65	1	RADIATOR TANK HOSE	\$	Sin	61.18
66	1	WINDSCREEN FRT	\$	Sin	1,364.06
67	1	ROTARY SWITCH	\$	Sin	1,253.11

TOTAL	\$	34,306.11
10%	\$	3,430.61
	\$	30,875.50

Specical Nett

1	1SET	RADAITOR GRILLE FRAME CLIP	\$	na	52.00 X
2	1SET	BUMPER CLIP FRT	\$	na	66.00
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00 X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50 X
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00 X
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF699H - AXA**AAD1712-263**

7	1	TOW COVER FRT	\$	Sn	14.50	}	X
8	1SET	RADAI TOR GRILLE SCREW	\$	nn	16.00		
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00		
13	1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50		
14	1	CAP HUB LH FRT	\$	Sn	35.00		
15	1	RIM LH FRT	\$	Sn	385.00		
16	1	TYRE LH FRT	\$	Sn	330.00		
17	1SET	Front licence plate with holder	\$	Sn	80.00		
18	1	DOOR STICKER "6555-3333" LH	\$	nn	80.00		
19	1	DOOR STICKER "6555-3333" RH	\$	nn	80.00		

TOTAL	\$	1,403.00
TOTAL PARTS	\$	32,278.50

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 ²⁰⁰

Towing Fees.

\$ nn 120.00 X

To apply paint protection system (PPS) maintain and enhancement

\$ nn 380.00 X

Putty and spray painting of the affected portion.

\$ 4,500.00 ²²⁰

To rust-proofing of the affected areas.

\$ nn 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ nn 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 ²⁰

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ nn 380.00 X

To replace, refix and top up coolant for radiator

\$ nn 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-263**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF699H - AXATo vacuum, replace, refix and recharge air
condenser\$ *nn* 380.00 XTo vacuum, replace, refix and recharge Air
Intercooler\$ *nn* 170.00 XTo Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.\$ *nn* 170.00 X**TOTAL \$ 11,580.00****Over All Total \$ 43,858.50**

< parts by parts > Repair Days

*15 DAYS**2 days*LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: