

ASS. REC. BY:

REF: CS/FCI17024672/Gad3

Special Instruction:

Surveyor
CWS

GA

ASSIGNMENT (Office)

From (Person): Joanne Yong

of

FCI

Date/Time: 10:30am @ 29/12/17

Estimated Cost:

Bill to:

OD ☒ TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLE1156J

Insured: SH 8337J

at Workshop no/s Hitachi Capital Asia

Tel: 64663022

of No. 8 Fourth Lokyang Rd.

Policy No: D-15077701MFSH

Claim No: D17011830MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time: 10:39am @ 29/12/17

Person Contacted: Grant Chong

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLE1156J-CC6/AIG/17001515/R7pg3q2 D.O.A: 22/01/2017
	SH 8337J-CC3/EQI/15008331/H1ua3q2 D.O.A: 15/05/2015
03/01/18 @ 5:45pm	revised to Joanne Yong by email.
04/01/18 @ 3:15pm	confirmed with Grant final fig to \$177.60, 7 days by email.
	(LHA \$6773.75, 57%)

Serial: Xbel.

REF: FCI

ASSIGNMENT

From: _____ Date: 29/12/17

Estimated Cost: _____
QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLE1156J
at Workshop in: Hitachi Capital
of: 8 Fourth Lok Yung Road
Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Grant Chang

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. of Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLE1156J Yr Reg: 08 Jul 2016
Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or:

Make: Toyota wish cc: 1798

Colour: Blue A/O Insured / Std / NI / NA

So Reading: 38519 T Radio Insured / Std / NI / NA

Eng No: _____

C No: JTD6620W00J-004571

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 225/45R17

R: 17

BS: ☒ DUK / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R.Bal: 6 mm R.Bal: 6 mm

L.Bal: 6 mm L.Bal: 6 mm

D.O.A. _____ D.O.I. 28-12-17

Survey held at: w/s 5:30pm

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

RECEIVED 04 APR 2018

Date/Time File Pass to: ☐ Prel. Report

24/12/17 turnin ☐ Final Report

Date/Time File Return to:

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee: 170+15

Transportation: 50

Food: 10+50

Other: 65

Add Fee: ☐ Site Insp: \$

☐ Interview: \$

☐ Tech. Insp: \$

☐ Freshing: \$

Report Format: 1P

Lump Sum / I.B.I: 5122.60

5/4/18 400



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17024672/Gqd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 8337J	Veh. Inspected	SLE 1156J
Policy No.		Coverage (\$)	0.00
Claim No.	D17011830MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	29/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/12/2017	Inspection Date	29/12/2017
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001575-9

MOTOR SURVEY ASSIGNMENT

Date	26-12-2017	Our Ref No. D17011830MFSH
Accident Date	22-12-2017	Claim Type. Third Party
Insured Vehicle	SH8337J	Third Party Vehicle. SLE1156J
Survey Location	JUN TAIYO SERVICE CENTRE NO 8 FOURTH LOK YANG ROAD	
Contact Person.	GRANT CHONG	
Contact No.	64663022/ 0	Fax No. 68966591
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HITACHI CAPITAL ASIA PACIFIC PTE. LTD.	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232324)



PRI Documents



Close



PRI Header Details

Claim No	D17011830MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & HITACHI (LTD.
Workshop Name	HITACHI CAPITAL ASIA PACIFIC PTE. LTD. (Contact Person : GRANT CHONG)	Survey Location & Contact Details	JUN TAIYO SERVICE CENTRE NO 8 FOURTH LOK YANG R Mobile: 0 , Phone: 64663022 , Fax: 68966591 EmailId: KEANYAP.CHONG@HCSPL.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH8337J	TP Vehicle No	SLE1156J
PRI Recieved Date	27-12-2017 06:56:51 PM	Surveyor Appointed Date	29-12-2017 10:29:31 AM	Surveyor Accept Date	29-12-2017 10:29:31 AM

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	29-12-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 4 April 2018 3:15 PM
To: 'KeanYap, Chong'; Guo Qiang (LKKAUTO); SUR
Cc: Jamilah, Binte MohdKassim
Subject: RE: SLE1156J TP/First Capital Finalization

Dear Grant,

Confirm final fig \$5,122.60 before GST and 7 repair days.

Please send the relevant documents to insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: KeanYap, Chong [mailto:keanyap.chong@hcspl.com.sg]
Sent: Thursday, 22 March 2018 8:58 AM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>;
Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: SLE1156J TP/First Capital Finalization

Dear all,

Attached with photo and preliminary report.

Please confirm final repair cost P/P \$5,122.60 before GST.
7 day

Best regards,

Grant Chong

Motor Claims Advisor

Auto Servicing Section

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road, Singapore 629705
t: 6833 6282 f: 6896 6591
e: KeanYap.Chong@hcspl.com.sg
w: www.hitachi-capital.com.sg

HITACHI
Inspire the Next

New Office Location Notice

From 12th March 2018, we will be relocated to a different floor.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 3 January, 2018 5:45 PM
To: 'Claim Workflow System'; assignments
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011830MFSH/1
Attachments: CSFCI17024672Gqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SLE 1156J.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 29 December, 2017 10:40 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011830MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

"Wishes you a Happy New Year 2018"

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Friday, 29 December, 2017 10:29 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011830MFSH/1

Dear Sir/Mdm,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011830MFSH
Our Ref: CS/FCI17024672/Gqd3

Date: 03 January 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLE 1156J.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/12/2017 at the premises of M/s HITACHI CAPITAL ASIA, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 11,562.60</u>
Revised Estimate Amount	: <u>S\$ 4,124.43</u>
"Check" Items Amount	: <u>S\$ 1,895.20</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

Guo Qiang
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/12/2017 17:40
Date Of Accident	22/12/2017 10:30
Exact Location Of Accident	PIE TWD CHANGI AIRPORT AFTER TOA PAYOH EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE1156J
Insured/Policyholder	
Name Of Registered Owner	SHINRYO CORPORATION
Co Reg No	S83FC3320B
Email Address	SHINRYO@SHINRYO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-90081716

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MI000996-R00
Cover Note Number	

Driver

Name of Driver	MUHAMMAD ALEEF SARBANI BIN SAZALI
NRIC No	S8633237Z
Date Of Birth	05/11/1986
Occupation	OUTDOOR
Date Of Driving Pass	29/05/2010
Driving Experience	7 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90081716
Fax Number	
Contact Number	
Email Address	SHICLALIP@HOTMAIL.COM

Address	-
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Details of Witness 1

Name	JESYKA TUALLY
Phone Number	83100149
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH8337J
Vehicle Make/Model/Colour	HYUNDAI I40
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TAN HWA SING
NRIC/Passport Number	
Contact Number	97530225
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/con be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (if driver is not the policyholder)
 Date & Time: 22 Dec 2017
 1427 hrs


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

PIE TOWARDS AIRPORT AFTER TGA PAYOH EXIT




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On Friday, 22 Dec 2017, at around 10:30am, I was driving along PIE Towards Changi Airport. Traffic is congested moving at about 15km/h - 20km/h due to an accident up ahead. After Tan Payoh Exit, a blue Comfort Taxi SH8337J banged me from behind causing damage to the rear of my car. A video clip of the incident is available for reference. (Video is from my car SLE 1156J). A witness (Taxi Passenger) is willing to be my witness as she also thought that it's the taxi driver's fault for not paying attention while driving. The witness is a lady (Jesyka Tually tel: 8310 0149). Me and the Taxi driver exchanged particulars but he declined showing his ID but wrote down his Name, HP No and Vehicle No on a piece of paper instead. So I did the same. No police report were made. - PHOTOS and VIDEO is available for reference.

- There is a witness to the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 22 December 2017
1430 hrs


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

First capital insurance ltd

QUOTE NO :
 ACCIDENT DATE : 22/12/2017, 10.30am
 VRN : SLE1156J
 MODEL : TOYOTA WISH 1.8 CVT A
 TP VRN : SH8337J

ATTN: MOTOR CLAIMS DEPT

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 Rear bumper / <i>Re</i>	1	\$ 595.90	\$ 595.90	
2 Rear bumper clips / <i>MC</i>	10	\$ 5.50	\$ 55.00	
3 Rear bumper retainer outer LH/RH / <i>MC</i>	2	\$ 55.80	\$ 111.60	
4 Rear bumper retainer inner LH/RH / <i>MC</i>	2	\$ 95.80	\$ 191.60	
5 Reverse sensor <i>X NN</i> S/Nett	1	\$ 250.00	\$ 250.00	<i>X</i>
6 End panel <i>X BT</i>	1	\$ 485.90	\$ 485.90	
7 End panel garnish <i>X NN</i>	1	\$ 285.70	\$ 285.70	<i>X</i>
8 Spare tyre compartment <i>X NN</i>	1	\$ 650.50	\$ 650.50	<i>X</i>
9 Tailgate / <i>buc</i>	1	\$ 1,400.50	\$ 1,400.50	
10 Tailgate hinge LH/RH <i>X</i>	2	\$ 65.70	\$ 131.40	<i>X</i>
11 Tailgate inner trim board <i>X NN</i>	1	\$ 450.80	\$ 450.80	<i>X</i>
12 Tailgate lock <i>X</i>	1	\$ 425.30	\$ 425.30	<i>X</i>
13 Tailgate weatherstripe <i>X</i>	1	\$ 320.70	\$ 320.70	<i>X</i>
14 Tailgate logo "Toyota" / <i>MC</i>	1	\$ 75.80	\$ 75.80	
15 Tailgate logo "Elegance" / <i>MC</i>	1	\$ 75.80	\$ 75.80	
16 Tailgate logo "Valvematic" / <i>MC</i>	1	\$ 85.70	\$ 85.70	
17 Tailgate reflector light LH/RH <i>X NN</i>	2	\$ 195.80	\$ 391.60	<i>X</i>
18 Taillamp LH/RH <i>X</i>	2	\$ 344.50	\$ 689.00	<i>X</i>
19 Tailgate windscreen moulding set / <i>MC</i>	4	\$ 38.50	\$ 154.00	
20 Tailgate windscreen sealant / S/Nett <i>MC</i>	1	\$ 45.00	\$ 45.00	
21 Rear number plate with casing <i>X S/Nett NN</i>	1	\$ 45.00	\$ 45.00	<i>X</i>
22 Rear fender LH <i>X</i> Repair	1	Repair	Repair	
23 Rear fender RH <i>X NN</i> Repair	1	Repair	Repair	
24 Discount 25%	1	(\$1,644.20)	\$ (1,644.20)	
TOTAL			\$ 5,272.60	

2. Labor Charges

1 Panel beat, cut, weld, re-align & replace damaged parts of affected area	<i>1050 700-900</i>	\$ 2,500.00
2 Putty, blend and paint affected area	<i>940 700</i>	\$ 2,000.00
3 Check Wiring and ensure proper function	<i>30</i>	\$ 80.00
4 Remove & reinstall bumper sensors	<i>40.</i>	\$ 120.00

5 Cavity treatment on new parts (End panel, tailgate, spare tyre compartment)	00	\$	200.00
6 Remove & reinstall Rear reverse camera	40	\$	120.00
7 Remove & re-install Tailgate Windscreen	100	\$	150.00
8 Transfer tailgate lock & mechanism to new tailgate	60	\$	180.00
9 Conduct water seepage test	X	\$	80.00
10 Remove & re-install rear trim compartment to facilitate cutting and repairing work	60	\$	180.00
11 Remove and refix tailgate spoiler to replace tailgate assembly	30	\$	150.00
12 Remove Upholstery Trim and Cushion	X	\$	280.00
13 Diagnostic check and reset	X	\$	250.00

Sub Total : \$ 6,290.00

Grand Total : \$ 11,562.60

Add 7% GST : \$ 809.38

Nett Total : \$ 12,371.98

No. of repair days: 12

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Guo Qiang - 82880282

Guo Qiang @ 14kauto.com

29/12/17

5-7 Days.

part by part.

before paint photos.


5/1/18

Insurance Consultants hence notify the Repaired of the following:

- To resurvey before after repair painting
- To resurvey damaged part(s) during resurvey
- Part price are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification (s) is allowed
- Supplementary dem (s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

11896.35

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE (SUPPLEMENTARY)

First capital insurance ltd
ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
ACCIDENT DATE : 22/12/2017, 10.30am
VRN : SLE1156J
MODEL : TOYOTA WISH 1.8 CVT A
TP VRN : SH8337J

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 Rear floor member cross lower / BUL	1	\$ 250.00	\$ 250.00	✓ 689
2 Rear antenna electric key / DM	1	\$ 195.00	\$ 195.00	✓ 689
3 Discount 25%	1	(\$111.25)	(\$111.25)	
TOTAL			\$ 333.75	

2. Labor Charges

Sub Total : \$ -
Grand Total : \$ 333.75
Add 7% GST : \$ 23.36
Nett Total : \$ 357.11

No. of repair days: 7

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Supplementary \$ 333.75

parts \$ 3231.80 - 25% = \$ 2423.85

Stress \$ 45

labour \$ 2320

* Total P/P \$ 5122.60 @ 7 day \$

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

First capital insurance ltd

 ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
 ACCIDENT DATE : 22/12/2017, 10.30am
 VRN : SLE1156J
 MODEL : TOYOTA WISH 1.8 CVT A
 TP VRN : SHB337J

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 Rear bumper / <i>Re</i>	1	\$ 595.90	\$ 595.90 ✓	
2 Rear bumper clips / <i>MSC</i>	10	\$ 5.50	\$ 55.00 ✓	
3 Rear bumper retainer outer LH/RH ✓	2	\$ 55.80	\$ 111.60 ✓	
4 Rear bumper retainer inner LH/RH ✓	2	\$ 95.80	\$ 191.60 ✓	
5 Reverse sensor ? S/Nett	1	\$ 250.00	\$ 250.00 X	
6 End panel - ?	1	\$ 485.90	\$ 485.90 ← ✓	
7 End panel garnish ?	1	\$ 285.70	\$ 285.70 X	
8 Spare tyre compartment ?	1	\$ 650.50	\$ 650.50 X	
9 Tailgate / <i>buc</i>	1	\$ 1,400.50	\$ 1,400.50 ✓	
10 Tailgate hinge LH/RH X ?	2	\$ 65.70	\$ 131.40 X	
11 Tailgate inner trim board ?	1	\$ 450.80	\$ 450.80 X	
12 Tailgate lock X	1	\$ 425.30	\$ 425.30 X	
13 Tailgate weatherstripe ?	1	\$ 320.70	\$ 320.70 X	
14 Tailgate logo "Toyota" /	1	\$ 75.80	\$ 75.80 ✓	
15 Tailgate logo "Elegance" / <i>MSC</i>	1	\$ 75.80	\$ 75.80 ✓	
16 Tailgate logo "Valvematic" /	1	\$ 85.70	\$ 85.70 ✓	
17 Tailgate reflector light LH/RH X	2	\$ 195.80	\$ 391.60 X	
18 Taillamp LH/RH X	2	\$ 344.50	\$ 689.00 X	
19 Tailgate windscreen moulding set / <i>MSC</i>	4	\$ 38.50	\$ 154.00 ✓	
20 Tailgate windscreen sealant / S/Nett <i>MSC</i>	1	\$ 45.00	\$ 45.00 ✓	
21 Rear number plate with casing X S/Nett	1	\$ 45.00	\$ 45.00 X	
22 Rear fender LH X Repair	1	Repair	Repair	
23 Rear fender RH X Repair	1	Repair	Repair	
24 Discount 25%	1	(\$1,644.20)	\$ (1,644.20)	
TOTAL			\$ 5,272.60	

2. Labor Charges

1 Panel beat, cut, weld, re-align & replace damaged parts of affected area	<i>(confirmed on 31/12) 700 - 900</i>	\$ 2,500.00
2 Putty, blend and paint affected area	<i>(confirmed on 31/12) 700</i>	\$ 2,000.00
3 Check Wiring and ensure proper function	<i>30</i>	\$ 80.00
4 Remove & reinstall bumper sensors	<i>40</i>	\$ 120.00

5 Cavity treatment on new parts (End panel, tailgate, spare tyre compartment)	60	\$	200.00
6 Remove & reinstall Rear reverse camera	40	\$	120.00
7 Remove & re-install Tailgate Windscreen	100	\$	150.00
8 Transfer tailgate lock & mechanism to new tailgate	60	\$	180.00
9 Conduct water seepage test	X	\$	80.00
10 Remove & re-install rear trim compartment to facilitate cutting and repairing work	60	\$	180.00
11 Remove and refix tailgate spoiler to replace tailgate assembly	30	\$	150.00
12 Remove Upholstery Trim and Cushion	X	\$	280.00
13 Diagnostic check and reset	X	\$	250.00

Sub Total : \$ 6,290.00

Grand Total : \$ 11,562.60

Add 7% GST : \$ 809.38

Nett Total : \$ 12,371.98

No. of repair days: 12

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Guo Qiang - 82880282
Guo Qiang @ 1kkauto.com

29/12/17

5-7 Days.

part by part.

before paint photos.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17024672/Gqd3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-04-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8337J	Veh. Inspected	SLE 1156J	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011830MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	29/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDGG20W00J004571	Colour	BLUE	
Odometer	38519	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	DUNLOP	6 mm	
L/H Front Tyre	225/45 R17	DUNLOP	6 mm	
R/H Rear Tyre	225/45 R17	DUNLOP	6 mm	
L/H Rear Tyre	225/45 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/12/2017	Inspection Date	29/12/2017	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1156J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	595.90	595.90
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
2	REAR BUMPER RETAINER OUTER LH /RH @\$55.80	NECESSARY	111.60	111.60
2	REAR BUMPER RETAINER INNER LH/RH @\$95.80	NECESSARY	191.60	191.60
1	END PANEL	BENT	485.90	485.90
1	END PANEL GARNISH	NOT NECESSARY	285.70	-
1	SPARE TYRE COMPARTMENT	NOT NECESSARY	650.50	-
1	TAILGATE	BUCKLED	1,400.50	1,400.50
2	TAILGATE HINGE LH/RH @\$65.70	NOT NECESSARY	131.40	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	450.80	-
1	TAILGATE LOCK	NOT NECESSARY	425.30	-
1	TAILGATE WEATHERSTRIPE	NOT NECESSARY	320.70	-
1	TAILGATE LOGO 'TOYOTA'	NECESSARY	75.80	75.80
1	TAILGATE LOGO 'ELEGANCE'	NECESSARY	75.80	75.80
1	TAILGATE LOGO 'VALVEMATIC'	NECESSARY	85.70	85.70
2	TAILGATE REFLECTOR LIGHT LH/RH @\$195.80	NOT NECESSARY	391.60	-
2	TAILLAMP LH/RH @\$344.50	NOT NECESSARY	689.00	-
4	SET TAILGATE WINDSCREEN MOULDING @\$38.50	NECESSARY	154.00	154.00
1	REAR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FLOOR MEMBER CROSS LOWER (ADDITIONAL)	BUCKLED	250.00	250.00
1	REAR ANTENNA ELECTRIC KEY (ADDITIONAL)	DAMAGED	195.00	195.00
	LESS 25% DISCOUNT		-1,755.45	-919.20
			5,266.35	2,757.60
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	NOT NECESSARY	250.00	-
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	45.00	45.00
1	REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	45.00	-
			340.00	45.00

Report Ref No. CS/FCI17024672/Gqd3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEAT ,CUT,WELD ,RE-ALIGN & REPLACE DAMAGED PARTS OF AFFECTED AREA.INCLUSIVE OF THE REPAIR OF REAR FENDER LH AND REAR FENDER RH.		2,500.00	1,000.00
	PUTTY,BLEND AND PAINT AFFECTED AREA.		2,000.00	900.00
	CHECK WIRING AND ENSURE PROPER FUNCTION .		80.00	30.00
	REMOVE & REINSTALL BUMPER SENSORS .		120.00	40.00
	CAVITY TREATMENT ON NEW PARTS (END PANEL, TAILGATE, SPARE TYRE COMPARTMENT).		200.00	60.00
	REMOVE & REINSTALL REAR REVERSE CAMERA.		120.00	40.00
	REMOVE & RE-INSTALL TAILGATE WINDSCREEN.		150.00	100.00
	TRANSFER TAILGATE LOCK & MECHANISM TO NEW TAILGATE.		180.00	60.00
	CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	80.00	-
	REMOVE & RE-INSTALL REAR TRIM COMPARTMENT TO FACILITATE CUTTING AND REPAIRING WORK.		180.00	60.00
	REMOVE AND REFIX TAILGATE SPOILER TO REPLACE TAILGATE ASSEMBLY.		150.00	30.00
	REMOVE UPHOLSTERY TRIM AND CUSHION.	NOT NECESSARY	280.00	-
	DIAGNOSTIC CHECK AND RESET.	NOT NECESSARY	250.00	-
			6,290.00	2,320.00
GRAND TOTAL			11,896.35	5,122.60
RECOMMENDED COST OF REPAIRS				5,122.60

Report Ref No. CS/FCI17024672/Gqd3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.