

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9523H**

**AAD1712-275**

*Not Authorized  
11/12/17 @ 2800*

Vehicle No.:	<b>SHD 9523H</b>
Chassis No.:	KL1LA69RJB074943
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	23.12.2017
Third Party Insurer :	<b>AXA</b>

<b>PART</b>			<b>LIST</b>
1	1 Front Bumper	\$	<i>Bu</i> 1,202.00 ✓
2	1 Front Bumper Lower Absorber	\$	<i>Sm</i> 180.00 X
3	1 Front Bumper Reinforcement	\$	<i>R</i> 356.00 X
4	1 Front Bumper Retainer LH	\$	<i>D</i> 102.00 X
5	1 Front Bumper Lower Grille	\$	<i>Sm</i> 78.00 X
6	1 Front Bumper Lower Stiffener	\$	<i>R</i> 134.37 X
7	1 Bumper Fog Lamp Cover LH	\$	<i>Sm</i> 32.40 X
8	1 Front Support Panel Assy	\$	<i>R</i> 1,222.32 X
9	1 Front brace panel	\$	<i>R</i> 134.37 X
10	1 Headlamp LH	\$	<i>CVT</i> 816.00 ✓
11	1 Headlamp LH inner panel	\$	<i>R</i> 611.16
12	1 Front headlamp bracket	\$	<i>R</i> 85.00
13	1 Indicator light switch	\$	<i>Sm</i> 420.00
14	1 Front Shock Absorber Assy LH	\$	<i>Sm</i> 216.17 } X
15	1 Front Shock Absorber Top Mounting LH	\$	<i>Sm</i> 48.32
16	1 Front Lower Arm LH	\$	<i>Sm</i> 283.00
17	1 Front Knuckle Arm LH	\$	<i>Sm</i> 230.00
18	1 Front Fender LH	\$	<i>Bu</i> 837.60 ✓
19	1 Front Fender Liner LH	\$	<i>D</i> 47.00 ✓
20	1 Fender Insulation LH	\$	<i>Sm</i> 39.00 X
21	1 Front Fender RR Bracket LH	\$	<i>R</i> 7.10 X
22	1 Front Fender Inner Wheel House Panel LH	\$	<i>R</i> 1,437.00 X

<b>TOTAL</b>	<b>\$</b>	<b>8,518.81</b>
<b>10%</b>	<b>\$</b>	<b>851.88</b>
	<b>\$</b>	<b>7,666.93</b>

**Special Nett**

1 Set Front Bumper Fastener Clip	\$	<i>nu</i> 24.00 ✓
1 Set Radiator Grille clip	\$	<i>nu</i> 35.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9523H****AAD1712-275**

1 Set Front Fender Liner clip	\$	<i>nr</i> 30.00 ✓
1 Front Wheel Rim Hub Cap LH	\$	<i>sr</i> 166.30 X
1 Front Tyre LH	\$	<i>sr</i> 180.00 X
1 Front Tyre Rim LH	\$	<i>sr</i> 126.00 X
<b>TOTAL</b>		<b>\$ 561.30</b>
<b>TOTAL PARTS</b>		<b>\$ 8,228.23</b>
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,450.00 <i>400</i>
Putty and spray painting of the affected portion.	\$	2,200.00 <i>400</i>
Towing Fees.	\$	<i>nr</i> 120.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nr</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00 X
To rust-proofing of the affected areas.	\$	170.00 <i>301</i>
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00 X
To transfer of fender fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111  
Tel No. : 6287 6666 Fax No. : 6257 1330  
CO./GST Reg. No. 201019626G  
**SHD 9523H**

**AAD1712-275**

**TOTAL \$ 6,440.00**

**Over All Total \$ 14,668.23**

**Repair Days**

**7 Days**

*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: