

ASS. REC. BY:

REF:

CS/CTU7024682/RHbe2

Special Instruction:

Surveyor:
Meinman

Rasul

ASSIGNMENT (Office)

From (Person):

Chong Soon Sen

of

CTL

Date/Time:

29/12/2017 1:13pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SGV 8921R

Insured:

at Workshop m/s

SMRT

Tel:

6555 5556

of

60 Woodlands Ind Park Ell

Policy No:

DMP CSN 3050961700

Claim No:

20170001988

Sum Insured:

Excess:

\$ 280.00

Make of Veh:

(Client's Record)

D.O.A.

23-12-2017

CA / REV /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

29/12/2017 2:11pm

Person Contacted:

Teller

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SGV 8921R x

07/01/18 @ 11:56pm revert to Chong Soon Sen via Meinman.

3/1 @ 1420 - authorise repair by Alfred Luy Sum \$6950/-

3/1 @ 2:46pm - email authorise repair (China adjustment)

STATIONER *For*

REF:

CS/CT17024682/RHB

6264A

LOG XRAY: 2022/Jun

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No: SHV 8921R

at Workshop m/s: SMRT

of _____

Insured: CTI/OD

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 250

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 36K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / FR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHV 8921R

Yr Regn: 2007 Jun

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: HONDA CIVIC 1.8LA 2007 1799

Colour: WHITE A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: 144044 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: JHMPD16307S213587

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 205/552R16

R: _____

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIZ / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. \$ mm R/Bal. \$ mm

L/Bal. \$ mm L/Bal. \$ mm

D.O.A. 23/12/17 D.O.I. 29/12/17

Survey held at: SMRT

Des. of Damages: ☒ Fr / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Type check in good condition. 9200s brake check in good condition and functional.

Lump Sum \$4950 (Red: 12516.21 : 71%)

Date/Time: File Pass to?

☐

Preli. Report

31/1 Typist

☒

Final Report

Date/Time: File Return to?

2)

Days Of Repair: 15

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Photos

Others

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Tech. Adv. \$

☐ Weekend \$

Report Format: OD

Lump Sum / I.B.I. \$ 4950/-

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Dec 2017 Sendback Est	29 Dec 2017 11:51 S\$16,667.37	29 Dec 2017 13:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	LIM KAH YEEN, ID: S8286264A		
Vehicle Reg. No.:	SGV8921R	Date of Loss:	23/12/2017 16:00 - :59
Claim Type:	OD / 20170001988	Policy/Cover Note No.:	DMPCSN3050961700 (Comprehensive)
		Excess:	S\$250.00
RepaIrer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/01/2018]		
Driver/Custodian:	LIM KAH YEEN (/ Male), NRIC: S8286264A		
Adj Asp. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17024682/R1tb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 29-12-2017		
		Code : CTI		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SGV 8921R	
Policy No.	DMPCSN3050961700	Coverage (\$)	0.00	
Claim No.	20170001988	Excess (\$)	250.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	29/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/12/2017	Inspection Date	29/12/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

View Received Message

This mail is associated with :

SGV8921R (SNM17D07255C01)

OD

Dec 23 2017 4:00PM

[LIM KAH YEEN]

SMRT Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 03/01/2018 14:20 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$6950.00) - SGV8921R - Claim Handler: Chong Boon Sen

Approved:6950.00:Please proceed to authorize repairs at \$6,950.00 (lump sum) BEFORE Excess of \$250.00. RE-INSPECTION OF VEHICLE REQUIRED.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 3 January, 2018 2:46 PM
To: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Shiau Chan (LKKAuto); SUR; Rasul (LKKAuto)
Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: RE: CTP OD - SGV8921R
Attachments: index.pdf

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGV 8921R (Excess \$250/-). LUMP SUM REPAIR**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

PLEASE FOLLOW THE ESTIMATE ABOVE ATTACHED REVISED ADJUSTMENT BY CHINA TAIPING

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) [mailto:TeyChorKeng@smrt.com.sg]
Sent: Wednesday, 3 January, 2018 2:10 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC) <YewChung@smrt.com.sg>; Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <PehEngHock@smrt.com.sg>
Subject: CTP OD - SGV8921R

Hi Shiau Chan,

Owner have call up several time to check for the authorization to start the repair work for SGV8921R.

The survey has been done on 29 Dec 2017.

Please assist ASAP to seek the approval for the authorization to start the repair work.

Thanks.
Regards,
Esther

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 6264A

Vehicle Details

Vehicle No.: SGV8921R

Vehicle to be Exported: No

Intended De-registration Date: 02 Jan 2018

Vehicle Make: HONDA

Vehicle Model: CIVIC 1.8L A

Primary Colour: White

Manufacturing Year: 2007

Engine No.: R18A12030161

Chassis No.: JHMF163075213587

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$19,923.00

Original Registration Date: 28 Jun 2007

First Registration Date: 28 Jun 2007

Transfer Count: 3

Actual ARF Paid: \$21,916.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 27 Jun 2022

COE Category: B - Car (1601cc & above)

COE Period(Years): 5

PQP Paid: \$27,044.00

COE Rebate Amount: \$24,264.00

Total Rebate Amount: \$24,264.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Jan 2018

Denise Tay (LKKAUTO)

From: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
<TeyChorKeng@smrt.com.sg>
Sent: Wednesday, 31 January 2018 1:32 PM
To: Denise Tay (LKKAUTO); Shiau Chan (LKKAUTO); SUR; Rasul (LKKAUTO)
Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: RE: CTP OD - SGV8921R

Hi Denise,

We have confirm to finalised at \$4950 lumpsum.

Regards,
Esther

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: 30 January 2018 09:08
To: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Shiau Chan (LKKAUTO); SUR; Rasul (LKKAUTO)
Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: RE: CTP OD - SGV8921R

Dear Esther,

Finalized at \$4950 lumpsum

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 3 January 2018 2:46 PM
To: Esther Tey Chor Keng (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <TeyChorKeng@smrt.com.sg>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC) <YewChung@smrt.com.sg>; Peh Eng Hock (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <PehEngHock@smrt.com.sg>
Subject: RE: CTP OD - SGV8921R

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGV 8921R (Excess \$250/-). LUMP SUM REPAIR**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 02 Jan 2018

Preliminary Advice

Vehicle No	: SGV8921R	Accident Date	: 23/12/2017
Make	: HONDA CIVIC	Policy No.	: DMPCSN3050961700
Assignment Date	: 29/12/2017	Excess	: S\$250.00
Date of Inspection	: 29/12/2017	Est. Duration of Repair	: 15.00
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,466.21
Revised Amount	:S\$	6,449.06
Check Items (Estimated)	:S\$	3,711.54
Total	:S\$	10,160.06
 Lump Sum Repair	 :S\$	 8,100.00 (ESTIMATE)

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	36,000.00
COE / PARF Rebate	:S\$	24,264.00
Salvage Value	:S\$	
Margin for Repair	:S\$	11,736.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.
WE HAVE NOT AUTHORISE REPAIR.



ANNOUNCING Benefit Auto
as sgCarMart Premium Dealer for the 4th Consecutive Year

BENEFIT AUTO

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year Coe Renewal 2007 Toyota Vios 1.5A



\$2500 Downpayment Monthly
From \$580 Onwards. Lowest
3.68% @gv Cars Financing.
GV Credit Pte Ltd StarAd



click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category ▼

◀ Back (1 2) Next ▶

Sort by Date Posted ▼

20 results/page ▼

21 vehicles


CIVIC 1.8

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	CIVIC 1.8		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Honda Civic 1.8A VTI-S (COE till 02/2021)		\$27,800	\$8,950 /yr	10-Feb-2006	1,799 cc	159,000 km	Sedan	Available
"One Year Warranty!" With Official Warranty Certificate For A Peace Of Mind, Our Company Renew COE Cars For Sale Base On Car Conditions Not On Ownership, Fully Refurbished, New Paintwork, Full Bodykit...									
Carway									
Posted: 02-Jan-2018 Tags: 2006 Honda Civic, 2006 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda									
	Honda Civic 1.8A VTI-S (COE till 11/2022)		\$40,800	\$8,310 /yr	12-Dec-2007	1,799 cc	-	Sedan	Available
Down Payment \$2800! Lowest Monthly \$728 Onwards. Interest 3.88% Per Annum At GV In House Loan 100% Approval. 2 Years Warranty By GV In House Workshop. New Fully Pure Leather Seat And New \$2k Metallic ...									
GV Credit Pte Ltd									
Posted: 01-Jan-2018 Tags: 2007 Honda Civic, 2007 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda									
	Honda Civic 1.8A VTI-S (COE till 06/2022)		\$35,800	\$7,990 /yr	27-Jun-2007	1,799 cc	-	Sedan	Available
\$0 Downpayment Available! Lowest Depreciation! Excellent Condition, No Repaired Needed! No Worries About Down Payment, Bank And In House Loan Available, Low Interest Rate, Low Down Payment Or No Down Payment...									
Posted: 01-Jan-2018 Tags: 2007 Honda Civic, 2007 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda									
	Honda Civic 1.8A VTI-S (COE till 06/2021)		\$28,800	\$8,240 /yr	03-Jul-2006	1,799 cc	-	Sedan	Available
1 Owner All These Years! 6 Months Workshop Warranty For Engine And Gearbox. Well Maintained And Timely Serviced By Careful Owner. Bank/In House Loan Available. Trade In Welcome. Call Our Friendly Sale...									
Posted: 30-Dec-2017 Tags: 2006 Honda Civic, 2006 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda									
Car Buying Car Ownership Car Selling On The Move Car Aftermarket Lifestyle Buy Tyres Online! Latest Special Offers from Tyrepatch!									
	Honda Civic 1.8A VTI-S (COE till 05/2021)		\$27,800	\$8,150 /yr	05-Jun-2006	1,799 cc	145,000 km	Sedan	Available
New Radiator, New Battery And Four New Tyres. 6 Months Workshop Warranty For Engine And Gearbox. Well Maintained And Timely Serviced By Careful Owner. Bank/In House Loan Available. Trade In Welcome. C...									
Posted: 30-Dec-2017 Tags: 2006 Honda Civic, 2006 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda									
	Honda Civic 1.8A VTI-S (COE till 07/2022)		\$43,800	\$9,570 /yr	01-Aug-2007	1,799 cc	155,000 km	Sedan	Available
Well Maintained And Timed Serviced By Careful Owner, No Repairs Needed, Trade In Welcomed, In-house Loan Provided, High Loan With Minimum Drive Away Welcomed! Call Us For An Appointment At Our Showroo...									
Tay Motor & Credit Pte Ltd									
Posted: 30-Dec-2017 Tags: 2007 Honda Civic, 2007 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda									
	Honda Civic 1.8A VTI-S (COE till 05/2022)		\$35,000	\$8,000 /yr	19-May-2007	1,799 cc	-	Sedan	Available
▼ To Make A Viewing Appointment!									



Posted: 29-Dec-2017 Tags: 2007 Honda Civic, 2007 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda



Honda Civic 1.8A VTI-S (COE till 04/2021) **\$28,800** **\$8,660 /yr** **18-May-2006** **1,799 cc** **-** **Sedan** **Available**

Very Well Maintained, COE Renewed Till 04/2021. Road Tax Valid Till Nov 2017, View To Appreciate And Offer. All Done Up! Fuss Free And Major Servicing Done Up. No Need To Repair! Call Now To View Or T...

DIRECT OWNER

Posted: 28-Dec-2017 Tags: 2006 Honda Civic, 2006 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details



Honda Civic 1.8A VTI-S (New 5-yr COE) **\$42,800** **\$8,560 /yr** **27-Dec-2007** **1,799 cc** **91,851 km** **Sedan** **Available**

We Are Open Today! Best Of The Best Condition! Act Now For The Best Deal! All Wear And Tear Parts Replaced With Receipts And Full Servicing Records! Rewind Back 10 Years When This Car Is Still Brand N...

Car House Pte Ltd

Posted: 25-Dec-2017 Tags: 2007 Honda Civic, 2007 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details



Honda Civic 1.8A VTI-S (COE till 06/2022) **\$38,800** **\$8,750 /yr** **09-Jun-2007** **1,799 cc** **-** **Sedan** **Available**

\$5000 To \$7000 Drive Away! 1 To 1 Exchange Available! Monthly From \$594. Guaranteed Approval! All Our Cars Have Undergone A Workshop Check. Buy With Trust And Assurance! Expect Only Honest Deals! Call...

Posted: 24-Dec-2017 Tags: 2007 Honda Civic, 2007 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details



Honda Civic 1.8A VTI-S (New 5-yr COE) **\$38,800** **\$7,760 /yr** **13-Dec-2007** **1,799 cc** **-** **Sedan** **Available**

\$0 Down Payment At Only \$900+ Per Month! We Are sgCarMart Premium Dealer 2015-2017 Buy With Zero Worries! 100% No Hidden Costs! Low Mileage! 100% Accident Free! In House Loan Or Bank Loan Available! N...

88 Motor Trading

Posted: 23-Dec-2017 Tags: 2007 Honda Civic, 2007 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details



Honda Civic 1.8A VTI-S (COE till 07/2022) **\$43,800** **\$9,720 /yr** **05-Jul-2007** **1,799 cc** **133,000 km** **Sedan** **Available**

With New 5 Years COE! Low Mileage. Quiet And Smooth Engine, Test Drive You Will Know! Original Condition. Well Kept. Road Tax. Most Popular Family Sedan, Reliable Engine, Spacious With Comfortable Rid...

Tay Motor & Credit Pte Ltd

Posted: 23-Dec-2017 Tags: 2007 Honda Civic, 2007 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details



Honda Civic 1.8A VTI-S (New 5-yr COE) **\$39,800** **\$7,960 /yr** **02-Jan-2008** **1,799 cc** **-** **Sedan** **Available**

New 5 Years COE With In-House Loan Available. Periodically Serviced And Maintained By Owner Most Wear And Tear Replaced. Original Leather Still In Good Condition. Interior Clean And Neat. Call To View...

Posted: 20-Dec-2017 Tags: 2008 Honda Civic, 2008 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details



Honda Civic 1.8A VTI-S (New 5-yr COE) **\$41,800** **\$8,360 /yr** **10-Dec-2007** **1,799 cc** **114,000 km** **Sedan** **Available**

AA Trust Certified Quality Pre-Own 1 Owner Vehicle. With As Low As \$5K Driveaway. Latest Addition To The Civic Line! Well Maintained By 1 Owner! Perfect For Work, Social And Family With Generous Legro...

AA Trust Automotive

Posted: 17-Dec-2017 Tags: 2007 Honda Civic, 2007 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details




Honda Civic 1.8A VTI-S (COE till 08/2021) **\$29,000** **\$7,920 /yr** **13-Sep-2006** **1,799 cc** **114,800 km** **Sedan** **Available**

Selling Cheap! Renewed Roadtax, Low Mileage, Brand New Battery With Voltage Stabiliser, Michelin Tyre With Sports Rim, No Repair Required, Well Maintained. Bidded Nice Carplate Number.

DIRECT OWNER

Posted: 12-Dec-2017 Tags: 2006 Honda Civic, 2006 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details



Honda Civic 1.8A VTI-S (COE till 05/2021) **\$28,888** **\$8,480 /yr** **31-May-2006** **1,799 cc** **83,120 km** **Sedan** **Available**

Well Maintained Interior And Vacuumed Fully Cleaned. Full Agent Motor Servicing Was Recently Done At 80000. New Engine Mounting Was Installed. Mileage Of 82499km As Of Now. Call Me Now For More Detail...

DIRECT OWNER

Posted: 10-Dec-2017 Tags: 2006 Honda Civic, 2006 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details



Honda Civic 1.8A VTI-S (COE till 07/2022) **\$39,800** **\$8,720 /yr** **26-Jul-2007** **1,799 cc** **145,000 km** **Sedan** **Available**

Cheapest In Town, Low Mileage Done, Just Arrival! Beautiful And Classic Silver In Black Honda Civic 1.8LA. Reliable And Low Maintenance Cost. Lotsa New Parts Replace. \$6000 Driveway, Inhouse Loan Arra...

Posted: 10-Dec-2017 Tags: 2007 Honda Civic, 2007 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details



**Honda Civic 1.8A VTI-S (COE
till 03/2026)**

\$62,800

\$7,620 /yr

30-Mar-2006

1,799 cc

-

Sedan

Available

Value For Money Low Depreciation! Buy With Peace Of Mind. Come Together With Plate No 399, Flawless And Stylish Interior And Exterior, No Repair Needed. All Wear And Tear Has Been Done Up. View To App...

Posted: 06-Dec-2017 Tags: 2006 Honda Civic, 2006 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details



**Honda Civic 1.8A VTI-S (COE
till 05/2026)**

\$53,800

\$6,440 /yr

11-May-2006

1,799 cc

161,307 km

Sedan

Available

Sporty Black Civic 1.8A, With Full Agent Serviced. One Free Service At Kah Motor. Excellent Condition, Well Maintained By Previous Owner, Viewing Strictly Via Appointment Only.

Carro

Posted: 04-Dec-2017 Tags: 2006 Honda Civic, 2006 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details



**Honda Civic 1.8A VTI-S (COE
till 09/2022)**

\$38,800

\$8,280 /yr

10-Sep-2007

1,799 cc

-

Sedan

Available

Fully Serviced, New Road Tax. You Wouldn't Believe The Tip Top Condition Of This Unit Without Viewing It. No Financial Strain As We Provide In House Loans And Other Financial Services To Meet Your Nee...

Posted: 18-Nov-2017 Tags: 2007 Honda Civic, 2007 Honda Civic, Honda Civic, Honda Civic, Honda, Civic, Civic, Used Honda

Details

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

« Back (1 2) Next »

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagon, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used CIVIC 1.8, CIVIC 1.8, CIVIC 1.8 Singapore, used CIVIC 1.8, used vehicles Singapore or even buy used CIVIC 1.8 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/12/2017 10:23
Date Of Accident	23/12/2017 16:30
Exact Location Of Accident	NORTH SOUTH HIGHWAY (186.4KM)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGV8921R
Insured/Policyholder	
Name Of Registered Owner	LIM KAH YEEN
NRIC No	S8286264A
Email Address	LIMKY@CHEVALIER.COM.SG
Mobile Phone No	(LOCAL) +65-97550103
Alternative Phone No	OFFICE-63623792

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3050961700
Cover Note Number	

Driver

Name of Driver	LIM KAH YEEN
NRIC No	S8286264A
Date Of Birth	30/09/1982
Occupation	INDOOR
Date Of Driving Pass	04/09/2010
Driving Experience	7 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97550103
Fax Number	
Contact Number	OFFICE-63623792
Email Address	LIMKY@CHEVALIER.COM.SG

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number WRB9838

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category BUS

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling to Melaka at lebuh raya utara selatan suddenly hit by a MPU car WPG 6435 at behind and was the car was hit by a bus WRB 9838. This cause my car hit at the front car but the front car does not have any damages as he just left. My car front and back was damages due to the impact of the MPU hit by behind.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:


Accident Photo



Accident Photo



Accident Photo



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S66500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MR117168842 Vehicle Registration No: SGV8921R
Name (as shown in NRIC) : Lim Kah Yuen NRIC/FIN/Passport No : 58286264A
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : _____
Email Address : _____
Date of Accident : 23/12/2017 Time of Accident : 1630hrs
Place of Accident : North South Highway (186.4KM)
Insurance Company : China Taiping Insurance (Singapore) Pte Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Claiming under own Policy

26/12/17
Policyholder / Driver's Signature
Date:

26/12/2017
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Dec 2017)

Parts: 143 HONDA CIVIC 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SMRT Automotive Services Pte Ltd/SGV8921R/29/12/2017 11:51

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*3RD BRAKE LAMP BULB	0.00	0.00	SVC X*2.87 F
2	1	NA	*ADD/BR/LAMP B/HOLDER	0.00	0.00	SVC X*14.20 F
3	1	NA	*BADGE 1.8	0.00	0.00	SVC X*10.99 F
4	1	NA	*BADGE CIVIC	0.00	0.00	SVC X*19.41 F
5	1	NA	*BADGE HONDA	0.00	0.00	NEC ✓*26.40 F ✓
6	1	NA	*BADGE HONDA	0.00	0.00	SVC X*28.80 F
7	1	NA	*BONNET	0.00	0.00	SVC X*575.80 F
8	1	NA	*BONNET LOCK	0.00	0.00	SVC X*125.00 F
9	1	NA	*BOOTFLOOR	0.00	0.00	K *858.80 F ✓
10	1	NA	*BOOTLID	0.00	0.00	BT ✓*530.70 F ✓
11	1	NA	*BOOTLID COVER	0.00	0.00	BT ✓*185.00 F ✓
12	1	NA	*BOOTLID LOCK	0.00	0.00	BT ✓*66.25 F ✓
13	1	NA	*BOOTLID SEAL	0.00	0.00	NEC ✓*67.40 F ✓
14	1	NA	*BOOTLID TRIM FASTEN	0.00	0.00	DE ✓*F
15	1	NA	*BOOTLID WIRING	0.00	0.00	DE ✓*209.11 F
16	1	NA	*END PANEL TRIM	0.00	0.00	DE ✓*57.50 F
17	1	NA	*FRONT BUMPER ✓ DE	0.00	0.00	DE ✓*601.20 F ✓
18	1	NA	*FRONT BUMPER SPOILER	0.00	0.00	DE ✓*150.00 F
19	1	NA	*FRONT BUMPER SUPPORT	0.00	0.00	DE ✓*202.20 F
20	1	NA	*FRONT NUMBER PLATE ✓ DE	0.00	0.00	(SIN) ✓*35.00 F ✓
21	1	NA	*FRT NO PLATE REINF ✓ DE	0.00	0.00	✓*35.00 F ✓
22	1	NA	*GRILL BRACKET	0.00	0.00	SVC X*180.00 F
23	1	NA	*GRILLE	0.00	0.00	SVC X*146.00 F
24	1	NA	*GRILLE BADGE	0.00	0.00	SVC X*24.00 F
25	1	NA	*HI-LEVEL BRAKE LAMP	0.00	0.00	SVC X*73.25 F
26	1	NA	*L/BACKUP LAMP B/HOLD	0.00	0.00	SVC X*15.00 F
27	1	NA	*L/BUMPER COVER	0.00	0.00	SVC *350.00 F
28	1	NA	*L/F HEADLAMP CPL	0.00	0.00	SVC X*768.80 F
29	1	NA	*L/F OUT BUMPER BRKT	0.00	0.00	NEC X*27.50 F
30	1	NA	*L/F UPP BUMPER BRKT	0.00	0.00	NEC ✓*15.00 F ✓
31	1	NA	*L/NO PLATE LAMP BULB	0.00	0.00	Mis- ✓*2.87 F ✓
32	1	NA	*L/NO PLATE LAMP LENS	0.00	0.00	SVC X*7.72 F
33	1	NA	*L/NO. PLATE LAMP	0.00	0.00	SVC X*9.65 F
34	1	NA	*L/PARK/BR LAMP BULB	0.00	0.00	SVC X*14.44 F
35	1	NA	*L/PARK/BR/LAMP BULB	0.00	0.00	SVC X*15.00 F
36	1	NA	*L/R AIR VENT GRILLE	0.00	0.00	SVC X*21.18 F
37	1	NA	*L/R BUMPER BRACKET	0.00	0.00	NEC ✓*18.07 F ✓
38	1	NA	*L/R FOG LAMP B/HOLD	0.00	0.00	SVC X*39.35 F
39	1	NA	*L/R FOG LAMP BULB	0.00	0.00	SVC X*2.87 F
40	1	NA	*L/R HINGE	0.00	0.00	SVC X*158.00 F
41	1	NA	*L/R INDIC BULB HOLD	0.00	0.00	SVC X*10.96 F
42	1	NA	*L/R INDICATOR BULB	0.00	0.00	SVC X*2.87 F
43	1	NA	*L/R INN BUMPER BRKT	0.00	0.00	NEC ✓*13.20 F ✓
44	1	NA	*L/R INNER LAMP CPL	0.00	0.00	SVC ✓*204.80 F ✓
45	1	NA	*L/R LAMP PANEL	0.00	0.00	PA ✓*125.00 F ✓

SMRT Automotive Services Pte Ltd/SGV8921R/29/12/2017 11:51. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1	NA	*L/R OUTER LAMP CPL	0.00	0.00	SVC X *97.11 F
47	1	NA	*L/R PARK SYS SENSOR	0.00	0.00	SVC X *120.00 F
48	1	NA	*L/R SIDE PANEL	0.00	0.00	R *671.70 F
49	1	NA	*L/R SIDE PANEL TRIM	0.00	0.00	SVC X *180.00 F
50	1	NA	*L/REVERSE BULB	0.00	0.00	SVC X *15.00 F
51	1	NA	*LOWER BUMPER COVER	0.00	0.00	over ✓ *125.50 F ✓
52	1	NA	*MOUNTING CLAMP	0.00	0.00	SK X *4.88 F
53	1	NA	*MOUNTING CLAMP	0.00	0.00	SVC X *8.80 F
54	1	NA	*MOUNTING CLAMP	0.00	0.00	SK X *8.28 F
55	1	NA	*MOUNTING CLAMP	0.00	0.00	SVC X *12.20 F
56	1	NA	*R/BACKUP LAMP B/HOLD	0.00	0.00	SVC X *15.00 F
57	1	NA	*R/BUMPER COVER	0.00	0.00	SVC X *350.00 F
58	1	NA	*R/F HEADLAMP CPL	0.00	0.00	SVC X *768.80 F
59	1	NA	*R/F OUT BUMPER BRKT	0.00	0.00	nm X *27.50 F
60	1	NA	*R/F UPP BUMPER BRKT	0.00	0.00	nm X *15.00 F ✓
61	1	NA	*R/NO PLATE LAMP BULB	0.00	0.00	nm X SVC X *2.87 F ✓
62	1	NA	*R/NO PLATE LAMP HSG	0.00	0.00	SVC X *9.65 F
63	1	NA	*R/NO PLATE LAMP LENS	0.00	0.00	cm X SVC X *7.72 F ✓
64	1	NA	*R/PARK/BR/LAMP B/HOL	0.00	0.00	SVC X *14.44 F
65	1	NA	*R/PARK-/BR/LAMP BULB	0.00	0.00	SVC X *15.00 F
66	1	NA	*R/R AIR VENT GRILLE	0.00	0.00	SVC X *21.18 F
67	1	NA	*R/R BUMPER BRACKET	0.00	0.00	nm X *18.07 F ✓
68	1	NA	*R/R FOG LAMP B/HOLD	0.00	0.00	SVC X *39.35 F
69	1	NA	*R/R FOG LAMP BULB	0.00	0.00	SVC X *2.87 F
70	1	NA	*R/R HINGE	0.00	0.00	SVC X *158.00 F
71	1	NA	*R/R INDIC BULB HOLD	0.00	0.00	SVC X *10.96 F
72	1	NA	*R/R INDICATOR BULB	0.00	0.00	SVC X *2.87 F
73	1	NA	*R/R INN BUMPER BRKT	0.00	0.00	nm X *13.20 F ✓
74	1	NA	*R/R INNER LAMP CPL	0.00	0.00	nm X *204.80 F ✓
75	1	NA	*R/R LAMP PANEL	0.00	0.00	BT X *125.00 F ✓
76	1	NA	*R/R OUTER LAMP CPL	0.00	0.00	SVC X *97.11 F
77	1	NA	*R/R PARK SYS SENSOR	nm 0.00	0.00	nm X *120.00 F ✓
78	1	NA	*R/R SIDE PANEL TRIM	0.00	0.00	SVC X *180.00 F
79	1	NA	*R/REVERSE BULB	0.00	0.00	SVC X *15.00 F
80	1	NA	*RADIATOR GRILLE TRIM	0.00	0.00	SK X *168.50 F
81	1	NA	*REAR BUMPER	0.00	0.00	DE X *601.02 F ✓
82	1	NA	*REAR LOCK CYL	0.00	0.00	SVC X *57.57 F
83	1	NA	*REAR LOCK STRIKER	0.00	0.00	BT X *15.56 F ✓
84	1	NA	*REAR MOULDING	0.00	0.00	SVC X *185.00 F
85	1	NA	*REAR NO PLATE BACKG	0.00	0.00	SVC X *35.00 F
86	1	NA	*REAR NUMBER PLATE	0.00	0.00	X DE X *35.00 F ✓
87	1	NA	*REAR PANEL CPL	0.00	0.00	BLK X *269.50 F ✓
88	1	NA	*REAR SCREEN	0.00	0.00	SVC X *356.39 F
89	1	NA	*REAR SCREEN BOND KIT	0.00	0.00	SVC X *30.00 F
90	1	NA	*REAR SCREEN CLAMPS	0.00	0.00	SVC X *10.70 F
91	1	NA	*REAR SCREEN FIX SET	0.00	0.00	SVC X *-F
92	1	NA	*REAR SCREEN SEAL	0.00	0.00	SVC X *125.00 F
93	1	NA	*REAR SCREEN SPACER	0.00	0.00	SVC X *7.26 F
94	1	NA	*REAR SCREEN SPACER	0.00	0.00	SVC X *8.44 F
95	1	NA	*REAR SPOILER	0.00	0.00	SVC X *450.00 F
96	1	NA	*RR BUMPER CLAMP KIT	0.00	0.00	X *-F
97	1	NA	*RR EXHAUST SILENCER	0.00	0.00	SVC X *450.00 F
98	1	NA	*SPARE WHEEL COVER	0.00	0.00	DE X *258.00 F ✓
99	1	NA	*SPECIALIST AUDATEX FEE	0.00	0.00	*42.00 F (S)
100	1	NA	*SUNDRY PARTS	0.00	0.00	*1000 X *251.96 F (S)

F=Franchise part.

Reverse SUNDAY

Glo

\$180

(S)

Sub Total (\$\$)

12,891.92

+ Margin on L,N Items 5.00% (\$\$)

644.60

SMRT Automotive Services Pte Ltd/SGV8921R/29/12/2017 11:51. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New	588.80 772.80
2	Total Paint Materials	New	292.65 375.45
3	Total Panel/Mechanical Labour	New	881.80 1,982.60
Gross Labour Cost (\$\$)			3,130.85

SMRT Automotive Services Pte Ltd/SGV8921R/29/12/2017 11:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
Total Parts (S\$)						13,536.52

SMRT Automotive Services Pte Ltd/SGV8921R/29/12/2017 11:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

SMRT Automotive Services Pte Ltd (Co.Reg.No:199004280Z)

60 Woodlands Industrial Park E4

Singapore 757705

Tel: 68662628 Fax: 63687421 Email: feiyuan@smrt.com.sg;wongkokwah@smrt.com.sg

(SUPPLEMENTARY)**INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WL/DEC2017/007
Policy No:	DMPCSN3050961700	Date of Loss:	23/12/2017
Vehicle Reg. No.:	SGV8921R	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury	NO	Third Party	YES
Involved?		Involved?	
Insured/Claimant:	LIM KAH YEEN		
Driver:	LIM KAH YEEN		
Make/Model:	HONDA CIVIC, 1.8 (A)	Vehicle Reg. Date:	28/06/2007
Vehicle Colour:	WHITE		
Engine No:	R18A12030161	Chassis No:	JHMFD16307S213587
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of	7		
Repair (day)			
Description of	PLEASE REFER TO THE SAS REPORT.		
Accident/Loss			
Present Location:	SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS)		

COST OF CLAIMS	Amount
Parts	798.84
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	798.84
+ GST 7.00% (S\$)	55.92
Nett Amount (S\$)	854.76
+ Previous Estimates (S\$)	17,834.09
Claim Total (S\$)	18,688.85

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Dec 2017)
 Parts: 143 HONDA CIVIC 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: SMRT Automotive Services Pte Ltd/SGV8921R/29/12/2017 14:17
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*REAR FENDER INNER SHIELD	0.00	0.00	*276.40 F
2	2		*REAR MUDFLAP	0.00	0.00	*152.80 F
3	1		*BOOTLID REFLECTOR RH	0.00	0.00	*132.10 F
4	1		*BOOTLID REFLECTOR LH	0.00	0.00	*132.10 F
5	1		*BOOTLID WEATHERSTRIP	0.00	0.00	*67.40 F

F=Franchise part.

Sub Total (S\$)	760.80
+ Margin on L,N Items 5.00% (S\$)	38.04
Total Parts (S\$)	798.84

SMRT Automotive Services Pte Ltd/SGV8921R/29/12/2017 14:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

SMRT Automotive Services Pte Ltd/SGV8921R/29/12/2017 14:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**SMRT AUTOMOTIVE
SERVICES PTE LTD
60 WOODLANDS
INDUSTRIAL PARK E4
757705**

Claim Reference: WL/DEC2017/007
Assessment Number: CTI10125
Version: SMRTAUTO/1
Date Calculated: 29/12/2017 03:31

Full Report - V1
Registration: SGV8921R
Printed: 29/12/2017 11:31

Summary Information


Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	yew chung smrt	Date of Incident:	23/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	WL/DEC2017/007	Estimated Repair Time:	
Policy Number:	DMPCSN3050961700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	HONDA	RR PARK DIST CONTROL	1.8 LTR 103 KW
Model:	Civic	MUDFLAP	REAR SPOILER
Sub Model:	VTI-S	TWO COAT METALLIC	
Model Sheet Number:	H48 38		
Registration:	SGV8921R		
Registration Month:	June		
Registration Year:	2007		
VIN Number:			
Manufacture Month:	June		
Manufacture Year:	2007		
Odometer:	Not Known		
Colour:			
Engine Number:			
Fuel Level:	%		

Vehicle Condition

Vehicle Status			
Pre-Accident Condition:		Severity of Impact:	
Steering:		Vehicle Status on Inspection:	
Brakes Pedal Travel:		Date of Inspection:	28/12/2017
Place of Inspection:			
Pre-Accident Damage:			
Tyres Condition:	Fair		
Tread Depth LHF:		Tread Depth RHF:	
Tread Depth LHR:		Tread Depth RHR:	
Damage Areas:		Direction of Impact:	

SMRT AUTOMOTIVE SERVICES PTE LTD**Claim Reference: WL/DEC2017/007****Assessment Number: CTI10125****Version: SMRTAUTO/1****Date Calculated: 29/12/2017 03:31****Full Report - V1****Registration: SGV8921R****Printed: 29/12/2017 11:31****Addresses****Cost Summary**

Total Labour	\$2,755.40
Total Paint/Material	\$375.45
Total Parts	\$13,479.82
Total of Additional Costs	\$42.00
Excess:	TBA
Grand Total Exc GST:	\$16,652.67
7 % GST:	\$1,165.69
Grand Total Inc GST:	\$17,818.36

Repair Information**LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR****Price/Dent = \$46.00/HR****Repair /****Guide Number Repair Details**

	WU	Cost Price (\$)
71101-SNB RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER CPL AND R + R RADIATOR GRILLE.	6.0	27.60
71130-SNA) R + R FRONT BUMPER BRACKET	2.0	9.20
33151-SNB) R + R LEFT HEADLAMP UNIT	4.0	18.40
33101-SNB) R + R RIGHT HEADLAMP UNIT	4.0	18.40
NO NUMBER ADJUST HEADLAMP	1.0	4.60
71125-SNB) R + R RADIATOR GRILLE BRACKET	1.0	4.60
17SNA-601 RENEW BONNET INCLUDES: R + R AND ADJUST BONNET	6.0	27.60
74120-SNB R + R BONNET LOCK	3.0	13.80
76805-SNA R + R FUEL FILLER NECK	1.0	4.60
83753-SNB R + R LEFT REAR DOOR TRIM	4.0	18.40
NO NUMBER R + R NUMBER PLATE LAMP BULB	2.0	9.20
71501-SNB RENEW REAR BUMPER	3.0	13.80
NO NUMBER R + R REAR PARKING AID SENSORS ADD/WORK	3.0	13.80
68500-SNB) RENEW BOOTLID (REMOVED) INCLUDES: R + R INNER TAILLAMPS, NUMBER PLATE, BADGE, NUMBER PLATE LAMPS AND LOCK	9.0	41.40
68660-SNA) R + R L/BOOTLID HINGE	8.0	36.80
68610-SNA) R + R R/BOOTLID HINGE	8.0	36.80
NO NUMBER RENEW R/INNER SIDE PANEL CONNECTION	23.0	105.80
62100-SMG RENEW REAR END PANEL CPL	41.0	188.60
NO NUMBER R + R ATTACHED PARTS OF THE L/SIDE PANEL INCLUDES: R + R BUMPER, TAIL LAMP, BOOT LID, BOOT LID SEAL, REAR SEAT, SEAT	55.0	253.00

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: WL/DEC2017/007

Assessment Number: CTI10125

Version: SMRTAUTO/1

Date Calculated: 29/12/2017 03:31

Full Report - V1

Registration: SGV8921R

Printed: 29/12/2017 11:31

	BELT, FUEL FILLER LID, FUEL FILLER NECK, REAR WINDOW AND ALL TRIMS IN THE REPAIR SECTION		
04646-SMG	RENEW L/SIDE PANEL	94.0	432.40
NO NUMBER	R + R ATTACHED PARTS OF THE REAR PANEL (REAR BUMPER AND BOTH TAIL LAMPS REMOVED)	35.0	161.00
	INCLUDES: R + R BOOT LID LOCK AND NECESSARY ATTACHED PARTS		
17044-SNA	R + R FUEL TANK	15.0	69.00
NO NUMBER	RENEW REAR FLOOR CPL	96.0	441.60
18310-SNA	R + R REAR SILENCER	2.0	9.20
9973	CARRY OUT TEST DRIVE	5.0*	23.00
LABOUR COST			
	Total Work Units	431.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	43.1HRS	\$1,982.60
	Paint Labour	16.8HRS	\$772.80
	Total Labour	59.9HRS	\$2,755.40

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$46.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
340	FRONT BUMPER SUPPORTSURFACE PAINT	4.0	
471	BONNET NEW PART PAINTING	17.0	
2711	REAR PANEL CPL NEW PART PAINTING	19.0	
2931	BOOTLID NEW PART PAINTING	16.0	
3481	L/R SIDE PANEL NEW PART PAINTING	29.0	
3900	BOOTFLOOR SURFACE PAINT	9.0	
283	FRONT BUMPER NEW PART PAINT K1R	12.0	
2583	REAR BUMPER NEW PART PAINT K1R	13.0	
2587	LOWER BUMPER COVER NEW PART PAINT K1R	3.0	
3045	REAR SPOILER NEW PART PAINT K1R	5.0	
3482	R/R SIDE PANEL REPAIR PAINTING <50%	15.0	
LABOUR COST - PAINT			
	TIME(PAINT)	142.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	168.0	
	Total Paintwork Labour	16.8HRS	\$772.80
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$154.48
	New Part Painting - Plastic K1R		\$138.73
	Surface-/Blend Paint		\$31.88
	Repair Painting		\$23.26
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$375.45
	Pearlescent Uplift @ 0.0%		\$0.00

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: WL/DEC2017/007

Assessment Number: CTI10125

Version: SMRTAUTO/1

Date Calculated: 29/12/2017 03:31

Full Report - V1

Registration: SGV8921R

Printed: 29/12/2017 11:31

Total Paint Material Cost

\$375.45

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015
					Bet. Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		0% <i>CA</i> 35.00* <i>X</i>
258	1	FRT NO PLATE REINF	KNPL0		0% <i>SVC</i> 35.00* <i>X</i>
283 ✓	1	FRONT BUMPER	04711SNB010ZZ		0% <i>DE</i> 601.20*
317	1	L/F OUT BUMPER BRKT	71198SNB003		0% <i>na</i> 27.50* <i>X</i>
318	1	R/F OUT BUMPER BRKT	71193SNB003		0% <i>na</i> 27.50* <i>X</i>
319 ✓	1	L/F UPP BUMPER BRKT	71190SNB000		0% <i>na</i> 15.00*
320 ✓	1	R/F UPP BUMPER BRKT	71140SNB000		0% <i>na</i> 15.00*
340	1	FRONT BUMPER SUPPORT	71130SNAU90ZZ		0% <i>X</i> 202.20* <i>X</i>
343	1	FRONT BUMPER SPOILER	71110SNB000		0% <i>SVC</i> 150.00* <i>X</i>
345	1	L/BUMPER COVER	71109SNB000		0% <i>X</i> 350.00*
346	1	R/BUMPER COVER	71104SNB000		0% <i>X</i> 350.00*
410	1	RADIATOR GRILLE TRIM	71122SNB003		0% <i>X</i> 168.50*
411	1	GRILL BRACKET	71125SNB000		0% <i>X</i> 180.00*
412	1	GRILLE	71121SNB003		0% <i>X</i> 146.00* <i>X</i>
431	1	GRILLE BADGE	75700S9AG00		0% <i>X</i> 24.00*
471	1	BONNET	60100SNB000ZZ		0% <i>X</i> 575.80*
492	1	BONNET LOCK	74120SNBE11		0% <i>X</i> 125.00*
561	1	L/F HEADLAMP CPL	33151SNBD01		0% <i>X</i> 768.80*
562	1	R/F HEADLAMP CPL	33101SNBD01		0% <i>X</i> 768.80*
2583 ✓	1	REAR BUMPER	71501SNB010ZB		0% <i>DE</i> 601.02*
2587 ✓	1	LOWER BUMPER COVER	71504SNB000		0% <i>CA</i> 125.50*
2619 ✓	1	L/R BUMPER BRACKET	71598SNAA01		0% <i>na</i> 18.07U
2620 ✓	1	R/R BUMPER BRACKET	71593SNAA01		0% <i>na</i> 18.07U
2621 ✓	1	L/R INN BUMPER BRKT	71540SNAA00		0% <i>na</i> 13.20*
2622 ✓	1	R/R INN BUMPER BRKT	71540SNAA00		0% <i>na</i> 13.20*
2650	1	RR BUMPER CLAMP KIT			0% <i>X</i> 0.00*
2665	2	MOUNTING CLAMP	91503SZ3003		0% <i>SVC</i> 4.88U
2666	8	MOUNTING CLAMP	91505S9A003		0% <i>X</i> 18.80U
2673	1	L/R PARK SYS SENSOR	08V67SNB61005		0% <i>X</i> 120.00* <i>X</i>
2674	1	R/R PARK SYS SENSOR	08V67SNB61005		0% <i>X</i> 120.00* <i>X</i>
2702	1	REAR NUMBER PLATE			0% <i>SVC</i> 35.00* <i>X</i>
2703	1	REAR NO PLATE BACKG			0% <i>SVC</i> 35.00* <i>X</i>
2711 ✓	1	REAR PANEL CPL	66100SNAA01ZZ		0% <i>na</i> 269.50*
2931 ✓	1	BOOTLID	68500SNDG00ZZ		0% <i>na</i> 530.70*
2944 ✓	1	BOOTLID SEAL	74865SNC013		0% <i>na</i> 67.40*
2953	1	L/R HINGE	68660SNAA00ZZ		0% <i>SVC</i> 158.00* <i>X</i>
2954	1	R/R HINGE	68610SNAA00ZZ		0% <i>SVC</i> 158.00* <i>X</i>
2973 ✓	1	REAR LOCK STRIKER	74862SE3003		0% <i>na</i> 15.56U
2977 ✓	1	BOOTLID LOCK	74851SNA003		0% <i>na</i> 66.25U
2979	1	REAR MOULDING	74890SNB000ZA		0% <i>X</i> 185.00* <i>X</i>
2981	1	REAR LOCK CYL	74861SNB003		0% <i>X</i> 57.57U
3013 ✓	1	BADGE HONDA	75711SNAK01		0% <i>na</i> 26.40*
3015	1	BADGE HONDA	75701SNB003		0% <i>X</i> 28.80* <i>X</i>
3017	1	BADGE CIVIC	75722SNBJ01		0% <i>X</i> 19.41U
3021	1	BADGE 1.8	75731SNAK01		0% <i>X</i> 10.99U
3045	1	REAR SPOILER	71700SNDJ01ZB		0% <i>X</i> 450.00* <i>X</i>
3151	1	REAR SCREEN	73211SNAA02		0% <i>X</i> 356.39U
3160	1	REAR SCREEN BOND KIT	08CRCX016N0		0% <i>X</i> 30.00U

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: WL/DEC2017/007

Assessment Number: CTI10125

Version: SMRTAUTO/1

Date Calculated: 29/12/2017 03:31

Full Report - V1

Registration: SGV8921R

Printed: 29/12/2017 11:31

3161	1	REAR SCREEN SEAL	04733SNAA00	0%	X	125.00*
3163	1	REAR SCREEN FIX SET		0%	X	0.00
3164	2	REAR SCREEN SPACER	91501S70003	0%	X	7.26U
3165	2	REAR SCREEN SPACER	91536SS0J01	0%	X	8.44U
3166	2	REAR SCREEN CLAMPS	91568SNA003	0%	X	10.70U
3189	1	3RD BRAKE LAMP BULB	33303S30003	0%	X	2.87U
3190	1	ADD/BR/LAMP B/HOLDER	33513S50003	0%	X	14.20U
3191	1	HI-LEVEL BRAKELAMP	34271S5AA01	0%	X	73.25U
3269	1	L/PARK-/BR/LAMP BULB	34906ST5003	0%	X	15.00*
3270	1	R/PARK-/BR/LAMP BULB	34906ST5003	0%	X	15.00*
3271	1	L/PARK/BR LAMP BULB	33515S50003	0%	X	14.44U
3272	1	R/PARK/BR/LAMP B/HOL	33515S50003	0%	X	14.44U
3277	1	L/R INDICATOR BULB	33303S2R003	0%	X	2.87U
3278	1	R/R INDICATOR BULB	33303S2R003	0%	X	2.87U
3279	1	L/R INDIC BULB HOLD	33514S2R003	0%	X	10.96U
3280	1	R/R INDIC BULB HOLD	33514S2R003	0%	X	10.96U
3281	1	L/R OUTER LAMP CPL	33551SNB003	0%	X	97.11U
3282	1	R/R OUTER LAMP CPL	33501SNB003	0%	X	97.11U
3283 ✓	1	L/R INNER LAMP CPL	34156SNB023	✓0%	CRA	204.80*
3284 ✓	1	R/R INNER LAMP CPL	34151SNB023	✓0%	PFO	204.80*
3301	1	L/REVERSE BULB	34901SHJA01HE	0%	X	15.00*
3302	1	R/REVERSE BULB	34901SHJA01HE	0%	X	15.00*
3303	1	L/BACKUP LAMP B/HOLD	33304SED003	0%	X	15.00*
3304	1	R/BACKUP LAMP B/HOLD	33304SED003	0%	X	15.00*
3355 ✓	1	L/NO PLATE LAMP BULB	33301SNA003HE	✓0%	MCS	2.87U
3356 ✓	1	R/NO PLATE LAMP BULB	33301SNA003HE	✓0%	PMO	2.87U
3361	1	L/NO. PLATE LAMP	34105SNB003	0%	X	9.65U
3362	1	R/NO PLATE LAMP HSG	34105SNB003	0%	X	9.65U
3371	1	L/NO PLATE LAMP LENS	34106SNB023	0%	X	7.72U
3372 ✓	1	R/NO PLATE LAMP LENS	34106SNB023	✓0%	MCS	7.72U
3401	1	L/R FOG LAMP BULB	33303S30003	0%	X	2.87U
3402	1	R/R FOG LAMP BULB	33303S30003	0%	X	2.87U
3407	1	L/R FOG LAMP B/HOLD	34152SNBG01	0%	X	39.35U
3408	1	R/R FOG LAMP B/HOLD	34152SNBG01	0%	X	39.35U
3481	1	L/R SIDE PANEL	04646SNBG00ZZ	0%	X	671.70*
3571	1	L/R LAMP PANEL	63720SNBE00ZZ	0%	X	125.00*
3572 ✓	1	R/R LAMP PANEL	63320SNBE00ZZ	0%	M	125.00*
3783	1	L/R AIR VENT GRILLE	75450TR6A00	0%	X	21.18U
3784	1	R/R AIR VENT GRILLE	75450TR6A00	0%	X	21.18U
3900	1	BOOTFLOOR	04655SNE305ZZ	0%	X	858.80*
4907 ✓	1	BOOTLID COVER	84620SNBJ01ZA	✓0%	DE	185.00*
4921	1	BOOTLID TRIM FASTEN		0%	X	0.00
4925	4	MOUNTING CLAMP	90671S0D003ZK	0%	X	8.28U
4926	4	MOUNTING CLAMP	91507SH3003	0%	X	12.20U
4985	1	END PANEL TRIM	84640SNAA01ZA	0%	X	57.50*
4986 ✓	1	SPARE WHEEL COVER	84521SNBE01ZA	✓0%	DE	258.00*
4991	1	L/R SIDE PANEL TRIM	84651SNAK13ZA	0%	X	180.00*
4992	1	R/R SIDE PANEL TRIM	84601SNAK13ZA	0%	X	180.00*
8827	1	RR EXHAUST SILENCER	18307SNBJ01	0%	X	450.00*
9615	1	BOOTLID WIRING	32108SNBE01	0%	X	209.11U
f: OEM Parts				Sub Total		\$12,597.96
g: Original				Mark Up From Cost (5 %)		\$629.90

SMRT AUTOMOTIVE SERVICES PTE LTD

Claim Reference: WL/DEC2017/007

Assessment Number: CTI10125

Version: SMRTAUTO/1

Date Calculated: 29/12/2017 03:31

Full Report - V1

Registration: SGV8921R

Printed: 29/12/2017 11:31

h: Secondhand

p: Parallel

x: Exchange

Sundry Parts

(2 %)

\$251.96

Total Parts

\$13,479.82

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description

AUDATEX FEE

SPECIALIST

Betterment

0%

Price

\$42.00

Total Extras

\$42.00

Final Calculation

Total Parts

\$13,479.82

Labour

Total Panel/Mechanical

\$1,982.60

Total Paintwork

\$772.80

Total Labour

\$2,755.40

Additional Costs

Corr Prot Materials External

\$0.00

Corr Prot Materials Internal

\$0.00

Cost of Specialist

\$42.00

Total of Additional Costs

\$42.00

Total Paint/Material Costs

\$375.45

Grand Total Excludes GST

\$16,652.67

GST @ 7 %

\$1,165.69

Grand Total Includes GST

\$17,818.36

Assessment Notes

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RABU

Hp 90010068

15 days



48

29/12/17 @ 1500

EXCESS: 250

Revert

Resurvey after repair

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference: 20170001988****Assessment Number: CTI10125****Version: CHINATAI/15****Date Calculated: 03/01/2018 03:23****Full Report - V1****Registration: SGV8921R****Printed: 03/01/2018 11:24****Addresses****Cost Summary**

Total Labour	\$1,495.00
Total Paint/Material	\$296.39
Total Parts	\$4,172.67
Total of Additional Costs	\$292.00
Repair Cost Exc GST:	\$6,256.06
Overall Discount (0.0%):	- \$0.00
Excess:	-\$250.00
After Deduction -	
Grand Total Exc GST:	\$6,006.06
7 % GST:	\$420.42
Grand Total Inc GST:	\$6,426.48

Repair Information**LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR****Price/Dent = \$46.00/HR****Repair /****Guide Number Repair Details**

		WU	Cost Price (\$)
71101-SNB	RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER CPL AND R + R RADIATOR GRILLE.	6.0	27.60
NO NUMBER	R + R NUMBER PLATE LAMP BULB	2.0	9.20
71501-SNB	RENEW REAR BUMPER	3.0	13.80
NO NUMBER	R + R REAR PARKING AID SENSORS ADD/WORK	3.0	13.80
68500-SNB)	R + R BOOT LID	3.0	13.80
68500-SNB)	RENEW BOOTLID (REMOVED) INCLUDES: R + R INNER TAILLAMPS, NUMBER PLATE, BADGE, NUMBER PLATE LAMPS AND LOCK	9.0	41.40
NO NUMBER	RENEW L/INNER SIDE PANEL CONNECTION	23.0	105.80
NO NUMBER	RENEW R/INNER SIDE PANEL CONNECTION	23.0	105.80
NO NUMBER	R + R REAR END PANEL ATTACHED PARTS INCLUDES: R + R BUMPER, TAIL LAMP, BOOT TRIM, BOOT FLOOR TRIM, REAR PANEL TRIM, BOOT LOCK AND SEAL	35.0	161.00
62100-SMG	RENEW REAR END PANEL CPL	41.0	188.60
9973	CARRY OUT TEST DRIVE	5.0*	23.00
3481	REPAIR L/R SIDE PANEL	10.0*	46.00
3482	REPAIR R/R SIDE PANEL	10.0*	46.00
3900	REPAIR BOOTFLOOR	20.0*	92.00
0340	CHECK FRONT BUMPER SUPPORT		
0411	CHECK GRILL BRACKET		
0412	CHECK GRILLE		

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001988

Assessment Number: CTI10125

Version: CHINATAI/15

Date Calculated: 03/01/2018 03:23

Full Report - V1

Registration: SGV8921R

Printed: 03/01/2018 11:24

0561 CHECK L/F HEADLAMP CPL
2979 CHECK REAR MOULDING
4991 CHECK L/R SIDE PANEL TRIM
4992 CHECK R/R SIDE PANEL TRIM
8827 CHECK RR EXHAUST SILENCER

LABOUR COST

Total Work Units	193.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	19.3HRS	\$887.80
Paint Labour	13.2HRS	\$607.20
Total Labour	32.5HRS	\$1,495.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
340	FRONT BUMPER SUPPORTSURFACE PAINT	4.0	
2711	REAR PANEL CPL NEW PART PAINTING	19.0	
2931	BOOTLID NEW PART PAINTING	16.0	
283	FRONT BUMPER NEW PART PAINT K1R	12.0	
2583	REAR BUMPER NEW PART PAINT K1R	13.0	
2587	LOWER BUMPER COVER NEW PART PAINT K1R	3.0	
3481	L/R SIDE PANEL REPAIR PAINTING <50%	15.0	
3482	R/R SIDE PANEL REPAIR PAINTING <50%	15.0	
3900	BOOTFLOOR SURFACE PAINT	9.0	

LABOUR COST - PAINT

TIME(PAINT)	106.0	
Preparation Main Work Metal	21.0	
Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	132.0	
Total Paintwork Labour	13.2HRS	\$607.20

MATERIAL COST - PAINT

New Part Painting	\$67.41
New Part Painting - Plastic K1R	\$123.48
Surface-/Blend Paint	\$31.88
Repair Painting	\$46.52
Material-Const Main Work Metal	\$18.10
Material-Const Comp. Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$296.39
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$296.39

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
258	1	FRT NO PLATE REINF	KNPL0		0%	35.00*
283	1	FRONT BUMPER	04711SNB010ZZ		0%	601.20*
319	1	L/F UPP BUMPER BRKT	71190SNB000		0%	15.00*
320	1	R/F UPP BUMPER BRKT	71140SNB000		0%	15.00*
2583	1	REAR BUMPER	71501SNB010ZB		0%	601.02*
2587	1	LOWER BUMPER COVER	71504SNB000		0%	125.50*

Price Valid: 01/06/2015

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001988

Assessment Number: CTI10125

Version: CHINATAI/15

Date Calculated: 03/01/2018 03:23

Full Report - V1

Registration: SGV8921R

Printed: 03/01/2018 11:24

2619	1	L/R BUMPER BRACKET	71598SNAA01	0%	18.07U ✓
2620	1	R/R BUMPER BRACKET	71593SNAA01	0%	18.07U ✓
2621	1	L/R INN BUMPER BRKT	71540SNAA00	0%	13.20* ✓
2622	1	R/R INN BUMPER BRKT	71540SNAA00	0%	13.20* ✓
2711	1	REAR PANEL CPL	66100SNAA01ZZ	0%	269.50* ✓
2931	1	BOOTLID	68500SNDG00ZZ	0%	530.70* ✓
2944	1	BOOTLID SEAL	74865SNC013	0%	67.40* ✓
2973	1	REAR LOCK STRIKER	74862SE3003	0%	15.56U ✓
2977	1	BOOTLID LOCK	74851SNA003	0%	66.25U ✓
3013	1	BADGE HONDA	75711SNAK01	0%	26.40* ✓
3281	1	L/R OUTER LAMP CPL	33551SNB003	0%	0.00F ✓
3283	1	L/R INNER LAMP CPL	34156SNB023	0%	204.80* ✓
3284	1	R/R INNER LAMP CPL	34151SNB023	0%	204.80* ✓
3355	1	L/NO PLATE LAMP BULB	33301SNA003HE	0%	2.87U ✓
3356	1	R/NO PLATE LAMP BULB	33301SNA003HE	0%	2.87U ✓
3372	1	R/NO PLATE LAMP LENS	34106SNB023	0%	7.72U ✓
3571	1	L/R LAMP PANEL	63720SNBE00ZZ	0%	125.00* ✓
3572	1	R/R LAMP PANEL	63320SNBE00ZZ	0%	125.00* ✓
4907	1	BOOTLID COVER	84620SNB01ZA	0%	185.00* ✓
4986	1	SPARE WHEEL COVER	84521SNBE01ZA	0%	258.00* ✓
1000	1	BOOTLID REFLECTOR RH	Renew	0%	132.10* ✓
1000	1	BOOTLID REFLECTOR RH	Renew	0%	132.10* ✓
1000	1	BOOTLID WEATHERSTRIP	Renew	0%	67.40* ✓
f: OEM Parts				Saving	\$97.11
g: Original				Sub Total	\$3,878.73
h: Secondhand				Mark Up From Cost (5 %)	\$193.94
p: Parallel				Sundry Parts (Fixed)	\$100.00
x: Exchange				Total Parts	\$4,172.67

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	0%	\$42.00
FRONT NO. PLATE		\$35.00
REAR NO. PLATE	0%	\$35.00
REVERSE SENSOR		\$180.00
Total Extras		\$292.00

Final Calculation

Total Parts \$4,172.67

Labour

Total Panel/Mechanical	\$887.80
Total Paintwork	\$607.20

Total Labour

\$1,495.00

Additional Costs

Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$292.00

Total of Additional Costs

\$292.00

Total Paint/Material Costs

\$296.39

Repair Costs Excludes GST

\$6,256.06

Deductions

7 + 2,406.60
8,662.66

-20% = 6,930.13

Audatex System Using Manufacturer Times

45 = 6,950.13

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001988

Assessment Number: CTI10125

Version: CHINATAI/15

Date Calculated: 03/01/2018 03:23

Full Report - V1

Registration: SGV8921R

Printed: 03/01/2018 11:24

Deduction for Excess (Fixed)	-\$250.00	
Total Deductions		-\$250.00
Grand Total Excludes GST (After Deduction)		\$6,006.06
GST @ 7 %		\$420.42
Grand Total Includes GST (After Deduction)		\$6,426.48

Assessment Notes

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER
079909**

LKK
reverse
estimate

**Claim Reference: 20170001988
Assessment Number: CT110125
Version: CHINATAI/14
Date Calculated: 02/01/2018 08:29**

**Full Report - V1
Registration: SGV8921R
Printed: 02/01/2018 16:30**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	23/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	20170001988	Estimated Repair Time:	
Policy Number:	DMPCSN3050961700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	



Vehicle Details

Vehicle	Model Specs
Manufacturer: HONDA	RR PARK DIST CONTROL 1.8 LTR 103 KW
Model: Civic	MUDFLAP REAR SPOILER
Sub Model: VTI-S	TWO COAT METALLIC
Model Sheet Number: H48 38	
Registration: SGV8921R	
Registration Month: June	
Registration Year: 2007	
VIN Number:	
Manufacture Month: June	
Manufacture Year: 2007	
Odometer: Not Known	
Colour:	
Engine Number:	
Fuel Level: %	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection: 28/12/2017
Place of Inspection:	
Pre-Accident Damage:	
Tyres Condition: Fair	Tread Depth RHF:
Tread Depth LHF:	Tread Depth RHR:
Tread Depth LHR:	Direction of Impact:
Damage Areas:	

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference: 20170001988****Assessment Number: CTI10125****Version: CHINATAI/14****Date Calculated: 02/01/2018 08:29****Full Report - V1****Registration: SGV8921R****Printed: 02/01/2018 16:30****Addresses****Cost Summary**

Total Labour	\$1,403.00
Total Paint/Material	\$311.64
Total Parts	\$8,403.96
Total of Additional Costs	\$42.00
Repair Cost Exc GST:	\$10,160.60
Overall Discount (0.0%):	- \$0.00
Excess:	-\$250.00
After Deduction -	
Grand Total Exc GST:	\$9,910.60
7 % GST:	\$693.74
Grand Total Inc GST:	\$10,604.34

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair /**Guide Number Repair Details**

	WU	Cost Price (\$)
71101-SNB RENEW COMPLETE FRONT BUMPER INCLUDES: FRONT BUMPER CPL AND R + R RADIATOR GRILLE.	6.0	27.60
71130-SNA) R + R FRONT BUMPER BRACKET	2.0	9.20
33151-SNB) R + R LEFT HEADLAMP UNIT	4.0	18.40
33101-SNB) R + R RIGHT HEADLAMP UNIT	4.0	18.40
NO NUMBER ADJUST HEADLAMP	1.0	4.60
71125-SNB) R + R RADIATOR GRILLE BRACKET	1.0	4.60
76805-SNA R + R FUEL FILLER NECK	1.0	4.60
NO NUMBER R + R NUMBER PLATE LAMP BULB	2.0	9.20
71501-SNB RENEW REAR BUMPER	3.0	13.80
NO NUMBER R + R REAR PARKING AID SENSORS ADD/WORK	3.0	13.80
68500-SNB) R + R BOOT LID	3.0	13.80
68500-SNB) RENEW BOOTLID (REMOVED)	9.0	41.40
INCLUDES: R + R INNER TAILLAMPS, NUMBER PLATE, BADGE, NUMBER PLATE LAMPS AND LOCK		
NO NUMBER RENEW L/INNER SIDE PANEL CONNECTION	23.0	105.80
NO NUMBER RENEW R/INNER SIDE PANEL CONNECTION	23.0	105.80
NO NUMBER R + R REAR END PANEL ATTACHED PARTS INCLUDES: R + R BUMPER, TAIL LAMP, BOOT TRIM, BOOT FLOOR TRIM, REAR PANEL TRIM, BOOT LOCK AND SEAL	35.0	161.00

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001988

Assessment Number: CTI10125

Version: CHINATAI/14

Date Calculated: 02/01/2018 08:29

Full Report - V1

Registration: SGV8921R

Printed: 02/01/2018 16:30

62100-SMG	RENEW REAR END PANEL CPL	41.0	188.60
18310-SNA	R + R REAR SILENCER	2.0	9.20
9973	CARRY OUT TEST DRIVE	5.0*	23.00

LABOUR COST

Total Work Units	168.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	16.8HRS	\$772.80
Paint Labour	13.7HRS	\$630.20
Total Labour	30.5HRS	\$1,403.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number	Description	WU	Cost Price (\$)
--------------	-------------	----	-----------------

	- TWO COAT METALLIC		
340	FRONT BUMPER SUPPORTSURFACE PAINT	4.0	
2711	REAR PANEL CPL NEW PART PAINTING	19.0	
2931	BOOTLID NEW PART PAINTING	16.0	
283	FRONT BUMPER NEW PART PAINT K1R	12.0	
2583	REAR BUMPER NEW PART PAINT K1R	13.0	
2587	LOWER BUMPER COVER NEW PART PAINT K1R	3.0	
3045	REAR SPOILER NEW PART PAINT K1R	5.0	
3481	L/R SIDE PANEL REPAIR PAINTING <50%	15.0	
3482	R/R SIDE PANEL REPAIR PAINTING <50%	15.0	
3900	BOOTFLOOR SURFACE PAINT	9.0	

LABOUR COST - PAINT

TIME(PAINT)	111.0	
Preparation Main Work Metal	21.0	
Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	137.0	
Total Paintwork Labour	13.7HRS	\$630.20

MATERIAL COST - PAINT

New Part Painting	\$67.41
New Part Painting - Plastic K1R	\$138.73
Surface-/Blend Paint	\$31.88
Repair Painting	\$46.52
Material-Const Main Work Metal	\$18.10
Material-Const Comp. Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$311.64
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$311.64

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		0%	35.00*
258	1	FRT NO PLATE REINF	KNPL0		0%	35.00*
283	1	FRONT BUMPER	04711SNB010ZZ		0%	601.20*
317	1	L/F OUT BUMPER BRKT	71198SNB003		0%	27.50*
318	1	R/F OUT BUMPER BRKT	71193SNB003		0%	27.50*
319	1	L/F UPP BUMPER BRKT	71190SNB000		0%	15.00*
320	1	R/F UPP BUMPER BRKT	71140SNB000		0%	15.00*
340	1	FRONT BUMPER SUPPORT	71130SNAU90ZZ		0%	202.20*

Price Valid: 01/06/2015

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: 20170001988

Assessment Number: CTI10125

Version: CHINATAI/14

Date Calculated: 02/01/2018 08:29

Full Report - V1

Registration: SGV8921R

Printed: 02/01/2018 16:30

343	1	FRONT BUMPER SPOILER	71110SNB000	0%	150.00*	✓
411	1	GRILL BRACKET	71125SNB000	0%	180.00*	✓
412	1	GRILLE	71121SNB003	0%	146.00*	✓
431	1	GRILLE BADGE	75700S9AG00	0%	24.00*	✓
561	1	L/F HEADLAMP CPL	33151SNBD01	0%	768.80*	✓
562	1	R/F HEADLAMP CPL	33101SNBD01	0%	768.80*	✓
2583	1	REAR BUMPER	71501SNB010ZB	0%	601.02*	✓
2587	1	LOWER BUMPER COVER	71504SNB000	0%	125.50*	✓
2619	1	L/R BUMPER BRACKET	71598SNAA01	0%	18.07U	✓
2620	1	R/R BUMPER BRACKET	71593SNAA01	0%	18.07U	✓
2621	1	L/R INN BUMPER BRKT	71540SNAA00	0%	13.20*	✓
2622	1	R/R INN BUMPER BRKT	71540SNAA00	0%	13.20*	✓
2673	1	L/R PARK SYS SENSOR	08V67SNB61005	0%	110.00*	✓
2674	1	R/R PARK SYS SENSOR	08V67SNB61005	0%	110.00*	✓
2702	1	REAR NUMBER PLATE		0%	35.00*	✓
2711	1	REAR PANEL CPL	66100SNAA01ZZ	0%	269.50*	✓
2931	1	BOOTLID	68500SNDG00ZZ	0%	530.70*	✓
2944	1	BOOTLID SEAL	74865SNC013	0%	67.40*	✓
2973	1	REAR LOCK STRIKER	74862SE3003	0%	15.56U	✓
2977	1	BOOTLID LOCK	74851SNA003	0%	66.25U	✓
2979	1	REAR MOULDING	74890SNB000ZA	0%	185.00*	✓
3013	1	BADGE HONDA	75711SNAK01	0%	26.40*	✓
3045	1	REAR SPOILER	71700SNDJ01ZB	0%	450.00*	✓
3281	1	L/R OUTER LAMP CPL	33551SNB003	0%	0.00FX	✓
3283	1	L/R INNER LAMP CPL	34156SNB023	0%	204.80*	✓
3284	1	R/R INNER LAMP CPL	34151SNB023	0%	204.80*	✓
3355	1	L/NO PLATE LAMP BULB	33301SNA003HE	0%	2.87U	✓
3356	1	R/NO PLATE LAMP BULB	33301SNA003HE	0%	2.87U	✓
3372	1	R/NO PLATE LAMP LENS	34106SNB023	0%	7.72U	✓
3571	1	L/R LAMP PANEL	63720SNBE00ZZ	0%	125.00*	✓
3572	1	R/R LAMP PANEL	63320SNBE00ZZ	0%	125.00*	✓
4907	1	BOOTLID COVER	84620SNBJ01ZA	0%	185.00*	✓
4986	1	SPARE WHEEL COVER	84521SNBE01ZA	0%	258.00*	✓
4991	1	L/R SIDE PANEL TRIM	84651SNAK13ZA	0%	180.00*	✓
4992	1	R/R SIDE PANEL TRIM	84601SNAK13ZA	0%	180.00*	✓
8827	1	RR EXHAUST SILENCER	18307SNBJ01	0%	450.00*	✓
1000	1	BOOTLID REFLECTOR RH	Renew	0%	132.10*	✓
1000	1	BOOTLID REFLECTOR RH	Renew	0%	132.10*	✓
1000	1	BOOTLID WEATHERSTRIP	Renew	0%	67.40*	✓
f: OEM Parts			Saving		\$97.11	
g: Original			Sub Total		\$7,908.53	
h: Secondhand			Mark Up From Cost	(5 %)	\$395.43	
p: Parallel			Sundry Parts	(Fixed)	\$100.00	
x: Exchange			Total Parts		\$8,403.96	

THIS ASSESSMENT CONTAINS UNPRICED PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	0%	\$42.00
SPECIALIST		
Total Extras		\$42.00

Final Calculation

Total Parts	\$8,403.96
-------------	------------

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference: 20170001988****Full Report - V1****Assessment Number: CT110125****Registration: SGV8921R****Version: CHINATAI/14****Printed: 02/01/2018 16:30****Date Calculated: 02/01/2018 08:29**

Labour

Total Panel/Mechanical \$772.80

Total Paintwork \$630.20

Total Labour**\$1,403.00****Additional Costs**

Corr Prot Materials External \$0.00

Corr Prot Materials Internal \$0.00

Cost of Specialist \$42.00

Total of Additional Costs**\$42.00****Total Paint/Material Costs****\$311.64****Repair Costs Excludes GST****\$10,160.60****Deductions**

Deduction for Excess (Fixed) -\$250.00

Total Deductions**-\$250.00****Grand Total Excludes GST (After Deduction)****\$9,910.60**

GST @ 7 %

\$693.74**Grand Total Includes GST (After Deduction)****\$10,604.34**

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Dec 2017	29 Dec 2017	29 Dec 2017	S\$4,950.00	S\$4,950.00		Pending for Survey Report
	Sendback Est	11:51 S\$16,667.37	13:13 Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	29 Dec 2017 14:13	29 Dec 2017 14:17 S\$798.84	29 Dec 2017 14:17			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	LIM KAH YEEN, ID: S8286264A		
Vehicle Reg. No.:	SGV8921R	Date of Loss:	23/12/2017 16:00 - :59
Claim Type:	OD / SNM17D07255C01	Policy/Cover Note No.:	DMPCSN3050961700 (Comprehensive)
		Excess:	S\$250.00
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 10/01/2018]		
Driver/Custodian:	LIM KAH YEEN (/ Male), NRIC: S8286264A		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- CHINA_TAIPING (03/01/2018): Alert - Adj Mandate Approved (S\$6950.00) - SGV8921R - Claim Handler: Chong Boon ...

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGV8921R (SNM17D07255C01)
OD
Dec 23 2017 4:00PM
[LIM KAH YEEN]
SMRT Automotive Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
----------------------------------	--	-------------------------------	------------------------------------	--------------------------------------	--

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
SMRT Automotive Services Pte Ltd (Woodlands)					
1	29/12/17 11:51	Repairer Estimates		Load HTM	
2	29/12/17 14:17	Repairer Estimates Suppl. #1		Load HTM	
LKK Auto Consultants Pte Ltd (HQ)					
1	02/01/18 16:55	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	☒
No	Relabel/ Reorder			Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)					
1	03/01/18 10:12	photograph		Load PDF	
2	31/01/18 14:30	General View		Load PDF	
3	31/01/18 14:30	Reinspection Photo		Load PDF	
4	31/01/18 14:30	Reinspection Photo		Load PDF	

Documentation				1 per page	☒
No	Finalized On			Thumbnail	Print
SMRT Automotive Services Pte Ltd (Woodlands)					
1	29/12/17 11:52	Singapore Accident Statement		Load PDF	
2	29/12/17 11:53	ic & DL		Load TIF	
China Taiping Insurance (Singapore) Pte. Ltd. (HQ)					
1	03/01/18 11:42	Revised Estimate		Load PDF	
LKK Auto Consultants Pte Ltd (HQ)					
1	02/01/18 16:51	ESTIMATE		Load PDF	
2	02/01/18 16:51	SUPPLEMENTARY LIST		Load PDF	
3	02/01/18 16:51	REVISED AUDATEX		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT117024682/R1TB22

Date: 02/02/2018

REFERENCE

Insured/Claimant: LIM KAH YEEN Policy No: DMPCSN3050961700
Date of Loss: 23/12/2017 Nature of Claim: OD Claim No: SNM17D07255C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV8921R**
Make & Model: HONDA CIVIC, 1.8 (A) Engine No: R18A12030161
Reg. Date: 28/06/2007 (Man. Year: 2007) Chassis No: JHMF16307S213587
Colour: White Odometer: 144044 km
Engine Capacity: 1799 cc
Market Value/New Car Price: S\$36,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16 Rear Tyre Size: 205/55Z R16
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,335.36	4,464.67	9,870.69	68.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.85	1,769.25	1,361.60	43.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,466.21	6,233.92	11,232.29	64.31
Approved Total (Overridden) (S\$)		4,950.00		
- Excess (S\$)	0.00	250.00	-250.00	
(S\$)	17,466.21	4,700.00	12,766.21	73.09
+ GST 7.00/7.00% (S\$)	1,222.64	329.00	893.64	73.09
Nett Amount (S\$)	18,688.85	5,029.00	13,659.85	73.09

INSPECTION

Date of Assignment: 29/12/2017 Present Location: SMRT Automotive Services Pte Ltd (Woodlands)
Date Inspected: 29/12/2017 Inspected At: 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair: 15.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 02 Feb 2018)
Parts: 143 **HONDA CIVIC 1.8 (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's **(Price-denominated Standard List)**
Print Code: (Unsubmitted, no print-code for SGV8921R)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REVERSE SENSOR	Shorted	-	*180.00 FS
2	1	NA	*3RD BRAKE LAMP BULB (WCP)	Serviceable	2.87 F	*- F
3	1	NA	*ADD/BR/LAMP B/HOLDER (WCP)	Serviceable	14.20 F	*- F
4	1	NA	*BADGE 1.8 (WCP)	Serviceable	10.99 F	*- F
5	1	NA	*BADGE CIVIC (WCP)	Serviceable	19.41 F	*- F
6	1	NA	*BADGE HONDA (WCP)	Necessary	26.40 F	*26.40 F
7	1	NA	*BADGE HONDA (WCP)	Serviceable	28.80 F	*- F
8	1	NA	*BONNET (WCP)	Serviceable	575.80 F	*- F
9	1	NA	*BONNET LOCK (WCP)	Serviceable	125.00 F	*- F
10	1	NA	*BOOTFLOOR (WCP)	Repair	858.80 F	*- F
11	1	NA	*BOOTLID (WCP)	Bent	530.70 F	*530.70 F
12	1	NA	*BOOTLID COVER (WCP)	Deformed	185.00 F	*185.00 F
13	1	NA	*BOOTLID LOCK (WCP)	Bent	66.25 F	*66.25 F
14	1	NA	*BOOTLID SEAL (WCP)	Necessary	67.40 F	*67.40 F
15	1	NA	*BOOTLID TRIM FASTEN (NPA) (WCP)	Serviceable	0.00 F	*- F
16	1	NA	*BOOTLID WIRING (WCP)	Serviceable	209.11 F	*- F
17	1	NA	*END PANEL TRIM (WCP)	Serviceable	57.50 F	*- F
18	1	NA	*FRONT BUMPER (WCP)	Deformed	601.20 F	*601.20 F
19	1	NA	*FRONT BUMPER SPOILER (WCP)	Serviceable	150.00 F	*- F
20	1	NA	*FRONT BUMPER SUPPORT (WCP)	Serviceable	202.20 F	*- F
21	1	NA	*FRONT NUMBER PLATE	Bent	35.00 F	*35.00 FS
22	1	NA	*FRT NO PLATE REINF (WCP)	Bent	35.00 F	*35.00 F
23	1	NA	*GRILL BRACKET (WCP)	Serviceable	180.00 F	*- F
24	1	NA	*GRILLE (WCP)	Serviceable	146.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1	NA	*GRILLE BADGE (WCP)	Serviceable	24.00 F	*- F
26	1	NA	*HI-LEVEL BRAKELAMP (WCP)	Serviceable	73.25 F	*- F
27	1	NA	*L/BACKUP LAMP B/HOLD (WCP)	Serviceable	15.00 F	*- F
28	1	NA	*L/BUMPER COVER (WCP)	Serviceable	350.00 F	*- F
29	1	NA	*L/F HEADLAMP CPL (WCP)	Serviceable	768.80 F	*- F
30	1	NA	*L/F OUT BUMPER BRKT (WCP)	Not Necessary	27.50 F	*- F
31	1	NA	*L/F UPP BUMPER BRKT (WCP)	Necessary	15.00 F	*15.00 F
32	1	NA	*L/NO PLATE LAMP BULB (WCP)	Missing	2.87 F	*2.87 F
33	1	NA	*L/NO PLATE LAMP LENS (WCP)	Serviceable	7.72 F	*- F
34	1	NA	*L/NO. PLATE LAMP (WCP)	Serviceable	9.65 F	*- F
35	1	NA	*L/PARK/BR LAMP BULB (WCP)	Serviceable	14.44 F	*- F
36	1	NA	*L/PARK-/BR/LAMP BULB (WCP)	Serviceable	15.00 F	*- F
37	1	NA	*L/R AIR VENT GRILLE (WCP)	Serviceable	21.18 F	*- F
38	1	NA	*L/R BUMPER BRACKET (WCP)	Necessary	18.07 F	*18.07 F
39	1	NA	*L/R FOG LAMP B/HOLD (WCP)	Serviceable	39.35 F	*- F
40	1	NA	*L/R FOG LAMP BULB (WCP)	Serviceable	2.87 F	*- F
41	1	NA	*L/R HINGE (WCP)	Serviceable	158.00 F	*- F
42	1	NA	*L/R INDIC BULB HOLD (WCP)	Serviceable	10.96 F	*- F
43	1	NA	*L/R INDICATOR BULB (WCP)	Serviceable	2.87 F	*- F
44	1	NA	*L/R INN BUMPER BRKT (WCP)	Necessary	13.20 F	*13.20 F
45	1	NA	*L/R INNER LAMP CPL (WCP)	Cracked	204.80 F	*204.80 F
46	1	NA	*L/R LAMP PANEL (WCP)	Bent	125.00 F	*125.00 F
47	1	NA	*L/R OUTER LAMP CPL (WCP)	Serviceable	97.11 F	*- F
48	1	NA	*L/R PARK SYS SENSOR (WCP)	Serviceable	120.00 F	*- F
49	1	NA	*L/R SIDE PANEL (WCP)	Repair	671.70 F	*- F
50	1	NA	*L/R SIDE PANEL TRIM (WCP)	Serviceable	180.00 F	*- F
51	1	NA	*L/REVERSE BULB (WCP)	Serviceable	15.00 F	*- F
52	1	NA	*LOWER BUMPER COVER (WCP)	Cracked	125.50 F	*125.50 F
53	1	NA	*MOUNTING CLAMP (WCP)	Serviceable	4.88 F	*- F
54	1	NA	*MOUNTING CLAMP (WCP)	Serviceable	18.80 F	*- F
55	1	NA	*MOUNTING CLAMP (WCP)	Serviceable	8.28 F	*- F
56	1	NA	*MOUNTING CLAMP (WCP)	Serviceable	12.20 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
57	1	NA	*R/BACKUP LAMP B/HOLD (WCP)	Serviceable	15.00 F	*- F
58	1	NA	*R/BUMPER COVER (WCP)	Serviceable	350.00 F	*- F
59	1	NA	*R/F HEADLAMP CPL (WCP)	Serviceable	768.80 F	*- F
60	1	NA	*R/F OUT BUMPER BRKT (WCP)	Not Necessary	27.50 F	*- F
61	1	NA	*R/F UPP BUMPER BRKT (WCP)	Necessary	15.00 F	*15.00 F
62	1	NA	*R/NO PLATE LAMP BULB (WCP)	Missing	2.87 F	*2.87 F
63	1	NA	*R/NO PLATE LAMP HSG (WCP)	Serviceable	9.65 F	*- F
64	1	NA	*R/NO PLATE LAMP LENS (WCP)	Cracked	7.72 F	*7.72 F
65	1	NA	*R/PARK/BR/LAMP B/HOL (WCP)	Serviceable	14.44 F	*- F
66	1	NA	*R/PARK-/BR/LAMP BULB (WCP)	Serviceable	15.00 F	*- F
67	1	NA	*R/R AIR VENT GRILLE (WCP)	Serviceable	21.18 F	*- F
68	1	NA	*R/R BUMPER BRACKET (WCP)	Necessary	18.07 F	*18.07 F
69	1	NA	*R/R FOG LAMP B/HOLD (WCP)	Serviceable	39.35 F	*- F
70	1	NA	*R/R FOG LAMP BULB (WCP)	Serviceable	2.87 F	*- F
71	1	NA	*R/R HINGE (WCP)	Serviceable	158.00 F	*- F
72	1	NA	*R/R INDIC BULB HOLD (WCP)	Serviceable	10.96 F	*- F
73	1	NA	*R/R INDICATOR BULB (WCP)	Serviceable	2.87 F	*- F
74	1	NA	*R/R INN BUMPER BRKT (WCP)	Necessary	13.20 F	*13.20 F
75	1	NA	*R/R INNER LAMP CPL (WCP)	Broken	204.80 F	*204.80 F
76	1	NA	*R/R LAMP PANEL (WCP)	Bent	125.00 F	*125.00 F
77	1	NA	*R/R OUTER LAMP CPL (WCP)	Serviceable	97.11 F	*- F
78	1	NA	*R/R PARK SYS SENSOR (WCP)	Not Necessary	120.00 F	*- F
79	1	NA	*R/R SIDE PANEL TRIM (WCP)	Serviceable	180.00 F	*- F
80	1	NA	*R/REVERSE BULB (WCP)	Serviceable	15.00 F	*- F
81	1	NA	*RADIATOR GRILLE TRIM (WCP)	Serviceable	168.50 F	*- F
82	1	NA	*REAR BUMPER (WCP)	Deformed	601.02 F	*601.02 F
83	1	NA	*REAR LOCK CYL (WCP)	Serviceable	57.57 F	*- F
84	1	NA	*REAR LOCK STRIKER (WCP)	Bent	15.56 F	*15.56 F
85	1	NA	*REAR MOULDING (WCP)	Serviceable	185.00 F	*- F
86	1	NA	*REAR NO PLATE BACKG (WCP)	Serviceable	35.00 F	*- F
87	1	NA	*REAR NUMBER PLATE	Deformed	35.00 F	*35.00 FS
88	1	NA	*REAR PANEL CPL (WCP)	Buckled	269.50 F	*269.50 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
89	1	NA	*REAR SCREEN (WCP)	Serviceable	356.39 F	*- F
90	1	NA	*REAR SCREEN BOND KIT (WCP)	Serviceable	30.00 F	*- F
91	1	NA	*REAR SCREEN CLAMPS (WCP)	Serviceable	10.70 F	*- F
92	1	NA	*REAR SCREEN FIX SET (NPA) (WCP)	Serviceable	0.00 F	*- F
93	1	NA	*REAR SCREEN SEAL (WCP)	Serviceable	125.00 F	*- F
94	1	NA	*REAR SCREEN SPACER (WCP)	Serviceable	7.26 F	*- F
95	1	NA	*REAR SCREEN SPACER (WCP)	Serviceable	8.44 F	*- F
96	1	NA	*REAR SPOILER (WCP)	Serviceable	450.00 F	*- F
97	1	NA	*RR BUMPER CLAMP KIT (WCP)	Serviceable	0.00 F	*- F
98	1	NA	*RR EXHAUST SILENCER (WCP)	Serviceable	450.00 F	*- F
99	1	NA	*SPARE WHEEL COVER (WCP)	Deformed	258.00 F	*258.00 F
100	1	NA	*SPECIALIST AUDATEX FEE		42.00 F	*42.00 FS
101	1	NA	*SUNDRY PARTS	Necessary	251.96 F	*100.00 FS
Supplementary #1						
102	2		*REAR FENDER INNER SHIELD (WCP)	Serviceable	276.40 F	*- F
103	2		*REAR MUDFLAP (WCP)	Serviceable	152.80 F	*- F
104	1		*BOOTLID REFLECTER RH (WCP)	Broken	132.10 F	*132.10 F
105	1		*BOOTLID REFLECTOR LH (WCP)	Cracked	132.10 F	*132.10 F
106	1		*BOOTLID WEATHERSTRIP (WCP)	Necessary	67.40 F	*67.40 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	13,652.72	4,270.73
+ Margin on L,N Items 5.00/5.00% (\$\$)	682.64	193.94
Total Parts (\$\$)	14,335.36	4,464.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	772.80	588.80
2	Total Paint Materials	New	375.45	292.65
3	Total Panel/Mechanical Labour	New	1,982.60	887.80
Gross Labour Cost (S\$)			3,130.85	1,769.25

Report was unsubmitted during this print-out.

< END OF ESTIMATES >