



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

## EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



### ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Mr YANG CHIU MING Blk 35 Marine Crescent #04-83 Singapore 440035	Cust No/Name /Mr Yang Chiu Ming Reg No/Reg Date SLD1967R / 07/06/2016 Date In/Mileage 26/12/2017/ 0 Chassis No MMBSTA13AHH000621 Engine No 3A92UDD7507 Make/Model MIT/17MY ATTRAGE 1.2 CVT Colour/Trim T06 / BK
Contact No Mobile: 98238996	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	26/12/2017/ 15:01	DS	218 / MarsLer	49637

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO CHECK LIGHTING & WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				60 80.00
S MIPNT88088 TO REMOVE AND RE-INSTALL REAR TRIMMING & CAPERTING TO GIVE WAY ACCESS REPAIR ON RHR ACCIDENT AFFECTED AREAS				300 600.00
S MIPNT88088 TO REPLACE REAR BUMPER ,RHR TAIL LAMP,ETC -REPAIR ON RHR FENDER & RHR END PANEL ACCIDENT AFFECTED AREAS STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS	600/day.			1800 2400.00
S MIPNT88088 TO SUPPLY AND REPLACE REAR REVERSE SENSOR				280.00
S MIPNT98088 SPRAY PAINTING ON RHR ACCIDENT AFFECTED AREAS	420/19.00			1260 1680.00
P JJ6410C750 FACE, RR BUMPER ✓ CRK	1.00	740.00	10.00	666.00
M JJMU001623 CLIP,RR BUMPER ✓ NEC.	10.00	3.00	10.00	27.00
M JJ6410C433 LH BRACKET, RR BUMPE ✓ NEC	1.00	27.00	10.00	24.30
M JJ6410C434 RH BRACKET, RR BUMPE ✓ NEC	1.00	27.00	10.00	24.30
M JJ8355A082 REFLECTOR, RH X	1.00	21.00	10.00	18.90
M JJ8330A852 RHR LAMP ASSY, COMBI ✓ CRK	1.00	332.00	10.00	298.80
Z NOTES ACCIDENT ON 26/12/2017 ALONG OLD AIRPORT ROAD (BEFORE MARKET) OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP : GZ5642U TP INS : AXA				

**Link Auto Consultants hence notify the Repairer of the following:**

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Confirm &amp; accepted by

Sebastian.  
9/1/18.  
- Part by part repair.  
- Photo Before Paint

Authorized signatory and company stamp

Acknowledged Parts

Signature:

Date:

Labour	1,059.30
Standard Menu	0.00
Specialist Job	0.00
Others (Lub, etc)	5,040.00
Sundry	0.00
Total (w/o GST)	6,099.30

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.