

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLJ217Y/1712329

28th December 2017

The Manager
Motor Claim Dept.
EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

Not Attached
2/1/18
3/1/18
To be photo before pay.
4/1/18

Date of Accident : 27th December 2017
Location : AYE
Third Party Claim Vehicle No : YM 9920 X
Repair Cost For Vehicle No : SLJ 217 Y (Toyota Voxy 2.0V A)

Estimated Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover (s/nett) 301500	1	1985.80	\$ 1,985.80 ✓
2	Rear windscreen glass (s/nett) 17	1	1800.00	\$ 1,800.00 X
3	Rear windscreen glass sealant (s/nett) 17	1	60.00	\$ 60.00 425.00
4	Rear windscreen moulding (s/nett) 17	1	97.10	\$ 97.10 ✓
5	Rear no plate chrome garnish (s/nett)	1	808.30	\$ 808.30 ?
6	Rear no plate chrome garnish clips (s/nett) 17	1set	58.90	\$ 58.90 X
7	Rear end panel (s/nett)	1	961.10	\$ 961.10 ?
8	Rear end panel sealer (s/nett)	1	80.00	\$ 80.00 ?
9	Rear boot cover weather stripe (s/nett)	1	380.70	\$ 380.70 ?
10	Rear end panel inner garnish (s/nett)	1	398.10	\$ 398.10 ?
11	Rear end panel inner garnish clips (s/nett)	1set	58.90	\$ 58.90 ?
12	Rear bumper fascia (s/nett) 20/22	1	1,078.10	\$ 1,078.10 ✓
13	Rear bumper clips (s/nett) 17	1set	58.90	\$ 58.90 ✓
14	Rear bumper reinforcement (s/nett)	1	599.60	\$ 599.60 ?
15	Rear bumper bracket LH&RH (s/nett)	2	99.30	\$ 198.60 ?
16	Rear bumper side retainer LH&RH (s/nett) 20	2	108.10	\$ 216.20 ✓
17	Rear bumper sensor (s/nett) 2015	1set	380.00	\$ 380.00 2025 ✓
				\$ 9,220.30

65%

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLJ217Y/1712329

28th December 2017

Balance b/f	\$ 9,220.30
<u>Labour Charges :-</u>	<u>Amounts</u>
Cut out, renew, knocking & welding rear boot cover, rear end panel, remove & install all damage parts, straighten & re-align body.	\$ 1,080.00 600
Remove & install rear windscreen glass	\$ 140.00 120
Remove & install rear bumper sensor	\$ 80.00 50
Tuff-kote on damage parts	\$ 80.00 50
Spray painting on rear damage parts	\$ 1,180.00 900
Check lighting after repairs	\$ 40.00 20
Labour Charge	\$ 2,600.00
Total Amount	\$ 11,820.30

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No ill-fa. modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: