

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

TAN BOON TECK

28/12/2017

Blk C, 1 Kaki Bukit Ave 6

01-43

Singapore 417883

T P Direct Asia
Xiao Tang

Accident date: 23/12/2017

Estimated repair cost for vehicle no: SLA1710E SUBARU FORESTER 2.0 A '16

S/n	Qty	Items	U/price	Amount
1	1	Rear Bumper <i>Rys</i>		\$640.30 <i>+</i>
2	10	Rear Bumper Clip <i>one n</i>	\$6.50	\$65.00 <i>+</i>
3	1	Rear R/H Bumper Side Retainer <i>one</i>		\$26.30 <i>+</i>
4	1	Rear R/H Rim <i>at</i>		\$750.30 <i>✓</i>
5	1	Rear R/H Tyre <i>at</i>		\$350.00 <i>2nd/sj</i>
6	1	Rear R/H Lower Arm <i>Best</i>		\$230.30 <i>✓</i>
7	1	Rear R/H Upper Arm <i>Best</i>		\$480.00 <i>✓</i>
8	1	Rear R/H Knuckle Arm <i>Best</i>		\$270.00 <i>✓</i>
9	1	Rear R/H Knuckle Arm Bearing <i>n</i>		\$240.60 <i>✓</i>
10	1	Rear R/H Trailing Arm <i>Best</i>		\$200.30 <i>✓</i>
11	1	Rear R/H Shock Absorber <i>Best</i>		\$340.30 <i>✓</i>
			Subtotal :-	<u>\$3,593.40</u>

2511-8 S.N: 2W

2009-44

Labour charges

To remove & refit reverse sensor	\$100.00	*
To remove & refit rear R/H undercarriage	\$380.00	220
To check wheel alignment	\$150.00	80
Tuff kote	\$150.00	+
To check wiring	\$60.00	*
Panel beating	\$600.00	220
Spray painting	\$500.00	220.

Subtotal :- \$1,940.00

Total:- \$5,533.40

total: 2809.44
L/S: 2.3K. ✓
03Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: