

INS. CASE OWNER:

Cynthia

CC4 / AXA170 24695 1UK53

LKK:

IDAC:

ASSIGNMENT

Surveyor:

MARCUS

DOI:

29/12/17

Date / Time:

29/12/17

Registered in Merimen:

28/12/17

Pre-assign / CCU / FTE

Insured Vehicle No.:

SRE 2333U

Claim No.:

C0464254

Name of Insured:

CHENG WEE FEN

Policy No.:

P339904

Insured Tel No.:

HP: 9783 6808

Make / Model:

MORISSES - BENZ E63 AMG

Excess Sec II :\$

D.O.A: 27/12/17

Place of Accident:

JUNCTION OF GRANGE ROAD AND
IRWELL BANK ROAD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: QUEK KENG SEANG

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.: 9669 6868

(V/L / NO)

Insured Liability:

% Final ? Yes / No

SH 4704J

INSRS:

WSP: Tan Lim Motor

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SH 4704J COLLISION WITH SRE 2333U DOA: 26/12/17
 - NA/ENC0802045/1 DOA: 26/12/17
 - NA/ENC0803212/1 DOA: 26/12/17
 - NA/ENC0803212/2 DOA: 26/12/17
 - NA/ENC0803212/3 DOA: 26/12/17

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR: TP.

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

(4/12/17) Side swipe & conflicting.

OI counter claim TP - IO reported TP cut lane.
 Please obtain evidence and liaise with OI before
 any settlement.

16/12/17 @ 2.15pm.
 Broke to OI (m3 driving) - confirmed accident
 details and witnessed that TP cut into lane.
 OI has submitted all accident photos and a
 CCTV footage. Informed that TP claim, OI was
 back and agree to settle. Send letter to OI

TP CCTV in folder based on TP CCTV footage.
 OI changed lane and caused accident.

20/12/17: File per to type mandate report.

in OI BANC (CHENG).

PRELIMINARY ADVICE Date/Time: 02/01/18

Sent By: Shirley Hiew

FINALIZATION

Date/Time: 29.12.17

Confirm with: William

Confirm by: OIA

Repair Cost:

43 SS3,500

(3 days) Reduction: 58 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 23.12.17

Confirm with: William

Email ☒ Call ☐

Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: NIL

If NO or B 28, Ass. Lia:

Repair Cost:

4147 SS 3,900.00

(Conflict of version)

Both reports stated same after cut lane

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 240.00

(\$ 80 x 3 days)

Loss of Income (LOI):

SS -

(\$ x days)

R only

LOU only

☒

LOR + LOU

☐

LOR + LOI

☐

(Tick only one)

CH/LTA Search

SS -

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Total Cost

SS -

at:

SS 4,145.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 23.12.17

Confirm with: Shirley Hiew

Email ☒ Call ☐

Fee 1:

SS 4,145.00

Name 1:

TAN LIM MOTOR PIE LTD.

Fee 2: (Strike if N.A.)

SS

Name 2:

RECEIVED 2 MAY 2018

Fee 3: (Strike if N.A.)

SS

Name 3:

RECEIVED 2 MAY 2018

CORRECT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/AXA17024695/Uks3

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 29-12-2017



Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBE 3333U	Veh. Inspected	SH 4704J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	27/12/2017	Inspection Date	29/12/2017
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel: 68585151 (24 Hours) Fax: 68580877

GST Regn. No.: M2-8922054-2

AXA Insured's Veh No: SBE3333U

Date of Accident: 27 December 2017

Mr Hang Tau Tee

Date: 28 December 2017

Estimate To Repair SH4704J - Toyota PRIUS HYBRID 1.8S CVT ABS D/A

Chassis No: ZVW506025164

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper <i>Dis</i>	\$ 495.50
02	1 pc	n/s front bumper sid retainer <i>sup</i>	\$ 76.90
03	1 pc	n/s front bumper LED light <i>scr</i>	\$ 910.20
04	1 pc	n/s front fender <i>20/24</i>	\$ 933.10
05	1 pc	front fender inner cowl	\$ 198.40
06	6 pc	front fender inner cowl clips @ \$4.30 <i>nu</i>	\$ 25.80
07	1 pc	front fender hybrid badge <i>nu</i>	\$ 52.30
08	1 pc	front fender air guide rear <i>11</i>	\$ 51.70
09	3 pc	front fender air guide clips @ \$4.30 <i>11</i>	\$ 12.90
10	1 pc	n/s headlamp <i>11</i>	\$ 3,378.30
11	1 pc	n/s front door <i>20/24</i>	\$ 1,249.60
12	1 pc	front door hinge top <i>11</i>	\$ 82.10
13	1 pc	front door outer weatherstrip molding <i>nu</i>	\$ 88.60
14	1 pc	front door window glass channel weatherstrip <i>nu</i>	\$ 148.00
15	1 pc	front bumper reinforcement <i>11</i>	\$ 691.10
16	1 pc	n/s front bumper air guide <i>11</i>	\$ 56.40
17	1 pc	front bumper upper air grille <i>11</i>	\$ 335.60
18	1 pc	front bumper lower air grille <i>11</i>	\$ 165.00
			\$ 8,951.50
Less 25 %			\$ 2,237.88
			\$ 6,713.63
<u>LABOUR & MISC. CHARGES</u>			
01		To transfer of door fittings and perform water seepage test.	\$ 120.00
02		To check steering geometry and computer wheel alignment.	\$ 120.00
03		To check electrical lighting concerned.	\$ 60.00
04		To rust-proofing of the affected areas.	\$ 150.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 700.00
06		Putty and spray painting of the affected portion.	\$ 850.00
			\$ 2,000.00
Total			\$ 8,713.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sun@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kwee May

Date: 02 Jan 2018

Preliminary Advice

Insured Vehicle No	: SBE3333U	Accident Date	: 27/12/2017
TP Vehicle No	: SH4704J	Assignment Date	: 28/12/2017
Make	: TOYOTA PRIUS HYBRID	Est. Duration of Repair	: 3 days
Date of Inspection	: 29/12/2017		
Inspection At	: Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10 Singapore 539216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesN/S front & N/S body.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,713.63
Revised Amount	:S\$	4,585.38
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,585.38

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref TP024122017

Date 01/02/18

Your Ref SB E3333U

WITHOUT PREJUDICE

Claims Department - Executive in charge _____

AXA Insurance (S) Pte Ltd

Dear Sir/Madam,

ACCIDENT INVOLVING SH4704J / SB E3333U on 27.12.17

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report / _____ copies of photographs _____

☒ Original Tax-invoice number TP0118/021 ☐ Original rental invoice number _____

☐ SAS / AS & IS / police report ☐ police result

☐ Certificate Of Insurance _____ ☐ Vehicle search result

☒ Authorization to act ☐ _____

* Survey under insurance instruction / Independent surveyor / No survey.

a)	Cost of repair (inclusive GST)	\$ <u>3905.50</u>
b)	Survey fees / Photographs as per request	\$ <u>-</u>
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>-</u>
d)	Loss of hire / use / rental / earnings / rental fees (3×20.00)	\$ <u>240.00</u>
e)	Scene photographs	\$ <u>-</u>
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>-</u>
g)	_____	\$ _____
	Total	\$ <u>4145.50</u>

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Patricia Tan / Sam Low / Johnson Chua

Email: pt@tlimotor.com.sg / sam@tlimotor.com.sg / johnson.chua@tlimotor.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

19 MARCH 2018

CHENG WOEI FEN
1 BERRIMA ROAD
SINGAPORE 299877

Dear Sir/Madam,

OUR REF : CC4/AXA17024695/Uks3

YOUR REF : SBE 3333U

ACCIDENT INVOLVING SBE 3333U AND SH 4704J ALONG JUNCTION OF GRANGE ROAD AND IRWELL BANK ROAD ON 27.12.2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s TAN LIM MOTOR PTE LTD, acting on behalf of the owner of SH 4704J against your motor insurance policy.

Based on the accident report, accident scenario, this is a conflicting version pending concrete evidence from both parties to determine the liable party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to Zaini@lkaauto.com within 10 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

STURGEON, 201-25 PAYA UBIN INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at Zaini@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Zaini
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Zaini@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AXA Third Party Claim)

I, Hang Tau Tee ("the third party claimant")
of Block 633 Veerasamy Road #09-138 S200633 (address),
owner of SH4704J (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd


("the workshop") to act for me with respect to my claim for
repair costs and/or rental and/or loss of use ("claim") for my
vehicle no. SH4704J that was damaged pursuant to the
accident which occurred on 27/12/17 (date) along
Inwell Bank Road (location)
involving vehicle no/s SBE33334
("the accident").

I further authorize the workshop to settle my above mentioned
claim in a manner that they deem fit and the workshop is further
authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach
on my behalf is on a without prejudice and without admission of
liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 27 day of 12 20 17 (year)


Signed by "the third party claimant"


Signed by "the workshop"
(with chop)

"The contents of this document apply to vehicle
damages only. All personal injuries and
damages arising therefrom are excluded from
the ambit and application of this document."



redefining / insurance

CLAIM REF : C0464854
INSURED : CHENG WOEI FEN

DISCHARGE VOUCHER

We/I [HANG TAU TEE, NRIC NO. S0025128C] hereby agree to accept the sum of dollars [FOUR THOUSAND ONE HUNDRED FORTY FIVE AND CENTS FIFTY ONLY.] [S\$4,145.50] paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their insured or the driver of motor vehicle no. [SBE 3333U] as a result of an accident along [IRWELL BANK ROAD] on [27/12/2017] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SH 4704J].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [SBE 3333U] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SBE 3333U].

Dated this 27 day of April 2018

Claimant's Signature

[Signature]

NRIC no./ Company Stamp

S0025128C

Occupation/ Business

Taxi driver

Address

Block 633 Veerasamy Road #04-138 Singapore 200633

Telephone No.

9842 5356

Witness's Name

Lam Wai Sheng

Witness's Signature

[Signature]

Witness's NRIC No.

G6864 092R



TAX-INVOICE
NUMBER: TP0118/021

(Please quote our reference number TP024122017 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Hang Tau Tee

Date: 22/01/2018

Vehicle No: SH 4704J
Model: TOYOTA PRIUS HYBIRD

Description	Amount
To lump sum repair as recommended by surveyor.	\$3,650.00

Sub Total	\$3,650.00
Add 7% GST	\$255.50
Total	\$3,905.50

Tan Lim Motor Pte Ltd



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408655
Tel +65 6547 0000
Fax +65 6547 4883
www.police.gov.sg

Our Ref : TP/IP/10225/2018
Date : 2 APRIL 2018

TAN HEOK BOON
BLK 2 JALAN BUKIT MERAH
#14-5160
SINGAPORE 150002

Dear Sir/Madam

**ROAD TRAFFIC ACCIDENT INVOLVING SH 4704 J AND SBE 3333 U ALONG IRWELL BANK
ROAD ON 27/12/2017 AT ABOUT 11.05AM**

I refer to the above accident.

Please be informed that we have completed our investigations which revealed that the driver of **SBE 3333 U** had committed an offence of **Inconsiderate driving under Section 65(b) of the Road Traffic Act Chapter 276**. Action has been initiated against the driver for the said offence.

Yours faithfully

**HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.

A FORCE FOR THE NATION

...CLAIM SUBFOLDER...(Pending for Survey Report)

Proceed Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Dec 2017		28 Dec 2017 16:57 Edit Adj Rpt	S\$3,650.00 Edit Estimates	S\$3,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHENG, WOEI FEN , ID: S12678773								
Main Claimant:	HANG TAU TEE , ID: S0025128C								
Vehicle Reg. No.:	SH4704J	Date of Loss:	27/12/2017 11:00 - :59 [14 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0464854	Policy/Cover Note No.:	P1389904 (Comprehensive)						
Vehicle Reg. No. (Insured):	SBE3333U	Policy No. (Claimant):	D-160085861MSH						
		Excess:	S\$0.00						
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 09/01/2018]								
Adj Asg. Remarks:	ARC - YES								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (10/04/2018): Alert - Adj Mandate Approved (S\$4145.50) - SH4704J - Claim Handler: Cynthia Loh AXA_SG (16/03/2018): Re: Fw: Direct Settlement - Accident Involving SBE3333U (OI : AXA - C0464854) an... AXA_SG (16/03/2018): TP settlement - C0464854/P1389904 AXA_SG (28/12/2017): WP / New TP Assignment - C0464854/P1389904 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

*SH4704J (C0464854)
[SBE3333U]
TP
HANG TAU TEE
Dec 27 2017 11:00AM
[CHENG, WOEI FEN]
Tan Lim Motor Pte Ltd

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer				
<small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SBE3333U (Insd veh)	Model:	TOYOTA PRIUS HYBRID 1.8
	SH4704J (TP veh)		S (A)
Date of Accident:	27/12/2017		

Global Sum Settlement	: [] Yes	[X] No
Repair Estimate	: \$	9,323.57
Final Repair Cost	: \$	3,905.50
Loss of Use	: \$	240.00
Rental (if any)	: \$	0.00
LTA / GIA Search Fee	: \$	0.00
Others:	: \$	0.00
	: \$	
Final Settlement Sum	: \$	4,145.50

3.00 days at \$80.00 per day
days

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	: \$	4,145.50
2)		: \$	

JOANNE LEE KHANG MIN

07 May
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17024695/UEA3Q2

Date: 07/05/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1389904

Claimant Vehicle No: SH4704J

Insured Vehicle No:

SBE3333U

Date of Loss: 27/12/2017

Nature of Claim:

TP

Claim No: C0464854

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH4704J

Make & Model: TOYOTA PRIUS HYBRID, 1.8 S (A)

Engine No: 2ZRR859942

Reg. Date: 03/10/2016 (Man. Year: 2016)

Chassis No: ZVW506025164

Colour: Yellow/Black

Odometer: 168509 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Maxxis 6 mm

Rear Left Side: Maxxis 6 mm

Front Right Side: Maxxis 6 mm

Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,713.62	3,195.37	3,518.25	52.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,390.00	610.00	30.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,713.62	4,585.37	4,128.25	47.38
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	8,713.62	3,650.00	5,063.62	58.11
+ GST 7.00/7.00% (S\$)	609.95	255.50	354.45	58.11
Nett Amount (S\$)	9,323.57	3,905.50	5,418.07	58.11
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
Nett Liability (S\$)		4,145.50		

INSPECTION

Date of Assignment: 28/12/2017

Date Inspected: 29/12/2017 Inspected At:

Tan Lim Motor Pte Ltd (Defu)

51 Defu Lane 10

Singapore 539216

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2018)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH4704J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CONSISTENT)	Distorted	495.50 FL	*495.50 FL
2	1		*N/S FRONT BUMPER SIDE RETAINER (CONSISTENT	Bent	76.90 FL	*76.90 FL
3	1		*N/S FRONT BUMPER LED LIGHT (CONSISTENT	Scratched	910.20 FL	*910.20 FL
4	1		*N/S FRONT FENDER (CONSISTENT	Dented / Bent	933.10 FL	*933.10 FL
5	1		*FRONT FENDER INNER COWLING (CONSISTENT	Torn	198.40 FL	*198.40 FL
6	6		*FRONT FENDER INNER COWLING CLIPS (CONSISTENT	Necessary	25.80 FL	*25.80 FL
7	1		*FRONT FENDER HYBRID BADGE (CONSISTENT	Necessary	52.30 FL	*52.30 FL
8	1		*FRONT FENDER AIR GUIDE REAR (CONSISTENT	Not Necessary	51.70 FL	*- FL
9	3		*FRONT FENDER AIR GUIDE CLIPS (CONSISTENT	Not Necessary	12.90 FL	*- FL
10	1		*N/S HEADLAMP (CONSISTENT	Not Necessary	3,378.30 FL	*- FL
11	1		*N/S FRONT DOOR (CONSISTENT	Dented / Bent	1,249.60 FL	*1,249.60 FL
12	1		*FRONT DOOR HINGE TOP (CONSISTENT	Twisted	82.10 FL	*82.10 FL
13	1		*FRONT DOOR OUTER WEATHERSTRIP MOLDING (CONSISTENT	Necessary	88.60 FL	*88.60 FL
14	1		*FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIPE (CONSISTENT	Necessary	148.00 FL	*148.00 FL
15	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT	Not Necessary	691.10 FL	*- FL
16	1		*N/S FRONT BUMPER AIR GUIDE (CONSISTENT	Not Necessary	56.40 FL	*- FL
17	1		*FRONT BUMPER UPPER AIR GRILLE (CONSISTENT	Not Necessary	335.60 FL	*- FL
18	1		*FRONT BUMPER LOWER AIR GRILLE (CONSISTENT	Not Necessary	165.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	8,951.50	4,260.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,237.88	1,065.13
Total Parts (\$\$)	6,713.62	3,195.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	120.00	60.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	120.00	0.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	60.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	700.00	450.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	850.00	800.00
Gross Labour Cost (S\$)			2,000.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >