

CASE OF: Bernard

CC6 / AIG 170 24698 / UK539

LKK:

IDAC:

Supervisor:

MARCUS

DOI:

29/12/17

Date / Time:

29/12/17

Registered in Merimen:

29/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.: SLS 4306A  
 Name of Insured: MOVA AUTOMOTIVE PTE LTD  
 Insured Tel No.: \_\_\_\_\_ HP: \_\_\_\_\_  
 Excess Sec II : \$ \$ \_\_\_\_\_ D.O.A: 15/12/17  
 Is driver the owner? (YES ☒ NO ☐ Nature of Accident: \_\_\_\_\_

Claim No.: 2330755497SG  
 Policy No.: 099999505  
 Make / Model: VOLKSWAGEN PASSAT-2.0 TSI  
 Place of Accident: (Rt) (A) ALONG BKE TOWARDS BUKIT PANTANG

If NO, Driver Name / Age: HUANG XU LIDriver Tel No.: 90068512

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SLS 4306A

OI

GBC 6562R

TP

GBG 81855

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP: Liu's Brother  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date / Time

03/01/18 (2am)GBC 6562R - X ; SLS 4306A - X11/01/2018 @3:21pm

Spoke to OIU (Mr Huang) - confirmed accident details and involved in a 3 veh c.c. and OIU last vehicle 27 will send any additional photo via email. Informed abt the claim amount NCO KNU and agree to settle. Send letter to OI.

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 7 11/01/2018After call ltr to OI: ✓

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

\$ \$

( days) Reduction:

%

Confirm by:

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.: 28If NO or B 28, Ass. Lia: 100%

Repair Cost:

\$ \$

Loss of Rental (LOR):

\$ \$

( days)

Loss of Use (LOU):

\$ \$

(\$60.00 x 12 days)

Loss of Income (LOI):

\$ \$

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$ \$

Medical:

\$ \$

Disbursement:

\$ \$

Legal Cost

\$ \$

(e.g. Tow/ Independent)

Total:

\$ \$

Global Sum \$ \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$ \$

Name 1:

Liu's Brother Auto Engineering Workshop

Payee 2: (Strike if N.A.)

\$ \$

Name 2:

Payee 3: (Strike if N.A.)

\$ \$

Name 3:

1) Claim status: Normal/Reject/Private Settle2) Report Format: TP3) Survey fee: \$300 TP20

RECEIVED 4 JUL 2018

3/7/2018

W1011

Signature (MRCU)

REF:

A16/

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/CD RES/EVA/INV/MV  
 To Inspect Vehicle No: GAC 6562R  
 at Workshop m/s: 114'S NW  
 of \_\_\_\_\_  
 Insured: SL 4306A  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: 47k.  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GlA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 10 days Res: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS. LTA 28858  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: GAC 6562R Yr Regn: 5 13  
 Type: M.Car / M.Cycle / Bus / Van / Car / Taxi / Prime Mover /  
 Truck / Trailer or Car /  
 Make: Toyota Dyna cc: 2982  
 Colour: white A.C: Insured / Std / NI / NA  
 Sp. Reading: 179303 T.Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTFAT 35710K202319  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/75 R15  
 R: 155 R12  
 BS/ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 6 mm R/Bal: 6/6 mm  
 L/Bal: 6 mm L/Bal: 6/6 mm  
 D.O.A: 15/12/17 D.O.I: 29/12/17  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear & fl.  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
5.15 PM. Not 18142  
7 (L/Sum: \$10,000.00 / Rcd: \$13,337.50 /  
57 %)  
\*surveyor's recommended days (10 days) + weekends (2d,  
= 12 days.

Date/Time: File Pass to? ☐ : Prel. Report ☐ : Final Report  
 1) \_\_\_\_\_  
 Date/Time: File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)  
 Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee: ☐ Site Insp (\$ \_\_\_\_\_)  
☐ Interview (\$ \_\_\_\_\_)  
☐ Tech. Insp (\$ \_\_\_\_\_)  
☐ Weekend (\$ \_\_\_\_\_)  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 3 - RS: \_\_\_\_\_  
 Gross: \_\_\_\_\_  
 Other: \_\_\_\_\_  
 TOTAL: \_\_\_\_\_




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG17024698/Uks3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 29-12-2017		
		Code : AIG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLS 4306A	Veh. Inspected	GBC 6562R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	29/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	12/12/2017	Inspection Date	29/12/2017	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kall Road Avenue 8 #01-01 Auto Shop (J) Kall Road Singapore 317887

GPO No. 33281790 Tel: 6744 4770 / 771 Fax: 6744 4744 Email: liubrother@comcast.com

Invoice/Ref No: GBC6562R171215

**Estimate**

Customer: AIG Asia Pacific Insurance Pte Ltd

Name: AIG Asia Pacific Insurance Pte Ltd

Address: Motor Claims Department  
78 Shenton Way #07-16  
AIG Building Singapore 079120

Date: 29-12-17

Vehicle No: GBC6562R

Model/Make: Toyota Dyna 150  
Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tail Lamp o/s	\$ 245.50	
2	Number Plate Bracket	\$ 126.30	
3	Exhaust Pipe	\$ 508.30	
4	Exhaust Mounting 02 pcs (@ \$58.60)	\$ 117.20	
6	Front Panel	\$ 1,265.50	
7	Panel Top Black Garnish	\$ 328.50	
8	Panel "Dyna" Emblem	\$ 68.25	
9	Panel Sealant	\$ 60.00	
10	Windscreen Rubber	\$ 303.60	
11	Grille	\$ 587.65	
12	Grille Clips 06 pcs (@ \$36.50)	\$ 39.00	
13	Grille Emblem	\$ 68.10	
14	Bumper	\$ 481.60	
15	Bumper Clip (1 set)	\$ 54.50	
16	Head Lamp 02 pcs (@ \$5704.35)	\$ 1,408.70	
17	Corner Panel 02 pcs (@ \$376.50)	\$ 752.60	
18	Door 02 pcs (@ \$1,568.30)	\$ 3,136.60	
19	Door Pillar	\$ 711.50	
20	Door View Convex Mirror	\$ 132.00	
21	Door Mirror Assy	\$ 689.50	
22	Aircon Blower Assy	\$ 628.00	
23	Aircon Heater Unit	\$ 1,919.40	
24	Aircon Pipe	\$ 189.20	
25	Rear Cargo Box Back Door Lh/Rh 02 pcs (@ \$1,475.00)	\$ 2,950.00	
26	Back Door "Corporate" Advertisement Sticker 1 set	\$ 800.00	
27	Cargo Box Lower Member	\$ 600.00	
28	Bumper Reverse Sensor 1 set	\$ 220.00	
29	Cargo Box Hinge 02 pcs (@ \$180.00 SN)	\$ 360.00	
30	Number Plate "Metal"	\$ 28.00	
31	Tailgate "70 KM/H" Sticker	\$ 15.00	
32	Front Panel "Corporate" Advertisement Sticker	\$ 80.00	
33	Number Plate "Metal"	\$ 28.00	
34	Door "Corporate" Advertisement Sticker	\$ 300.00	
	Door LTA "Corporate Detail" sticker	\$ 45.00	
	To check all wiring & electrical component for proper function	\$ 80.00	
	Remove and refix rear reverse sensor	\$ 80.00	
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 80.00	
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test	\$ 150.00	
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc...	\$ 300.00	
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 150.00	
	To apply Rust Proofing, resal tuff coating treatment on accident area	\$ 150.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,500.00	
	To putty & spray painting & including touch up paint on accident affected area	\$ 1,600.00	

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 23,337.50

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

SDLS:

LSEA to Disputants hence notify the Reparer of the following:

- To resurvey & re-spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer



M/s Liu's Brother Auto Engrg Wks

P-7662-58

257

5746.91

S.N 3800

1420 - 3260

12806.91

NIP Allowed  
Make  
29/12/17  
1/50 10,000  
10 day  
take photo after  
rep



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : M4-0006529-2

Print Date/Time : 28 Dec 2017 / 13:29:12

Receipt Date/Time : 28 Dec 2017 / 13:29:12

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-171228-001133

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLS4306A				
As at 15 Dec 2017/19:50:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLS4306A			
	Enquiry Fee	7.00	0.49	7.49
	20171228132649440433			
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
Paid By				
	xxxxxxxxxxxx4466	Credit Card: Visa/MasterCard		7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 28 Dec 2017 / 13:29:12

Receipt Date/Time : 28 Dec 2017 / 13:29:12

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-171228-001133

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLS4306A				
As at 15 Dec 2017/19:50:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLS4306A			
	Enquiry Fee	7.00	0.49	7.49
	20171228132649440433			
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
Paid By				
	xxxxxxxxxxxx4466	Credit Card:		
		Visa/MasterCard		7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



**A-Assurance**  
*Assurance in Insurance*
**Car Insurance Expiring?**  
 We get you the cheapest insurance renewal

[click to get quote](#)

Username / Email Add

password

Submit Qu



Connect

Sign Up New Account

Forgot Password

**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**
[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)
**2016 Nissan Qashqai 2.0 Premium.**

 Careful Owner! Joy To Drive,  
 Maintenance Package With TC.  
 Priced To Sell.  
 Direct Owner. SizeAd.

**AutoInn**  
*An Inspiration For Car Buyers*

 click here to view  
 our **PRISTINE USED CARS**  
 at **GREAT PRICES**

Browse by Category

Sort by Date Posted

20 results/page

5 vehicles

toyota dyna

Advanced Search

Submit f

	Make	Model	Price	Depreciation	Reg. Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	toyota dyna		Any	Any	2013	Any	Any	Any	Available


**Toyota Dyna 150**
**\$49,800**
**\$9,210 /yr**
**27-May-2013**
**2,982 cc**
**Truck**
**Available**
**Fuel Type:** Diesel

Only 1 Owner, Well Maintained By Previous Owner, New Paintwork, High Trade In Value, Call Now!

ABWIN (1994) Pte Ltd

Posted: 27-Dec-2017 Tags: 2013 Toyota Dyna, 2013 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota

[Details](#)

**Toyota Dyna 150**
**\$50,800**
**\$9,130 /yr**
**23-Jul-2013**
**2,982 cc**
**180,000 km**
**Truck**
**Available**
**Fuel Type:** Diesel

One Of The Cheapest And Best Condition Toyota Dyna 10 Feet Truck On The Market. Only 1 Owner And Low Mileage, Vehicle In Superb Condition, View To Believe.

Car (S) Pte Ltd

Posted: 26-Dec-2017 Tags: 2013 Toyota Dyna, 2013 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota

[Details](#)

**Toyota Dyna 150**
**\$49,800**
**\$9,480 /yr**
**01-Apr-2013**
**2,982 cc**
**155,353 km**
**Truck**
**Available**
**Fuel Type:** Diesel

1 Owner Reliable Toyota Dyna With Box, Economical And Low Maintenance. Vehicle In Excellent Condition, Low Mileage, In House Loan Available, High Trade In Value For Your Vehicle, Door Step Viewing Can...

ABWIN (1994) Pte Ltd

Posted: 26-Dec-2017 Tags: 2013 Toyota Dyna, 2013 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota

[Details](#)

**Toyota Dyna 150**
**\$48,800**
**\$9,110 /yr**
**08-May-2013**
**2,982 cc**
**123,000 km**
**Truck**
**Available**
**Fuel Type:** Diesel

Lowest Depreciation In Town, Well Maintained, No Repairs Needed. One Owner, Accident Free. Kindly Contact For Test Drive Appointment Today Before It's Gone. (Look Forward To Your Support In Bid To Hel...

Posted: 13-Dec-2017 Tags: 2013 Toyota Dyna, 2013 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota

[Details](#)
[Car Buying](#)
[Car Selling](#)
[Car Aftermarket](#)

 Buying a pre-owned car, but  
 Unsure of its Condition?  
 Get, STA Car Evaluation

[Car Ownership](#)
[On The Move](#)
[Lifestyle](#)

**Toyota Dyna 150**
**\$49,838**
**\$9,530 /yr**
**22-Mar-2013**
**2,982 cc**
**Truck**
**Available**
**Fuel Type:** Diesel

Most Reliable Lorry For Commercial Use! Good Engine, Chassis And Gearbox Condition! 100% In House Loan Available, 100% Worth Buy. Don't Miss It. Call Now To Enquire For More Details, Act Fast Or Else ...

Posted: 06-Dec-2017 Tags: 2013 Toyota Dyna, 2013 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota, Dyna, Dyna, Used Toyota

[Details](#)

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & CPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota dyna, toyota dyna Singapore, used toyota dyna Singapore, used toyota dyna, used vehicles Singapore or even buy used toyota dyna Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 28 Dec 2017 / 13:29:12

Receipt Date/Time : 28 Dec 2017 / 13:29:12

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-171228-001133

Previous Receipt No. :

**S/N Item Description/****Business Transaction Reference  
No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SLS4306A

As at 15 Dec 2017/19:50:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SLS4306A

Enquiry Fee

20171228132649440433

7.00 0.49 7.49

**Sub-Total**

7.00 0.49 7.49

**Total Before Rounding**

7.00 0.49 7.49

**Rounding Difference**

0.04

**Total Amount Payable**

7.45

Paid By

xxxxxxxxxxxx4466

Credit Card:

Visa/MasterCard

7.45

Total

7.45

Cash Change

0.00

Tendered Amount

7.45

Excess Refundable Amount

0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



## Zaini (LKK Auto)

---

**From:** Susan Low <liusbro@ymail.com>  
**Sent:** Tuesday, 3 April 2018 1:10 PM  
**To:** Zaini (LKK Auto)  
**Subject:** Re: Your Ref: GBC6562R\_ACCIDENT INVOLVING SLS 4306A / GBC 6562R / OTHERS ON 15/12/2017

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

We hereby confirm acceptance of your offer. Kindly let us have your discharge for our client's execution and your cheque made in our favour as soon as possible.

Thank.

Best Regards,

Susan Low  
M/s Liu's Brother Auto Engineering Workshop  
No. 1 Kaki Bukit Avenue 6 #01-01  
AutoBay @ Kaki Bukit  
Singapore 417883  
Tel: 67411730 Fax: 67445746

---

**From:** Zaini (LKK Auto) <Zaini@lkkauto.com>  
**To:** Susan Low <liusbro@ymail.com>  
**Cc:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>  
**Sent:** Tuesday, 20 March 2018, 15:13  
**Subject:** Your Ref: GBC6562R\_ACCIDENT INVOLVING SLS 4306A / GBC 6562R / OTHERS ON 15/12/2017

### WITHOUT PREJUDICE

Your Ref: GBC6562R  
Our Ref: CC6/AIG17024698/Uks3

Dear Susan,

### ACCIDENT INVOLVING SLS 4306A / GBC 6562R / OTHERS ON 15/12/2017

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 10,000.00
2. Loss of Use(12days x \$60.00)	\$ 720.00
3. LTA/GIA Search Fee	\$ 7.45
<b>TOTAL</b>	<b><u>\$ 10,727.45</u></b>

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

Our Ref: GBC6562R171215

Date: 06/02/2018

Your Ref:

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #07-16  
Chartis Building  
Singapore 079120

Attn: Motor Claims Department

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG BKE TOWARDS WOODLANDS BEFORE BUKIT PANJANG EXIT  
INVOLVING GBC6562R AND SLS4306A ON 15/12/2017**

We/I, **Messers Stve Pte Ltd** (Nric / ROC No: **198703585C**), the registered owners of m/vehicle – **GBC6562R** at all material times of the above accident. Our/my vehicle was surveyed by "AIG Asia" authorized appraiser and we/I based our/my on his recommendation for **S\$10,000-00** being the repair for **10 Days** (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **SLS4306A** when the same was involved in the aforesaid accident with our/my m/vehicle – **GBC6562R**.

We/I whereby you are the insurers of m/vehicle **SLS4306A** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **GBC6562R** has suffered loss and damage as follows:

(a) Cost of repairs	S\$	10,000-00
(b) LOU for pre-repair notice 02 days @\$80-00		160-00
(c) LOU Fee for 10 days @\$80-00		800-00
(d) GIA / LTA search fee		7-45

**Total Amount**

**S\$ 10,967-45**

We/I enclose herewith copies of the supporting documents for vehicle no. **GBC6562R** as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,



The owner of m/vehicle **GBC6562R**  
Messers Stve Pte Ltd  
cc, Liu's Bro Auto Engrg Ws

**Subject:** Re: Your Ref: GBC6562R\_ACCIDENT INVOLVING SLS 4306A / GBC 6562R / OTHERS ON 15/12/2017  
**From:** Susan Low (liusbro@ymail.com)  
**To:** Zaini@lkkauto.com;  
**Date:** Tuesday, 3 April 2018, 13:10

We hereby confirm acceptance of your offer. Kindly let us have your discharge for our client's execution and your cheque made in our favour as soon as possible.

Thank.

Best Regards,

Susan Low  
M/s Liu's Brother Auto Engineering Workshop  
No. 1 Kaki Bukit Avenue 6 #01-01  
AutoBay @ Kaki Bukit  
Singapore 417883  
Tel: 67411730 Fax: 67445746

---

**From:** Zaini (LKK Auto) <Zaini@lkkauto.com>  
**To:** Susan Low <liusbro@ymail.com>  
**Cc:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>  
**Sent:** Tuesday, 20 March 2018, 15:13  
**Subject:** Your Ref: GBC6562R\_ACCIDENT INVOLVING SLS 4306A / GBC 6562R / OTHERS ON 15/12/2017

**WITHOUT PREJUDICE**

Your Ref: GBC6562R  
Our Ref: CC6/AIG17024698/Uks3

Dear Susan,

**ACCIDENT INVOLVING SLS 4306A / GBC 6562R / OTHERS ON 15/12/2017**

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 10,000.00
2. Loss of Use(12days x \$60.00)	\$ 720.00
3. LTA/GIA Search Fee	\$ 7.45
<b>TOTAL</b>	<b><u>\$ 10,727.45</u></b>

Please confirm acceptance.

## Zaini (LKK Auto)

---

**From:** Zaini (LKK Auto)  
**Sent:** Monday, 26 February 2018 5:28 PM  
**To:** 'Loh, Chee-Heng'  
**Cc:** Hsiao Tong (LKKAuto)  
**Subject:** <Seek Mandate> Your Ref: 0946007602SG\_ACCIDENT INVOLVING SLS 4306A(OI) / GBC 6562R(TP) / OTHERS ON 15/12/2017

### WITHOUT PREJUDICE

Your Ref: 0946007602SG  
Our Ref: CC6/AIG17024698/Uks3

Dear Sirs,

### ACCIDENT INVOLVING SLS 4306A(OI) / GBC 6562R(TP) / OTHERS ON 15/12/2017

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle.  
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.  
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, **LIU'S BROTHER AUTO ENGINEERING WORKSHOP** is as follows:-

	Amount <u>Claimed</u>	Amount <u>Revised</u>
1. Cost of Repair(w/GST)	\$ 23,337.50	\$ 10,000.00
2. Loss of Use(12days x \$80.00)	\$ 960.00	\$ 960.00 (12days x \$80.00)
3. LTA / GIA Search fee	\$ 7.45	\$ 7.45
<b>TOTAL</b>	<b>\$ 24,304.95</b>	<b>\$ 10,967.45</b>
<b>Total amount of claim (Liability 100%)</b>		<b>\$ 10,967.45</b>

For your approval in Merimen please.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com) | fax: 6741-4108

Blk 51, Faya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Print Received Message

This mail is associated with :

\*GBC6562R (0946007602SG)  
[SLS4306A]

TP

STVE PTE LTD

Dec 15 2017 7:00PM

[MOVA AUTOMOTIVE PTE LTD]

Liu's Brother Auto Engineering Workshop

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 05/03/2018 10:14 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$10967.45) - GBC6562R - Claim Handler: Loh, Chee-Heng

Approved:10967.45:kindly settle at best.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref:** CC6/AIG17024698/Uks3

15 JANUARY 2018

**MOVA AUTOMOTIVE PTE LTD**  
22 JALAN KILANG  
#07-01 MOVA BUILDING  
SINGAPORE 159419  
ATTN: HR / MANAGEMENT

Dear Sir/Madam,

**ACCIDENT INVOLVING SLS 4306A / GBC 6562R / OTHERS ON 15.12.2017**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

  
Zaini  
Case Handler  
DID: 6841 2132  
FAX: 6741 4108  
Email: [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)



## **AUTHORISATION TO ACT**

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

We / I, Messers STVE Pte Ltd ("the third party claimant") of No. 18 Tuas Avenue 10 Singapore 639142 (address), owner of GBC6562R (vehicle No.) hereby authorize M/s Liu's Brother Auto Engineering Workshop ("the workshop") to act for me / us with respect to my / our claim for repair costs and/or rental and/or loss of use ("claim") for my / our vehicle no. GBC6562R that was damaged pursuant to the accident which occurred on 15/12/2017 (date) along BKE Towards Woodlands Before Bukit Panjang Exit (location) involving vehicle no / s SLS4306A ("the accident").

We / I further authorize the workshop to settle my / our above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my / our claim with payment cheque / s being made in favour of the workshop.

We / I further acknowledge that any settlement the workshop may reach on my / our behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle / is concerned.

Dated this 20th (day) of June (month) 2018 (years)

  
\_\_\_\_\_



Signed by "the third party claimant"

Messers STVE Pte Ltd

198703585C

GBC6562R



Signed by "the workshop"

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, LIU'S BROTHER AUTO ENGINEERING WORKSHOP ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$10,000.00 (Repair Cost), S\$720.00 (Loss of Use )S\$7.45 (Disbursement)for vehicle no. GBC 6562R that was damaged pursuant to the accident which occurred on 15/12/2017 (date) along BKE TOWARDS BUKIT PANJANG (location) involving vehicle no/s SLS 4306A. This is pursuant to the inspection conducted on 29/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner STVE PTE LTD ("the third party claimant") of vehicle no. GBC 6562R make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GBC 6562R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 2 (day) of July (month) **2018** (year)

 CKS

Signed by appointed surveyor



Signed by "the workshop" (with chop)

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 4 #01-01 Auto Bay @ Kaki Bukit Singapore 417801

REG No: 32281793 Tel: 6743 1738 / 733 Fax: 6743 4746 Email: liubro@ymail.com

Invoice/Ref No: GBC6562R171215

**Final Bill****Customer**

Name: AIG Asia Pacific Insurance Pte Ltd  
 Address: Motor Claims Department  
 78 Shenton Way #07-16  
 AIG Building Singapore 079120

Date: 06-02-18  
 Vehicle No: GBC6562R  
 Model/Make: Toyota Dyna 150  
 Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	<b>Rear</b> Tail Lamp	\$ 245.50	\$ -
2	Number Plate Bracket	\$ 126.30	\$ -
3	Exhaust Pipe	\$ 508.30	\$ -
4	Exhaust Mounting 02 pcs (@ \$58.60)	\$ 117.20	\$ -
6	<b>Front</b> Panel	\$ 1,265.50	\$ -
7	Panel Top Black Garnish	\$ 328.50	\$ -
8	Panel "Dyna" Emblem	\$ 68.25	\$ -
9	Panel Sealant	\$ 60.00	\$ -
10	Windscreen Rubber	\$ 303.60	\$ -
11	Grille	\$ 587.65	\$ -
12	Grille Clips 06 pcs (@ \$6.50)	\$ 39.00	\$ -
13	Grille Emblem	\$ 68.10	\$ -
14	Bumper	\$ 481.60	\$ -
15	Bumper Clip (1 set)	\$ 54.50	\$ -
16	Head Lamp 02 pcs (@ \$704.35)	\$ 1,408.70	\$ -
17	Corner Panel 02 pcs (@ \$376.50)	\$ 752.60	\$ -
18	Door 02 pcs (@ \$1,568.30)	\$ 3,136.60	\$ -
19	Door Pillar	\$ 711.50	\$ -
20	Door View Convex Mirror	\$ 132.00	\$ -
21	Door Mirror Assy	\$ 689.50	\$ -
22	Aircon Blower Assy	\$ 628.00	\$ -
23	Aircon Heater Unit	\$ 1,919.40	\$ -
24	Aircon Pipe	\$ 189.20	\$ -
25	<b>Rear</b> Cargo Box Back Door Lh/Rh 02 pcs (@ \$1,475.00)	\$ 2,950.00	SN \$ -
26	Back Door "Corporate" Advertisement Sticker 1 set	\$ 800.00	SN \$ -
5	Cargo Box Lower Member	\$ 600.00	SN \$ -
27	Bumper Reverse Sensor 1 set	\$ 220.00	SN \$ -
28	Cargo Box Hinge 02 pcs (@ \$180.00 SN)	\$ 360.00	SN \$ -
29	Number Plate "Metal"	\$ 28.00	SN \$ -
30	Tailgate "70 KM/H" Sticker	\$ 15.00	SN \$ -
31	<b>Front</b> Panel "Corporate" Advertisement Sticker	\$ 80.00	SN \$ -
32	Number Plate "Metal"	\$ 28.00	SN \$ -
33	Door "Corporate" Advertisement Sticker	\$ 300.00	SN \$ -
34	Door LTA "Corporate Detail" sticker	\$ 45.00	SN \$ -
	To check all wiring & electrical component for proper function	\$ 80.00	\$ -
	Remove and refix rear reverse sensor	\$ 80.00	\$ -
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 80.00	\$ -
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test	\$ 150.00	\$ -
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc.	\$ 300.00	\$ -
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 150.00	\$ -
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 150.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,500.00	\$ -
	To putty & spray painting & including touch up paint on accident affected area	\$ 1,600.00	\$ -

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 23,337.50

Total amount in Lump Sum Basis for repaired vehicle

\$ 10,000.00

SDLS: Ten Thousand Only



M/s Liu's Brother Auto Engrg Wks



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 28 Dec 2017 / 13:29:12

Receipt Date/Time : 28 Dec 2017 / 13:29:12

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-171228-001133

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLS4306A				
As at 15 Dec 2017/19:50:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLS4306A			
	Enquiry Fee	7.00	0.49	7.49
	20171228132649440433			
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
Paid By				
	xxxxxxxxxxxx4466	Credit Card:		
		Visa/MasterCard		7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Dec 2017 <a href="#">Edit Reg</a>		29 Dec 2017 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$10,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$10,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

MOVA AUTOMOTIVE PTE LTD, Co. Reg. No.: 198904033G

Main Claimant:

STVE PTE LTD, Co. Reg. No.: 198703585C

Vehicle Reg. No.:

GBC6562R

Date of Loss:

15/12/2017 19:00 - :59  
[54 Months and 22 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 0946007602SG

Policy/Cover Note No.:

0999995097 (Comprehensive)

Vehicle Reg. No. (Insured):

SLS4306A

Policy No. (Claimant):

D-17087422MFCV

Excess:

Repairer:

Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com

Claimant's Insurer:

MS First Capital Insurance Ltd (HQ) - Tel: 62222311

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/01/2018]

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

- AIG\_SG\_EXPRESS (05/03/2018): Alert - Adj Mandate Approved (S\$10967.45) - GBC6562R - Claim Handler: Loh, Chee-...
- AIG\_SG (02/01/2018): Request fro TP GIA Report
- AIG\_SG (02/01/2018): No Policy Found

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete














































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									











## Claim Documents

\*GBC6562R (0946007602SG)  
[SLS4306A]  
TP  
STVE PTE LTD  
Dec 15 2017 7:00PM  
[MOVA AUTOMOTIVE PTE LTD]  
Liu's Brother Auto Engineering Workshop

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a> <input type="checkbox"/>	
<b>Letters/Correspondences</b>			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown	<input type="checkbox"/> Edit	
<b>Photos/Images</b>			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print	
1	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
2	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
3	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
4	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
5	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
6	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
7	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
8	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
9	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
10	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
11	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
12	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
13	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
14	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
15	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
16	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
17	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
18	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
19	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
20	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
21	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
22	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
23	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
24	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
25	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
26	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
27	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
28	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
29	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
30	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
31	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
32	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
33	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	
34	29/12/17 16:35	General View	<input type="checkbox"/> Load JPG	



Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
36	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
37	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
38	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
39	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
40	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
41	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
42	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
43	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
44	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
45	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
46	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
47	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
48	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
49	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
50	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
51	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
52	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
53	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
54	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
55	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
56	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
57	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
58	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
59	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
60	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
61	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
62	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
63	29/12/17 16:35	General View	 Load JPG	<input checked="" type="checkbox"/>
64	29/12/17 16:35	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
65	29/12/17 16:35	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
66	09/01/18 07:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	09/01/18 07:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	09/01/18 07:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	09/01/18 07:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	09/01/18 07:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	09/01/18 20:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	09/01/18 20:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	09/01/18 20:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	09/01/18 20:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	09/01/18 20:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	09/01/18 20:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	22/01/18 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	22/01/18 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	22/01/18 14:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	22/01/18 14:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
81	22/01/18 14:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
82	22/01/18 14:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
83	22/01/18 14:01	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
84	22/01/18 14:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
85	22/01/18 14:01	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/01/18 10:00	TP GIA REPORT		Load PDF	
2	03/01/18 11:16	OI GIA REPORT		Load PDF	
3	29/01/18 08:34	TP ESTIMATE - MARKED.		Load PDF	
4	23/02/18 15:28	LETTER TO OI		Load PDF	
5	26/02/18 17:01	LTA SEARCH		Load PDF	
6	05/07/18 10:41	WORKSHOP INVOICE		Load PDF	
7	05/07/18 10:41	AUTHORISATION TO ACT FORM		Load PDF	
8	05/07/18 10:41	Release Voucher		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLS4306A (Insd veh)	Model:	TOYOTA DYNA 150 3.0 D (M)
	GBC6562R (TP veh)		
Date of Accident:	15/12/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	23,337.50
Final Repair Cost	:	\$	10,000.00
Loss of Use	:	\$	720.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	10,727.45

12.00 days at \$60.00 per day  
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ 100 \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Liu's Brother Auto Engineering Workshop	:	\$ 10,727.45
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

05 Jul  
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17024698/UJA3Q2

Date: 05/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995097  
**Claimant Vehicle No :** GBC6562R **Insured Vehicle No :** SLS4306A  
 Date of Loss: 15/12/2017 Nature of Claim: TP Claim No: 0946007602SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC6562R**  
 Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2291841  
 Reg. Date: 23/05/2013 (Man. Year: 2013) Chassis No: JTFAT35Y10K202319  
 Colour: White Odometer: 179303 km  
 Engine Capacity: 2982 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15 Rear Tyre Size: 155 R12 (D)  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,247.50	9,246.91	10,000.59	51.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,090.00	3,260.00	830.00	20.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,337.50</b>	<b>12,506.91</b>	<b>10,830.59</b>	<b>46.41</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>10,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>23,337.50</b>	<b>10,000.00</b>	<b>13,337.50</b>	<b>57.15</b>
<b>+ Loss of Use (12.0 x S\$60.00/day) (S\$)</b>		720.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>10,727.45</b>		

INSPECTION

Date of Assignment: 29/12/2017  
 Date Inspected: 29/12/2017 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)  
 BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT  
 Singapore 417883  
 Estimated Period of Repair: 10.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL LAMP O/S	Cracked	245.50 F	*245.50 FL
2	1		*REAR NUMBER PLATE BRACKET	Bent	126.30 F	*126.30 FL
3	1		*REAR EXHAUST PIPE	Bent / Twisted	508.30 F	*508.30 FL
4	2		*REAR EXHAUST MOUNTING	Not Necessary	117.20 F	*- FL
5	1		*FRONT PANEL	Badly Dented	1,265.50 F	*1,265.50 FL
6	1		*FRONT PANEL TOP BLACK GARNISH	Cut	328.50 F	*328.50 FL
7	1		*FRONT PANEL DYNA EMBLEM	Necessary	68.25 F	*68.25 FL
8	1		*FRONT PANEL SEALANT	Not Necessary	60.00 F	*- FL
9	1		*FRONT WINDSCREEN RUBBER	Necessary	303.60 F	*303.60 FL
10	1		*FRONT GRILLE	Not Necessary	587.65 F	*- FL
11	6		*FRONT GRILLE CLIP	Necessary	39.00 F	*39.00 FL
12	1		*FRONT GRILLE EMBLEM	Not Necessary	68.10 F	*- FL
13	1		*FRONT BUMPER	Repair	481.60 F	*- FL
14	1		*SET FRONT BUMPER CLIP	Not Necessary	54.50 F	*- FL
15	2		*FRONT HEAD LAMP	Cracked	1,408.70 F	*1,408.70 FL
16	2		*FRONT CORNER PANEL	Repair	752.60 F	*- FL
17	2		*FRONT DOOR	Repair	3,136.60 F	*- FL
18	1		*FRONT DOOR PILLAR	Repair	711.50 F	*- FL
19	1		*FRONT DOOR VIEW CONVEX MIRROR	Broken	132.00 F	*132.00 FL
20	1		*FRONT DOOR MIRROR ASSY	Bent	689.50 F	*689.50 FL
21	1		*FRONT AIRCON BLOWER ASSY	Cracked	628.00 F	*628.00 FL
22	1		*FRONT AIRCON HEATER UNIT	Cracked	1,919.40 F	*1,919.40 FL
23	1		*FRONT AIRCON PIPE	Not Necessary	189.20 F	*- FL
24	2		*REAR CARGO BOX BACK DOOR LH /RH	Dented / Bent	2,950.00 FS	*1,800.00 FS
25	1		*SET REAR BACK DOOR CORPORATE ADVERTISEMENT STICKER	Necessary	800.00 FS	*600.00 FS
26	1		*REAR CARGO BOX LOWER MEMBER	Bent	600.00 FS	*500.00 FS
27	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
28	2		*REAR CARGO BOX HINGE	Bent	360.00 FS	*50.00 FS
29	1		*REAR NUMBER PLATE METAL	Bent	28.00 FS	*15.00 FS
30	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
31	1		*FRONT PANEL CORPORATE ADVERTISEMENT STICKER	Necessary	80.00 FS	*80.00 FS
32	1		*FRONT NUMBER PLATE METAL	Bent	28.00 FS	*15.00 FS
33	1		*FRONT DOOR CORPORATE ADVERTISEMENT STICKER O/S	Necessary	300.00 FS	*200.00 FS
34	1		*FRONT DOOR LTA CORPORATE DETAIL STICKER O/S	Necessary	45.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 19,247.50 11,162.55  
 - List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 1,915.64

Total Parts (\$\$) 19,247.50 9,246.91

Report was unsubmitted during this print-out.
-----------------------------------------------



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	30.00
2	REMOVE AND REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS	New	80.00	60.00
4	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS & PERFORM WATER TEST	New	150.00	80.00
5	REMOVE & REINSTALL DASHBOARD ,METER INSTRUMENTS ,DISCONNECT WIRING & ETCS	New	300.00	160.00
6	TO REMOVE & REFIX AIR CON ,REFILL AIR CON GAS & TEST FOR LEAKAGES	New	150.00	100.00
7	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	150.00	80.00
8	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	1,500.00	1,200.00
9	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	1,600.00	1,500.00
Gross Labour Cost (S\$)			<b>4,090.00</b>	<b>3,260.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;