



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 . Tel: 6741-1720 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBC6562R171215

Estimate

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Address: Motor Claims Department

78 Shenton Way #07-16

AIG Building

Singapore 079120

Date:

29-12-17

Vehicle No:

GB3C6562R

Model/Make:

Toyota Dyna 150

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tail Lamp	\$ 245.50	
2	Number Plate Bracket	\$ 126.30	
3	Exhaust Pipe	\$ 508.30	
4	Exhaust Mounting 02 pcs (@ \$58.60)	\$ 117.20	
6	Front Panel	\$ 1,265.50	
7	Panel Top Black Garnish	\$ 328.50	
8	Panel "Dyna" Emblem	\$ 68.25	
9	Panel Sealant	\$ 60.00	
10	Windscreen Rubber	\$ 303.60	
11	Grille	\$ 587.65	
12	Grille Clips 06 pcs (@ \$6.50)	\$ 39.00	
13	Grille Emblem	\$ 68.10	
14	Bumper	\$ 481.60	
15	Bumper Clip (1set)	\$ 54.50	
16	Head Lamp 02 pcs (@ \$704.35)	\$ 1,408.70	
17	Corner Panel 02 pcs (@ \$376.50)	\$ 752.60	
18	Door 02 pcs (@ \$1,568.30)	\$ 3,136.60	
19	Door Pillar	\$ 711.50	
20	Door View Convex Mirror	\$ 132.00	
21	Door Mirror Assy	\$ 689.50	
22	Aircon Blower Assy	\$ 628.00	
23	Aircon Heater Unit	\$ 1,919.40	
24	Aircon Pipe	\$ 189.20	
25	Rear Cargo Box Back Door Lh/Rh 02 pcs (@ \$1,475.00)	\$ 2,950.00	
26	Back Door "Corporate" Advertisement Sticker 1 set	\$ 800.00	
5	Cargo Box Lower Member	\$ 600.00	
27	Bumper Reverse Sensor 1 set	\$ 220.00	
28	Cargo Box Hinge 02 pcs (@ \$180.00 SN)	\$ 360.00	
29	Number Plate "Metal"	\$ 28.00	
30	Tailgate "70 KM/H" Sticker	\$ 15.00	
31	Front Panel "Corporate" Advertisement Sticker	\$ 80.00	
32	Number Plate "Metal"	\$ 28.00	
33	Door "Corporate" Advertisement Sticker	\$ 300.00	
34	Door LTA "Corporate Detail" sticker	\$ 45.00	
	To check all wiring & electrical component for proper function	\$ 80.00	
	Remove and refix rear reverse sensor	\$ 80.00	
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 80.00	
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test	\$ 150.00	
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc...	\$ 300.00	
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 150.00	
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 150.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,500.00	
	To putty & spray painting & including touch up paint on accident affected areas	\$ 1,600.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 23,337.50

Total amount in Part By Part / Lump Sum Basis for repaired vehicle


SDLS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



M/s Liu's Brother Auto Engrg Wks

P-7662-17

25%

5746-91

S.N 3500

1260 - 3260

12506-91