

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01, Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931, Tel: 6744-1730 / 731, Fax: 6744-5746, Email: liubro@gmail.com

Invoice/Ref No: GBC8062D171214

Estimate**Customer**

Name: EQ Insurance Company Limited

Date: 29-12-17

Address: Motor Claims Department

Vehicle No: GBC8062D

5 Maxwell Road #17-00

Model/Make: Toyota Hiace

Tower Block MND Complex Singapore 069110

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>30/Dec</i>	\$ 496.10	
2	Bumper Clips 1 set <i>neu</i>	\$ 48.00	
3	Bumper Side Bracket <i>neu</i>	\$ 202.00	
4	Bumper Reverse Sensor <i>shut off</i>	\$ 220.00	
5	Tailgate	\$ 2,051.60	
6	Tail Lamp <i>1/5</i>	\$ 365.00	
7	Tailgate "Toyota Logo" <i>neu</i>	\$ 70.50	
8	Tailgate "Hiace" Emblem <i>neu</i>	\$ 75.00	
9	Tailgate "Toyota" Sticker <i>neu</i>	\$ 95.00	
10	Tailgate "70 KM/H" Sticker <i>neu</i>	\$ 15.00	
11	Tailgate "8 PAX" Sticker <i>neu</i>	\$ 15.00	
12	Tailgate "Corporate" Advertisement Sticker <i>neu</i>	\$ 300.00	
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	
	Remove and refix rear Bumper distance sensor	\$ 90.00	
	To check all wiring & electrical component for proper function	\$ 80.00	
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 200.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	
	To putty & spray painting & including touch up paint on accident affected areas	\$ 800.00	
	To apply Rust Proofing, reseat tuff-coating treatment on accident area	\$ 100.00	
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 6,223.20

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

\$ -

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not Authorized**L/S \$2850**4 day**29/12/17**take photo after repair**P-3071-7**25%*
*2303.77**3583.77*