

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 312A

DATE 28/12/2017 9:59

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille ✓			\$ 282.10
	Radiator Grille U Moulding ✓			\$ 108.90
	Front Bumper Cover <i>x repair</i>			\$ 538.80
	Front Bumper Sponge ?			\$ 136.30
	Front Bumper Reinforcement ?			\$ 504.10
	Front Bumper Bracket Top (LH/RH) ?		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) ?		\$ 20.10	\$ 40.20
	SUB TOTAL			\$ 1,655.20
	LESS 20%			\$ 331.04
	DISCOUNTED TOTAL			\$ 1,324.16
	Front Number Plate ✓			\$ 25.00 Nett
	Front No Plate Trim Cover ✓			\$ 30.00 Nett
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 350.00 <i>200</i>
	Spray Painting Charge			\$ 200.00 <i>180</i>
	TOTAL LABOUR			\$ 550.00
	ESTIMATE TOTAL			\$ 1,929.16
<i>Kahni 16/16/17</i> <i>28/12/17 11:25am</i> <i>2 Days</i> <i>45</i> <i>After Repair photo</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				