

INS. CASE OWNER:

JACKIN

Kian Chuan

CC6 / AIG170 24710 / A439

LXX

IDAC

Surveyor:

AOLIAN

DOI:

28/12/17

Date / Time:

23/12/17

Registered in Marimen:

29/12/17

Pre-assign / CCU / ETE



Insured Vehicle No.:

SLG 9907X

Claim No.:

4519519696 SG

Name of Insured:

DAMLER SOUTH EAST ASIA PTE LTD

Policy No.:

Insured Tel No.:

HP:

Make / Model:

MERCEDES-BENZ CLA 180

Excess Sec II:SS

D.O.A:

22/12/17

Place of Accident:

ALONG BUKIT BATOK ST 23
JUNCTION OF ST 24

Is driver the owner?

(YES ☒ NO ☐)

Nature of Accident:

If NO, Driver Name / Age: HOW XEN ZHI

Driver Tel No.: 9757 4503

(V/L ☒ / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLA 17166



INSRS:

WSP: Modern

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

04/01/18 (vic)

SLA 17166 - X ; SLG 9907X - X
* NO ESTIMATE

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call CR: 5/1/18 x 1121 11419

After call ltr to CR: 09/01/18 - vic cu

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to CR:

Authorization To Act

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / SEA:

Medical Bill:

FIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L15

S\$

42,000.00 (42 days) Reduction: 44 %

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

100% 100%

Email ☒Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

4a

Repair Cost: (w/acc)

S\$

44,940.00

If NO or B 24, Ass. Lis:

COVD FROM UNDER BOARD

Loss of Rental (LOR):

S\$

-

(days)

Loss of Use (LOU):

S\$

3,000.00 x 50 days

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

114.00

Disbursement:

S\$

-

Legal Cost

S\$

-

(e.g. Tow/ Independent)

Total:

S\$

45,041.45

Global Sum S\$:

41,000.00

1) Claim status: ☒ Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4320.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

S\$

41,000.00

Name 1:

MODERN AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

REF:

ASSIGNMENT

24/02/16

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / CO RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / FR Seen: _____ Consistent? : Yes or No

Est. Repairs: 42 days Res: Yes or NoLump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLA17366 Yr Regn: 2016 FebType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel cc: 1496Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: _____ T.Radio: Insured / Std / NI / NA

Engine No: _____

C.No: RU11109296Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / SiRim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS / OUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mmR/Bal: 06 mmL/Bal: 06 mmL/Bal: 06 mm

D.O.A. _____

D.O.I. 28/12/17Survey held at ModernDes. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPALG

Lto \$42,000.00

Crash: \$33,144.96 (44%)

MV: 85K

PV: 43K

Nett: 42K

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Insp: \$

☐

Weekend: \$

1 3 4 5 6 7 8 9 0

Phone

Other

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG17024710/Ahs3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 29-12-2017	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLG 9907X	Veh. Inspected	SLA 1736G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/12/2017	Inspection Date	28/12/2017
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Quotation

DATE : 28.12.2017
VEH NO : SLA1736G
MODEL : Honda Vezel
D O A : 22.12.2017
YR REF : SLG9907X

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLA1736G (Honda Vezel)

Item	Description	Qty	Amt
<u>NO</u>	<u>LIST ITEMS</u>		
1	Bonnet <i>Dented</i>	1	985.40 ✓
2	Bonnet Lock <i>Damaged</i>	1	128.00 ✓
3	Bonnet Hinge <i>2 sets</i>	2	138.20 ✓
4	Headlamp <i>at</i>	2	3,569.00 ✓
5	Front Bumper <i>repair</i>	1	880.00 +
6	Front Bumper Clips <i>3 from</i>	1 set	30.00 +
7	Front Bumper Side Holder	2	50.60 +
8	Front Fender <i>RH Dented</i>	2	4,417.40 <i>558.70</i>
9	Front Fender Arc Garnish <i>at</i>	2	310.60 ✓
10	Front Fender Arc Garnish Clips <i>new</i>	2 sets	40.00 ✓
11	Front Mudflap <i>LH 2nd, RH 1st</i>	2	120.80 ✓
12	Front Door - RH <i>Distorted</i>	1	989.50 ✓
13	Front Door Lock - RH <i>2nd</i>	1	278.20 ✓
14	Front Door Weatherstripe - RH <i>at</i>	1	133.90 ✓
15	Front Door Outer Handle - RH <i>at</i>	1	220.40 ✓
16	Front Door Wing Mirror - RH <i>Distorted</i>	1	723.90 ✓
17	Front Door Inner Trim Board - RH <i>2nd</i>	1	585.20 ✓
18	Front Door Inner Trim Board Clips - RH <i>new</i>	1 set	30.00 ✓
19	Front Door Glass - RH <i>shattered</i>	1	389.60 ✓
20	Front Door Glass Outer Moulding - RH <i>at</i>	1	68.50 ✓
21	Front Door Glass Regulator Gear - RH <i>Damaged</i>	1	358.00 ✓
22	Front Door Hinge - RH <i>3 from</i>	2	150.00 x
23	Front Door Check - RH	1	48.00 x
24	Front Door Glass Channel - RH <i>2nd</i>	1	78.20 ✓
25	Front Door Glass Channel Rubber - RH <i>new</i>	1	105.00 ✓
26	Centre Pillar - RH <i>Dented</i>	1	695.60 ✓
27	Centre Pillar Inner - RH <i>Repair</i>	1	584.20 x

10368 SD

RE: ESTIMATE FOR ACCIDENT REPAIR SLA1736G (Honda Vezel)

28	Centre Pillar Lower Garnish	1	158.40	✓
29	Centre Pillar Lower Garnish Clips	1 set	20.00	✓
30	Centre Pillar Upper Garnish	1	104.20	✓
31	Centre Pillar Upper Garnish Clips	1 set	20.00	✓
32	Rear Door - RH Distorted	1	978.40	✓
33	Rear Door Lock - RH Jammed	1	298.00	✓
34	Rear Door Weatherstrips - RH Lt	1	168.90	✓
35	Rear Door Inner Trim Board - RH Replaced	1	645.10	✓
36	Rear Door Inner Trim Board Clips - RH	1 set	30.00	✓
37	Rear Door Glass Outer Moulding - RH Lt	1	66.40	✓
38	Rear Door Glass Channel - RH Lt	1	75.10	✓
39	Rear Door Glass Channel Rubber - RH	1	94.10	✓
40	Rear Door Glass Regulator Gear - RH Dgd	1	358.00	✓
41	Rear Door Hinge - RH Rest	2	150.00	✓
42	Rear Door Check - RH Dgd	1	48.00	✓
43	Rocker Panel - RH Rymie	1	660.80	✓
44	Rear Bumper Rymie	1	825.00	✓
45	Rear Bumper Clips	1 set	30.00	✓
46	Rear Bumper Side Holder	2	52.80	✓
47	Rear Side Bumper Rymie	2	390.00	✓
48	Taillamp LH Replaced	2	961.20 480.60	✓
49	Taillamp Panel LH Replaced	2	342.40 156.20	✓
50	Rear Fender - RH Distorted	1	995.00	✓
51	Rear Fender Arc Garnish - RH Missing	1	151.40	✓
52	Rear Fender Arc Garnish Clips - RH	1 set	20.00	✓
53	Rear Fender Inner Shield - RH Replaced	1	210.40	✓
54	Rear Fender Inner Shield Clips - RH	1 set	30.00	✓
55	Rear Fender Inner Trim Board - RH Replaced	1	326.00	✓
56	Rear Fender Inner Trim Board Clips - RH	1 set	30.00	✓
57	Rear Fender Inner Trim Board (Upper) - RH	1	210.40	✓
58	Rear Fender Inner Trim Board (Upper) Clips - RH	1 set	20.00	✓
59	Rear Mudflap - RH Replaced	1	65.10	✓
60	Rear Fender - LH Distorted	1	995.00	✓
61	Rear Fender Arc Garnish - LH Lt	1	151.40	✓
62	Rear Fender Arc Garnish Clips - LH	1 set	20.00	✓
63	Rear Fender Inner Shield - LH	1	210.40	✓
64	Rear Fender Inner Shield Clips - LH	1 set	30.00	✓
65	Rear Fender Inner Trim Board - LH Replaced	1	326.00	✓
66	Rear Fender Inner Trim Board Clips - LH	1 set	30.00	✓
67	Rear Fender Inner Trim Board (Upper) - LH	1	210.40	✓
68	Rear Fender Inner Trim Board (Upper) Clips - LH	1 set	20.00	✓
69	Rear Fender Quarter Garnish - LH Lt	1	45.40	✓
70	Fuel Lid Distorted	1	90.40	✓
71	Fuel Lid Lock Jammed	1	35.10	✓
72	Rear Mudflap - LH Lt	1	65.10	✓
73	Rear Door - LH Replaced	1	978.40	✓
74	Rear Door Lock - LH Dgd	1	298.00	✓

85215

RE: ESTIMATE FOR ACCIDENT REPAIR SLA1736G (Honda Vezel)

75	Rear Door Weatherstripe - LH <i>ut</i>	1	168.90 ✓
76	Rear Door Outer Handle - LH <i>ut</i>	1	151.40 ✓
77	Rear Door Glass Outer Moulding - LH <i>ut</i>	1	66.40 ✓
78	Rear Door Glass Regulator Gear - LH <i>Brkd</i>	1	358.00 ✓
79	Rear Door Glass Channel - LH <i>Brkd</i>	1	76.10 ✓
80	Rear Door Glass Channel Rubber - LH <i>new</i>	1	94.10 ✓
81	Rear Door Inner Trim Board - LH <i>Brkd</i>	1	645.10 ✓
82	Rear Door Inner Trim Board Clips - LH <i>new</i>	1 set	30.00 ✓
83	Rear Door Hinge - LH <i>for new</i>	2	150.00 x
84	Rear Door Check - LH <i>for new</i>	1	48.00 x
85	Centre Pillar - LH <i>for new</i>	1	695.60 x
86	Front Door - LH <i>dent</i>	1	989.50 ✓
87	Front Door Lock - LH <i>new</i>	1	278.20 x
88	Front Door Weatherstripe - LH <i>new</i>	1	133.90 x
89	Front Door Wing Mirror - LH <i>distorted</i>	1	723.90 ✓
90	Front Door Hinge - LH <i>for new</i>	2	150.00 x
91	Front Door Check - LH <i>for new</i>	1	48.00 x
92	Front Windscreen <i>shattered</i>	1	1,345.10 ✓
93	Front Windscreen Moulding <i>new</i>	1	132.00 ✓
94	Front Windscreen Pillar <i>dent</i>	2	797.00 ✓
95	Front Windscreen Pillar Inner Trim <i>new</i>	2	204.80 ✓
96	Front Windscreen Pillar Inner Trim Clips <i>new</i>	2 sets	40.00 ✓
97	Door Frame <i>LH dent</i>	2	1,670.00 765
98	Roof Panel <i>distorted</i>	1	1,650.00 ✓
99	Roof Panel Front Reinforcement <i>for new</i>	1	420.00 ✓
100	Roof Panel Centre Reinforcement	1	395.00 ✓
101	Roof Panel Top Moulding <i>ut</i>	2	276.00 ✓
102	Roof Panel Top Moulding Clips <i>new</i>	2 sets	60.00 ✓
103	Roof Panel Inner Trim Board <i>crushed</i>	1	825.90 ✓
104	Roof Panel Inner Trim Board Clips <i>new</i>	1 set	100.00 ✓
105	Roof Panel Side Air Bag <i>Activated</i>	2	2,100.40 ✓
106	Roof Panel Side Air Bag Sensor	2	278.00 ✓
107	Front Driver Seat Air Bag <i>Activated</i>	1	785.90 ✓
108	Front Driver Seat Air Bag Sensor	1	139.00 ✓
109	Front Passenger Seat Air Bag <i>Activated</i>	1	785.90 ✓
110	Front Passenger Seat Air Bag Sensor	1	139.00 ✓
111	Air Bag ECU <i>Activated</i>	1	1,092.00 ✓
112	Front Seat Belt <i>Activated</i>	2	1,330.00 ✓
113	Rear Shock Absorber <i>RH Bent</i>	2	660.00 330
114	Rear Axle Beam <i>Bent</i>	1	1,513.00 ✓
115	Rear Wheel Hub c/w Bearing <i>new</i>	2	774.40 ✓
116	Front Lower Arm <i>Bent</i>	2	732.40 ✓
117	Front Shock Absorber <i>Bent</i>	2	990.00 ✓
118	Front Knuckle Arm <i>Bent</i>	2	781.00 ✓
119	Front Wheel Hub c/w Bearing <i>new</i>	2	690.00 ✓
120	Steering Rack and Pinion <i>Bent</i>	1	1,178.40 ✓
121	Engine Piston <i>damaged</i>	4	1,400.00 ✓

25167-8

Front LH
Rear Handle
23040 ✓
ut

RE: ESTIMATE FOR ACCIDENT REPAIR SLA1736G (Honda Vezel)

122	Engine Con Rod <i>Best</i>	4	1,180.00	-
123	Engine Con Rod Bearing <i>new</i>	1	220.00	-
124	Engine Main Bearing <i>new</i>	1	260.00	✓
125	Top Timing Gear <i>new</i>	2	780.00	+
126	Timing Chain	1	225.00	+
127	Exhaust Valve <i>new</i>	8	552.00	-
128	Inlet Valve <i>new</i>	8	576.00	-
129	Crankshaft <i>new</i>	1	2,460.00	+
130	Camshaft <i>new</i>	2	2,800.00	+
131	Overhaul Gasket <i>new</i>	1	650.00	150
132	Flywheel Oil Seal <i>new</i>	1	48.00	✓
133	Timing Tensioner <i>new</i>	1	195.00	+
			<u>62,756.20</u>	
			(12,551.24)	
Less 20%			<u>\$ 50,204.96</u>	

S/NET ITEMS

1	Front Wheel Rim <i>lot</i>	2	\$ 1,380.00	1100
2	Front Door Glass Solar Film - RH <i>new</i>	1	\$ 180.00	✓
3	Front Door Speaker - RH <i>new</i>	1	\$ 200.00	150
4	Front Door Black Tape - RH <i>new</i>	1	\$ 60.00	✓
5	Front Door Visor - RH <i>new</i>	1	\$ 65.00	✓
6	Rear Door Black Tape - RH <i>new</i>	1	\$ 60.00	✓
7	Rear Door Visor - RH <i>new</i>	1	\$ 65.00	✓
8	Rocker Panel Outer Board <i>lot</i>	1	\$ 580.00	✓
9	Rocker Panel Outer Board Top Chrome <i>lot</i>	1	\$ 350.00	✓
10	Rear Wheel Rim - RH <i>lot</i>	1	\$ 680.00	550
11	Rear Tyre - RH <i>new</i>	1	\$ 250.00	220
12	Rear Wheel Rim - LH <i>lot</i>	1	\$ 680.00	550
13	Rear Tyre - LH <i>new</i>	1	\$ 250.00	+
14	Rear Door Black Tape - LH <i>new</i>	1	\$ 60.00	✓
15	Rear Door Visor - LH <i>new</i>	1	\$ 65.00	✓
16	Front Door Visor - LH <i>new</i>	1	\$ 65.00	✓
17	Front Door Black Tape - LH <i>new</i>	1	\$ 60.00	✓
18	Front Windscreen Sealant <i>new</i>	1	\$ 60.00	✓
19	Front Windscreen Solar Film	1	\$ 250.00	✓
20	Tailgate Top Spoiler <i>new</i>	1	\$ 800.00	+
21	Front Driver Seat <i>new</i>	1	\$ 1,500.00	150
22	Front Passenger Seat <i>new</i>	1	\$ 1,500.00	150
Total Parts			<u>\$ 69,344.96</u>	

LABOUR CHARGE

1	To knocking & pull out front & rear portion & renew above parts	\$ 4,200.00	3200
---	---	-------------	------

RE : ESTIMATE FOR ACCIDENT REPAIR SLA1736G (Honda Vezel)

2	To putty & spray up paint works	\$	3,200.00 2500
3	To check wiring	\$	200.00 100
4	To underseal	\$	380.00 250
5	To transfer front LH & RH door fittings	\$	300.00 160
6	To transfer rear LH & RH door fittings	\$	300.00 160
7	To remove roof upholstery	\$	280.00 200
8	To remove cabin upholstery	\$	350.00 200
9	To remove front windscreen	\$	180.00 120
10	To remove fuel tank	\$	150.00 80
11	To remove front & rear LH & RH seat	\$	450.00 350
12	To remove front LH & RH undercarriage	\$	650.00 500
13	To remove rear undercarriage	\$	450.00 300
14	To remove roof and seat air bags	\$	600.00 400
15	To reset air bag configuration	\$	280.00 120
16	To perform wheel alignment	\$	150.00 80
17	To remove engine block	\$	400.00 300
18	To dismantle and overhaul engine block	\$	10130 500.00 X
19	To crane up and towing fees	\$	150.00 ✓
20	To skim cylinder head and perform top overhaul	\$	680.00 280
21	To dismantle, replace and general overhaul of engine components	\$	1,950.00 680

Total Labour \$ 15,800.00

Grand Total \$ 75,144.96

LKK Auto Consultants hence notify the Repairs of the following:
GST Will be reflected in the final bills
 • To resurvey before/after repairs
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total : 52795.04


1/5 42k

42 days

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9571F
Vehicle Details	
Vehicle No.:	SLA1736G
Vehicle to be Exported:	Yes
Intended De-registration Date:	28 Dec 2017
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	L15B4029298
Chassis No.:	RU11109296
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,063.00
Original Registration Date:	24 Feb 2016
First Registration Date:	24 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$9,063.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Feb 2026
PARF Rebate Amount:	\$6,797.00
Intended COE Rebate Details	
COE Expiry Date:	23 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,002.00
COE Rebate Amount:	\$36,001.00
Total Rebate Amount:	\$42,798.00

The information contained herein is correct as at 28 Dec 2017



Username / Email Add
password
Connect Sign Up New Account
Forgot Password

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2016 Mercedes B180 At Only 119800 Or Nearest Offer!



Fixed To Sell, Agent Warranty,
 Excellent Condition High Low
 Price!! Welcome!
 Straits Drive

PRIME MOTOR & LEASING
 KONG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES
 With over 200 units of vehicles
 to choose from, ranging from
 all European to Japanese Makes.

Browse by Category

< Back (1 2) Next >

Sort by Date Posted 20 results/page

34 vehicles

Vezel

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Vezel	Any	Any	2016	Any	Any	Any	Available



Honda Vezel 1.5A S

\$86,800

\$9,830 /yr

15-Jan-2016

1,496 cc

33,958 km

SUV

Available

Popular Honda Vezel SUV With 1.5L Engine Providing Adequate Power For Your Daily Drive! Compact Exterior Give You The Ability To Squeeze Through Tight Urban Confines, Yet Giving You The Sense Of Roomi...

Select By Performance Premium Selection

Posted: 28-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

Details



Honda Vezel 1.5A X

\$88,800

\$10,410 /yr

21-Jan-2016

1,496 cc

35,000 km

SUV

Available

1 Owner, Extremely Well Maintained And Regularly Service, Excellent Fuel Consumption Making This One Of The Most Popular Cars On The Market. Call Our Friendly Salesman Now To Book And Appointment Befo...

Hui Hua Credit Pte Ltd

Posted: 04-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

Details



Honda Vezel 1.5A X

\$85,000

\$9,960 /yr

22-Jan-2016

1,496 cc

27,650 km

SUV

Available

Not Your Average Vezel, Owner Upgraded Sound System, Rims, LTA Approved Exhaust, Only One Owner, Low Mileage, Everything In The Car Is Brand New, Owner Used It To Travel To Work Only, Very Fuel Econom...

Prem Roy Motoring

Posted: 12-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

Details



Honda Vezel 1.5A X

\$96,800

\$10,600 /yr

07-Mar-2016

1,496 cc

-

SUV

Available

Honda Vezel, YOM 2015 Upgraded Version With Aircon Ionizer, Best Selling SUV. Colour Of Your Choice, Pioneer DVD Player, USB, Reverse Sensor And Camera, Leather Seat, 16" Rims, Auto H.

Posted: 18-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

Details

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Buy Types Online
 Latest Special Offers from Tempus



Honda Vezel 1.5A X

\$84,800

\$9,750 /yr

09-Mar-2016

1,496 cc

22,000 km

SUV

Available

1 Owner. Selling Cheap. Private Usage. Like Brand New Showroom Condition. Meticulously Well Maintained By Previous Owner. Excellent Fuel Efficiency With Easy Maintenance And Good Safety Features Like ...

Posted: 22-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

Details



Honda Vezel 1.5A X

\$83,800

\$9,650 /yr

14-Mar-2016

1,496 cc

33,000 km

SUV

Available

One Lady Owner, Warranty Till Mar 2019, Battery And Recalled Part Replaced Few Days Ago. View To Believe. Flexible Loan Packages Available. Viewing Strictly By Appointment Only.

Car Search

Posted: 28-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

Details



Honda Vezel 1.5A X

\$86,800

\$9,950 /yr

21-Mar-2016

1,496 cc

24,862 km

SUV

Available

1 Careful Owner. Immaculate Condition. View To Appreciate. Recalled BBC Changed With Proof. Up To 90% Loan Package Available. High Approval Rate. Accident Free. No Repairs Needed. Still Under Warranty...

Posted: 14-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

Details



Honda Vezel 1.5A S **\$89,888** **\$9,960 /yr** **30-Mar-2016** **1,496 cc** **14,000 km** **SUV** **Available**

Viewing Strictly By Appointment Only. Hardly Used With Very Low Mileage Clocked At 14000km.

Posted: 10-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

[Details](#)



Honda Vezel 1.5A X **\$85,800** **\$9,640 /yr** **22-Apr-2016** **1,496 cc** **-** **SUV** **Available**

Elegant SUV, Almost Brand New, One Owner Only, Low Mileage, Very Well Maintained, Only \$8,880 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Ar...

Classic Credit Pte Ltd

Posted: 11-Nov-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

[Details](#)



Honda Vezel 1.5A S **\$89,666** **\$9,800 /yr** **10-May-2016** **1,496 cc** **12,000 km** **SUV** **Available**

Beautiful Black Unit With Original Contrasting Gunmetal Grey Lower Body Cladding. Under Warranty From Authorized Workshop Until 09/05/2019. Regularly Serviced. Super Low Mileage. Accident Free. Coated...

Posted: 02-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

[Details](#)



Honda Vezel Hybrid 1.5A X **\$89,800** **\$10,420 /yr** **13-May-2016** **1,496 cc** **21,000 km** **SUV** **Available**

Fuel Type: Petrol-Electric

1st Careful Lady Owner, Guarantee Not From Rental Car, No Repair Needed, Well Maintained By Owner, Wear And Tear All Replaced, 100% Accident Free, One Of The Best Condition In The Market. We Provide E...

Posted: 23-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

[Details](#)



Honda Vezel 1.5A S **\$93,888** **\$10,220 /yr** **13-May-2016** **1,496 cc** **-** **SUV** **Available**

10% Down Payment, 10 Years Loan Available!

Posted: 08-Nov-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

[Details](#)



Honda Vezel 1.5A X **\$96,800** **\$10,910 /yr** **27-May-2016** **1,496 cc** **7,469 km** **SUV** **Available**

1 Owner Only! As Good As Brand New! Extended Warranty Available! Fancy A Stylish Designed Compact Crossover? Engineered To Give You Excellent Fuel Efficiency Yet Comes With Spacious Cabin For Your Com...

Dickson Automobile

Posted: 20-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

[Details](#)



Honda Vezel 1.5A X **\$85,500** **\$9,500 /yr** **01-Jun-2016** **1,496 cc** **30,000 km** **SUV** **Available**

1 Owner Only! As Good As Brand New! Buy It From Us With A Peace Of Mind. Always Parked Under Shelter. Fuel Economic. Viewings And Test Drives Are Strictly By Appointment Only. Up To 80% Loan And Trade...

Master Motors Pte Ltd

Posted: 25-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

[Details](#)



Honda Vezel 1.5A X **\$87,800** **\$9,750 /yr** **21-Jun-2016** **1,496 cc** **10,582 km** **SUV** **Available**

*Free: New Leather Seats: Choice Of Colours Available! * New Arrival, 1 Careful Owner. Almost Brand New Condition. Super Low Mileage Done At 19K KM. Non Smoker Owner, 100% Accident Free. Minimal Mainte...

Posted: 23-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

[Details](#)



Honda Vezel 1.5A X **\$86,999** **\$9,640 /yr** **23-Jun-2016** **1,496 cc** **-** **SUV** **Available**

Sporty Black SUV, One Careful Owner, Low Mileage, As Good As New, 100% Accident Free Which Can Be Supported By STA Evaluation, Flexible Loan, Bank/In House Loan Available.

Posted: 23-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

[Details](#)



Honda Vezel 1.5A X **\$88,800** **\$9,790 /yr** **05-Jul-2016** **1,496 cc** **30,000 km** **SUV** **Available**

This Unit Is Still Under 3 Years Warranty From Hitachi Capital, Comes With HU With Bluetooth, Solar Film, Reverse Camera, Tonneau Cover, Well Maintained, Loan Available, Trade In Welcome, Price Negotia...

Posted: 22-Nov-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

[Details](#)



Honda Vezel 1.5A X **\$88,000** **\$9,770 /yr** **15-Jul-2016** **1,496 cc** **-** **SUV** **Available**

Elegant Black SUV, One Owner Only, Comes With Warranty, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 16-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

[Details](#)



Honda Vezel 1.5A X **\$98,888** **\$10,940 /yr** **22-Jul-2016** **1,496 cc** **50 km** **SUV** **Available**

2016 New Facelift Honda Vezel! 80% 10Years Loan Available! Package With Pioneer DVD AVH-X8850BT, In Car Cam, Reverse Sensor, Reverse Camera, Full Leather And Many More!

JOM Cars

Posted: 29-Dec-2017 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda, Vezel, Vezel, Used Honda

[Details](#)

Vic (LKKAUTO)

From: Kesaval, Jaclyn-M <Jaclyn-M.Kesaval@aig.com>
Sent: Tuesday, 31 July, 2018 8:51 AM
To: Vic (LKKAUTO)
Cc: Admin A
Subject: RE: <SEEK MANDATE> Your Ref: 4519319696SG_ACCIDENT INVOLVING VEHICLES SLG 9907X (OI) AND SLA 1736G (TP) ON 22/12/2017

Dear Vic,

We refer to the above matter.

Kindly let us have the following clarifications:-

Pictures showing damage to the following:-

Bonnet lock jammed at time of 1st inspection -
BONNET LOCK LH 133-135 RH 143-144.
FRONT MUDFLAP
FRONT DOOR INNER TRIM BOARD -RH 215-219.
SET FRONT DOOR INNER TRIM BOARD CLIPS -RH NCL.
FRONT DOOR GLASS REGULATOR GEAR -RH 207-210.
FRONT DOOR GLASS CHANNEL -RH 2 211-212.
FRONT DOOR GLASS CHANNEL RUBBER -RH 1.
SET CENTRE PILLAR LOWER GARNISH CLIPS } NCL.
SET CENTRE PILLAR UPPER GARNISH CLIPS
REAR DOOR INNER TRIM BOARD -RH 203-205.
SET REAR DOOR INNER TRIM BOARD CLIPS -RH NCL.
REAR DOOR GLASS CHANNEL -RH 2 201-202.
REAR DOOR GLASS CHANNEL RUBBER -RH
REAR DOOR GLASS REGULATOR GEAR -RH 188-192.
REAR DOOR HINGE -RH 102-103.
REAR FENDER INNER TRIM BOARD -RH 237-240.
SET REAR FENDER INNER TRIM BOARD CLIPS -RH } NCL.
SET REAR FENDER INNER TRIM BOARD (UPPER) CLIPS -RH
REAR MUDFLAP -RH 8.
SET REAR FENDER INNER SHIELD CLIPS -LH NCL.
REAR FENDER INNER TRIM BOARD -LH 233-236.
SET REAR FENDER INNER TRIM BOARD CLIPS -LH } NCL.
SET REAR FENDER INNER TRIM BOARD (UPPER) CLIPS -LH
REAR MUDFLAP -LH 140.
FRONT LH DOOR HANDLE RH LH Door Handle 122-125.
REAR DOOR WEATHERSTRIP -LH No Photo.
REAR DOOR GLASS REGULATOR GEAR -LH 223-225.
REAR DOOR GLASS CHANNEL -LH } 226-227.
REAR DOOR GLASS CHANNEL RUBBER -LH
REAR DOOR INNER TRIM BOARD -LH 228-231.
FRONT DOOR -LH 130-135, 158-62.
ROOF PANEL CENTRE REINFORCEMENT 174-175, 58-62.
REAR WHEEL HUB C/W BEARING 330-331.
STEERING RACK AND PINION 300-308.
EXHAUST VALVE } 312-320.
INLET VALVE
FRONT DOR SPEAKER -RH 204-205.

Also let us have the diagnostic report and alignment report for our review.

Thank you.

Jaclyn M K

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1953 | Fax +(65) 6835 7416

Jaclyn-M.Kesaval@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Vic (LKKAuto) [<mailto:vicalpeh@lkkauto.com>]

Sent: Friday, July 20, 2018 9:39 AM

To: Kesaval, Jaclyn-M

Cc: Admin A; Vic (LKKAuto)

Subject: RE: <SEEK MANDATE> Your Ref: 4519319696SG_ACCIDENT INVOLVING VEHICLES SLG 9907X (OI) AND SLA 1736G (TP) ON 22/12/2017

Dear Jaclyn,

We refer to your below email.

Please find attached documents as requested.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

REPAIR DETAILS

Recommended Parts

SLA 1736G

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	985.40 FL	*985.40 FL
2	1		*BONNET LOCK	Damaged	128.00 FL	*128.00 FL
3	2		*BONNET HINGE	Not Necessary	138.20 FL	*- FL
4	2		*HEADLAMP	Cut	3,569.00 FL	*3,569.00 FL
5	1		*FRONT BUMPER	Repair	880.00 FL	*- FL
6	1		*SET FRONT BUMPER CLIPS	Not Necessary	30.00 FL	*- FL
7	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	50.60 FL	*- FL
8	1		*FRONT FENDER	O/S Dented	1,117.40 FL	*558.70 FL
9	2		*FRONT FENDER ARC GARNISH	Cut	310.60 FL	*310.60 FL
10	2		*SETS FRONT FENDER ARC GARNISH CLIPS	Necessary	40.00 FL	*40.00 FL
11	2		*FRONT MUDFLAP	N/S Deformed / O/S Cut	120.80 FL	*120.80 FL
12	1		*FRONT DOOR -RH	Distorted	989.50 FL	*989.50 FL
13	1		*FRONT DOOR LOCK -RH	Damaged	278.20 FL	*278.20 FL
14	1		*FRONT DOOR WEATHERSTRIP -RH	Cut	133.90 FL	*133.90 FL
15	1		*FRONT DOOR OUTER HANDLE -RH	Cut	220.40 FL	*220.40 FL
16	1		*FRONT DOOR WING MIRROR -RH	Distorted	723.90 FL	*723.90 FL
17	1		*FRONT DOOR INNER TRIM BOARD -RH	Deformed	585.20 FL	*585.20 FL
18	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS -RH	Necessary	30.00 FL	*30.00 FL
19	1		*FRONT DOOR GLASS -RH	Shattered	389.60 FL	*389.60 FL
20	1		*FRONT DOOR GLASS OUTER MOULDING-RH	Cut	68.50 FL	*68.50 FL
21	1		*FRONT DOOR GLASS REGULATOR GEAR -RH	Damaged	358.00 FL	*358.00 FL
22	2		*FRONT DOOR HINGE -RH	Not Necessary	150.00 FL	*- FL
23	1		*FRONT DOOR CHECK-RH	Not Necessary	48.00 FL	*- FL
24	1		*FRONT DOOR GLASS CHANNEL -RH	Bent	78.20 FL	*78.20 FL
25	1		*FRONT DOOR GLASS CHANNEL RUBBER -RH	Necessary	105.00 FL	*105.00 FL
26	1		*CENTRE PILLAR -RH	Dented	695.60 FL	*695.60 FL
27	1		*CENTRE PILLAR INNER-RH	Repair	584.20 FL	*- FL
28	1		*CENTRE PILLAR LOWER GARNISH	Not Necessary	158.40 FL	*- FL
29	1		*SET CENTRE PILLAR LOWER GARNISH CLIPS	Necessary	20.00 FL	*20.00 FL
30	1		*CENTRE PILLAR UPPER GARNISH	Not Necessary	104.20 FL	*- FL
31	1		*SET CENTRE PILLAR UPPER GARNISH CLIPS	Necessary	20.00 FL	*20.00 FL
32	1		*REAR DOOR -RH	Distorted	978.40 FL	*978.40 FL
33	1		*REAR DOOR LOCK -RH	Jammed	298.00 FL	*298.00 FL
34	1		*REAR DOOR WEATHERSTRIP -RH	Cut	168.90 FL	*168.90 FL
35	1		*REAR DOOR INNER TRIM BOARD -RH	Deformed	645.10 FL	*645.10 FL
36	1		*SET REAR DOOR INNER TRIM BOARD CLIPS -RH	Necessary	30.00 FL	*30.00 FL
37	1		*REAR DOOR GLASS OUTER MOULDING -RH	Cut	66.40 FL	*66.40 FL
38	1		*REAR DOOR GLASS CHANNEL-RH	Cut	75.10 FL	*75.10 FL
39	1		*REAR DOOR GLASS CHANNEL RUBBER -RH	Necessary	94.10 FL	*94.10 FL
40	1		*REAR DOOR GLASS REGULATOR GEAR-RH	Damaged	358.00 FL	*358.00 FL
41	2		*REAR DOOR HINGE -RH	Bent	150.00 FL	*150.00 FL
42	1		*REAR DOOR CHECK-RH	Damaged	48.00 FL	*48.00 FL
43	1		*ROCKER PANEL-RH	Repair	660.80 FL	*- FL
44	1		*REAR BUMPER	Repair	825.00 FL	*- FL
45	1		*SET REAR BUMPER CLIPS	Not Necessary	30.00 FL	*- FL
46	2		*REAR BUMPER SIDE HOLDER	Not Necessary	52.80 FL	*- FL
47	2		*REAR SIDE BUMPER	Repair	390.00 FL	*- FL
48	1		*TAILLAMP	N/S Cracked	961.20 FL	*480.60 FL
49	1		*TAILLAMP PANEL	N/S Dented	312.40 FL	*156.20 FL
50	1		*REAR FENDER -RH	Distorted	995.00 FL	*995.00 FL
51	1		*REAR FENDER ARC GARNISH -RH	Missing	151.40 FL	*151.40 FL
52	1		*SET REAR FENDER ARC GARNISH CLIPS -RH	Necessary	20.00 FL	*20.00 FL
53	1		*REAR FENDER INNER SHIELD -RH	Deformed	210.40 FL	*210.40 FL
54	1		*SET REAR FENDER INNER SHIELD CLIPS-RH	Necessary	30.00 FL	*30.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*REAR FENDER INNER TRIM BOARD -RH	Deformed	326.00 FL	*326.00 FL
56	1		*SET REAR FENDER INNER TRIM BOARD CLIPS-RH	Necessary	30.00 FL	*30.00 FL
57	1		*REAR FENDER INNER TRIM BOARD (UPPER) -RH	Not Necessary	210.40 FL	*- FL
58	1		*SET REAR FENDER INNER TRIM BOARD (UPPER) CLIPS -RH	Necessary	20.00 FL	*20.00 FL
59	1		*REAR MUDFLAP -RH	Deformed	65.10 FL	*65.10 FL
60	1		*REAR FENDER -LH	Distorted	995.00 FL	*995.00 FL
61	1		*REAR FENDER ARC GARNISH -LH	Cut	151.40 FL	*151.40 FL
62	1		*SET REAR FENDER ARC GARNISH CLIPS-LH	Necessary	20.00 FL	*20.00 FL
63	1		*REAR FENDER INNER SHIELD -LH	Not Necessary	210.40 FL	*- FL
64	1		*SET REAR FENDER INNER SHIELD CLIPS -LH	Necessary	30.00 FL	*30.00 FL
65	1		*REAR FENDER INNER TRIM BOARD -LH	Deformed	326.00 FL	*326.00 FL
66	1		*SET REAR FENDER INNER TRIM BOARD CLIPS -LH	Necessary	30.00 FL	*30.00 FL
67	1		*REAR FENDER INNER TRIM BOARD (UPPER) -LH	Not Necessary	210.40 FL	*- FL
68	1		*SET REAR FENDER INNER TRIM BOARD (UPPER) CLIPS -LH	Necessary	20.00 FL	*20.00 FL
69	1		*REAR FENDER QUARTER GARNISH -LH	Cut	45.40 FL	*45.40 FL
70	1		*FUEL LID	Distorted	90.40 FL	*90.40 FL
71	1		*FUEL LID LOCK	Jammed	35.10 FL	*35.10 FL
72	1		*REAR MUDFLAP -LH	Cut	65.10 FL	*65.10 FL
73	1		*REAR DOOR -LH	Dented	978.40 FL	*978.40 FL
74	1		*REAR DOOR LOCK -LH	Damaged	298.00 FL	*298.00 FL
75	1		*FRONT LH DOOR HANDLE	Cut	220.40 FL	*220.40 FL
76	1		*REAR DOOR WEATHERSTRIP -LH	Cut	168.90 FL	*168.90 FL
77	1		*REAR DOOR OUTER HANDLE -LH	Cut	151.40 FL	*151.40 FL
78	1		*REAR DOOR GLASS OUTER MOULDING -LH	Cut	66.40 FL	*66.40 FL
79	1		*REAR DOOR GLASS REGULATOR GEAR -LH	Damaged	358.00 FL	*358.00 FL
80	1		*REAR DOOR GLASS CHANNEL -LH	Bent	75.10 FL	*75.10 FL
81	1		*REAR DOOR GLASS CHANNEL RUBBER -LH	Necessary	94.10 FL	*94.10 FL
82	1		*REAR DOOR INNER TRIM BOARD -LH	Deformed	645.10 FL	*645.10 FL
83	1		*SET REAR DOOR INNER TRIM BOARD CLIPS -LH	Necessary	30.00 FL	*30.00 FL
84	2		*REAR DOOR HINGE -LH	Not Necessary	150.00 FL	*- FL
85	1		*REAR DOOR CHECK-LH	Not Necessary	48.00 FL	*- FL
86	1		*CENTRE PILLAR -LH	Repair	695.60 FL	*- FL
87	1		*FRONT DOOR -LH	Dented	989.50 FL	*989.50 FL
88	1		*FRONT DOOR LOCK -LH	Not Necessary	278.20 FL	*- FL
89	1		*FRONT DOOR WEATHERSTRIP -LH	Not Necessary	133.90 FL	*- FL
90	1		*FRONT DOOR WING MIRROR -LH	Distorted	723.90 FL	*723.90 FL
91	2		*FRONT DOOR HINGE -LH	Not Necessary	150.00 FL	*- FL
92	1		*FRONT DOOR CHECK -LH	Not Necessary	48.00 FL	*- FL
93	1		*FRONT WINDSCREEN	Shattered	1,345.10 FL	*1,345.10 FL
94	1		*FRONT WINDSCREEN MOULDING	Necessary	132.00 FL	*132.00 FL
95	2		*FRONT WINDSCREEN PILLAR	Dented	797.00 FL	*797.00 FL
96	2		*FRONT WINDSCREEN PILLAR INNER TRIM	Not Necessary	204.80 FL	*- FL
97	2		*SETS FRONT WINDSCREEN PILLAR INNER TRIM CLIPS	Necessary	40.00 FL	*40.00 FL
98	1		*DOOR FRAME	N/S Dented	1,570.00 FL	*785.00 FL
99	1		*ROOF PANEL	Distorted	1,650.00 FL	*1,650.00 FL
100	1		*ROOF PANEL FRONT REINFORCEMENT	Bent	420.00 FL	*420.00 FL
101	1		*ROOF PANEL CENTRE REINFORCEMENT	Bent	395.00 FL	*395.00 FL
102	2		*ROOF PANEL TOP MOULDING	Cut	276.00 FL	*276.00 FL
103	2		*SETS ROOF PANEL TOP MOULDING CLIPS	Necessary	60.00 FL	*60.00 FL
104	1		*ROOF PANEL INNER TRIM BOARD	Crumpled	825.90 FL	*825.90 FL
105	1		*SET ROOF PANEL INNER TRIM BOARD CLIPS	Necessary	100.00 FL	*100.00 FL
106	2		*ROOF PANEL SIDE AIR BAG	Activated	2,100.40 FL	*2,100.40 FL
107	2		*ROOF PANEL SIDE AIR BAG SENSOR	Activated	278.00 FL	*278.00 FL
108	1		*FRONT DRIVER SEAT AIR BAG	Activated	785.90 FL	*785.90 FL
109	1		*FRONT DRIVER SEAT AIR BAG SENSOR	Activated	139.00 FL	*139.00 FL
110	1		*FRONT PASSENGER SEAL AIR BAG	Activated	785.90 FL	*785.90 FL
111	1		*FRONT PASSENGER SEAL AIR BAG SENSOR	Activated	139.00 FL	*139.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
112	1		*AIR BAG ECU	Activated	1,092.00 FL	*1,092.00 FL
113	2		*FRONT SEAT BELT	Activated	1,330.00 FL	*1,330.00 FL
114	1		*REAR SHOCK ABSORBER	O/S Bent	660.00 FL	*330.00 FL
115	1		*REAR AXLE BEAM	Bent	1,513.00 FL	*1,513.00 FL
116	2		*REAR WHEEL HUB C/W BEARING	Necessary	774.40 FL	*774.40 FL
117	2		*FRONT LOWER ARM	Bent	732.40 FL	*732.40 FL
118	2		*FRONT SHOCK ABSORBER	Bent	990.00 FL	*990.00 FL
119	2		*FRONT KNUCKLE ARM	Bent	781.00 FL	*781.00 FL
120	2		*FRONT WHEEL HUB C/W BEARING	Necessary	690.00 FL	*690.00 FL
121	1		*STEERING RACK AND PINION	Bent	1,178.40 FL	*1,178.40 FL
122	4		*ENGINE PISTON	Damaged	1,400.00 FL	*1,400.00 FL
123	4		*ENGINE CON ROD	Bent	1,180.00 FL	*1,180.00 FL
124	1		*ENGINE CON ROD BEARING	Necessary	220.00 FL	*220.00 FL
125	1		*ENGINE MAIN BEARING	Necessary	260.00 FL	*260.00 FL
126	2		*TOP TIRNING GEAR	Not Necessary	780.00 FL	*- FL
127	1		*TIMING CHAIN	Not Necessary	225.00 FL	*- FL
128	8		*EXHAUST VALVE	Damaged	552.00 FL	*552.00 FL
129	8		*INLET VALVE	Damaged	576.00 FL	*576.00 FL
130	1		*CRANKSHAFT	Not Necessary	2,460.00 FL	*- FL
131	2		*CAMSHAFT	Not Necessary	2,800.00 FL	*- FL
132	1		*OVERHAUL GASKET	Necessary	650.00 FL	*450.00 FL
133	1		*FLYWHEEL OIL SEAL	Necessary	48.00 FL	*48.00 FL
134	1		*TIMING TESIONER	Not Necessary	195.00 FL	*- FL
135	2		*FRONT WHEEL RIM	Cut	1,360.00 FS	*1,100.00 FS
136	1		*FRONT DOOR GLASS SOLAR FILM -RH	Necessary	180.00 FS	*180.00 FS
137	1		*FRONT DOR SPEAKER -RH	Damaged	200.00 FS	*150.00 FS
138	1		*FRONT DOOR BLACK TAPE-RH	Necessary	60.00 FS	*60.00 FS
139	1		*FRONT DOOR VISOR -RH	Necessary	65.00 FS	*65.00 FS
140	1		*REAR DOOR BLACK TAPE-RH	Necessary	60.00 FS	*60.00 FS
141	1		*REAR DOOR VISOR -RH	Necessary	65.00 FS	*65.00 FS
142	1		*ROCKER PANEL OUTER BOARD	Cut	580.00 FS	*580.00 FS
143	1		*ROCKER PANEL OUTER BOARD TOP CHROME	Cut	350.00 FS	*350.00 FS
144	1		*REAR WHEEL RIM -RH	Cut	680.00 FS	*550.00 FS
145	1		*REAR TYRE-RH	Punctured	250.00 FS	*220.00 FS
146	1		*REAR WHEEL RIM -LH	Cut	680.00 FS	*550.00 FS
147	1		*REAR TYRE -LH	Not Necessary	250.00 FS	*- FS
148	1		*REAR DOOR BLACK TAPE-LH	Necessary	60.00 FS	*60.00 FS
149	1		*REAR DOOR VISOR -LH	Necessary	65.00 FS	*65.00 FS
150	1		*FRONT DOOR VISOR-LH	Necessary	65.00 FS	*65.00 FS
151	1		*FRONT FOOR BLACK TAPE-LH	Necessary	60.00 FS	*60.00 FS
152	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
153	1		*FRONT WINDSCREEN SOLAR FILM	Necessary	250.00 FS	*250.00 FS
154	1		*TAILGATE TOP SPOILER	Repair	800.00 FS	*- FS
155	1		*FRONT DRIVE SEAT	Necessary	1,500.00 FS	*150.00 FS
156	1		*FRONT PASSENGER SEAT	Necessary	1,500.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	72,116.60	52,354.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	12,595.32	9,512.84
Total Parts (\$\$)	59,521.28	42,841.36

Report was unsubmitted during this print-out.

Print Received Message

This mail is associated with :

***SLA1736G (4519319696SG)
[SLG9907X]**

TP

ONG SOON LEONG

Dec 22 2017 11:00AM

[DAIMLER SOUTH EAST ASIA PTE. LTD]

Modern Automotive Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 11/07/2019 17:04 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$42000.00) - SLA1736G - Claim Handler: Kesaval, Jaclyn-M

Approved:42000.00:Pls do your utmost to negotiate settlement not exceeding: \$42k (All-in).

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6745-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

Your Ref : SLG9907X

Our Ref : SLA1736G

Date : 04.05.2018

The Claims Manager

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78, Shenton Way #07-16

Singapore 079120

Tel : 6-419-300 Fax : 6-415-3727

Attn : The Motor Claim Dept

RE : ACCIDENT INVOLVING SLA1736G & SLG9907X ON 22.12.2017
ALONG BUKIT BATOK ST 23 TWDS BUKIT BATOK ST 25

We refer to the above matter.

We have been authorized by our client Mr Ong Soon Leong to make claim against your insured vehicle No. SLG9907X in respect of the above accident for the following :

Repair Cost	\$ 44,940.00	(Incl GST)
Loss of use (\$100 x 50 days)	\$ 5,000.00	(42 repair days, 1 PH, 7 Sundays)
Loss of PRI (\$100 x 5 days)	\$ 500.00	(23/12/2017 to 27/12/2017)
Search fee	\$ 7.49	
Medical fee	\$ 114.00	(Ong Soon Leong)
Total :	\$ 50,561.49	

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap

Yours faithfully


Modern Automotive Pte Ltd

Vic (LKKAUTO)

From: Kesaval, Jaclyn-M <Jaclyn-M.Kesaval@aig.com>
Sent: Monday, 14 January, 2019 11:49 AM
To: Vic (LKKAUTO)
Cc: Admin A
Subject: RE: <SEEK MANDATE> Your Ref: 4519319696SG_ACCIDENT INVOLVING VEHICLES SLG 9907X (OI) AND SLA 1736G (TP) ON 22/12/2017 LKK REF CC6/AIG17024710/Ahb3

Hi Vic,

We refer to the above matter.

Kindly assist to provide the breakdown of the recommended 42 days for repair.

Thank you.

Kind regards,
Jaclyn

Jaclyn M K
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1953

Jaclyn-M.Kesaval@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

Panel Bending 16 Days.
Spray Painting 05 Days.
Wiring Work 02 Days.
Upholstery Work 04 Days.

Front, Rear Windscreen 01

Undercarriage (Front, Rear) 04 Days.

Air Bag, Seat Belt 04 Days.

Engine Work 04 Days. 1/42 Days

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]

Sent: Friday, January 11, 2019 3:33 PM

To: Kesaval, Jaclyn-M

Cc: Admin A; Vic (LKKAUTO)

Subject: RE: <SEEK MANDATE> Your Ref: 4519319696SG_ACCIDENT INVOLVING VEHICLES SLG 9907X (OI) AND SLA 1736G (TP) ON 22/12/2017 LKK REF CC6/AIG17024710/Ahb3

Dear Jaclyn,

We refer to your below email.

Please be informed that mandate request is up in merimen.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG17024710/Ahs3

05 JANUARY 2018

DAIMLER SOUTH EAST ASIA PTE.LTD
1 GATEWAY DRIVE (WEST GATE TOWER)
#15-01
SINGAPORE 608531

Dear Sir/Madam,

ACCIDENT INVOLVING SLG 9907X AND SLA 1736G ON 22.12.17

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Siti

Case Handler

DID: 6256 3561

FAX: 6741 4108

Email: vicalpeh@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

LETTER OF AUTHORIZATION

Date: 26/12/17

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

..... SLA1736G & SLG9907X

ON 22/12/17 ALONG Bukit Batok St 23

..... twds Bukit Batok St 25

This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully



.....
Signature of Owner

..... Ong Soon Leong S1849571/F

Name / NRIC

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, MODERN AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$41,000.00 (Global Sum – all in) for vehicle no. SLA 1736G that was damaged pursuant to the accident which occurred on 22/12/2017 (date) along BUKIT BATOK STREET 23 (location) involving vehicle no/s SLG907X. This is pursuant to the inspection conducted on 28/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ONG SOON LEONG ("the third party claimant") of vehicle no. SLA 1736G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLA 1736G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 16 (day) of July (month) 2019 (year)



LWP

Signed by appointed surveyor



Signed by "the workshop" (with chop)

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1# 01-58/61 SINGAPORE 408717

TEL : 67474422, 67454422 FAX : 67476720

GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
SINGAPORE 079120

Attention : Motor Claim Department

Contact : 6415-3727 6419-3000

Tax Invoice : TP001182

Date : 02/05/2018

Vehicle Num. : SLA 1736G

Make/Model : HONDA VEZEL-2016

Chassis/Eng# : RU11109296/L15B4029298

Accident Date : 22/12/2017

Claim No. :

Reference :

Policy No. : 5077811490-01

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		ACCIDENT REPAIR (LUMPSUM)		42,000.00
		Labour Total S\$:		42,000.00

Total S\$: 42,000.00
GST @ 7% S\$: 2,940.00
Amount Due S\$: 44,940.00
=====



MODERN AUTOMOTIVE PTE LTD

Thank you



Minder Kaur has successfully logged out.

Your last login date and time was 26 Dec 2017, 16:11:46.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

<u>S/No</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SLG9907X	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	26 Dec 2017 / 16:12:56

Enquire Vehicle & Owner Information (Vehicle No. SLG9907X As At 22 Dec 2017 / 11:15:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: MODERN AUTOMOTIVE

Current Owner Details

Owner ID Type: Company
Owner ID: 199000355E
Owner Name: DAIMLER SOUTH EAST ASIA PTE LTD
Registered Address Type: Private Residential (non-Condo Apt / non-House)
Registered Block/House No.: 1
Registered Street Name: GATEWAY DRIVE
Registered Unit No.: # 15 - 01
Registered Building Name: WESTGATE TOWER
Registered Postal Code: 608531

Current Vehicle Details

Vehicle No.: SLG9907X
Make Description/Model: MERCEDES BENZ / CLA180 COUPE URBAN (R18 LED)
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.



TAX INVOICE

TO:
MR. ONG SOON LEONG
BLK 415 #03-34
SAUJANA ROAD
SINGAPORE 670415

MRN/NRIC : S1849571F
BILL NO : 12095666C
BILL DATE : 22.12.2017
VISIT DATE : 22.12.2017
TYPE OF SUPPLY : CASH/CREDIT
GST REG NO : 200910555Z

PATIENT NAME: ONG SOON LEONG

PLEASE PAY UPON RECEIPT OF THIS INVOICE

SERVICES	AMOUNT PAYABLE (\$)
Case No : 9218091969F Specialty / Class : Accident & Emergency / NA	
A&E Attendance Fee	114.00
Paracetamol 500MG Tablet	2.00
Ketoprofen 2.5% Gel (Fastum)	2.70
Total Charges	118.70
Less: Government Subsidy	4.70-
Add: 7% GST	7.98
Less: GST Absorbed	7.98-
Amount Payable	114.00

Payer(s) Summary					
Payable By	Payable Amt (\$)	Payment Amt (\$)	Adjustment (\$)	Amount Due (\$)	Policy No
Total Bill Amount	114.00				
ONG SOON LEONG	114.00	114.00-	0.00	0.00	

Amount to be paid: \$0.00

Receipt Information

22.12.2017 Receipt No: J000619787 \$114.00 (CASH)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2017 Edit Reg		28 Dec 2017 00:00 Edit Adj Rpt	\$42,000.00 Edit Estimates	\$42,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	DAIMLER SOUTH EAST ASIA PTE. LTD. , Co. Reg. No.: 199000355E								
Main Claimant:	ONG SOON LEONG , ID: S1849571F								
Vehicle Reg. No.:	SLA1736G	Date of Loss:	22/12/2017 11:00 - :59 [21 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4519319696SG	Policy/Cover Note No.:	0999995190 (Comprehensive) Coverage: 01/01/2017 - 31/12/2017						
Vehicle Reg. No. (Insured):	SLG9907X	Policy No. (Claimant):	5077811490-01						
		Excess:							
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by VIC ALPEH] ... [Final Rpt due 10/01/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (11/07/2019): Alert - Adj Mandate Approved (\$42000.00) - SLA1736G - Claim Handler: Kesaval, J... - AIG_SG_EXPRESS (24/08/2018): Alert - Adj Mandate Maintained - SLA1736G - Claim Handler: Kesaval, Jaclyn-M									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLA1736G (4519319696SG)
[SLG9907X]
TP
ONG SOON LEONG
Dec 22 2017 11:00AM
[DAIMLER SOUTH EAST ASIA PTE. LTD]
Modern Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page ☐	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	
Assessment Reports			1 per page ☐	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	02/01/18 14:23	Accident Statement Prom:OD - Reg. No: SLG9907X, Claimant: DAIMLER SOUTH EAST ASIA PTE. LTD	 Load HTML	
Photos/Images			3 per page ☐	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/05/18 16:13	General View	 Load JPG	☒
2	03/05/18 16:13	General View	 Load JPG	☒
3	03/05/18 16:13	General View	 Load JPG	☒
4	03/05/18 16:13	General View	 Load JPG	☒
5	03/05/18 16:13	General View	 Load JPG	☒
6	03/05/18 16:13	General View	 Load JPG	☒
7	03/05/18 16:13	General View	 Load JPG	☒
8	03/05/18 16:13	General View	 Load JPG	☒
9	03/05/18 16:13	General View	 Load JPG	☒
10	03/05/18 16:13	General View	 Load JPG	☒
11	03/05/18 16:13	General View	 Load JPG	☒
12	03/05/18 16:13	General View	 Load JPG	☒
13	03/05/18 16:13	General View	 Load JPG	☒
14	03/05/18 16:13	General View	 Load JPG	☒
15	03/05/18 16:13	General View	 Load JPG	☒
16	03/05/18 16:13	General View	 Load JPG	☒
17	03/05/18 16:13	General View	 Load JPG	☒
18	03/05/18 16:13	General View	 Load JPG	☒
19	03/05/18 16:13	General View	 Load JPG	☒
20	03/05/18 16:13	General View	 Load JPG	☒
21	03/05/18 16:13	General View	 Load JPG	☒
22	03/05/18 16:13	General View	 Load JPG	☒
23	03/05/18 16:13	General View	 Load JPG	☒
24	03/05/18 16:13	General View	 Load JPG	☒
25	03/05/18 16:13	General View	 Load JPG	☒
26	03/05/18 16:13	General View	 Load JPG	☒
27	03/05/18 16:13	General View	 Load JPG	☒
28	03/05/18 16:13	General View	 Load JPG	☒
29	03/05/18 16:13	General View	 Load JPG	☒
30	03/05/18 16:13	General View	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	03/05/18 16:13	General View	 Load JPG	☒
32	03/05/18 16:13	General View	 Load JPG	☒
33	03/05/18 16:13	General View	 Load JPG	☒
34	03/05/18 16:13	General View	 Load JPG	☒
35	03/05/18 16:13	General View	 Load JPG	☒
36	03/05/18 16:13	General View	 Load JPG	☒
37	03/05/18 16:13	General View	 Load JPG	☒
38	03/05/18 16:13	General View	 Load JPG	☒
39	03/05/18 16:13	General View	 Load JPG	☒
40	03/05/18 16:13	General View	 Load JPG	☒
41	03/05/18 16:13	General View	 Load JPG	☒
42	03/05/18 16:13	General View	 Load JPG	☒
43	03/05/18 16:13	General View	 Load JPG	☒
44	03/05/18 16:13	General View	 Load JPG	☒
45	03/05/18 16:13	General View	 Load JPG	☒
46	03/05/18 16:13	General View	 Load JPG	☒
47	03/05/18 16:13	General View	 Load JPG	☒
48	03/05/18 16:13	General View	 Load JPG	☒
49	03/05/18 16:13	General View	 Load JPG	☒
50	03/05/18 16:13	General View	 Load JPG	☒
51	03/05/18 16:13	General View	 Load JPG	☒
52	03/05/18 16:13	General View	 Load JPG	☒
53	03/05/18 16:13	General View	 Load JPG	☒
54	03/05/18 16:13	General View	 Load JPG	☒
55	03/05/18 16:13	General View	 Load JPG	☒
56	03/05/18 16:13	General View	 Load JPG	☒
57	03/05/18 16:13	General View	 Load JPG	☒
58	03/05/18 16:13	General View	 Load JPG	☒
59	03/05/18 16:13	General View	 Load JPG	☒
60	03/05/18 16:13	General View	 Load JPG	☒
61	03/05/18 16:13	General View	 Load JPG	☒
62	03/05/18 16:13	General View	 Load JPG	☒
63	03/05/18 16:13	General View	 Load JPG	☒
64	03/05/18 16:13	General View	 Load JPG	☒
65	03/05/18 16:13	General View	 Load JPG	☒
66	03/05/18 16:13	General View	 Load JPG	☒
67	03/05/18 16:13	General View	 Load JPG	☒
68	03/05/18 16:13	General View	 Load JPG	☒
69	03/05/18 16:13	General View	 Load JPG	☒
70	03/05/18 16:13	General View	 Load JPG	☒
71	03/05/18 16:13	General View	 Load JPG	☒
72	03/05/18 16:13	General View	 Load JPG	☒
73	03/05/18 16:13	General View	 Load JPG	☒
74	03/05/18 16:13	General View	 Load JPG	☒
75	03/05/18 16:13	General View	 Load JPG	☒
76	03/05/18 16:13	General View	 Load JPG	☒
77	03/05/18 16:13	General View	 Load JPG	☒
78	03/05/18 16:13	General View	 Load JPG	☒
79	03/05/18 16:13	General View	 Load JPG	☒
80	03/05/18 16:13	General View	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	03/05/18 16:13	General View	 Load JPG	☒
82	03/05/18 16:13	General View	 Load JPG	☒
83	03/05/18 16:13	General View	 Load JPG	☒
84	03/05/18 16:13	General View	 Load JPG	☒
85	03/05/18 16:13	General View	 Load JPG	☒
86	03/05/18 16:13	General View	 Load JPG	☒
87	03/05/18 16:13	General View	 Load JPG	☒
88	03/05/18 16:13	General View	 Load JPG	☒
89	03/05/18 16:13	General View	 Load JPG	☒
90	03/05/18 16:13	General View	 Load JPG	☒
91	03/05/18 16:13	General View	 Load JPG	☒
92	03/05/18 16:13	General View	 Load JPG	☒
93	03/05/18 16:13	General View	 Load JPG	☒
94	03/05/18 16:13	General View	 Load JPG	☒
95	03/05/18 16:13	General View	 Load JPG	☒
96	03/05/18 16:13	General View	 Load JPG	☒
97	03/05/18 16:13	General View	 Load JPG	☒
98	03/05/18 16:13	General View	 Load JPG	☒
99	03/05/18 16:13	General View	 Load JPG	☒
100	03/05/18 16:13	General View	 Load JPG	☒
101	03/05/18 16:13	General View	 Load JPG	☒
102	03/05/18 16:13	General View	 Load JPG	☒
103	03/05/18 16:13	General View	 Load JPG	☒
104	03/05/18 16:13	General View	 Load JPG	☒
105	03/05/18 16:13	General View	 Load JPG	☒
106	03/05/18 16:13	General View	 Load JPG	☒
107	03/05/18 16:13	General View	 Load JPG	☒
108	03/05/18 16:13	General View	 Load JPG	☒
109	03/05/18 16:13	General View	 Load JPG	☒
110	03/05/18 16:13	General View	 Load JPG	☒
111	03/05/18 16:13	General View	 Load JPG	☒
112	03/05/18 16:13	General View	 Load JPG	☒
113	03/05/18 16:13	General View	 Load JPG	☒
114	03/05/18 16:13	General View	 Load JPG	☒
115	03/05/18 16:13	General View	 Load JPG	☒
116	03/05/18 16:13	General View	 Load JPG	☒
117	03/05/18 16:13	General View	 Load JPG	☒
118	03/05/18 16:13	General View	 Load JPG	☒
119	03/05/18 16:13	General View	 Load JPG	☒
120	03/05/18 16:13	General View	 Load JPG	☒
121	03/05/18 16:13	General View	 Load JPG	☒
122	03/05/18 16:13	General View	 Load JPG	☒
123	03/05/18 16:13	General View	 Load JPG	☒
124	03/05/18 16:13	General View	 Load JPG	☒
125	03/05/18 16:13	General View	 Load JPG	☒
126	03/05/18 16:13	General View	 Load JPG	☒
127	03/05/18 16:13	General View	 Load JPG	☒
128	03/05/18 16:13	General View	 Load JPG	☒
129	03/05/18 16:13	General View	 Load JPG	☒
130	03/05/18 16:13	General View	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
131	03/05/18 16:13	General View	 Load JPG	☒
132	03/05/18 16:13	General View	 Load JPG	☒
133	03/05/18 16:13	General View	 Load JPG	☒
134	03/05/18 16:13	General View	 Load JPG	☒
135	03/05/18 16:13	General View	 Load JPG	☒
136	03/05/18 16:13	General View	 Load JPG	☒
137	03/05/18 16:13	General View	 Load JPG	☒
138	03/05/18 16:13	General View	 Load JPG	☒
139	03/05/18 16:13	General View	 Load JPG	☒
140	03/05/18 16:13	General View	 Load JPG	☒
141	03/05/18 16:13	General View	 Load JPG	☒
142	03/05/18 16:13	General View	 Load JPG	☒
143	03/05/18 16:13	General View	 Load JPG	☒
144	03/05/18 16:13	General View	 Load JPG	☒
145	03/05/18 16:13	General View	 Load JPG	☒
146	03/05/18 16:13	General View	 Load JPG	☒
147	03/05/18 16:13	General View	 Load JPG	☒
148	03/05/18 16:13	General View	 Load JPG	☒
149	03/05/18 16:13	General View	 Load JPG	☒
150	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
151	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
152	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
153	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
154	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
155	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
156	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
157	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
158	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
159	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
160	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
161	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
162	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
163	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
164	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
165	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
166	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
167	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
168	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
169	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
170	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
171	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
172	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
173	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
174	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
175	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
176	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
177	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
178	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
179	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
180	03/05/18 16:14	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
181	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
182	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
183	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
184	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
185	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
186	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
187	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
188	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
189	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
190	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
191	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
192	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
193	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
194	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
195	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
196	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
197	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
198	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
199	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
200	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
201	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
202	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
203	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
204	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
205	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
206	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
207	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
208	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
209	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
210	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
211	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
212	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
213	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
214	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
215	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
216	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
217	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
218	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
219	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
220	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
221	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
222	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
223	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
224	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
225	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
226	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
227	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
228	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
229	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
230	03/05/18 16:14	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
231	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
232	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
233	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
234	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
235	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
236	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
237	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
238	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
239	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
240	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
241	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
242	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
243	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
244	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
245	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
246	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
247	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
248	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
249	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
250	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
251	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
252	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
253	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
254	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
255	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
256	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
257	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
258	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
259	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
260	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
261	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
262	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
263	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
264	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
265	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
266	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
267	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
268	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
269	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
270	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
271	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
272	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
273	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
274	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
275	03/05/18 16:14	Reinspection Photo	 Load JPG	☒
276	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
277	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
278	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
279	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
280	03/05/18 16:15	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
281	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
282	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
283	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
284	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
285	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
286	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
287	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
288	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
289	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
290	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
291	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
292	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
293	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
294	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
295	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
296	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
297	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
298	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
299	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
300	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
301	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
302	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
303	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
304	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
305	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
306	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
307	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
308	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
309	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
310	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
311	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
312	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
313	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
314	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
315	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
316	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
317	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
318	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
319	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
320	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
321	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
322	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
323	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
324	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
325	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
326	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
327	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
328	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
329	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
330	03/05/18 16:15	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
331	03/05/18 16:15	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/12/17 16:21	TP GIA REPORT	 Load PDF	
2	05/01/18 11:29	LETTER TO OI	 Load PDF	
3	09/05/18 17:59	TP ESTIMATE - MARKED	 Load PDF	
4	19/07/18 15:15	MEDICAL FEE	 Load PDF	
5	19/07/18 15:15	LTA SEARCH	 Load PDF	
6	20/07/18 09:40	TP MARKET VALUE AND LTA REBATE	 Load PDF	
7	20/07/18 09:41	EMAIL FROM TP	 Load PDF	
8	23/07/19 10:45	WORKSHOP INVOICE	 Load PDF	
9	23/07/19 10:45	AUTHORISATION TO ACT FORM	 Load PDF	
10	23/07/19 10:45	Release Voucher	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLG9907X (Insd veh)	Model:	HONDA VEZEL 1.5 X A (A)
	SLA1736G (TP veh)		
Date of Accident:	22/12/2017		

Global Sum Settlement	:	☒ Yes	☐ No	
Repair Estimate	:	\$		80,593.77
Final Repair Cost	:	\$		41,000.00
Loss of Use	:	\$		50.00 days at \$60.00 per day
Rental (if any)	:	\$		days
LTA / GIA Search Fee	:	\$		
Others: Medical fee	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		41,000.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	: \$	41,000.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

23 Jul
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17024710/AHB3Q2

Date: 23/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995190
Claimant Vehicle No : SLA1736G **Insured Vehicle No :** SLG9907X
Date of Loss: 22/12/2017 **Nature of Claim:** TP **Claim No:** 4519319696SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA1736G**
 Make & Model: HONDA VEZEL, 1.5 X A (A) Engine No: L15B4029298
 Reg. Date: 24/02/2016 (Man. Year: 2015) Chassis No: RU11109296
 Colour: Black Odometer: 0 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	59,521.28	42,841.36	16,679.92	28.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,800.00	10,130.00	5,670.00	35.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	75,321.28	52,971.36	22,349.92	29.67
Approved Total (Overridden) (\$\$)		42,000.00		
(\$\$)	75,321.28	42,000.00	33,321.28	44.24
+ GST 7.00/7.00% (\$\$)	5,272.49	2,940.00	2,332.49	44.24
Nett Amount (\$\$)	80,593.77	44,940.00	35,653.77	44.24
+ Loss of Use (50.0 x S\$60.00/day) (\$\$)		3,000.00		
+ Medical Costs (\$\$)		114.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		48,061.45		
Global Sum Settlement (\$\$)		41,000.00		

INSPECTION

Date of Assignment: 28/12/2017

Date Inspected: 28/12/2017 Inspected At: Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 42.0 days

Adjuster: VIC ALPEH

Manager: ADRIAN LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	985.40 FL	*985.40 FL
2	1		*BONNET LOCK	Damaged	128.00 FL	*128.00 FL
3	2		*BONNET HINGE	Not Necessary	138.20 FL	*- FL
4	2		*HEADLAMP	Cut	3,569.00 FL	*3,569.00 FL
5	1		*FRONT BUMPER	Repair	880.00 FL	*- FL
6	1		*SET FRONT BUMPER CLIPS	Not Necessary	30.00 FL	*- FL
7	2		*FRONT BUMPER SIDE HOLDER	Not Necessary	50.60 FL	*- FL
8	1		*FRONT FENDER	O/S Dented	1,117.40 FL	*558.70 FL
9	2		*FRONT FENDER ARC GARNISH	Cut	310.60 FL	*310.60 FL
10	2		*SETS FRONT FENDER ARC GARNISH CLIPS	Necessary	40.00 FL	*40.00 FL
11	2		*FRONT MUDFLAP	N/S Deformed / O/S Cut	120.80 FL	*120.80 FL
12	1		*FRONT DOOR -RH	Distorted	989.50 FL	*989.50 FL
13	1		*FRONT DOOR LOCK -RH	Damaged	278.20 FL	*278.20 FL
14	1		*FRONT DOOR WEATHERSTRIP -RH	Cut	133.90 FL	*133.90 FL
15	1		*FRONT DOOR OUTER HANDLE -RH	Cut	220.40 FL	*220.40 FL
16	1		*FRONT DOOR WING MIRROR -RH	Distorted	723.90 FL	*723.90 FL
17	1		*FRONT DOOR INNER TRIM BOARD -RH	Deformed	585.20 FL	*585.20 FL
18	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS -RH	Necessary	30.00 FL	*30.00 FL
19	1		*FRONT DOOR GLASS -RH	Shattered	389.60 FL	*389.60 FL
20	1		*FRONT DOOR GLASS OUTER MOULDING-RH	Cut	68.50 FL	*68.50 FL
21	1		*FRONT DOOR GLASS REGULATOR GEAR -RH	Damaged	358.00 FL	*358.00 FL
22	2		*FRONT DOOR HINGE -RH	Not Necessary	150.00 FL	*- FL
23	1		*FRONT DOOR CHECK-RH	Not Necessary	48.00 FL	*- FL
24	1		*FRONT DOOR GLASS CHANNEL -RH	Bent	78.20 FL	*78.20 FL
25	1		*FRONT DOOR GLASS CHANNEL RUBBER -RH	Necessary	105.00 FL	*105.00 FL
26	1		*CENTRE PILLAR -RH	Dented	695.60 FL	*695.60 FL
27	1		*CENTRE PILLAR INNER-RH	Repair	584.20 FL	*- FL
28	1		*CENTRE PILLAR LOWER GARNISH	Not Necessary	158.40 FL	*- FL
29	1		*SET CENTRE PILLAR LOWER GARNISH CLIPS	Necessary	20.00 FL	*20.00 FL
30	1		*CENTRE PILLAR UPPER GARNISH	Not Necessary	104.20 FL	*- FL
31	1		*SET CENTRE PILLAR UPPER GARNISH CLIPS	Necessary	20.00 FL	*20.00 FL
32	1		*REAR DOOR -RH	Distorted	978.40 FL	*978.40 FL
33	1		*REAR DOOR LOCK -RH	Jammed	298.00 FL	*298.00 FL
34	1		*REAR DOOR WEATHERSTRIP -RH	Cut	168.90 FL	*168.90 FL
35	1		*REAR DOOR INNER TRIM BOARD -RH	Deformed	645.10 FL	*645.10 FL
36	1		*SET REAR DOOR INNER TRIM BOARD CLIPS -RH	Necessary	30.00 FL	*30.00 FL
37	1		*REAR DOOR GLASS OUTER MOULDING -RH	Cut	66.40 FL	*66.40 FL
38	1		*REAR DOOR GLASS CHANNEL-RH	Cut	75.10 FL	*75.10 FL
39	1		*REAR DOOR GLASS CHANNEL RUBBER -RH	Necessary	94.10 FL	*94.10 FL
40	1		*REAR DOOR GLASS REGULATOR GEAR-RH	Damaged	358.00 FL	*358.00 FL
41	2		*REAR DOOR HINGE -RH	Bent	150.00 FL	*150.00 FL
42	1		*REAR DOOR CHECK-RH	Damaged	48.00 FL	*48.00 FL
43	1		*ROCKER PANEL-RH	Repair	660.80 FL	*- FL
44	1		*REAR BUMPER	Repair	825.00 FL	*- FL
45	1		*SET REAR BUMPER CLIPS	Not Necessary	30.00 FL	*- FL
46	2		*REAR BUMPER SIDE HOLDER	Not Necessary	52.80 FL	*- FL
47	2		*REAR SIDE BUMPER	Repair	390.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		*TAILLAMP	N/S Cracked	961.20 FL	*480.60 FL
49	1		*TAILLAMP PANEL	N/S Dented	312.40 FL	*156.20 FL
50	1		*REAR FENDER -RH	Distorted	995.00 FL	*995.00 FL
51	1		*REAR FENDER ARC GARNISH -RH	Missing	151.40 FL	*151.40 FL
52	1		*SET REAR FENDER ARC GARNISH CLIPS -RH	Necessary	20.00 FL	*20.00 FL
53	1		*REAR FENDER INNER SHIELD -RH	Deformed	210.40 FL	*210.40 FL
54	1		*SET REAR FENDER INNER SHIELD CLIPS-RH	Necessary	30.00 FL	*30.00 FL
55	1		*REAR FENDER INNER TRIM BOARD -RH	Deformed	326.00 FL	*326.00 FL
56	1		*SET REAR FENDER INNER TRIM BOARD CLIPS-RH	Necessary	30.00 FL	*30.00 FL
57	1		*REAR FENDER INNER TRIM BOARD (UPPER) -RH	Not Necessary	210.40 FL	*- FL
58	1		*SET REAR FENDER INNER TRIM BOARD (UPPER) CLIPS -RH	Necessary	20.00 FL	*20.00 FL
59	1		*REAR MUDFLAP -RH	Deformed	65.10 FL	*65.10 FL
60	1		*REAR FENDER -LH	Distorted	995.00 FL	*995.00 FL
61	1		*REAR FENDER ARC GARNISH -LH	Cut	151.40 FL	*151.40 FL
62	1		*SET REAR FENDER ARC GARNISH CLIPS-LH	Necessary	20.00 FL	*20.00 FL
63	1		*REAR FENDER INNER SHIELD -LH	Not Necessary	210.40 FL	*- FL
64	1		*SET REAR FENDER INNER SHIELD CLIPS -LH	Necessary	30.00 FL	*30.00 FL
65	1		*REAR FENDER INNER TRIM BOARD -LH	Deformed	326.00 FL	*326.00 FL
66	1		*SET REAR FENDER INNER TRIM BOARD CLIPS -LH	Necessary	30.00 FL	*30.00 FL
67	1		*REAR FENDER INNER TRIM BOARD (UPPER) -LH	Not Necessary	210.40 FL	*- FL
68	1		*SET REAR FENDER INNER TRIM BOARD (UPPER) CLIPS -LH	Necessary	20.00 FL	*20.00 FL
69	1		*REAR FENDER QUARTER GARNISH -LH	Cut	45.40 FL	*45.40 FL
70	1		*FUEL LID	Distorted	90.40 FL	*90.40 FL
71	1		*FUEL LID LOCK	Jammed	35.10 FL	*35.10 FL
72	1		*REAR MUDFLAP -LH	Cut	65.10 FL	*65.10 FL
73	1		*REAR DOOR -LH	Dented	978.40 FL	*978.40 FL
74	1		*REAR DOOR LOCK -LH	Damaged	298.00 FL	*298.00 FL
75	1		*FRONT LH DOOR HANDLE	Cut	220.40 FL	*220.40 FL
76	1		*REAR DOOR WEATHERSTRIP -LH	Cut	168.90 FL	*168.90 FL
77	1		*REAR DOOR OUTER HANDLE -LH	Cut	151.40 FL	*151.40 FL
78	1		*REAR DOOR GLASS OUTER MOULDING -LH	Cut	66.40 FL	*66.40 FL
79	1		*REAR DOOR GLASS REGULATOR GEAR -LH	Damaged	358.00 FL	*358.00 FL
80	1		*REAR DOOR GLASS CHANNEL -LH	Bent	75.10 FL	*75.10 FL
81	1		*REAR DOOR GLASS CHANNEL RUBBER -LH	Necessary	94.10 FL	*94.10 FL
82	1		*REAR DOOR INNER TRIM BOARD -LH	Deformed	645.10 FL	*645.10 FL
83	1		*SET REAR DOOR INNER TRIM BOARD CLIPS -LH	Necessary	30.00 FL	*30.00 FL
84	2		*REAR DOOR HINGE -LH	Not Necessary	150.00 FL	*- FL
85	1		*REAR DOOR CHECK-LH	Not Necessary	48.00 FL	*- FL
86	1		*CENTRE PILLAR -LH	Repair	695.60 FL	*- FL
87	1		*FRONT DOOR -LH	Dented	989.50 FL	*989.50 FL
88	1		*FRONT DOOR LOCK -LH	Not Necessary	278.20 FL	*- FL
89	1		*FRONT DOOR WEATHERSTRIP -LH	Not Necessary	133.90 FL	*- FL
90	1		*FRONT DOOR WING MIRROR -LH	Distorted	723.90 FL	*723.90 FL
91	2		*FRONT DOOR HINGE -LH	Not Necessary	150.00 FL	*- FL
92	1		*FRONT DOOR CHECK -LH	Not Necessary	48.00 FL	*- FL
93	1		*FRONT WINDSCREEN	Shattered	1,345.10 FL	*1,345.10 FL
94	1		*FRONT WINDSCREEN MOULDING	Necessary	132.00 FL	*132.00 FL
95	2		*FRONT WINDSCREEN PILLAR	Dented	797.00 FL	*797.00 FL
96	2		*FRONT WINDSCREEN PILLAR INNER TRIM	Not Necessary	204.80 FL	*- FL
97	2		*SETS FRONT WINDSCREEN PILLAR INNER TRIM CLIPS	Necessary	40.00 FL	*40.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	1		*DOOR FRAME	N/S Dented	1,570.00 FL	*785.00 FL
99	1		*ROOF PANEL	Distorted	1,650.00 FL	*1,650.00 FL
100	1		*ROOF PANEL FRONT REINFORCEMENT	Bent	420.00 FL	*420.00 FL
101	1		*ROOF PANEL CENTRE REINFORCEMENT	Bent	395.00 FL	*395.00 FL
102	2		*ROOF PANEL TOP MOULDING	Cut	276.00 FL	*276.00 FL
103	2		*SETS ROOF PANEL TOP MOULDING CLIPS	Necessary	60.00 FL	*60.00 FL
104	1		*ROOF PANEL INNER TRIM BOARD	Crumpled	825.90 FL	*825.90 FL
105	1		*SET ROOF PANEL INNER TRIM BOARD CLIPS	Necessary	100.00 FL	*100.00 FL
106	2		*ROOF PANEL SIDE AIR BAG	Activated	2,100.40 FL	*2,100.40 FL
107	2		*ROOF PANEL SIDE AIR BAG SENSOR	Activated	278.00 FL	*278.00 FL
108	1		*FRONT DRIVER SEAT AIR BAG	Activated	785.90 FL	*785.90 FL
109	1		*FRONT DRIVER SEAT AIR BAG SENSOR	Activated	139.00 FL	*139.00 FL
110	1		*FRONT PASSENGER SEAL AIR BAG	Activated	785.90 FL	*785.90 FL
111	1		*FRONT PASSENGER SEAL AIR BAG SENSOR	Activated	139.00 FL	*139.00 FL
112	1		*AIR BAG ECU	Activated	1,092.00 FL	*1,092.00 FL
113	2		*FRONT SEAT BELT	Activated	1,330.00 FL	*1,330.00 FL
114	1		*REAR SHOCK ABSORBER	O/S Bent	660.00 FL	*330.00 FL
115	1		*REAR AXLE BEAM	Bent	1,513.00 FL	*1,513.00 FL
116	2		*REAR WHEEL HUB C/W BEARING	Necessary	774.40 FL	*774.40 FL
117	2		*FRONT LOWER ARM	Bent	732.40 FL	*732.40 FL
118	2		*FRONT SHOCK ABSORBER	Bent	990.00 FL	*990.00 FL
119	2		*FRONT KNUCKLE ARM	Bent	781.00 FL	*781.00 FL
120	2		*FRONT WHEEL HUB C/W BEARING	Necessary	690.00 FL	*690.00 FL
121	1		*STEERING RACK AND PINION	Bent	1,178.40 FL	*1,178.40 FL
122	4		*ENGINE PISTON	Damaged	1,400.00 FL	*1,400.00 FL
123	4		*ENGINE CON ROD	Bent	1,180.00 FL	*1,180.00 FL
124	1		*ENGINE CON ROD BEARING	Necessary	220.00 FL	*220.00 FL
125	1		*ENGINE MAIN BEARING	Necessary	260.00 FL	*260.00 FL
126	2		*TOP TIRNING GEAR	Not Necessary	780.00 FL	*- FL
127	1		*TIMING CHAIN	Not Necessary	225.00 FL	*- FL
128	8		*EXHAUST VALVE	Damaged	552.00 FL	*552.00 FL
129	8		*INLET VALVE	Damaged	576.00 FL	*576.00 FL
130	1		*CRANKSHAFT	Not Necessary	2,480.00 FL	*- FL
131	2		*CAMSHAFT	Not Necessary	2,800.00 FL	*- FL
132	1		*OVERHAUL GASKET	Necessary	650.00 FL	*450.00 FL
133	1		*FLYWHEEL OIL SEAL	Necessary	48.00 FL	*48.00 FL
134	1		*TIMING TESIONER	Not Necessary	195.00 FL	*- FL
135	2		*FRONT WHEEL RIM	Cut	1,360.00 FS	*1,100.00 FS
136	1		*FRONT DOOR GLASS SOLAR FILM -RH	Necessary	180.00 FS	*180.00 FS
137	1		*FRONT DOR SPEAKER -RH	Damaged	200.00 FS	*150.00 FS
138	1		*FRONT DOOR BLACK TAPE-RH	Necessary	60.00 FS	*60.00 FS
139	1		*FRONT DOOR VISOR -RH	Necessary	65.00 FS	*65.00 FS
140	1		*REAR DOOR BLACK TAPE-RH	Necessary	60.00 FS	*60.00 FS
141	1		*REAR DOOR VISOR -RH	Necessary	65.00 FS	*65.00 FS
142	1		*ROCKER PANEL OUTER BOARD	Cut	580.00 FS	*580.00 FS
143	1		*ROCKER PANEL OUTER BOARD TOP CHROME	Cut	350.00 FS	*350.00 FS
144	1		*REAR WHEEL RIM -RH	Cut	680.00 FS	*550.00 FS
145	1		*REAR TYRE-RH	Punctured	250.00 FS	*220.00 FS
146	1		*REAR WHEEL RIM -LH	Cut	680.00 FS	*550.00 FS
147	1		*REAR TYRE -LH	Not Necessary	250.00 FS	*- FS
148	1		*REAR DOOR BLACK TAPE-LH	Necessary	60.00 FS	*60.00 FS
149	1		*REAR DOOR VISOR -LH	Necessary	65.00 FS	*65.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
150	1		*FRONT DOOR VISOR-LH	Necessary	65.00 FS	*65.00 FS
151	1		*FRONT FOOR BLACK TAPE-LH	Necessary	60.00 FS	*60.00 FS
152	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
153	1		*FRONT WINDSCREEN SOLAR FILM	Necessary	250.00 FS	*250.00 FS
154	1		*TAILGATE TOP SPOILER	Repair	800.00 FS	*- FS
155	1		*FRONT DRIVE SEAT	Necessary	1,500.00 FS	*150.00 FS
156	1		*FRONT PASSENGER SEAT	Necessary	1,500.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **72,116.60** **52,354.20**

- List Item Discount on L Items 20.00/20.00% (\$\$) 12,595.32 9,512.84

Total Parts (\$\$) **59,521.28** **42,841.36**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT FRONT & REAR PORTION & RENEW ABOVE PARTS	New	4,200.00	3,200.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	3,200.00	2,500.00
3	TO CHECK WIRING	New	200.00	100.00
4	TO UNDERSEAL	New	380.00	250.00
5	TO TRANSFER FRONT LH & RH DORO FITTINGS	New	300.00	160.00
6	TO TRANSFER REAR LH & RH DOOR FITTINGS	New	300.00	160.00
7	TO REMOVE ROOF UPHOLSTERY	New	280.00	200.00
8	TO REMOVE CABIN UPHOLSTERY	New	350.00	200.00
9	TO REMOVE FRONT WINDSCREEN	New	180.00	120.00
10	TO REMOVE FUEL TANK	New	150.00	80.00
11	TO REMOVE FRONT & REAR LH & RH SEAT	New	450.00	350.00
12	TO REMOVE FRONT LH & RH UNDERCARRIAGE	New	650.00	500.00
13	TO REMOVE REAR UNDERCARRIAGE	New	450.00	300.00
14	TO REMOVE ROOF AND SEAT AIR BAGS	New	600.00	400.00
15	TO RESET AIR BAG CONFIGURATION	New	280.00	120.00
16	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
17	TO REMOVE ENGINE BLOCK	New	400.00	300.00
18	TO DISMANTLE AND OVERHAU ENGINE BLOCK	New	500.00	0.00
19	TO CRAME UP AND TOWING FEES	New	150.00	150.00
20	TO SKIM CYCLINDER HAND AND PERFORM TOP OVERHAUL	New	680.00	280.00
21	TO DISMANTLE ,REPLACE AND GENERAL OVERHAUL OF ENGINE COMPONENTS	New	1,950.00	680.00
Gross Labour Cost (S\$)			15,800.00	10,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >