

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5125A - III**AAD1712-281**

Not Authored
Resurvey B4 paint **82844.93**

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD5125A - CANDY
VF1ABL15AUC283236
RENAULT
LATITUDE
27.12.2017
III

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68
3	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
4	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75
5	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80
6	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.22
7	1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 151.41
8	1	BUMPER BRACKET FRT RH	\$	<i>R</i> 181.75
9	1	HEADLAMP RH	\$	<i>Sn</i> 1,184.43
10	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15
11	1	FENDER PANEL FRT RH	\$	<i>Bu</i> 783.83 ✓
12	1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
13	1	FENDER BRACKET FRT RH	\$	<i>R</i> 34.14
14	1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84
15	1	RADAITOR GRILLE	\$	<i>Sn</i> 1,707.78
16	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 173.36
17	1	RADAITOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
18	1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 615.90
19	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
20	1	BONNET	\$	<i>R</i> 1,941.63
21	1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
22	1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50
23	1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55
24	1	DOOR MOULDING FRT RH	\$	<i>Sn</i> 176.82
25	1	DOOR MIRROR RH	\$	<i>Sn</i> 1,483.40
26	1	DOOR MIRROR GLASS RH	\$	<i>Sn</i> 148.20
27	1	DOOR MIRROR BACK COVER RH	\$	<i>Sn</i> 218.46
28	1	DOOR WHETHERSTRIP FRT RH	\$	<i>Sn</i> 474.21
29	1	DOOR SEAL FRT RH	\$	<i>Sn</i> 68.67
30	1	ROCKER PANEL OUTER RH	\$	<i>R</i> 987.49

TOTAL	\$	18,980.52
10%	\$	1,898.05
	\$	17,082.47

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-281

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD5125A - III

Specical Nett

1	1SET	WHEELARCH CLIP FRT RH	\$	nn	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	nn	66.00	✓
3	1	RIM RH FRT	\$	nn	385.00	X
4	1	TYRE RH FRT	\$	nn	330.00	X
5	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	X
6	1	DOOR STICKER "Classic"	\$	nn	30.00	X
7	1	DOOR STICKER "6555-3333"	\$	nn	80.00	X

TOTAL	\$	1,037.00
TOTAL PARTS	\$	18,119.47

To Check Electrical Lighting Concerned.	\$	170.00	10/
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	400/
Putty and spray painting of the affected portion.	\$	3,000.00	440/
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn	170.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00 X
To check steering geometry and computer wheel alignment	\$	220.00	60/
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	170.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	nn	170.00 X
Towing fees	\$	nn	120.00 X
To rust-proofing of the affected areas.	\$	170.00	30/

(PARTS BY PARTS) Repair Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

by the Repairer

TOTAL	\$	7,160.00
Over All Total	\$	25,279.47

10-Days
2 days