

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1269/2017/JT
Date : 28-Dec-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Eduardo Miszputen
Address : 61 Grange Road
#20-03
Singapore 249570
Telephone : HP +65 8876 7962
Type of Claim : Own Damage Claims
Policy No. : 2100427330-02
Vehicle No : **SKV 1998 T**
Model Code : Audi Q5 2.0 TFSI qu
Model / Year : Sep-15
Engine No : CNC 073455
Chassis No : WAUZZZ8R9FA032675
Mileage :
Date In : 28-Dec-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Dec-17
Place of Accident : Tanglin Shopping Mall entrance

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKV 1998 T.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer LHS front and rear door multi lock system and power window devices.	S/N \$ 560.00	✓
2	To dismantle and renew LHS front and rear doors. Align to position. Repair LHS rear fender and door entrance. Reinstall all parts removed.	\$ 2,450.00	1000.
3	To respray LHS front and rear doors, door covers, LHS rear door entrance and LHS rear fender.	\$ 3,500.00	$550 \times 3 = 1650$ $200 \times 2 = 400$ 350 } 2050. 2400
4	To renew LHS rear rim and carry out wheel alignment.	S/N \$ 280.00	X
5	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,982.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1998 T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR - LHS <i>Dented</i>	\$ 2,158.00	✓
2	FRONT DOOR OUTER SEAL - LHS <i>new</i>	\$ 167.00	-
3	BONDING AGENT ?	\$ 42.00	?
4	FRONT DOOR CATCH - LHS <i>new</i>	\$ 123.00	+
5	FRONT DOOR COVER - LHS <i>new</i>	\$ 439.00	✓
6	REAR DOOR - LHS <i>Dented</i>	\$ 2,158.00	✓
7	REAR DOOR OUTER SEAL - LHS <i>new</i>	\$ 170.00	-
8	BONDING AGENT ?	\$ 42.00	?
9	REAR DOOR STONE CHIP GUARD - LHS ?	\$ 66.00	?
10	REAR DOOR CATCH - LHS <i>new</i>	\$ 123.00	x
11	REAR DOOR COVER - LHS <i>new</i>	\$ 351.00	✓
12	REAR ALUMINIUM RIM - LHS <i>new</i>	\$ 892.00	x
13	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS		\$ 7,231.00	
TOTAL LABOUR CHARGES		\$ 6,982.00	
GRAND TOTAL		\$ 14,213.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *29/12/17*
Authorised Date :
Excess Cost :
Liability :
Remarks : *not Authorised, 05 Days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant