

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

To: Adrian Ling

Xiao Tony

Estimate Quotation

Quotation No	Dec-0005/2017
Date	27/12/2017
Vehicle No	SGQ5000U
Make / Model	Mercedes Benz C200

WDD2040482A379700

To: M/s Direct Asia

Address:

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	w/s front fender <i>Detached</i>		\$ 985.00 ✓
1 pc	w/s front fender inner shield		\$ 162.00 x
1 set	w/s front fender inner shield clip		\$ 50.00 x.
1 pc	w/s front fender emblem <i>new</i>		\$ 97.00 ✓
1 pc	w/s front door <i>Detached</i>		\$ 1,975.00 ✓
1 pc	w/s front door protector <i>lt</i>		\$ 92.00 ✓
1 pc	w/s front door glass regulator & motor <i>Damaged</i>	7204	\$ 1,445.00 688
1 pc	w/s side mirror <i>Damaged</i>	6483-60	\$ 1,115.00 ✓
1 pc	w/s front door outer handle <i>Repair</i>		\$ 192.00 x.
1 pc	w/s rear door <i>Detached</i>		\$ 2,252.00 ✓
1 pc	w/s rear door protector <i>lt</i>		\$ 98.00 ✓
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair	1890	\$ 800.00 700
2	to putty and spray painting on affected area		\$ 1,000.00 900
3	anti rust		\$ 100.00 40.
4	transfer door fittings.		\$ 150.00 ✓
5	To perform diagnostic test.		150 100.
Subtotal:			\$ 10,513.00

BEST SOLUTION AUTOCARE PTE LTD

Authorised signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling. total 83B60
w/s 28/12/17 1/s 67K
04 Days.