

INS. CASE OWNER: Boyeagan

CC 4/LCR170 24 7271/KWS39V

LKK:
IDAC:

Surveyor:

KENNETH

DOI:

29/12/17

Date / Time:

29/12/17

Registered in Merimen:

29/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLF 503 S

Name of Insured:

LCR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 27/12/17

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

Claim No.:

295821613289

Policy No.:

0999995053

Make / Model:

MAZDA 2-1.5 SEDAN L SP. 6 GEAR

Place of Accident:

ALONG BKE BEFORE WOODLANDS
AVE 12If NO, Driver Name / Age: MAK MUN FAI (MAI WENHUI)Driver Tel No.: 88212626(V/L: ☒ YES / NO)OI GIA REPORT: ☒ YES / NO; TP GIA REPORT: ☒ YES / NO

Insured Liability: % Final? Yes / No

OLE 5483M

INSRS:

WSP: Cheng Hoe (Chen)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

03/01/18 (v.vian)OLE 5483M - X ; SLF 503 S - X3/1/18Email letter to O2.

RECEIVED 11 MAY 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

3/1/18 email.
v.vian

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with JuneEmail ☐ Call ☐

Final Liability:

%

100(Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

5631.11

Loss of Rental (LOR):

SS

700.00

(

7 days) X100.00

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only ☐ LOU only ☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

SS

8.00

Medical:

SS

-

Disbursement:

SS

-

Legal Cost:

SS

-

(e.g. Tow/ Independent)

Total:

SS

6339.11

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

6339.11

Name 1:

Cheng Hoe Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
2018/1/5



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/LCR17024727/Kws3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 29-12-2017		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 503S	Veh. Inspected	SLE 5483M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	29/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/12/2017	Inspection Date	29/12/2017	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLE 5483M

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP-AIG

Claim Type: Third Party

Accident Date: 27/12/2017

TP Veh Reg No: SLF503S

Estimate No: ES1791456/WS

Date: 29 Dec 2017

Policy No: 5082365683-01

Veh Reg No: SLE5483M

Make/Model: HONDA VEZEL 1.5

Chassis No: RU31118597

Engine No: LEB5068612

Reg. Date: 26/07/2016

Estimate Repair Cost to Vehicle No :SLE5483M

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	850.70	1 PC	850.70	✓
2 REAR BUMPER REFLECTOR	148.30	2 PC	296.60	✓
3 REAR TAILGATE	1,100.90	1 PC	1,100.90	✓
4 TAILGATE EMBLEM (VEZEL)	56.20	1 PC	56.20	✓
5 TAILGATE EMBLEM (HYBRID)	66.20	1 PC	66.20	✓
6 TAILGATE INNER LOCK	180.00	1 PC	180.00	✓
7 TAILGATE INNER RUBBER	96.80	1 PC	96.80	✓
8 REAR WINDSCREEN GLASS MOULDING	158.20	1 PC	158.20	✓
9 REAR CENTRE PANEL	415.60	1 PC	415.60	✓
10 REAR SPARE TYRE PANEL TOOL BOX	230.60	1 PC	230.60	✓
11 REAR SPARE TYRE PANEL LOWER COVER	190.00	1 PC	190.00	✓
12 REAR WHEEL ARP GARNISHS	201.50	2 PCS	403.00	✓
13 REAR BUMPER SIDE RH	191.50	1 PC	191.50	✓
14 SPARE TYRE TOP BOARD	430.30	1 PC	430.30	✓
15 REAR EXHAUST PIPE	960.10	1 PC	960.10	✓
			5,626.70	
		Less 20%	1,125.34	4,501.36
Special Net				
16 REVERSE SENSOR	200.00	1 PC	200.00	✓
17 REVERSE CAMERA	350.00	1 PC	350.00	✓
18 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
			590.00	590.00
Labour				
19 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
20 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTACHMENT, REAR WIPER ASSY, REAR TOP SPOILER, TO CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT, REAR FENDERS & REALIGN THE SAME	800.00	1 LA	800.00	540

Not Authorized
 1-B1
 Repair B4 painting
 6 days

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP-AIG

Claim Type: Third Party

Accident Date: 27/12/2017

TP Veh Reg No: SLF503S

Estimate No: ES1791456/WS

Date: 29 Dec 2017

Policy No: 5082365683-01

Veh Reg No: SLE5483M

Make/Model: HONDA VEZEL 1.5

Chassis No: RU31118597

Engine No: LEB5068612

Reg. Date: 26/07/2016

Estimate Repair Cost to Vehicle No :SLE5483M

Description	U/Price	Quantity	List Price	Amount
			SS	SS
21 PUTTY AND RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR BOTH FENDERS, TAILGATE. REAR PANEL, REAR PANEL AND REAR AFFECTED	900.00	1 LA	900.00	800
22 REMOVE AND REFIX REAR EXHAUST AND CHECK SYSTEM	60.00	1 LA	60.00	✓
23 REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM	60.00	1 LA	60.00	✓
24 RUSTPROOFING	60.00	1 LA	60.00	30
			1,980.00	1,980.00
Total				SS 7,071.36
Add GST @ 7%				495.00
Total Amount Payable				SS 7,566.36

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- Pre repair inspection request - SLE5483M VS SLF503S (OI) DOA 27/12/2017

From: Chan, Yoke Shi
To: Admin A, assignments
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang
Sent: Thursday, 28 December, 2017 4:37:40 PM

Hi,

Please refer to the enclosed request from **Cheng Hoe Motor Pte Ltd (Yishun-June)**.

Claim no : 2958216132SG003
Case Owner : JOANE TIK-CHAP BOYOGAN
If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

10:17am @ 29/12/17
Vehicle in
person @ Sharon
Sur @ Kenneth.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Thursday, December 28, 2017 4:33 PM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE AND SLE5483M ON 27/12/2017

Hi,

Our selection as below :-

Kenneth Kong	LKK Auto Consultants Pte Ltd
--------------	------------------------------

Pls assist to arrange for survey.
Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Chan, Yoke Shi
Sent: Thursday, December 28, 2017 4:10 PM
To: chmotor@singnet.com.sg
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLF503S AND SLE5483M ON 27/12/2017

Without Prejudice

Your Reference : SLE5483M
 Our Reference : 2958216132SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
 Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
 Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
 Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Dec 2017 Edit Reg		29 Dec 2017 00:00 Edit Adj Rpt	S\$5,262.72 Edit Estimates	S\$5,262.72 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	CHIA WEE TECK, ID: S6811427F		
Vehicle Reg. No.:	SLE5483M	Date of Loss:	27/12/2017 00:00 - :59 [17 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2958216132SG	Policy/Cover Note No.:	0999995053 (Comprehensive)
Vehicle Reg. No. (Insured):	SLF503S	Policy No. (Claimant):	5082365683-01
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/01/2018]		
Driver/Custodian (Insured):	MAK MUN FAI (MAI WENHU) (), NRIC: S7830643B		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLE5483M (2958216132SG)**
[SLF503S]

TP

CHIA WEE TECK
Dec 27 2017 12:00AM
[LCRF PTE LTD]
Cheng Hoe Motor Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser ▼
------------------	---------------	--------------------	--------------	--------------	------	-------------------

Letters/Correspondences				1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Assessment Reports				1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	02/01/18 14:12	Accident Statement From: SC - Reg. No: SLF503S, Claimant: LCRF PTE LTD	1	Load HTM	

Photos/Images				3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/05/18 12:16	General View	1	Load JPG	✓
2	07/05/18 12:16	General View	1	Load JPG	✓
3	07/05/18 12:16	General View	1	Load JPG	✓
4	07/05/18 12:16	General View	1	Load JPG	✓
5	07/05/18 12:16	General View	1	Load JPG	✓
6	07/05/18 12:16	General View	1	Load JPG	✓
7	07/05/18 12:16	General View	1	Load JPG	✓
8	07/05/18 12:16	General View	1	Load JPG	✓
9	07/05/18 12:16	General View	1	Load JPG	✓
10	07/05/18 12:16	General View	1	Load JPG	✓
11	07/05/18 12:16	General View	1	Load JPG	✓
12	07/05/18 12:16	General View	1	Load JPG	✓
13	07/05/18 12:16	General View	1	Load JPG	✓
14	07/05/18 12:16	General View	1	Load JPG	✓
15	07/05/18 12:16	General View	1	Load JPG	✓
16	07/05/18 12:16	General View	1	Load JPG	✓
17	07/05/18 12:16	General View	1	Load JPG	✓
18	07/05/18 12:16	General View	1	Load JPG	✓
19	07/05/18 12:16	General View	1	Load JPG	✓
20	07/05/18 12:16	General View	1	Load JPG	✓
21	07/05/18 12:16	General View	1	Load JPG	✓
22	07/05/18 12:16	General View	1	Load JPG	✓
23	07/05/18 12:16	General View	1	Load JPG	✓
24	07/05/18 12:16	General View	1	Load JPG	✓
25	07/05/18 12:16	General View	1	Load JPG	✓

Documentation				1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/12/17 17:31	EMAIL FROM AIG DD 28.12.2017	1	Load PDF	

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
2	29/12/17 17:31	ACKNOWLEDGEMENT EMAIL TO AIG DD 29.12.2017	 Load PDF	
3	02/01/18 08:45	TP GIA REPORT	 Load PDF	
4	03/01/18 09:45	TP ESTIMATE- MARKED	 Load PDF	
5	03/01/18 14:06	Email letter to OI ACCIDENT INVOLVING SLF 503S AND SLE 5483M ON 27.12.2017	 Load PDF	
6	14/05/18 14:41	AUTHORISATION TO ACT	 Load PDF	
7	14/05/18 14:41	LETTER TO OI	 Load PDF	
8	14/05/18 14:41	LTA SEARCH	 Load PDF	
9	14/05/18 14:41	RELEASE VOUCHER	 Load PDF	
10	14/05/18 14:41	RENTAL RECEIPT	 Load PDF	
11	14/05/18 14:41	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLF503S (Insd veh)	Model:	HONDA VEZEL HYBRID 1.5 Z (A)
	SLE5483M (TP veh)		
Date of Accident:	27/12/2017		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				7,566.36
Final Repair Cost	:	\$				5,631.11
Loss of Use	:	\$				days at \$0.00 per day
Rental (if any)	:	\$				7 days
LTA / GIA Search Fee	:	\$				8.00
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$				6,339.11

Is Third Party Workshop GIA Registered?	[X]	YES	[]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability		(%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No		BOLA Scenario No: <u>27</u>	
BOLA Liability: <u>100</u> (%)		Assessed Liability (*):		(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown

1)	Cheng Hoe Motor Pte Ltd	:	\$	6,339.11
2)		:	\$	
3)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

14 May
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR17024727/KWA3S2
Date: 14/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995053
Claimant Vehicle No: SLE5483M Insured Vehicle No: SLF503S
Date of Loss: 27/12/2017 Nature of Claim: TP Claim No: 2958216132SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE5483M
Make & Model: HONDA VEZEL HYBRID, 1.5 Z (A) Engine No: LEB5068612
Reg. Date: 26/07/2016 (Man. Year: 2016) Chassis No: RU31118597
Colour: Metallic Pearl White Odometer: 28033 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55R17 Rear Tyre Size: 215/55R17
Front Left Side: Hankook 7 mm Rear Left Side: Hankook 7 mm
Front Right Side: Hankook 7 mm Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,091.36	3,672.72	1,418.64	27.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,590.00	390.00	19.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,071.36	5,262.72	1,808.64	25.58
+ GST 7.00/7.00% (S\$)	495.00	368.39	126.61	25.58
Nett Amount (S\$)	7,566.36	5,631.11	1,935.25	25.58
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		6,339.11		

INSPECTION

Date of Assignment: 29/12/2017
Date Inspected: 29/12/2017 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Singapore 768761
Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	850.70 FL	*850.70 FL
2	2		*REAR BUMPER REFLECTOR	Serviceable	296.60 FL	*- FL
3	1		*REAR TAILGATE	Bent	1,100.90 FL	*1,100.90 FL
4	1		*TAILGATE EMBLEM (VEZEL)	Necessary	56.20 FL	*56.20 FL
5	1		*TAILGATE EMBLEM (HYBRID)	Necessary	66.20 FL	*66.20 FL
6	1		*TAILGATE INNER LOCK	Dented	180.00 FL	*180.00 FL
7	1		*TAILGATE INNER RUBBER	Distorted / Dented	96.80 FL	*96.80 FL
8	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	158.20 FL	*158.20 FL
9	1		*REAR CENTRE PANEL	Repair	415.60 FL	*- FL
10	1		*REAR SPARE TYRE PANEL TOOL BOX	Serviceable	230.60 FL	*- FL
11	1		*REAR SPARE TYRE PANEL LOWER COVER	Cracked	190.00 FL	*190.00 FL
12	1		*REAR WHEEL ARP GARNISHS	O/s Buckled	403.00 FL	*201.50 FL
13	1		*REAR BUMPER SIDE RH	Serviceable	191.50 FL	*- FL
14	1		*SPARE TYRE TOP BOARD	Deformed	430.30 FL	*430.30 FL
15	1		*REAR EXHAUST PIPE	Bent	960.10 FL	*960.10 FL
16	1		*REVERSE SENSOR	Cracked	200.00 FS	*200.00 FS
17	1		*REVERSE CAMERA	Serviceable	350.00 FS	*- FS
18	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	6,216.70	4,530.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,125.34	858.18
Total Parts (\$\$)	5,091.36	3,672.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS.	New	100.00	100.00
2	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTACHMENT, REAR WIPER ASSY, REAR TOP SPOILER, TO CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT, REAR FENDERS & REALIGN THE SAME.	New	800.00	540.00
3	PUTTY AND RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR BOTH FENDERS, TAILGATE. REAR PANEL, REAR PANEL AND REAR AFFECTED.	New	900.00	800.00
4	REMOVE AND REFIX REAR EXHAUST AND CHECK SYSTEM.	New	60.00	60.00
5	REMOVE AND REFIX REVERSE CAMERA AND RESET SYSTEM.	New	60.00	60.00
6	RUSTPROOFING.	New	60.00	30.00
Gross Labour Cost (\$\$)			1,980.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >