

Ref: 17024734/T1us3

ASSIGNMENT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC17024734/T1us3

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 29-12-2017



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 5029X	Veh. Inspected	SLF 7224B
Policy No.	Z15VP05008166	Coverage (\$)	0.00
Claim No.	15/16/16/VP05/019348	Excess (\$)	0.00
Assign From		Assign Date	29/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/10/2016	Inspection Date	12/02/2018
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVENUE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 15/16/16/VP05/019348
Our ref: CC4/LPC17024734/T1us3

Date: 13.02.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLF 7224B

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.02.2018 at the M/s Wearnes Automotive Pte Ltd (Alexandra) have the following to report:-

Workshop Estimate Amount	: S\$	9,079.10
Revised Estimate Amount	: S\$	4,902.10
"Check" Items Amount	: S\$	1,951.60
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 27 December, 2017 5:15 PM
To: Catherine Chong (LKK Auto); assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: SLF7224B Claim against SKP5029X Our Ref : 15/16/16/VP05/019348
Attachments: 4786_001.pdf

Dear Catherine

fya

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Mandy Neo [<mailto:mandy.neo@wearnes.com>]
Sent: Wednesday, 27 December, 2017 3:12 PM
To: GERALD POH WEE BIN
Subject: FW:SLF7224B Claim against SKP5029X

Hi Gerald,

Attached for TP Claim,

Kindly advise if direct settlement is possible

Best regards,

Mandy Neo
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte. Ltd.
49 Alexandra Road 159935
F (65) 6264 7137 O (65) 97704368
www.wearnes.com mandy.neo@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Your Scan Copy
Sent: Wednesday, 27 December, 2017 10:22 AM
To: Mandy Neo
Subject: Attached Image

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SERVICE ESTIMATE

86636 - 000001

SL: SERVICE SALES - PC

Ms Amy ong

37 Jalan Tarum

Singapore 576756

Closed by : Mandy Neo

Svc Consultant :

Remarks : Ms Amy ong

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 26/12/2017

WIP No. : 36327

Veh.In/Out:

*Tel.No. : Mobile: 98512417

Reg.No. : SLF7224B

Reg.date : 25/08/2016

Mileage .. : 0

Chassis No: SALCA2AGRGH618771

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

							1200
802	TO REPLACE REAR BUMPER	0	2400.00	0		2,400.00	S
LOWER CHROME PANEL							
800	TO PUTTY & SPRAY REAR BUMPER	0	2000.00	0		2,000.00	S 1000
280	TO CHECK WIRING INCLUDING	0	486.00	0		486.00	S ✓
RESETTING OF ALL ELECTRICAL							
MODULES							
	BUMPER COVER REAR DS	1.0 EA	1790.70	1913.60		1,790.70	S de ✓ 1726.74
	TOW EYE COVER REAR D	1.0 EA	401.30	430.00		401.30	S X ✓ de ✓ 387.00
	BRACKET - BUMPER MOU	1.0 EA	99.70			99.70	S X
	BRACKET - BUMPER MOU	1.0 EA	99.70			99.70	S X
	BRACKET - BUMPER	1.0 EA	187.50			187.50	S X un
	BRACKET - BUMPER	1.0 EA	187.50			187.50	S X
	BRACKET - BUMPER MOU	1.0 EA	107.00			107.00	S X
	BRACKET - BUMPER MOU	1.0 EA	107.00			107.00	S X
	TOW HOOK COVER REAR	1.0 EA	25.40			25.40	S X X un
	REINFORCEMENT BAR RE	1.0 EA	761.90			761.90	S X
	ADHESIVE SEALER FL2	1.0 EA	425.40			425.40	S ✓ 382.86

Gross Total. 9,079.10

Labour Total 4,886.00
Parts Total 4,193.10
Package Total 0.00

Net..... 9,079.10

GST @ 7.0% 635.54

Total..... 9,714.65

Paid..... 0.00

Please Pay.. 9,714.65

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Tan Jiah 97495749
wp

12/2/18 @ 1020.

Resurvey before paint
resurvey new parts
sur @ lkkauto.com
3 days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC17024734/T1ua3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 16-07-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKP 5029X	Veh. Inspected	SLF 7224B	
Policy No.	Z15VP05008166	Coverage (\$)	0.00	
Claim No.	15/16/16/VP05/019348	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	29/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	LAND ROVER DISCOVERY	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	SALCA2AG8GH618771	Colour	WHITE	
Odometer	36220	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	PIRELLI	6 mm	
L/H Front Tyre	235/60 R18	PIRELLI	6 mm	
R/H Rear Tyre	235/60 R18	PIRELLI	6 mm	
L/H Rear Tyre	235/60 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/10/2016	Inspection Date	12/02/2018	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 7224B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR DS (SN)	DEFORMED	1,790.70	1,726.74
1	TOW EYE COVER REAR D (SN)	DEFORMED	401.30	387.00
1	BRACKET -BUMPER MOU (SN)	NOT NECESSARY	99.70	-
1	BRACKET -BUMPER MOU (SN)	NOT NECESSARY	99.70	-
1	BRACKET -BUMPER (SN)	NOT NECESSARY	187.50	-
1	BRACKET -BUMPER (SN)	NOT NECESSARY	187.50	-
1	BRACKET -BUMPER MOU (SN)	NOT NECESSARY	107.00	-
1	BRACKET -BUMPER MOU (SN)	NOT NECESSARY	107.00	-
1	TOW HOOK COVER REAR (SN)	NOT NECESSARY	25.40	-
1	REINFORCEMENT BAR RE (SN)	NOT NECESSARY	761.90	-
1	ADHESIVE SEALER FL2 (SN)	NECESSARY	425.40	382.86
			4,193.10	2,496.60
LABOUR				
TO REPLACE REAR BUMPER LOWER CHROME PANEL .			2,400.00	1,200.00
TO PUTTY & SPRAY REAR BUMPER .			2,000.00	1,000.00
TO CHECK WIRING INCLUDING RESETTING OF ALL ELECTRICAL MODULES.			486.00	486.00
			4,886.00	2,686.00
GRAND TOTAL			9,079.10	5,182.60
RECOMMENDED COST OF REPAIRS				5,182.60

Report Ref No. CC4/LPC17024734/T1ua3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.