

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SERVICE ESTIMATE

86636 - C00001

SL: SERVICE SALES - PC

Ms Amy ong

37 Jalan Tarum

Singapore 576756

Closed by : Mandy Neo

Svc Consultant :

Remarks : Ms Amy ong

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 26/12/2017

WIP No. : 36327

Veh.In/Out:

*Tel.No. : Mobile: 98512417

Reg.No. : SLF7224B

Reg.date : 25/08/2016

Mileage ... : 0

Chassis No: SALCA2AG8GH618771

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
						1200	
802	TO REPLACE REAR BUMPER	0	2400.00	0	2,400.00	S	
	LOWER CHROME PANEL						
800	TO PUTTY & SPRAY REAR BUMPER	0	2000.00	0	2,000.00	S	1000
280	TO CHECK WIRING INCLUDING	0	486.00	0	486.00	S	✓
	RESETTING OF ALL ELECTRICAL						
	MODULES						
	BUMPER COVER REAR DS	1.0 EA	1790.70		1,790.70	S	de✓
	TOW EYE COVER REAR D	1.0 EA	401.30		401.30	S	?
	BRACKET - BUMPER MOU	1.0 EA	99.70		99.70	S	?
	BRACKET - BUMPER MOU	1.0 EA	99.70		99.70	S	?
	BRACKET - BUMPER	1.0 EA	187.50		187.50	S	?
	BRACKET - BUMPER	1.0 EA	187.50		187.50	S	?
	BRACKET - BUMPER MOU	1.0 EA	107.00		107.00	S	?
	BRACKET - BUMPER MOU	1.0 EA	107.00		107.00	S	?
	TOW HOOK COVER REAR	1.0 EA	25.40		25.40	S	X
	REINFORCEMENT BAR RE	1.0 EA	761.90		761.90	S	?
	ADHESIVE SEALER FL2	1.0 EA	425.40		425.40	S	NC✓

Gross Total. 9,079.10

Labour Total 4,886.00
Parts Total 4,193.10
Package Total 0.00

Net..... 9,079.10
GST @ 7.0% 635.54
Total..... 9,714.65
Paid..... 0.00
Please Pay.. 9,714.65

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Tanfah 97495749
wp

12/2/18 @ 1020.
Resurvey before paint
resurvey new parts
sur @ lkhauto.com
3 days.