

ASS. REC. BY:

REF: CS/FCI 18000067/Rwbhz

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): serene lerof First Capital InsuranceDate/Time: 02.01.2018 8:11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBG 4048 BInsured: STC 8489 Kat Workshop m/s SG98 Motor Pte LtdTel: 6452 4898of Blk 4001 Ang Mo Kio Industrial Park 1 #01-21

Policy No:

Claim No: D17011708 MPST

Sum Insured:

Excess:

Make of Veh:

D.O.A 18122017

(Client's Record)

CA / REV / REP. / REV 24 HRS

3/1/2018

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

FBG 4048 B - X.5/1/18Email FCI informed pending est from repairer14/3/18LS \$ 3300 confirmed by email (Ref 3128.40, 499)20/3/18Email preti revised to FCI

SPECIAL

REF:

PCT

E330 I

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBG 4048B

at Workshop m/s: 8698

of: BIK 4001 AMK #01-21

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:


(Client's Record)

Make of Veh.:

3/1/2018

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBG 4048B

Yr Regn:

2012 July

Type: M.Car / Truck / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA JUPITER MX (40) cc 13X

Colour:

MULTI

A/C:

Insured / Std / NI / NA

So. Reading:

91320

T. Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH 350C 002CK 360840

Gen. Cond: Good / Fair / Poor / BurntSteering: Normal / Jammed / Leaked / Burnt orBrake: Normal / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

80/80 - 17

R:

90/80 - 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

12/12/17

D.O.A.

04/01/18

Survey held at

SG 98 MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/3/2018

RECEIVED 20 MAR 2018

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2) 20/3 - typist

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee

Transportation

Photo

Sheet

TOTAL

Add Fee:

☐

Site Insp

\$

☐

Interview

\$

☐

Tech Insp

\$

☐

Misc. exp

\$

Report Format:

CWS

Lump Sum / I.B.I.:

3300/-

145

50

50

100

345

Survey Department Check List (Case Handler)

Reference No. : CS/FC18000007/R1/b
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Veron 20/3/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18000007/R1vb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-01-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8489K	Veh. Inspected	FBG 4048B
Policy No.		Coverage (\$)	0.00
Claim No.	D17011708MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	02/01/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		
Engine No.	Year of Reg.		
Chassis No.	Colour		
Odometer	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/12/2017	Inspection Date	
Survey held at			
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17011708MFSH
Our Ref: CS/FCI18000007/R1vb

Date : 20/3/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. FBG 4048B


We thank you for your instruction on 2/1/2018

Please be informed that we had conducted the inspection of the above mentioned
4/1/2018 at the premises of M/s SG 98 MOTOR PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$6,428.40
Revised Estimate Amount	: S\$4,107.20
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
o/s and n/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	20-12-2017	Our Ref No. D17011708MFSH
Accident Date	18-12-2017	Claim Type. Third Party
Insured Vehicle	SHC8489K	Third Party Vehicle. FBG4048B
Survey Location	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21	
Contact Person.	LEENA	
Contact No.	64524898/ 91711655	Fax No. 64524868
Survey Type	WITHOUT PREJUDICE: EST NOT PROVIDED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SG 98 MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Sg Motor <sgmotor2000@yahoo.com.sg>
Sent: Wednesday, 14 March 2018 6:17 PM
To: Rasul (LKKAUTO)
Cc: Sg Motor; Veron Chen (LKKAUTO)
Subject: Re: Please finalize bike FBG 4048B
Attachments: FBG 4048B-EST.pdf

Dear Rasul

Confirm acceptance \$3300 as per attached

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Tuesday, 13 March 2018, 1:10:33 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul

Please finalize bike FBG 4048B.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Thursday, 22 February 2018, 4:23:38 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul

Please finalize bike FBG 4048B.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Tuesday, 6 February 2018, 3:55:46 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul

Please finalize bike FBG 4048B.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Wednesday, 31 January 2018, 5:28:31 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul

Please finalize bike FBG 4048B.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Friday, 5 January 2018, 1:34:49 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Hi Rasul,

Attached photo of FBG 4048B,

Thank You
rose

Regards

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

Veron Chen (LKKAUTO)

From: Sg Motor <sgmotor2000@yahoo.com.sg>
Sent: Wednesday, 31 January 2018 5:29 PM
To: Rasul (LKKAUTO)
Cc: Sg Motor; CS A Team; Veron Chen (LKKAUTO)
Subject: Please finalize bike FBG 4048B
Attachments: FBG 4048B-COR.pdf

Dear Rasul

Please finalize bike FBG 4048B.

Thank You

Regards
Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

On Friday, 5 January 2018, 1:34:49 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Hi Rasul,

Attached photo of FBG 4048B,

Thank You
rose

Regards

SG 98 Motor Pte Ltd

Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 20 March 2018 9:21 AM
To: 'Claim Workflow System'
Cc: SUR; 'SERENELER@FIRST-INSURANCE.COM.SG'
Subject: RE: SURVEY ASSESSMENT - D17011708MFSH/1, FBG 4048B
Attachments: FBG 4048B PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle FBG 4048B
Date of survey: 4/1/2018
Number of days:4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 5 January 2018 1:34 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>
Cc: SUR <sur@lkkauto.com>; SERENELER@FIRST-INSURANCE.COM.SG
Subject: RE: SURVEY ASSESSMENT - D17011708MFSH/1, FBG 4048B

Dear Sir/Madam,

Please be informed that we have inspected the vehicle FBG 4048B on 4/1/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 5 January, 2018 1:30 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D17011708MFSH/1

"Wishes you a Happy New Year 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]

Sent: Tuesday, 2 January, 2018 8:34 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SERENELER@FIRST-INSURANCE.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D17011708MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 5 January, 2018 1:34 PM
To: 'Claim Workflow System'
Cc: SUR; SERENELER@FIRST-INSURANCE.COM.SG
Subject: RE: SURVEY ASSESSMENT - D17011708MFSH/1, FBG 4048B

Dear Sir/Madam,

Please be informed that we have inspected the vehicle FBG 4048B on 4/1/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 5 January, 2018 1:30 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D17011708MFSH/1

"WISHES YOU A HAPPY NEW YEAR 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 2 January, 2018 8:34 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SERENELER@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011708MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

On 14/03

Faxed: 6/1/2018

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 5 January 2018

To : LKK

By Fax: 6256-4315

Attn: Rasul

Tel : 90010068

VEHICLE NO : FBG 4048B

Yamaha MX Jupiter

ACCIDENT DATE: 18 December 2017

Description	Qty	Quotation \$
1 Handle Bar	1	135.00 PA
2 Handle Bar Bracket	1	125.00 X SC
3 Head Lamp	1	350.00 X SC
4 Brake Lever	1	35 78.00 SC
5 Mirror	1 set	60 150.00 SC
6 Front Cowling	1	198.00 SC
7 Head Lamp Cover	1	165.00 SC
8 Fork Tube	1 set	480.00 R
9 Fork Bracket	1	135.00 X SC
10 Fork Oil Seal	1	80 130.00 SC
11 Front Mudguard	1	195.00 R
12 Front Rim	1	250.00 R
13 Front Cowling Inner Panel	1	155.00 CA
14 Front Basket	1	95.00 CA
15 Front RH Side Panel (Fairing)	1	170.00 SC
16 Front LH Side Panel (Fairing)	1	170.00 SC
17 Front Fairing Inner Garnish	1 set	280.00 CA
18 Engine Lower Cover	1	235.00 CA
19 Lower Cover Bracket	1 set	250.00 PA
20 Leg Shield	1	135.00 SC
21 Gear Pedal	1	65.00 PA
22 Exhaust Pipe	1	480.00 SC
23 Exhaust Chrome Guard	1	220.00 SC
24 Water Pump	1	250.00 X SC
25 Radiatory Assy	1	480.00 PA
Sub-Total		5,376.00
Less 10%		537.60
Sub-Total		4,838.40

3408

106

3667.20

(1)

VEHICLE NO : FBG 4048B

Yamaha MX Jupiter

Nett items

- 1 IU unit
- 2 Yamaha Logo
- 3 Rear box
- 4 Body decal sticker
- 5 Towing fee
- 6 Remove & replace damaged parts,
align & etc
- 7 Remove & replace fork tube & top up
fork oil
- 8 Re-align front body frame
- 9 Check electrical harness

160.00 *500*
80.00 *100*
~~280.00~~ *150*
~~250.00~~ *150*
40.00
~~350.00~~ *250*

~~120.00~~ *80*

~~250.00~~ *100*
~~60.00~~ *30*

Sub-Total

1,590.00

1040

Nett Total

6,428.40

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

LG

Rashid
Hp 90010068

4 days

4/5

04/01/18 @ 1415

3067.20

1040.00

4107.20

20%

3,285.76

43-3,300

4 days



Faxed: 6/4/2018

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 549022

Tel: 6452 4308 Fax: 6452 4888

Email: sg_motor_enterprise@yahoo.com.sg

Date: 5 January 2018

To : LKK

By Fax: 6256-4315

Attn: Rasul

Tel : 90010068

VEHICLE NO : FBG 4048B

Yamaha MX Jupiter

ACCIDENT DATE: 18 December 2017

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Handle Bar	1	135.00 <i>HA</i>
2 Handle Bar Bracket	1	125.00 <i>X</i>
3 Head Lamp	1	350.00 <i>X</i>
4 Brake Lever	1	35 <i>78.00 <i>scr</i></i>
5 Mirror	1 set	60 <i>150.00 <i>scr</i></i>
6 Front Cowling	1	198.00 <i>scr</i>
7 Head Lamp Cover	1	165.00 <i>scr</i>
8 Fork Tube	1 set	480.00 <i>R</i>
9 Fork Bracket	1	135.00 <i>X</i>
10 Fork Oil Seal	1	80 <i>138.00 <i>scr</i></i>
11 Front Mudguard	1	195.00 <i>R</i>
12 Front Rim	1	250.00 <i>R</i>
13 Front Cowling Inner Panel	1	155.00 <i>CR</i>
14 Front Basket	1	95.00 <i>CR</i>
15 Front RH Side Panel (Fairing)	1	170.00 <i>scr</i>
16 Front LH Side Panel (Fairing)	1	170.00 <i>scr</i>
17 Front Fairing Inner Garnish	1 set	280.00 <i>CR</i>
18 Engine Lower Cover	1	235.00 <i>CR</i>
19 Lower Cover Bracket	1 set	250.00 <i>HA</i>
20 Leg Shield	1	135.00 <i>scr</i>
21 Gear Pedal	1	65.00 <i>HA</i>
22 Exhaust Pipe	1	480.00 <i>scr</i>
23 Exhaust Chrome Guard	1	220.00 <i>scr</i>
24 Water Pump	1	250.00 <i>X</i>
25 Radiatory Assy	1	480.00 <i>HA</i>

Sub-Total

5,376.00

Less 10%

537.80

Sub-Total

4,838.40

3408

106

3667.20 ✓

(1)

VEHICLE NO : FBG 4048B

Yamaha MX Jupiter

Nett Items

- 1 IU unit
- 2 Yamaha Logo
- 3 Rear box
- 4 Body decal sticker
- 5 Towing fee
- 6 Remove & replace damaged parts, align & etc
- 7 Remove & replace fork tube & top up fork oil
- 8 Re-align front body frame
- 9 Check electrical harness

160.00 ~~500~~
 80.00 ~~100~~
 280.00 ~~150~~ ~~500~~
 250.00 ~~150~~ ~~100~~
 40.00
 350.00 ~~250~~

120.00 ~~80~~250.00 ~~100~~80.00 ~~30~~

Sub-Total

1,590.00 1040

Nett Total

6,428.40

NO: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
 Thank you

SG 98 MOTOR PTE LTD

16

Rasul
Hp 960100068

4 days

4/5

04/01/18 @ 1415

3067.20

1040.00

4107.20

20%

3,285.76

4/5 - 3,300

4 days

OK
 confirm acceptance
 14/3/18
 (2)





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18000007/R1vbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8489K	Veh. Inspected	FBG 4048B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17011708MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	02/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA JUPITER MX (HC)	c.c	134	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	MH350C002CK360840	Colour	MULTI	
Odometer	91320	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80/80-17	MAXXIS	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90/80-17	MAXXIS	3 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND NS BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/12/2017	Inspection Date	04/01/2018	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 4048B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HANDLE BAR	BENT	135.00	135.00
1	HANDLE BAR BRACKET	SERVICEABLE	125.00	-
1	HEAD LAMP	SERVICEABLE	350.00	-
1	BRAKE LEVER	SCRATCHED	78.00	35.00
1	SET MIRROR	SCRATCHED	150.00	60.00
1	FRONT COWLING	SCRATCHED	198.00	198.00
1	HEAD LAMP COVER	SCRATCHED	165.00	165.00
1	SET FORK TUBER	TO REPAIR SEE LABOUR	480.00	-
1	FORK BRACKET	SERVICEABLE	135.00	-
1	FORK OIL SEAL	NECESSARY	130.00	80.00
1	FRONT MUDGUARD	TO REPAIR SEE LABOUR	195.00	-
1	FRONT RIM	TO REPAIR SEE LABOUR	250.00	-
1	FRONT COWLING INNER PANEL	CRACKED	155.00	155.00
1	FRONT BASKET	CRACKED	95.00	95.00
1	FRONT RH SIDE PANEL (FAIRING)	SCRATCHED	170.00	170.00
1	FRONT LH SIDE PANEL (FAIRING)	SCRATCHED	170.00	170.00
1	SET FRONT FAIRING INNER GARNISH	CRACKED	280.00	280.00
1	ENGINE LOWER COVER	CRACKED	235.00	235.00
1	SET LOWER COVER BRACKET	BENT	250.00	250.00
1	LEG SHIELD	SCRATCHED	135.00	135.00
1	GEAR PEDAL	BENT	65.00	65.00
1	EXHAUST PIPE	SCRATCHED	480.00	480.00
1	EXHAUST CHROME GUARD	SCRATCHED	220.00	220.00
1	WATER PUMP	SERVICEABLE	250.00	-
1	RADIATOR ASSY	BENT	480.00	480.00
	LESS 10% DISCOUNT		-537.60	-340.80
			4,838.40	3,067.20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	IU UNIT (SN)	SCRATCHED	160.00	160.00
1	YAMAHA LOGO (SN)	NECESSARY	80.00	80.00
1	REAR BOX (SN)	SCRATCHED	280.00	150.00
1	BODY DECAL STICKER (SN)	NECESSARY	250.00	150.00
			770.00	540.00
	<u>LABOUR</u>			
	TOWING FEE.		40.00	40.00
	REMOVE & REPLACE DAMAGED PARTS,ALIGN & ETC.INCLUSIVE OF THE REPAIR OF SET FORK TUBER,FRONT MUDGUARD AND FRONT RIM.		350.00	250.00
	REMOVE & REPLACE FORK TUBE & TOP UP FORK OIL.		120.00	80.00
	RE-ALIGN FRONT BODY FRAME.		250.00	100.00
	CHECK ELECTRICAL HARNESS.		60.00	30.00
			820.00	500.00
	GRAND TOTAL		6,428.40	4,107.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,300.00

Report Ref No. CS/FC118000007/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.