

ALG-LEK

DATE 29/12/2017 11:43

Jumani

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Side Bracket, LH ×			\$ 14.30
	Front Bumper Clips 10 pcs ×			\$ 22.00
	Sub Total			\$ 598.60
	Less 20%			\$ 119.72
	Discounted Total			\$ 478.88
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00
	Labour Charge			200
	Panel Beating			\$ 250.00
	Spray Painting Charge			\$ 400.00 360
	Total Labour			\$ 650.00
	Estimate Total			\$ 1,228.88
	1 Calvi 1664 N 29/12/15 2 Dr. P/P P/H Repair p/h Before Rep. p/h			
	This is an initial estimate based on a visual inspection of the above vehicle.	The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.	LKK Auto Centre wants you to notify the Repairer before doing: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on "Without Prejudice" basis • No illegal modification is allowed • Supplementary items must be surveyed and is subject to final approval from Insurance Company	Acknowledged by Repairer _____ Date: _____